

**NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL  
(TEMPORARY FORM)**

CONTROL NO: 13642  
FILE: INCIDENT REPORT FI

FROM: Iowa Elec. Light & Power Cedar Rapids, Iowa E.L. Hammond		DATE OF DOC 11-28-75	DATE REC'D 12-5-75	LTR XXX	TWX	RPT	OTHER
TO: James G. Keppler		ORIG 1 Signed	CC 0	OTHER	SENT AEC PDR SENT LOCAL PDR		XXX XXX
CLASS	UNCLASS XXX	PROP INFO	INPUT	NO CYS REC'D 1	DOCKET NO: 50-331		

**DESCRIPTION:**  
Letter trans the following.....

**PLANT NAME:** Duane Arnold

**ENCLOSURES:**  
Abnormal Occurrence # 75-63, on 11-19-75,  
Concerning Reactor Low Pressure switches  
being out of specification:.....

(1 Copy Received)

**FOR ACTION/INFORMATION** SAB 12-8-75

- |                         |                            |                             |                        |
|-------------------------|----------------------------|-----------------------------|------------------------|
| BUTLER (L)<br>W/ Copies | SCHWENCER (L)<br>W/ Copies | ZIEMANN (L)<br>W/ Copies    | REGAN (E)<br>W/ Copies |
| CLARK (L)<br>W/ Copies  | STOLZ (L)<br>W/ Copies     | DICKER (E)<br>W/ Copies     | LEAR (L)<br>W/3 Copies |
| PARR (L)<br>W/ Copies   | VASSALLO (L)<br>W/ Copies  | KNIGHTON (E)<br>W/ Copies   | SPELS<br>W/ Copies     |
| KNIEL (L)<br>W/ Copies  | PURPLE (L)<br>W/ Copies    | YOUNGBLOOD (E)<br>W/ Copies | REID<br>W/ Copies      |

**ACKNOWLEDGED**  
**DO NOT REMOVE**

**INTERNAL DISTRIBUTION**

- |   |   |   |   |  |
|---|---|---|---|--|
| <del>REG FILE</del><br>NRC PDR<br>OGC, ROOM P-506A<br>GOSSICK/STAFF<br>CASE | <u>TECH REVIEW</u><br><del>SCHROEDER</del><br>MACCARY<br>KNIGHT<br>PAWLICKI<br>SHAO<br>**STELLO<br>**HOUSTON<br>**NOVAK<br>ROSS<br>IPPOLITO<br>TEDESCO<br>J. COLLINS<br>LAINAS<br>BENAROYA<br>VOLLMER | DENTON<br>**GRIMES<br>GAMMILL<br>KASTNER<br>BALLARD<br>SPANGLER<br><br><u>ENVIRO</u><br>MULLER<br>DICKER<br>KNIGHTON<br>YOUNGBLOOD<br>REGAN<br>PROJECT LDR<br><br>HARLESS | <u>LIC ASST</u><br>R. DIGGS (L)<br>H. GEARIN (L)<br>E. GOULBOURNE (L)<br>P. KREUTZER (E)<br>J. LEE (L)<br>M. RUSHBROOK (L)<br>S. REED (E)<br>M. SERVICE (L)<br>S. SHEPPARD (L)<br>M. SLATER (E)<br>H. SMITH (L)<br>S. TEETS (L)<br>G. WILLIAMS (E)<br>V. WILSON (L)<br>R. INGRAM (L)<br>M. DUNCAN (E) | <u>A/T IND.</u><br>BRAITMAN<br>SALTZMAN<br>MELTZ<br><br><u>PLANS</u><br>MCDONALD<br>CHAPMAN<br>DUBE (Ltr)<br>E. COUPE<br>PETERSON<br>HARTFIELD (2)<br>KLECKER<br>EISENHUT<br>WIGGINTON<br><br>F. WILLIAMS<br>HANAUER |
|---|---|---|---|--|

**EXTERNAL DISTRIBUTION**

- |                                   |                                |   |
|-----------------------------------|--------------------------------|---|
| 1 - LOCAL PDR Cedar Rapids, Iowa  | 1 - NATIONAL LABS              | 1 - PDR-SAN/LA/NY                       |
| 1 - TIC (ABERNATHY) (1)(2)(10)    | 1 - W. PENNINGTON, Rm E-201 GT | 1 - BROOKHAVEN NAT LAB                  |
| 1 - NSIC (BUCHANAN)               | 1 - CONSULTANTS                | 1 - G. ULRIKSON, ORNL                   |
| 1 - ASLB                          | NEWMARK/BLUME/AGBABIAN         | 1 - AGMED (RUTH GUSSMAN)<br>Rm B-127 GT |
| 1 - Newton Anderson               |                                | 1 - J. D. RUNKLES, Rm E-201<br>GT       |
| 16 ACRS SENT TO LIC ASST S. Teets |                                |   |
| ** SEND ONLY TEN DAY REPORTS      |                                |   |

12


**IOWA ELECTRIC LIGHT AND POWER COMPANY** *Reg. System*

DUANE ARNOLD ENERGY CENTER  
P. O. Box 351  
Cedar Rapids, Iowa 52406

DAEC - 75 - 437

November 28, 1975

Mr. James G. Keppler, Director  
Office of Inspection and Enforcement  
U. S. Nuclear Regulatory Commission-Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137




Subject: Abnormal Occurrence No. AO 50-331/75-63

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence.



Very truly yours,

*E. L. Hammond*  
E. L. Hammond  
Assistant Chief Engineer  
Duane Arnold Energy Center

DLW/ELH/mg

cc: B. C. Rusche  
Duane Arnold  
J. A. Wallace  
L. Liu  
H. W. Rehrauer - Chairman, Safety Committee  
J. R. Newman  
G. G. Hunt

13642

DEC 1 1975

# IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER  
P. O. Box 351  
Cedar Rapids, Iowa 52406

Subject: Abnormal Occurrence  
Report Number: AO 50-331/75-63  
Report Date: November 28, 1975  
Occurrence Date: November 19, 1975  
Facility: Duane Arnold Energy Center, Palo, Iowa

## Identification of Occurrence

Out-of-specification Reactor Low Pressure (RHR Shutdown Cooling Isolation) pressure switches, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.a and 3.2.A.

## Conditions Prior to Occurrence

Reactor at rated pressure and temperature.

1295 MWth      438 MWe

## Description of Occurrence

While performing Surveillance Test Procedure No. 42A002 - Reactor Low Pressure (RHR Shutdown Cooling), maintenance personnel incorrectly calibrated pressure switches 4637, 4638A and 4638B. These switches provide an interlock function to isolate and prevent operation of the RHR system in the shutdown cooling mode when reactor pressure is  $\gt$  135 psig. In accordance with the surveillance test procedure, the switches should have been calibrated using increasing pressure. However, the maintenance technicians incorrectly calibrated the switches using decreasing pressure, and as a result, the trip point of the switches for increasing reactor pressure was approximately 160 psig and was above the 135 psig setpoint required by the Technical Specifications. The switches were in an out-of-specification condition for approximately three hours.

## Designation of Apparent Cause of Occurrence

The cause of the occurrence was personnel error. Maintenance personnel performing the surveillance test did not comply with the requirements of the approved test procedure.

Analysis of Occurrence

The occurrence did not present an unsafe plant condition. Even though the setpoint of the switches was out-of-specification for a short time, reactor pressure was well above this point and the RHR Shutdown Cooling System remained isolated as required.

Corrective Action

Pressure switches 4637, 4638A and 4638B were recalibrated when the error in calibration was discovered.

Maintenance personnel involved have been reinstructed as to the requirements for strictly adhering to the requirements of surveillance test procedures.

Conclusion

This report was reviewed and approved by the DAEC Operations Committee on November 28, 1975. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

*E. L. Hammond*

E. L. Hammond  
Assistant Chief Engineer  
DAEC

DLW/ELH/mg