(TEMPORARY FORM)

CONTROL NO:\_

1 - J. D. RUNKLES, Rm E-201

Rm B-127 GT

FILE: INCIDENT REPORT

FROM: Iowa Electric Light And Power Co. Cedar Rpaids, Iowa		DATE OF DOC	DAT	E REC'D	LTR	TWX	RPT	OTHER
		11-19-75	11-24-75		xxxx			
G.G. Hunt O:		ORIG	CC OTHER SENT AE		C PDR_	<b>XX</b>		
Mr. James G. Keppler		none	1 SENT LOCAL PDR				?	
		INPUT		NO CYS REC'D DOCKET NO:				
CLASS UNCLASS	PROPINEO	INFOI						
xxx				1 50-331				
DESCRIPTION:			ENCL	OSURES:	ACK	MOU	מים זיגו	
Ltr trans the following:			ACKNOWLEDGED Abnormal Occurrence #75-59 on 11-5-75					
		concerning violation of primary contain			<b>co</b> ntainmen			
			rec	uirements	• • • •	•		
	•							• • •
		•	1	•	·			
				TA OUT	OM T	· .	( ) moreover	
PLANT NAME:			<b>!</b>	DON	ULI	TILLY (		•
Duane A	rnold		]			26 7	IE TOD	
		FOR ACTION/		<del></del>		L26-7	3 JGB	
BUTLER (L)	SCHWENCER			REGAN W/ Co				
W/ Copies CLARK (L)	W/ Copies STOLZ (L)	W/ Copies DICKER (E		LEAR			•	
W/ Copies	W/ Copies	W/ Copies		W/3C				
PARR (L)	VASSALLO (I			SPELS				
W/ Copies	W/ Copies	W/ Copies		W/ C	opies			
KNIEL (L) W/ Copies	PURPLE (L) W/ Copies	YOUNGBLO W/ Copies		W/ C	opies			
W Copies	tt, Copies	INTERNAL D			<u>'</u>			<del></del>
REG FILE	TECH REVIE			LIC AS	ST		A/T II	ND .
NRC PDR	SCHROEDER			R. DIGGS			BRAI	TMAN
OGC, ROOM P-506A	<b>⊘</b> MACCARY	GAMMILL		H. GEARI	N (L)			ZMAŅ
GOSSICK/STAFF	KNIGHT	KASTNER BALLARD		E. GOULE P. KREUT			MEL.	12
CASE GIAMBUSSO	PAWLICKI SHAO	SPANGLER	}	J. LEE (L		L- /	PLAN	!S_
	STELLO			M. RUSHBR		.)		DNALD
	HOUSTON	ENVIRO		S. REED			CHAF	IVIAN E (Ltr)
DEYOUNG (L) ***	NOVAK ROSS	MULLER DICKER		M. SERVI		١	E. CO	
SKOVHOLT (L) GOLLER (L) (Ltr)	IPPOLITO	KNIGHTON	J	S. SHEPPARD (L) M. SLATER (E)			PETERSON	
P. COLLINS	TEDESCO	YOUNGBLOO		H. SMITH (L)			HARTFIELD (2)	
DENISE	J. COLLINS	REGAN PROJECT LDR		G. WILLIAMS (E)			→ KLECKER EISENHUT	
REG OPR FILE &, REGION (2)	LAINAS BENAROYA	PROJECT (	ากม	V. WILLIA		1		GINTON
MIPC/PE (3)	VOLLMER	HARLESS		R. INGRA				HILLIAMS
STEELE	<u></u>			M. DUNCA			HAN!	
		EXTERNAL D	ISTRI					
-1 - LOCAL PDR Ce	dar Rapids, Id				Sec			
ارً – TIC (ABERNAT	HY) (1)(2)(10)	- NATIONAL LA					R-SAN/LA	
1 - NSIC (BUCHAN		- W. PENNINGT		m E-201 GT	-	I BRC	JUKHAV	EN NAT LA N, ORNL
1 - ASLB	1	- CONSULTAN		A C D A DEAD		. – G. C I – AGI	MED IBL	TH GUSSM

NEWMARK/BLUME/AGBABIAN

1 – Newton Anderson

5- ACRS SENT TO LIC ASST \*\* SEND ONLY TEN DAY REPORTS

# IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406

DAEC - 75 - 429 November 19, 1975

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission - Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137

Subject: Abnormal Occurrence No.

AO 50-331/75-59

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center, please find enclosed a written report on the subject abnormal occurrence. Submittal of the report was delayed due to a delay in completing the investigation of the occurrence. Mr. H. Kister of your office was advised of the delay by telephone on November 14, 1975. A written notification of the delay was also transmitted to your office on the same date.

Very truly yours,

G. G. Hunt Chief Engineer

Duane Arnold Energy Center

DLW/GGH/mg

cc: (B. C. Rusche)

Duane Arnold

J. A. Wallace

L. Liu

H. Rehrauer - Chairman, Safety Committee

J. R. Newman

E. L. Hammond

13278

File Cy.

Property of

# IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER

P. O. Box 351

Cedar Rapids, Iowa 52406

Subject:

Abnormal Occurrence

Report Date:

November 19, 1975

Report Number:

AO 50-331/75-59

Occurrence Date:

November 5, 1975

Facility:

Duane Arnold Energy Center, Unit No. 1, Palo, Iowa

# Identification of Occurrence

Violation of primary containment requirements, reportable in accordance with Appendix A to Operating License DPR-49, Specifications 1.0.4.b and 3.7.A.2.

## Conditions Prior to Occurrence

Reactor in a hot shutdown condition.

# Description of Occurrence

While in the process of placing the reactor in a cold shutdown condition, RHR shutdown cooling valve MOV 1908 was opened manually. The valve was opened manually because surveillance testing performed in September 1975 had determined that the valve was inoperable and could not be opened remotely from the Control Room. Since the automatic isolation function of the valve was assumed inoperable, primary containment integrity was violated from the time the valve was manually opened on November 5, 1975 until the reactor was placed in a cold shutdown condition on the same date. It should be noted that MOV 1908 and redundant isolation valve MOV 1909 were maintained in a closed position during the period September 3 to November 5, 1975 in order to satisfy Technical Specification requirements.

#### Designation of Apparent Cause of Occurrence

The cause of the occurrence was an inoperable RHR shutdown cooling isolation valve (MOV 1908). The violation of the requirements for primary containment integrity resulted from the fact that the valve was manually opened when the automatic isolation function of the valve was declared inoperable. It was necessary to open MOV 1908 in order to place the reactor in a cold shutdown condition using normal cooldown procedures.

It is not known why MOV 1908 failed to open during surveillance testing in September 1975. The breaker to MOV 1908 tripped on overload but it is not known what caused the overload condition. The valve operator was subsequently inspected and tested during the November 5th shutdown and no abnormalities were noted.

AO 50-331/75-59 Page 2 November 19, 1975

# Analysis of Occurrence

The occurrence did not present an unsafe plant condition. RHR shutdown cooling isolation valve MOV 1909 was operable during the occurrence and would have provided a redundant capability for isolating the RHR shutdown cooling line.

# Corrective Action

Since it was necessary to open MOV 1908 in order to place the plant in cold shutdown condition using normal cooldown techniques, the occurrence could not be avoided and no corrective action can be implemented in that respect.

MOV 1908 was inspected and functionally tested prior to commencing reactor startup on November 5, 1975. No abnormalities were noted during testing which included a measurement of closing times. The valve will again be functionally tested on the next occassion the shutdown cooling mode of the RHR system is initiated.

#### Conclusion

This report was reviewed and approved by the DAEC Operations Committee on November 19, 1975. The Committee concluded that the occurrence did not present a hazard to the health and safety of the public.

G. G. Hunt Chief Engineer

DAEC

DLW/GGH/mg