REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:7904230192 DOC.DATE: 79/03/27 NOTARIZED: NO FACIL:50=331 DUANE ARNOLD ENERGY CENTER, IOWA ELECTRIC LIGHT & POW AUTH.NAME AUTHOR AFFILIATION IOWA ELECTRIC LIGHT & POWER CO. RECIP.NAME RECIPIENT AFFILIATION KEPPLER, J.G. REGION 1, PHILADELPHIA, OFFICE OF THE DIRECTOR DOCKET # 05000331

SUBJECT: NOTIFICATION OF REPORTABLE OCCURRENCE ON 790326:DIFFERENTIAL: TEMP INSTRUMENTAL ACTIVATED. ISOLATION VALVE SHOULD HAVE CLOSED, BUT WAS FOUND OPEN. CAUSED BY SLIGHT BEND IN STATIONARY CONTACT ARM, RELAY REPAIRED & TESTED.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 2 SIZE:

NOTES:_	- X	i da		y 7
ACTION:	RECIPIENT ID CODE/NAME 05 BC ORB#3	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
INTERNAL:	01 REG FILE 09 184 14 TA/EDO 16 EEB 18 PLANT SYS BR 20 AD PLANT SYS 22 REAC SAFT BR 24 KREGER 26 AD/SITE ANAL 28 ACDENT ANLYS E JORDAN/IE		OZ NRC PDR 11 MPA 15 NOVAK/KNIEL 17 AD FOR ENGR 19 I&C SYS/PROJ 21 AD SYS/PROJ 23 ENGR BR 25 PWR SYS BR 27 OPERA LIC BR 29 AUX SYS BR	
EXTERNAL:	03 LPDR 29 ACRS	16 16	04 NSIC	1

APR 24 1979

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL

, PEB

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406
March 27, 1979
DAEC - 79 - 60

Mr. James G. Keppler, Director
Office of Inspection and Enforcement-Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Prompt Notification of a

Reportable Occurrence

File: A-118a

Dear Mr. Keppler:

This letter, telecopied to your office, is intended to satisfy the requirement for prompt notification of a Reportable Occurrence in accordance with Specification 6.11.2.a of the Duane Arnold Energy Center Technical Specifications.

Technical Specification paragraph(s) violated:

Description Occurrence: While performing operational testing on March 26, 1979 in the reactor water cleanup system room, the room high differential temperature instrumentation was inadvertently activated. This action should have closed RWCU system isolation valve MOV 2700 and provided control room annunciation. The reactor operator acknowledged the annunciator and found MOV 2700 had not closed. The operator immediately closed MOV 2700 as well as the redundant isolation valve MOV 2701. Investigation revealed the valve had not closed due to the logic relay having a slightly bent stationary contact arm. The relay was repaired and tested.

Very truly yours,

Ellery L. Hammond

Chief Engineer

Duane Arnold Energy Center

ELH/JVS/n

Director, Management Information and Program Control (2) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

1002