REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7906250301 DOC.DATE: 79/06/21 NOTAKIZED: NO DOCKET # FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331

AUTH NAME

AUTHOR AFFILIATION

SICKEL, J. V. RECIP. NAME Iowa Electric Light & Power Co. RECIPIENT AFFILIATION

Region 3, Chicago, Office of the Director

SUBJECT: LER 79-012/03L-0 on 790522:during surveillance testing, small leak was noted at threaded base of diesel lube oil high temp alarm. Caused by switch which had vibrated loose in mounting socket allowing lubricant to escape. Switch tightened.

DISTRIBUTION CODE: A0028 COPIES RECEIVED:LTR _/ ENCL _/ SIZE:__/+/__ TITLE: INCIDENT REPORTS

NOTES:

ACTION:	RECIPIENT ID CODE/NAME 05 BC ORB#3	COPIE LTTR 4		RECIPIENT ID CODE/NAME	COPII LTTR I	
INTERNAL:	01-REG FIL- 09 I&E 14 TA/ED0 16 EEB 18 PLANT SYS BR 20 AD PLANT SYS 22 REAC SAFT BR 24 KREGER 26 AD/SITE ANAL 28 ACDENT ANLYS E JORDAN/IE TMI DOC CENTER	1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 2 1 1 1 1 1 1 1 1 1	02 NRC PDR 11 MPA 15 NOVAK/KNIEL 17 AD FOR ENGR 19 I&C SYS BR 21 AD SYS/PROJ 23 ENGR BR 25 PWR SYS BR 27 OPERA LIC BR 29 AUX SYS BR HANAUER,S.	1 3 1 1 1 1 1 1 1	1 3 1 1 1 1 1 1 1
EXTERNAL:	03 LPDR 29 ACRS	1 16	1 16	04 NSIC	1	1

JUN 26 1979

(7-72)	LICENSEE EVENT REPORT
	CONTROL BLOCK: [
0 1	1 A D A C 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 4 57 CAT 58 5
0 1 7 8	SOURCE L 6 0 5 0 0 0 3 3 1 7 0 5 2 2 7 9 3 0 6 2 1 7 9 9 9
0 2	During surveillance testing a small leak was noted at the threaded base
0 3	of TS-3254A, 1G-31 diesel lube oil high temp. alarm. During the course o
0 4	f the test the leak increased in magnitude such that the engine was shut
0 5	down and declared inoperable until the leak could be repaired. Standby
0 6	I diesel generator operability requirements listed in Tech. Spec. 3.8.A.2,
0 7	[3.8.B.l and 3.5.G. Redundant standby diesel generator IG-21 was operable.
08	9 80
0 9	SYSTEM CAUSE CAUSE SUBCODE COMPONENT CODE SUBCODE SUBC
+ 7	LER/RO EVENT YEAR SEQUENTIAL REPORT NO. 17 REPORT NUMBER 21 22 23 24 26 27 28 29 30 31 31 32
	ACTION FUTURE COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT SUBMITTED FORM SUB. PRIME COMP. COMPONENT MANUFACTURER B 18 Z 19 Z 20 Z 21 1 0 0 0 0 0 N 23 N 24 A 25 C 5 6 0 26 CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
10	The switch apparently vibrated loose in its mounting socket allowing lubr
	icating oil to escape. The switch was removed, the threads covered with
1 2	teflon tape and the switch reinstalled and securely tightened. TS-3245A
1 3	is a Consolidated Controls Corp. Type 22A temperature switch. The switch
14	will be replaced if further serious leaking problems occur.
1 5	FACILITY STATUS STATUS STATUS OTHER STATU
1 6 ^R	ELEASED OF RELEASE AMOUNT OF ACTIVITY (35) Z (33) Z (34) NA LOCATION OF RELEASE (36) 9 10 11 44 45
1 7 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (39) O O O O (37) Z (38) NA
1 3	NUMBER DESCRIPTION 41 0 0 0 40 NA
7 8 1 9 7 8	Uoss of OR DAMAGE TO FACILITY 43 TYPE DESCRIPTION NA 790625030/ 9
2 0	PUBLICITY ISSUED DESCRIPTION 45 NRC USE ONLY NRC USE ONLY 10 68 69 80 80 80 80 80 80 80 80 80 8
	NAME OF PREPARER J. Van Sickel PHONE: 319-851-5611 0