

DSB

Iowa Electric Light and Power Company
September 27, 1979
DAEC-79-254

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission - Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 79-020
(30 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

EL Hammond /lh

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/lh

cc: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

7910030465

OCT 1 1979

LICENSEE EVENT REPORT

CONTROL BLOCK:

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I A D A C 1 2 0 0 - 0 0 0 0 0 0 - 0 0 3 4 1 1 1 1 1 1 4 5
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54 55 56 57 58 59 60 61 62 63 64 65 66 67 68 69 70 71 72 73 74 75 76 77 78 79 80 81 82 83 84 85 86 87 88 89 90 91 92 93 94 95 96 97 98 99 100

CON'T

0 1

REPORT
SOURCE

L 6

0 5

0 0

0 3

3 1

7 0

9 0

2 7

9 8

0 9

2 7

7 9

9 9

2 7

7 9

9 9

2 7

7 9

9 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2

Following a power increase in accordance with approved procedures, CPR

0 3

was found to be 1.289, below the Technical Specification limit of greater

0 4

than or equal to 1.290. Recirculation flow was immediately reduced and

0 5

22 minutes later CPR was again checked and found to be 1.303, well above

0 6

the Tech. Spec. limit. Reference Tech. Spec. Table 3.12-2.

0 7

0 8

7 8 9

0 9

7 8 9

SYSTEM
CODE

R B

11

CAUSE
CODE

X

12

CAUSE
SUBCODE

Z

13

COMPONENT CODE

X X X X X X X

14

COMP.
SUBCODE

Z

15

VALVE
SUBCODE

Z

16

(17) LER/RO
REPORT
NUMBER

EVENT YEAR

7 9

21 22

—

23

SEQUENTIAL
REPORT NO.

0 2 0

24 25 26

/

27

OCCURRENCE
CODE

0 3

28 29

REPORT
TYPE

L

30 31

REVISION
NO.

0

32

ACTION
TAKEN

X

18

33 34

FUTURE
ACTION

Z

19

35 36

EFFECT
ON PLANT

Z

20

37 38

SHUTDOWN
METHOD

Z

21

39 40

HOURS

0 0 0 0

22 23 24 25

ATTACHMENT
SUBMITTED

N

23

41 42

NPRD-4
FORM SUB.

N

24

43 44

PRIME COMP.
SUPPLIER

Z

25

45 46

COMPONENT
MANUFACTURER

Z 9 9 9

47 48 49 50

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0

This occurrence was the result of a Xenon transient causing thermal power

1 1

to increase. Corrective actions to increase CPR were proper and well

1 2

within the time limits specified in Technical Specifications Paragraph

1 3

3.12-C. The plant has been and will continue to be operated in a manner

1 4

which will minimize this type of occurrence.

7 8 9

FACILITY
STATUS

F

28

7 8 9

% POWER

0 9

10 11

12 13

OTHER STATUS

NA

14 15

METHOD OF
DISCOVERY

A

30

44 45

DISCOVERY DESCRIPTION

Operator Observation

31 32

ACTIVITY CONTENT
RELEASED OF RELEASE

Z

33

7 8 9

10 11

12 13

AMOUNT OF ACTIVITY

NA

35 36

NA

LOCATION OF RELEASE

37 38

PERSONNEL EXPOSURES

NUMBER

0 0 0

11 12

13 14

15 16

17 18

19 20

21 22

23 24

25 26

27 28

29 30

31 32

33 34

35 36

37 38

39 40

41 42

43 44

45 46

47 48

49 50

PERSONNEL INJURIES

NUMBER

0 0 0

11 12

13 14

15 16

17 18

19 20

21 22

23 24

25 26

27 28

29 30

31 32

33 34

35 36

37 38

39 40

41 42

43 44

45 46

47 48

49 50

LOSS OF OR DAMAGE TO FACILITY

TYPE

Z

42

7 8 9

10 11

12 13

14 15

16 17

18 19

20 21

22 23

24 25

26 27

28 29

30 31

32 33

34 35

36 37

38 39

40 41

42 43

44 45

PUBLICITY

ISSUED

N

44

7 8 9

10 11

12 13

14 15

16 17

18 19

20 21

22 23

24 25

26 27

28 29

30 31

32 33

34 35

36 37

38 39

40 41

42 43

44 45

NRC USE ONLY

68 69