NRC FORM 195		U.S. NU	CLEAR REGULATO	DRY COMILISSION	DOCKET NUMBER
(2-76)				A_	FILE NUMBER
NRC DISTRIBU	JTION FOR	PART 50 DOCKET	MATERIAL		INCIDENT REPORT
TO: -9		FROM:			DATE OF DOCUMENT
Mr. James G. Keppler		Towa Elect	Light & Powe:	r Co.	10/05/77
			s, Iowa 524		DATE RECEIVED
		Ellery L. H			10/20/77
☐CETTER □NO	TORIZED	PROP	INPUT F	ORM	NUMBER OF COPIES RECEIVED
	CLASSIFIED				
COPY					ISIGHED
PLANT NAME: DUANE jcm 10 BRANCH CHIEF:	/21/77 /)		77) on 09/2 not develop quired flow surveillanc plp NOTE: I	1/77 concern sufficient and dischare testing	t Report (RO 50-331/77- ing HPCI system would RPM to produce the re- ge pressure during
LIC ASST.:					
			 		
			+		· · · · · · · · · · · · · · · · · · ·
		INTERNAL D	DISTRIBUTION		
REG FILE					
NRC PDR					
I & E (2)					·
MIPC			,		
SCHROEDER/IPPOLIT	0				
HOUSTON					
NOVAK/CHECK					
GRIMES					
KNIGHT			ļ		
BUTLER			_		
HANAUER			<u> </u>		
TEDESCO					
EISENHUT					<u> </u>
BAER		<u></u>			<u> </u>
SHAO					
VOLLMER/BUNCH			 		
KREGER/ J. COLLIN	IS			<u></u>	
ROSA			 		
	FXTF	RNAL DISTRIBUTION			CONTROL NUMBER
LPDR: CEOAR			T		
TIC:	111				
	 				772940108 M4
NSIC: ACRS (16) SENT AS	S dAT R			1,1,1,1	1/2240100
ACRO (10) SENT AL		-			
	11		1 1	·····	7 (1)

O. Lankam


REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER

P. O. Box 351
Cedar Rapids, Iowa 52406
October 5, 1977
DAEC-77 - 502

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission - Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137



(30 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Skyork / for Ellery L. Hammond

Chief Engineer

Duane Arnold Energy Center

ELH/JVS/mg

Docket 50-331

attachment

cc: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

OCT 7 1977



ર	CONTROL BLOCK: PLEASE PRINT ALL REQUIRED INFORM	MATION]
7 (1 6 LICENSE NUMBER LICENSE EVENT TYPE 1 A D A C 1 0 0 0 0 0 0 0 0 0	
01 7	CATEGORY TYPE SOURCE OOCKET NUMBER EVENT DATE REPORT DATE CON'T TYPE SOURCE OOCKET NUMBER EVENT DATE REPORT	
0 2		i
7 B	industrial and the state of the	80
7 B	emergency core cooling systems were operable. Adjustments were made to	80
7 6 05	lube oil control valves and the system tested for satisfactory operatio	60
7 6 06	n. (RO 77–77)	80
7 8	SYSTEM	80
08	The operating instruction for the HPCI system included a requirement th	1
7 6 09	at the turbine and pump bearing lube oil supply throttling valves be al	80
7 B	igned in the full open position. This produced excessive oil demand an	80
7 8	FACILITY STATUS 8 POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION E	80
12 7 8	FORM OF ACTIVITY CONTENT RELEASE OF RELEASE NA LOCATION OF RELEASE NA NA NA NA	80
13 7 8	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 0 0 0 Z NA 9 11 12 13	80
14 7 8	PERSONNEL INJURIES NUMBER DESCRIPTION O O 1 1 12	80
15	OFFSITE CONSEQUENCES NA NA	1
7 8	LOSS OR DAMAGE TO FACILITY	80
16 7 8	Z DESCRIPTION NA NA 9 10	1
	PUBLICITY	80
17 7 8 9	NA 9	80
18 7 8 9	ADDITIONAL FACTORS – Cause Desc. Cont. d prevented sufficient oil pressure being developed to open the turbine 9	
19 7 8 9	stop valve far enough to develop rated speed. OI to be corrected.	80
, 08	NAME:	80