NRC FORM 195	U.S. N		ON DOCKET NUMBER
(2-76)		•	FILE NUMBER
A NRC DISTRIBUTION FOR	PART 50 DOCKET	MATERIAL	INCIDENT REPORT
TO:	FROM:	7: 1: 0 D	DATE OF DOCUMENT
		Light & Pwr. Company	11/18/77
Mr. James G. Keppler	Cedar Rapi Ellery L•		DATE RECEIVED 11/28/77
ZETTER NOTORIZED	PROP	INPUT FORM	NUMBER OF COPIES RECEIVED
ORIGINAL COCLASSIFIED			
COPY			ISIGNED
DESCRIPTION	•	ENCLOSURE	
		10/28/77 concerning pump being noted to slightly, and the a	rt (RO 50-331/77-85) on the "A" recirculation have decreased in flow ssocited M-G set field & the M-G set generator increasing
PLANT NAME:Duane Arnold RJL 11/28/77	(1 - P)	(1-P)	
		SEND DIRECT	EL EXPOSURE IS INVOLVED TLY TO KREGER/J. COLLINS
		VINFORMATION	
BRANCH CHIEF: (4)	KEAR		
W/ CYS FOR ACTION			
LIC ABST.:			
	INTERNAL	DISTRIBUTION	
	INTERIVAL	DISTRIBUTION	
REG FILE			
NRC PDR			
I & E (2)			
MTPC			
SCHROEDER/IPPOLITO			
HOUSTON NOVAK/CHECK	· · · · · · · · · · · · · · · · · · ·		
GRIMES			
KNIGHT			
RITTER			
HANAIIER			
TEDESCO			
FISENHUT			
BAFR			
SHAO			
VOLLMER/BUNCH			
KREGER/ J. COLLINS			
ROSA			
L CROCKER			
EXT	ERNAL DISTRIBUTIO	N	CONTROL NUMBER
LPDR: COUAR RAPIOS /	4.		,
TIC:			773320179 40 4
NSTC:			1 Community of the second
ACRS (16) SENT AS CAT B			Go

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER

P. O. Box 351

Cedar Rapids, Iowa 52406

November 18, 1977 DAEC-77-579

Mr. James G. Keppler, Director Office of Inspection and Enforcement U. S. Nuclear Regulatory Commission - Region III 799 Roosevelt Road Glen Ellyn, Illinois 60137



Subject: Licensee Event Report No. 77-85

(30 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Eller L. Hammond

Chief Engineer

Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (30)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

NOV 22 1977

773320179

LICENSEE EVENT REPORT

•,	CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)
0 1 8	I A D A C 1 2 0 0 - 0 0 0 0 - 0 0 3 4 1 1 1 1 4 57 CAT 58 5
CON'T 0 1 7 8	REPORT L 6 0 5 0 0 0 3 3 1 7 1 0 2 8 7 7 8 1 1 1 1 7 7 7 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)
0 2	During normal operation the "A" recirculation pump was noted to have de
0 3	creased in flow slightly, the associated M-G set field voltage had incr
0 4	eased and the M-G set generator winding temperature was increasing. Th
0 5	e M-G set was removed from service to investigate this problem. No sig
0 6	nificant occurrence resulted from this event. See also RO 77-84.
0 7	
0 8	
0 9	SYSTEM CAUSE CODE SUBCODE COMPONENT CODE SUBCODE SUBCODE C B (11) E (12) A (13) T R A N S F (14) Z (15) Z (16) SEQUENTIAL OCCURRENCE REPORT REVISION
	17 REPORT NUMBER 7 7 7
	TAKEN ACTION ON PLANT METHOD HOURS (22) SUBMITTED FORM SUB. SUPPLIER MANUFACTURER C 18 Z 19 B 20 Z 21 O O O B N 23 N 24 N 25 G O B O 2
1 0	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) [Investigation revealed the primary side fuses of a M-G set voltage req
	·
1 1	ulator reference transformer were opened. The reference transformer and
1 1	ulator reference transformer were opened. The reference transformer and fuses were replaced with like-for-like spares. The reference transform
1 3	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 448215966-001. The M-G set was re turned to service and no further problems have been experienced.
1 2 1 3 1 4 7 8	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. The M-G set was re turned to service and no further problems have been experienced. PACILITY SPOWER OTHER STATUS NA A 31 Operator Observation PORTON CONTROL OF THE STATUS OPERATOR OPERATOR OF THE STATUS OPERATOR OPERATOR OPERATOR OPERATOR OPER
1 2 1 3 1 4 7 8 1 5 7 8 A RI	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. **TATUS** **POWER** OTHER STATUS** OPERATOR OF PELEASE COLORTON OF RELEASE AMOUNT OF ACTIVITY* **TOTAL OF THE PROBLEM
1 2 1 3 7 8 1 5 7 8 1 6 7 8	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. STATUS SPOWER OTHER STATUS OF DISCOVERY DESCRIPTION (32) F 28 0 9 13 29 NA A A A A A A A A A A A A A A A A A A
1 2 1 3 1 4 7 8 1 5 7 8 1 6 7 8	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. **BOOK TOTALLY STATUS** **POWER** **OTHER STATUS** **POWER** **OTHER STATUS** **POWER** **OTHER STATUS** **OPOWER** **OTHER STATUS** **OPOWER** **OPOWER*
1 2 1 3 1 4 7 8 1 5 7 8 1 6 7 8 1 7 7 8	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. **ACILITY SPOWER OTHER STATUS 30 METHOD OF DISCOVERY DESCRIPTION 32 DISCOVERY DESCRIPTION 33 DISCOVERY DESCRIPTION 34 DISCOVERY DESCRIPTION 35 DISCOVERY DESCRIPTION 35 DISCOVERY DESCRIPTION 35 DISCOVERY DESCRIPTION 36 DISCOVERY DESCRIPTION 37 DISCOVERY DISCOVERY DESCRIPTION 37 DISCOVERY DISCOVERY DESCRIPTION 37 DISCOVERY DISCOVERY DESCRIPTION 37 DISCOVERY DESCRIPTION 37 DISCOVERY DIS
1 2 1 3 1 4 7 8 1 5 7 8 1 6 7 8 1 7 7 8 1 3 7 8	fuses were replaced with like-for-like spares. The reference transform er is a General Electric part number 44B215966-001. The M-G set was re turned to service and no further problems have been experienced. **POWER OTHER STATUS ** **POWER OTH

RECEIVED DOCUMENT

1977 NOV 28 PM 12 30

.

.