

50-331

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

TO:

Mr. James G. Keppler

FROM:

Iowa Elec. Light & Power Co.
Cedar Rapids, Iowa
Ellery L. Hammond

DATE OF DOCUMENT

12/22/77

DATE RECEIVED

1/4/78

LETTER
 ORIGINAL
 COPY

NOTORIZED
 UNCLASSIFIED

PROP

INPUT FORM

NUMBER OF COPIES RECEIVED

1 SIGNED

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-331/77-93) on 12/12/77 concerning the RGIC system steam supply line high flow pressure differential indicating switches being found with their setpoints out of calibration.....

PLANT NAME: Duane Arnold
RJL 1/4/78

(1-P)

(1-P)+(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

1 ENCC

FOR ACTION/INFORMATION

BRANCH CHIEF: (4)
7/ DAYS FOR ACTION
CLASSIFIED

LEAR

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

T S F (2)

MTEC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

CRIMES

KNIGHT

BUTLER

HANAUER

TEDESCO

EISENHUT

BAER

SHAO

VOLLMEYER/BUNCH

KREGER/J. COLLINS

ROSA

L. CROCKER

EXTERNAL DISTRIBUTION

CONTROL NUMBER

L PDR: CEDAR RAPIDS 1/4

TIC:

NSIC:

ACRS (16) SENT AS CAT. B

780040152

704
GD

D. Lantam

REGULATORY DOCKET FILE COPY

IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER
P. O. Box 351
Cedar Rapids, Iowa 52406

December 22, 1977
DAEC -77 - 650



Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. 77-93
(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours,

Ellery L. Hammond

Ellery L. Hammond
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

ELH/JVS/mg

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

DEC 27 1977

780040152

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 I A D A C 1 2 0 0 0 - 0 0 0 0 0 - 0 0 0 3 4 1 1 1 1 1 1 1 4 5
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
0 1 REPORT SOURCE L 6 0 1 5 0 0 0 3 3 1 7 1 2 1 2 7 7 8 1 2 7 7 9
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 | During Surveillance Testing, RCIC steam line high flow trip settings four
0 3 | d out of specification. PDIS 2441 tripped at 119.5 inches of water and PD
0 4 | IS 2242 tripped at 127 inches of water. Required setpoint 110+/-5 inches
0 5 | of water. Reference TS Table 3.2-B. Repetitive occurrence. See LER 77-052
0 6 | Redundant ECCS operable.
0 7 |
0 8 |

0 9 SYSTEM CODE C E 11 CAUSE CODE E 12 CAUSE SUBCODE B 13 COMPONENT CODE I N S T R U 14 COMP. SUBCODE S 15 VALVE SUBCODE Z 16
7 8 9 10 11 12 13 14 15 16 17 18 19 20
17 LER/RO REPORT NUMBER EVENT YEAR 7 7 21 22 SHUTDOWN METHOD Z 21 HOURS 0 0 0 0 22 ATTACHMENT SUBMITTED Y 23 NRPD-4 FORM SUB. N 24 PRIME COMP. SUPPLIER N 25 COMPONENT MANUFACTURER B 0 8 0 26
10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 | Instrument drift. Barton Model 288 pressure differential indicating switc
1 1 | hes. Switches were recalibrated and functionally tested. Additional corre
1 2 | ctive action may be initiated depending on results of next scheduled sur
1 3 | veillance test. Engineering design review will be initiated.
1 4 |

1 5 FACILITY STATUS E 28 % POWER 0 9 4 29 OTHER STATUS NA 30 METHOD OF DISCOVERY B 31 DISCOVERY DESCRIPTION Surveillance Test 32
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 6 ACTIVITY CONTENT Z 33 Z 34 AMOUNT OF ACTIVITY NA 35 LOCATION OF RELEASE NA 36
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 7 PERSONNEL EXPOSURES NUMBER 0 0 0 37 TYPE Z 38 DESCRIPTION NA 39
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 8 PERSONNEL INJURIES NUMBER 0 0 0 40 DESCRIPTION NA 41
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
1 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z 42 DESCRIPTION NA 43
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50
2 0 ISSUED DESCRIPTION N 44 NA 45
7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32 33 34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50

947-926

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

LICENSEE EVENT REPORT-Supplemental Data

Docket Number 50-331

Licensee Event Report Date: 121277

Reportable Occurrence No: 77-93

Description of Event

During Surveillance testing on December 12 and 13, 1977 the RCIC system steam supply line high flow pressure differential indicating switches were found with their setpoints out of calibration. PDIS 2441 tripped at 119.5 inches H₂O and PDIS 2442 tripped at 127 inches H₂O. The required setpoint is 110 ± 5 inches H₂O listed in Technical Specification table 3.2-B. Redundant emergency core cooling systems were operable.

Cause of Occurrence

The cause of the occurrence is instrument drift. The out of calibration setpoint problem is repetitive. (See RO 77-052) An analysis of trend data indicates that the as-found setpoints are erratic and alternate above and below the required setpoint. The specific cause of the instrument drift is unknown at this time.

Corrective Action

Both instruments were recalibrated and functionally tested. Additional corrective action may be initiated depending on the results of the next scheduled monthly surveillance test. In addition, a design review will be initiated to determine the cause of the problem and verify proper design application.

RECEIVED DOCUMENT
PROCESSING UNIT

1973 JAN 4 AM 7 29