Bon/12/100

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS) DISTRIBUTION FOR INCOMING MATERIAL

50-331

REC: KEPPLER J G NRC

2.00

ORG: HAMMOND E L IA ELEC LIGHT & PWR DOCDATE: 06/30/78 DATE RCVD: 07/10/78

> COPIES RECEIVED LTR 1 ENCL 1

DOCTYPE: LETTER NOTARIZED: NO SUBJECT: FORWARDING LICENSEE EVENT REFT (R0 50-331/78-031) ON 06/17/78 CONCERNING

AUTOMATIC REACTOR SCRAM OCCURRED, DUE TO SEVEN REACTOR PROTECTION SYSTEM RELAY AUXILIARY SWITCHES BECOMING LOOSE ON THE RELAY AND RESULTING IN THE BACK UP SCRAM VALVES BEING ENERGIZED

FLANT NAME: DUANE ARNOLD

REVIEWER INITIAL: XJM DISTRIBUTOR INITIAL:

INCIDENT REPORTS (DISTRIBUTION CODE A002)

FOR ACTION: BR CHIEF ORB#3 BC**W/4 ENCL

INTERNAL:

REG FILE**W/ENCL I & E**W/2 ENCL I & C SYSTEMS BR**W/ENCL NOVAK/CHECK**W/ENCL AD FOR ENG**W/ENCL HANAUER**W/ENCL AD FOR SYS & PROJ**W/ENCL ENGINEERING BR**W/ENCL KREGER/J. COLLINS**W/ENCL K SEYFRIT/IE**W/ENCL

NRC PDR**W/ENCL MIPC**W/3 ENCL EMERGENCY PLAN BR**W/ENCL EEB**W/ENCL PLANT SYSTEMS BR**W/ENCL AD FOR PLANT SYSTEMS**W/ENCL REACTOR SAFETY BR**W/ENCL VOLLMER/BUNCH**W/ENCL POWER SYS BR**W/ENCL

EXTERNAL:

LPDR1S CEDAR RAPIDS, IA**W/ENCL TERA**W/ENCL NSIC**W/ENCL ACRS CAT B**W/16 ENCL

LTR 45 ENCL 45 DISTRIBUTION: SIZE: 1P+1P+1P

CONTROL NBR:

781930033

THE END

78 2031

sr.

<u>...</u>

· IOWA ELECTRIC LIGHT AND POWER COMPANY

DUANE ARNOLD ENERGY CENTER P. O. Box 351 Cedar Rapids, Iowa 52406 June 30, 1978 DAEC - 78 - 325

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission-Region III
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Licensee Event Report No. (14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted)

Very truly yours, Kullon for

Ellery L. Hammond Chief Engineer Duane Arnold Energy Center

Docket 50-331.

attachment

ELH/DLW/nf

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Director, Management Information and Program Control (3) U. S. Nuclear Regulatory Commission Washington, D.C. 20555

781930033

. . .

NRC FORM 366 U. S. NUCLEAR REGULATORY COMMISSION	
CONTROL BLOCK:	
$\begin{array}{ c c c c c }\hline \hline 0 & 1 \\ \hline 1 & 1 $	
CON'T REPORT L 6 0 5 0 0 3 3 1 0 0 6 1 7 8 3 0 6 3 0 7 8 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)	
0 2 [During weekly control valve testing an automatic reactor scram occurred.	I
O I3 Subsequent investigation revealed the scram had occurred due to seven	
I reactor protection system relay auxiliary switches becoming loose on the	
os [relay and resulting in the back up scram valves being energized. The pl	
ole Lant was left in the shutdown condition for repairs. The operation of the	J
I reactor protection system relays was not affected by the problem with	ļ
0 8 7 8	0
$\begin{array}{c cccc} & & & & & & & \\ \hline \textbf{SYSTEM} & & & & & \\ \hline \textbf{CODE} & & & \\ \hline \textbf{SUBCODE} & & & \\ \hline \textbf{SUBCODE} & & & \\ \hline \textbf{SUBCODE} & & \\ \hline \textbf{SUBCODE & & \\ \hline \textbf{SUBCODE} & & \\ \hline \textbf{SUBCODE}$	
$\begin{array}{c c c c c c c c c c c c c c c c c c c $	
ACTION FUTURE EFFECT SHUTDOWN HOURS (22) ATTACHMENT NPRD-4 PRIME COMP. COMPONENT MANUFACTURER $ACTION FUTURE ON PLANT METHOD HOURS (22) ATTACHMENT FORM SUB. SUPPLIER SUPPLIER GOMP. COMPONENT MANUFACTURER B_{33} (3) A_{35} (3) C (2) O (3) C (2) A_{41} (3) A_{42} (4) A_{43} (3) C (4) A_{44} (4) A_{45} (4) A_{44} (4) A_{45} (4) A_{44} (4) A_{45} (4) $	26
10 The cause of the switch problems was traced to the screw which retains t	!
111 Lhe operating arm of the auxiliary switch becoming loose and backing out]
12 This caused misoperation and in one case allowed the arm to fall off. The]
13 [retaining screws and operating arms were reinstalled and tightened. Eng	
ineering evaluation in progress to determine a better screw retaining method.	
$ \begin{array}{c c c c c c c c c c c c c c c c c c c $	
RELEASED OF RELEASE AMOUNT OF ACTIVITY (35) 1 6 Z (33) Z (34) NA LOCATION OF RELEASE (30) PERSONNEL EXPOSURES 44 45 80	· ·
I 7 8 9 PERSONNEL INJURIES 13 13 80	
LOSS OF OR DAMAGE TO FACILITY (1) TYPE DESCRIPTION 7 8 9 10 NA 10 80	
PUBLICITY MRC USE ONLY ISSUED DESCRIPTION 2 0 NA 1	- 92 @
7 8 9 10 68 69 80 NAME OF PREPARER J. Van Sickel PHONE: 319-851-5611	6 P O 011

۲....

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

LICENSEE EVENT REPORT-Supplemental Data Docket Number 050-0331

Licensee Event Report Date: 063078

Reportable Occurrence No: 78-031

Event Description

During weekly control valve testing an automatic reactor scram occurred. Subsequent investigation revealed the scram had occurred due to seven reactor protection system relay auxiliary switches becoming loose on the relay and resulting in the back up scram valves being energized. The plant was left in the shutdown condition for repairs. The operation of the reactor protection system relays was not affected by the problem with the auxiliary switches.

Cause Description

The cause of the switch problems was traced to the screw which retains the operating arm of the auxiliary switch becoming loose and backing out. This caused misoperation and in one case allowed the arm to fall off. The screw as designed is secured by a lock washer whichs mates with a chambered surface which does not provide a good locking surface. The relay is a General Electric Model CR105X.

Corrective Action

The retaining screws and operating arms were reinstalled and tightened. An engineering evaluation is in progress to determine a more reliable screw retaining method.

Page 1 of 1