

DSB

Iowa Electric Light and Power Company

February 20, 1980

DAEC - 80 - 81

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission - Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Licensee Event Report No. 80-002
(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted).

Very truly yours,

Daniel L. Mineck for

Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

DLM/JCZ/n

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

RO/E 4
A-002 5/11

FEB 25 1980

8002250532

60

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ ①

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

① I A D A C 1 ② 0 0 - 0 0 0 0 0 0 - 0 0 ③ 4 1 1 1 1 1 ④ _____ ⑤
7 8 9 14 15 25 26 30 37 CAT 38

CONT
① REPORT SOURCE L ⑥ 0 5 0 0 0 3 3 1 ⑦ 0 2 0 6 8 0 ⑧ 0 2 2 0 8 0 ⑨
7 8 50 61 68 69 74 75 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

② With the CO-2 system tagged out to permit maintenance in the cable spread
③ ding room, site security shift supervision removed fire watch personnel
④ from the area without notifying the shift supervising engineer. The room
⑤ door was locked with no personnel inside when the fire watch was secured
⑥ . The cable spreading room was left unattended with the CO-2 system inop
⑦ for approximately six hours thus violating T.S.3.13.D.b. No similar
⑧ reports have been made.
7 8 9

⑨ SYSTEM CODE A B ⑪ CAUSE CODE A ⑫ CAUSE SUBCODE F ⑬ COMPONENT CODE Z Z Z Z Z Z ⑭ COMP. SUBCODE Z ⑮ VALVE SUBCODE Z ⑯
9 10 11 12 13 18 19 20
⑰ LER/RO REPORT NUMBER 8 0 ⑱ EVENT YEAR 8 0 ⑲ SEQUENTIAL REPORT NO. 0 0 2 ⑳ OCCURRENCE CODE 0 1 ㉑ REPORT TYPE T ㉒ REVISION NO. 0
21 22 23 24 28 27 28 29 30 31 32
⑳ ACTION TAKEN H ⑳ FUTURE ACTION Z ㉑ EFFECT ON PLANT Z ㉒ SHUTDOWN METHOD Z ㉓ HOURS 0 0 0 0 ㉔ ATTACHMENT SUBMITTED Y ㉕ NPRO-4 FORM SUB. N ㉖ PRIME COMP. SUPPLIER Z ㉗ COMPONENT MANUFACTURER Z 9 9 9 9
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ⑳

⑩ Personnel error. Security shift supervision removed fire watch personnel
⑪ from post without notifying the shift supervising engineer. The CO-2 sys
⑫ tem was immediately returned to service when situation was recognized.
⑬ The persons involved have been reinstructed to adhere to T.S. requiremen
⑭ ts and associated surveillance procedures pertaining to fire watches.
7 8 9

⑮ FACILITY STATUS E ⑰ % POWER 0 7 8 ⑱ OTHER STATUS NA ⑳ METHOD OF DISCOVERY Z ㉑ DISCOVERY DESCRIPTION Operator Observation ㉒
7 8 9 10 12 13 44 45 46 80
⑮ ACTIVITY CONTENT Z ⑰ RELEASED OF RELEASE Z ⑱ AMOUNT OF ACTIVITY NA ㉑ LOCATION OF RELEASE NA ㉒
7 8 9 10 11 44 45 80

⑮ PERSONNEL EXPOSURES NUMBER 0 0 0 ⑰ TYPE Z ⑱ DESCRIPTION NA ㉑
7 8 9 11 12 13 80

⑮ PERSONNEL INJURIES NUMBER 0 0 0 ⑰ DESCRIPTION NA ㉑
7 8 9 11 12 80

⑮ LOSS OF OR DAMAGE TO FACILITY TYPE Z ⑰ DESCRIPTION NA ㉑
7 8 9 11 12 80

⑮ PUBLICITY ISSUED DESCRIPTION NA ㉑
7 8 9 10 80

NAME OF PREPARER J. C. Zimmerman

PHONE: 319-851-5611
NRC USE ONLY

800 22 50 532

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

LICENSEE EVENT REPORT-Supplemental Data

Docket No. 050-0331

Licensee Event Report Date: 022080

Reportable Occurrence No: 80-002

Event Description:

At 0715 on February 6, 1980 the CO₂ System for the electrical cable spreading room was tagged out of service to permit maintenance in the room. A fire watch was established at that time per T.S.3.13.D.2.b. At approximately 0950, the fire watch was secured by Security Shift Supervision when maintenance personnel did not show up (no access to the spreading room had been made during the fire watch): This was done without notifying the Shift Supervising Engineer. As a result the cable spreading room was left unattended with the CO₂ system inoperable.

Cause Description:

Personnel Error.

Corrective Action:

At 1600 on February 6, 1980 the situation was recognized by operations, and the CO₂ system immediately restored to operability. The personnel involved have been reinstructed to adhere to the Technical Specification requirements and associated surveillance procedures pertaining to fire watches. No further corrective action is planned at this time.

Iowa Electric Light and Power Company

February 20, 1980

DAEC - 80 - 81

Mr. James G. Keppler, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission - Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Licensee Event Report No. 80-002
(14 day)

File: A-118a

Dear Mr. Keppler:

In accordance with Appendix A to Operating License DPR-49, Technical Specifications and Bases for Duane Arnold Energy Center and Regulatory Guide 10.1, please find attached a copy of the subject Licensee Event Report. (Total of 3 copies transmitted).

Very truly yours,

Daniel L. Mineck
Chief Engineer
Duane Arnold Energy Center

Docket 50-331

attachment

DLM/JCZ/n

cc: Director, Office of Inspection and Enforcement (40)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

Director, Management Information and Program Control (3)
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

*1002
3/11*

8002250532