DUANE ARNOLD ENERGY CENTER

UNIT #1 PALO, IOWA

Commercial Service Date: February 1, 1975

INSERVICE INSPECTION REPORT

November 1, 1985 through June 29,1987


Date: October 26, 1987

**OWNER:** 

Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa

Prepared by: Engineer, NDE/Metallurgical Reviewed by: <u>Ronald C. Montarnen</u> ASME Section XI Administrator <u>fills</u> Engineer Concurred by: sina Super , Systems Approved by: Egineering anager, Design

Date: <u>10/26/8</u>7 Date: <u>10/26/87</u> Date: <u>10/26/87</u> Date: <u>10/26/87</u>



---

# TABLE OF CONTENTS

PART	DESCRIPTION	PAGE NO.
T of C	Table of Contents	i - iii
Part A	Form NIS-1	A, 1-2
Part B	Listing of Components Examined	B, 1-14
Part C	Abstract	C, 1
Part D	Abstract of Conditions Noted and Corrective Measures Taken	D, 1-24
Part E	Table of Component and Weld Examination Identification Records	E, 1-46
Par <b>t</b> F	ISI Figures and ISO's (as listed below)	F, 1-60
	Class 1 ISI FIGURES	
Page No.	Reactor Pressure Vessel	ISI Figure No.
F-1 F-2	Top Head Welds Circumferential Seam Welds	1.1-2
F-3	Vessel Nozzle Location	1.1-3 1.1-6
	<u>Class 1 ISI ISO's</u>	
<u>Page No.</u>	System	ISI ISO No.
F-4 F-5	Main Steam Loop "A" (MSA) Main Steam Loop "B" (MSB)	1.2-1 1.2-2
F-6 F-7	Main Steam Loop "C" (MSC) Main Steam Loop "D" (MSD)	1.2-3
F-8	Feedwater Loops "A" and "B" (FWA, FWB) •	1.2-4 1.2-5
<b>F-9</b> F-10	Feedwater Loops "C" and "D" (FWC, FWD). Core Spray Loop "A" (CSA)	1. <b>2-6</b> 1.2 <b>-</b> 7
F-11 F-12	Core Spray Loop "B" (CSB) High Pressure Coolant Injection-Steam (PSA)	1.2-8 1.2-9
F-13 F-14	High Pressure Coolant Injection-Water (PSB)	1.2.10
• <b>1</b> .1	Reactor Water Cleanup - Suction (CUA)	1.2.11-A

# TABLE OF CONTENTS

# Class 1 ISI ISO's (Continuation)

Page No.	System	ISI ISO No.
F-15	Reactor Water Cleanup - Discharge (CUB)	1.2-11-B
F-16	Control Rod Drive Return (CRA)	1.2-12-A
F-17	Residual Heat Removal - Headspray (RHA)	1.2-13
F-18	Residual Heat Removal - 18B (RHB)	1.2-14
F-19	Residual Heat Removal - 20A (RHC)	1. <b>2-1</b> 5
F-20	Residual Heat Removal - 20B (RHD)	1.2-16
F-21	Reactor Core Isolation Cooling - Steam (RSA)	1.2-17
F-22	Reactor Core Isolation Cooling - Water (RS8)	1.2-18
F-23	Recirculation Pump "A" and Discharge Valve	
	Bypass (RCA) (RBA)	1.2-19
F-24	Recirculation Pump "A" Supports (Figure)	1.3-2
F-25	Recirculation Manifold "A" and Risers	
	E, F, G, H (RMA, RRE, RRF, RRG and RRH)	1.2-20
F-26	Recirculation Pump "B" and Discharge	
	Valve Bypass (RCB, RBB)	1.2-21
F-27	Recirculation Manifold "B" and Risers	
	A, B, C and D (RMB, RRA, RRB, RRC and RRD)	1.2-22
F-28	Head Vent (HVA)	1.2-24
F-29	Jet Pump Instrumentation "A" (JPA)	1.2-25
F-30	Jet Pump Instrumentation "B" (JPB)	1.2-26
F-31	Liquid Level Control (LCA)	1.2-27
F-32	Vessel Instrumentation N16A (VIE)	1.2-33
F-33	Main Steam Drain - Common (SDR)	1.2-36

# Class 2 ISI ISO's

Page No.	System	ISI ISO No.
F-34	RHR-Heat Exchanger (HEA) (Figure)	2.1-1
F-35	RHR-Pump Suction (S.E.) (RHA)	2.2-32
F-36	RHR-Pump Suction (N.W.) (RHB)	2.2-33
F-37	RHR-Pump Shutdown (RHC)	2.2-34
F-38	RHR-Heat Exchanger Steam Supply . (S.E./N.W.) (RHD)	2.2-35
F-39	RHR-Pump Discharge (S.E.) (RHE)	2.2-36
F-40	RHR-Heat Exchanger Discharge (S.E.) (RHF)	2.2-37
F-41	RHR-Pump Discharge (N.W.) (RHI)	2.2-39
F-42	RHR-Heat Exchanger Discharge (RHJ)	2.2-40

. . . . . . . . . . . .

-

# TABLE OF CONTENTS

# <u>Class 2 ISI ISO's (Continuation)</u>

Page No.	System	ISI ISO No.
F-43 F-44 F-45 F-46 F-47 F-48	RHR Fuel Pool Cooling and Cleanup (RHM) HPCI-Pump Suction (HPA) HPCI-Pump Discharge (HPB) HPCI Pump Discharge (HPB)-MO-2315 Replacement HPCI-Turbine Steam Inlet (HPC) Core Spray Suction (S.E.) (CSA)	2.2-43 2.2-44 2.2-45 2.2-46 2.2-48
F-49 F-50 F-51 F-52 F-53 F-54 F-55	Core Spray Discharge (S.E.) (CSR) Core Spray Discharge (S.E.) (Cont.) (CSC) Core Spray Suction (N.W.) (CSD) Core Spray Discharge (N.W.) (CSE) Main Steam Loop "A" (MSA) Main Steam Loop "B" (MSB) Main Steam Loop "C" (MSC)	2.2-49 2.2-50 2.2-51 2.2-52 2.2-53 2.2-54
F-56 F-57 F-58 F-59 F-60	Main Steam Loop "D" (MSC) Main Steam Bypass (MSE) Main Steam Bypass (MSF) Scram Discharge Header - South (SDS) Scram Discharge Header - North (SDN)	2.2-55 2.2-56 2.2-57 2.2-58 2.2-60 2.2-61

\_\_\_\_\_

-----

;

- -

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Reactor Pressure Vessel

Manufacturer: Chicago Bridge and Iron Post Office Box 13308 Memphis, TN 38113

National Board Number 3663, MFG. Serial Number 3-4833

-----

Refer to Part A, pages 1 and 2, Form NIS-1, Owners Data Report for Inservice Inspections.

:

Part A (Refer to 7 Below for List of Total Pages)

Page 1 of 2

# FORM NIS-1 OWNERS' DATA REPORT FOR INSERVICE INSPECTIONS

# As required by the Provisions of the ASME Code Rules

1. Owner <u>Iowa Electric Light and Power Company, Cedar Rapids, Iowa</u> (Name and Address of Owner)

2. Plant \_\_\_\_ Duane Arnold Energy Center, Palo, Iowa \_\_\_\_\_ (Name and Address of Plant)

3. Plant Unit <u>Humber 1</u> 4. Owner Certificate of Authorization (if required) <u>N/A</u>

5. Commercial Service Date <u>02-01-75</u> 6. National Board Number for Unit <u>N/A</u>

7. Components Inspected (pp. 1-2), Part B (pp. 1-14), Part C (p. 1), Part D (pp. 1-24), Part E (pp. 1-46) and Part F (pp. 1-60)

Component or Appurtenance	Manufacturer or Installer	Manufacturer or Installer Serial No.	State or Province No.	National Board No.
Reactor Pres- sure Vessel	Chicago Bridge and Iron	3-4833	35059	3663
Vessel Top Head Welds	U	11	14	11
<u>HCC-B2</u>	н	11	11	14
HCC-C1	в	18	n	11
HMC-B2	н	14	16	11
Vessel Circ Seam Welds	11	11	H N	11
VCB-C5	н	11	11	Ð
Vessel Nozzle Welds	и	11	11	11
HVA-BD-1	· II	15	11	n
RHA-BD-1	ê1	11	11	11
MSA-BD-1	11	11	11	11
FWA-BD-1	11		11	11
VIC-BE-1	н	11	iı	11
RRE-BD-1	II	11	11	11
RRF-BD-1	ıl	11	11	11
RRC-BD-1	и	41	11	н

Note: Supplemental sheets in form of lists, sketches, or drawings may be used provided (1) size is  $8\frac{1}{2}$  in. x 11 in., (2) information in items 1 through 6 on this data report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.

8. Examination Dates <u>11-01-85</u> to <u>06-29-87</u> 9. Inspection Interval from <u>11-01-85</u> to <u>11-01-95</u>

10. Abstract of Examinations. Include a list of examinations and a statement concerning status of work required for current interval.

11. Abstract of Conditions Noted

12. Abstract of Corrective Measures Recommended and Taken

We certify that the statements made in this report are correct and the examinations and corrective measures taken conform to the rules of the ASME Code, Section XI.

Iowa Electric Light Date October 26 1987 Signed and Power Company By Owner Manager, Nuclear Division

Certificate of Authorization No. (if applicable) \_\_\_\_\_N/A \_\_\_\_\_Expiration Date \_\_\_\_\_N/A

#### CERTIFICATE OF INSERVICE INSPECTION

1, the undersigned, holding a valid commission issued by the National Board of Boiler and Bressure Vessel Inspectors and/or the State or Province of 10Wa and employed by Casual ty Company of Long Grove, IL have inspected the components described in this Owners' Data Report during the period 11-01-85 to 06-29-87, and state that to the best of my knowledge and belief, the Owner has performed examinations and taken corrective measures described in this Owners' Data Report in accordance with the requirements of the ASME Code, Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations and corrective measures described in this Owners' Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

27 19 87 Date October \_\_\_\_\_Commissions National Board 5813(I)(N), IA1041 National Board, State, Province and No. ector's Signature

Part A (Refer to 7 Below for List of Total Pages)

Page 2 of 2

### FORM NIS-1 OWNERS' DATA REPORT FOR INSERVICE INSPECTIONS

#### As required by the Provisions of the ASME Code Rules

1. Owne	r Iowa	Electric	Light	and	Power	Company,	Cedar	Rapids,	Iowa	
(Name and Address of Owner)										

2. Plant \_\_\_\_\_ Duane Arnold Energy Center, Palo, Iowa (Name and Address of Plant)

3. Plant Unit Number 1 4. Owner Certificate of Authorization (if required) N/A

5. Commercial Service Date 02-01-75 6. National Board Number for Unit <u>N/A</u>

7. Components Inspected

This report includes a Table of Contents (pp. i-iii), Part A (pp. 1-2), Part B (pp. 1-14), Part C (p. 1), Part D (pp. 1-24), Part E (pp. 1-46) and Part F (pp. 1-60)

•	componenta	mspected	- N
			0

Component or Appurtenance	Manufacturer or Installer	Manufacturer or Installer Serial No.	State or Province No.	National Board No.
RRD-BD-1	Chicago Bridge and Iron	3-4833	35059	3663
RCA-BD-1	ji ji	16	"	н
Vessel Nozzle Inside Radius	11		11	H
HVA-N7	U	11	11	lŧ
RHA-N6-A	14	11	ti .	11
MSA-N3-A	11		11	11
FWA-N4-A	Ш	11	11	11
VIC-N12-A	н		41	11
RRE-N2-E	IJ		11	11
RRF-N2-F	11	IJ	11	11
RRC-N2-C	11	IL	11	' 11
<u>RRD-N2-D</u>	lt	. 11	n	11
RCA-N1-A	15	18	11	11
(Refer to	Part B, Pages 1 through 1	4, of this re	port for	
continuat	ion of components examine	d)		

Note: Supplemental sheets in form of lists, sketches, or drawings may be used provided (1) size is  $8\frac{1}{2}$  in. x 11 in., (2) information in items 1 through 6 on this data report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.

8. Examination Dates <u>11-01-85</u> to <u>06-29-87</u> 9. Inspection Interval from <u>11-01-85</u> to <u>11-01-95</u>

10. Abstract of Examinations. Include a list of examinations and a statement concerning status of work required for current interval.

11. Abstract of Conditions Noted

12. Abstract of Corrective Measures Recommended and Taken

We certify that the statements made in this report are correct and the examinations and corrective measures taken conform to the rules of the ASME Code, Section XI.

Iowa Electric Light Date Cr 19 87 Signed and Power Company Βv Owner Manager, Nuclear Division N/A Expiration Date <u>N/A</u> Certificate of Authorization No. (if applicable)

# CERTIFICATE OF INSERVICE INSPECTION

1, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of 10Wa and employed by Casual ty Company of Long Grove, IL have inspected the components described in this Owners' Data Report during the period 11-01-85 to 06-29-87, and state that to the best of my knowledge and belief, the Owner has performed examinations and taken corrective measures described in this Owners' Data Report in accordance with the requirements of the ASME Code, Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations and corrective measures described in this Owners' Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

27 19 87 Date OC

 Inspector's Signarure
 Commissions
 National Board 5813(I)(N), IA1041

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit #1 4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

# CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Reactor Pressure Vessel

Manufacturer: Chicago Bridge and Iron Post Office Box 13308 Memphis, TN 38113

National Board Number 3663, MFG. Serial Number 3-4833

Refer to Part A, pages 1 and 2, Form NIS-1, Owners Data Report for Inservice Inspections.

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit #1\_\_\_\_4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u>

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED: Piping

Manufacturers, sizes, part numbers and locations are noted and traceable through the piping isometric and piping instrumentation drawings (P&ID). Installation contractor, fabricator, systems P&ID's and isometric drawings are listed below. Welds and components are examined as noted on the numbered ISO sketches as identified under each system.

Constructor - Bechtel Power Co. P.O. Box 3865 San Francisco, CA 94119

Fabricator - Southwest Fabricating and Welding Co. P.O. Box 9449 Houston, TX 77011

<u>Class 1 Components</u> Main Steam Loops A, B, C and D

P&ID M-103 GE Drawing 731E615 FSO No's 1.2-1, 1.2-2, 1.2-3, and 1.2-4

P&ID M-106, M-107 Bechtel ISO DLA-2-4 ISO No. 1.2-5

Feedwater A and B

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406
 Central Iowa Power Cooperative Marion, Iowa

> Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u> 5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u> GROSS GENERATING CAPACITY: <u>565 MWE</u>

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Feedwater C and D

Core Spray A and B

-----

P&ID M-106, M-107 Bechtel ISO DLA-2-4 ISO No. 1.2-6

P&ID M-122 Bechtel Drawings DLA-7-1 and DLA-7-2 ISO No's. 1.2-7 and 1.2-8

High Pressure Coolant Injection - Steam P&ID M-122 Bechtel Drawing DBA-3-1 ISO 1.2-9

High Pressure Coolant Injection - Water P&ID M-123 Bechtel Drawing DLA-1-1 ISO No. 1.2-10

Reactor Water Clean-Up - Suction

P&ID M-127 Bechtel Drawing DCA-6-1 ISO No. 1.2-11-A  Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u>

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Reactor Water Clean-Up - Discharge

Control Rod Drive Return

**RHR-Headspray** 

Residual Heat Removal - 18B

P&ID M-127 Bechtel Drawing DCA-14-1 ISO No. 1.2-11B

P&ID M-117 Bechtel Drawing DBA-6-1 ISO No. 1.2-12A

P&ID M-119 Bechtel Drawing DBA-5-1 ISO No. 1.2-13

P&ID M-119 Bechtel Drawing DCA-4-1 ISO No. 1.2-14

. . . . . . . . . . . . . . . .

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u> 5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u> GROSS GENERATING CAPACITY: <u>565 MWE</u>

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Residual Heat Removal-20A P&ID M-120 Bechtel Drawing DCA-5-1 ISO No. 1.2-15 P&ID M-119 Residual Heat Removal - 20B Bechtel Drawing DLA-6-1 ISO No. 1.2-16 Reactor Core Isolation Cooling - Steam P&ID M-124 Bechtel Drawing DBA-4-1 ISO No. 1.2-17 P&ID M-125 Reactor Core Isolation Cooling - Water Bechtel Drawing DBA-7-1 ISO No. 1.2-18

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit #1 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

# CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Recirculation Pump A and Bypass

P&ID M-116 GE Drawing 731E781 APED B31-9-(1)-6 ISO No. 1.2-19

1

Recirculation Manifold A and Risers E, F, G, and H

Recirculation Pump B and Bypass

Recirculation Manifold B and Risers A, B, C and D

-----

P&ID M-116 GE Drawing 731E781 APED B31-9-(1)-6 ISO No. 1.2-20

P&ID M-116 GE Drawing 731E781 APED B31-9-(1)-6 ISO No. 1.2-21

P&ID M-116 GE Drawing 731E781 APED B31-9-(1)-6 ISO No. 1.2-22

------

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Head Vent

Jet Pump Instrumentation A

Jet Pump Instrumentation B

Liquid Level Control

Vessel Instrumentation N16A

P&ID M-114 APED B11-2655-104-3 ISO No. 1.2-24

P&ID M-115 APED B11-2655-105-4 ISO No. 1.2-25

P&ID M-115 APED B11-2655-105-4 ISO No. 1.2-26

P&ID M-126 Bechtel Drawing FSK 3734 and FSK-3992 ISO No. 1.2-27

-----

-----

-----

P&ID M-115 Bechtel Drawing FSK-5555 ISO No. 1.2-33

- a case of second-sector and a

------

Part B, Page 8 of 14

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit #1 4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

# CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Main Steam Drain-Common

P&ID M-114 Bechtel Drawing DBA-2-1 ISO No. 1.2-35

# Class 2

RHR Pump Suction (S.E.)

P&ID M-120 Bechtel Drawing M-712 ISO No. 2.2-32

:

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u> 5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u> GROSS GENERATING CAPACITY: <u>565 MWE</u>

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

-----

··· ·· - ····· -----

### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

RHR Pump Suction (N.W.)

RHR Pump Shutdown

RHR Heat Exchanger Steam Supply (S.E./N.W.)

RHR Pump Suction (S.E.)

P&ID M-119 Bechtel Drawing M-713 ISO No. 2.2-33

P&ID M-119 and M-120 Bechtel Drawing M-719 ISO No. 2.2-34

P&ID M-119, M-120 and M-122 Bechtel Drawing M-723 ISO No. 2.2-35

-----

P&ID M-120. Bechtel Drawing M-714 ISO No. 2.2-36

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

## CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

RHR Heat Exchanger Discharge (S.E.)

RHR Pump Discharge (N.W.)

. \_ \_ . \_ .

RHR Heat Exchanger Discharge (N.W.)

RHR Fuel Pool Cooling and Cleanup

P&ID M-120 Bechtel Drawing M-720 ISO No. 2.2-37

P&ID M-119 Bechtel Drawing M-115 ISO No. 2.2-39

P&ID M-119 Bechtel Drawing M-721 ISO No. 2.2-40

P&ID M-119 and M-134 Bechtel Drawing HBB-24-2, 3, 4 and 5 ISO No. 2.2-43

....

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

**HPCI** Pump Suction

HPCI Pump Discharge

-----

-----

----

HPCI Turbine Steam Inlet

HPCI Turbine Steam Exhaust

P&ID M-123 Bechtel Drawing M-700 ISO No. 2.2-44

P&ID M-123 Bechtel Drawing M-701 ISO No. 2.2-45

P&ID M-122 Bechtel Drawing M-702 ISO No. 2.2-46

P&ID M-122 Bechtel Drawing M-703 ISO No. 2.2-47

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

Marion, Iowa

Central Iowa Power Cooperative

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) N/A

5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u>

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

# CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Core Spray Suction (S.E.)

P&ID M-121 Bechtel Drawing M-708 ISO No. 2.2-48

Bechtel Drawing M-710

P&ID M-121

ISO No. 2.2-49

Core Spray Discharge (S.E.)

Core Spray Discharge (S.E.)(Cont.)

Core Spray Suction (N.W.)

P&ID M-119 Bechtel Drawing M-710 ISO No. 2.2-50

P&ID M-121 Bechtel Drawing M-709 ISO No. 2.2-51

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

GROSS GENERATING CAPACITY: 565 MWE

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

# CERTIFICATE OF INSERVICE INSPECTION

-----

COMPONENTS EXAMINED:

Core Spray Discharge (N.W.)

Main Steam Loop A

Main Steam Loop B

Main Steam Loop C

Ň

P&ID M-121 Bechtel Drawing M-711 ISO No. 2.2-52

P&ID M-103 Bechtel Drawing M-716 ISO No. 2.2-53

P&ID M-103 Bechtel Drawing M-716 ISO No. 2.2-54

P&ID M-103 Bechtel Drawing M-716 ISO No. 2.2-55

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

2) Plant Duane Arnold Energy Center, Palo, Iowa

3) Plant Unit <u>#1</u> 4) Owners Certificate of Authorization (if required) <u>N/A</u> 5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u> GROSS GENERATING CAPACITY: <u>565 MWE</u>

NUMBER ASSIGNED TO COMPONENTS BY STATE (See Page 1)

#### CERTIFICATE OF INSERVICE INSPECTION

COMPONENTS EXAMINED:

Main Steam Loop D

Main Steam Bypass

Main Steam Bypass

Scram Discharge Header - South

Scram Discharge Header - North

P&ID M-103 Bechtel Drawing M-716 ISO No. 2.2-56

i.

P&ID M-103 Bechtel Drawing EBD-6-1 and EBD-6-2 ISO No. 2.2-57

P&ID M-103 Bechtel Drawing EBD-6-3 ISO No. 2.2-58

P&ID M-118 ISO No. 2.2-60

P&ID M-118 ISO No. 1.2-61

-----

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406
 Central Iowa Power Cooperative Marion, Iowa
 Corn Belt Power Cooperative

2) Plant Duane Arnold Energy Center, Palo, Iowa

Humboldt, Iowa

3) Plant Unit #1 4) Owners Certificate of Authorization (if required) <u>N/A</u>

5) Commercial Service Date <u>2-1-75</u> 6) National Board Number of Unit <u>N/A</u>

#### Abstract:

The Inservice Inspection covered in this report was performed in accordance with the American Society of Mechanical Engineers Boiler and Pressure Vessel Code, Section XI 1980 Edition through Winter 1981 Addenda, and the Duane Arnold Energy Center Updated Final Safety Analysis Report. The examinations were performed utilizing ultrasonic, magnetic particle, visual, liquid penetrant and radiographic techniques. The examinations were conducted during the period of November 1, 1985 thru June 29, 1987. The specific details and associated records of the examinations are on file at Iowa Electric Light and Power Company.

 Owners: Iowa Electric Light and Power Company P.O. Box 351 Cedar Rapids, Iowa 52406

> Central Iowa Power Cooperative Marion, Iowa

Corn Belt Power Cooperative Humboldt, Iowa

- 2) Plant Duane Arnold Energy Center, Palo, Iowa
- 3) Plant Unit #1 4) Owners Certificate of Authorization (if required) N/A
- 5) Commercial Service Date 2-1-75 6) National Board Number of Unit N/A

#### Abstract of Conditions Noted and Corrective Measures Taken:

During 1986 and 1987, Iowa Electric examined 161 Class 1 and 2 Component Supports (49 Class 1 and 112 Class 2) located within the ISI boundaries. Sixteen (16) Class 1 and twenty-one (21) Class 2 Component Supports were unacceptable in the as-found condition.

In accordance with the requirements of ASME Section XI, 1980 Edition through and including the Winter 1981 Addenda, IWF-2430, an additional 31 Component Supports were scheduled for examination as an additional sample.

All Component Support discrepancies were resolved previous to startup.

Class 1 Recirculation Piping Weld Overlay Surface Conditioning (DCP-1389)

During the 1987 Refueling Outage, DCP-1389 was generated to condition the surface of eight (8) of the nine (9) full structural weld overlay repairs and to perform weld buildup repairs on weld overlays RRA-BJ-4/J4A and RRF-BJ-4/J4A, 10-inch diameter Recirculation Inlet Risers. Surface conditioning was required to ensure conformance with EPRI NP-4720-LD, "Examination of Weld-Over Layed Pipe Joints" dated October 1986 and NUREG-0313, Revision 2, "Technical Report on Material Selection and Processing Guidelines for BWR Coolant Pressure Boundary Piping -Draft Report" dated June 1986.

All nine (9) full structural overlays were examined by Ultrasonic and Liquid Penetrant methods in accordance with the requirements of NUREG-0313, Revision 2 and EPRI NP-4720-LD. Results of the examinations were acceptable. (Ref. Class 1 ISI Isometrics 1.2-14, 1.2-20 and 1.2-22 for locations of weld overlay repairs).

. . . . . . . . . . .

Class 2 HPCI Valve MO-2315 Repair (CMAR 72961)

During 1986, MO-2315 (the 8-inch diameter HPCI Pump Bypass Valve to the Condensate Storage Tanks) failed to perform its flow control function while being used during a system test. The valve was disassembled for inspection and maintenance. The inspection noted conditions in the valve as follows:

broken stem and broken tack welds (stem to stem nut) deformed disc and disc guides internal corrosion ID wear on the bonnet 4-inch long horizontal crack on the seat ring

The stem, stem nut and disc were replaced and the corrosion was removed from the internal surfaces of the valve. A liquid penetrant examination (ISI 86-029) of the internal surfaces of the valve and a UT for thickness of the valve body followed repair. The VT-2 pressure test (ISI 86-028) was acceptable.

Class 2 HPCI Valve MO-2315 Replacement (DCP-1331-A) (CMAR 73048) (CMAR 75471)

Subsequent to the repair performed on CMAR 72961, MO-2315 (the 8-inch diameter HPCI Pump Bypass Valve to the Condensate Storage Tank) was replaced with a control valve due to the conditions noted during the CMAR 72961 repair work. Replacement of MO-2315 included the removal of 2 welds, 1 flow orifice, (FO-2314) the re-design of 2 supports and the re-routing of the Fuel Pool Return Line due to interference with the actuator of the new valve (CV-2315). The 2 new welds were preservice examined by radiographic, ultrasonic and liquid penetrant methods. The examinations were acceptable.

The Flow Orifice (FO-2314) and flange, and flange bolting were replaced with a new spectacle flange/blind flange and new flange bolting. An in-shop hydrostatic test was performed on the flange. After installation into the system, a functional test was performed on the spectacle flange, 2 new welds and CV-2315. Functional and hydrostatic tests were performed in accordance with ASME Section XI, 1980 Edition through and including the Winter 1981 Addenda. Results of the hydrostatic and functional tests were acceptable.

-----

Class 2 Component Supports

Scram Discharge Header Component Support Modification (FCN-1323, Seq. 5, 7 & 8)

Scram Discharge Header Component Supports H-1 (ISI VT Report 87-383), H-3 (ISI Report 87-384), H-14 (ISI VT Report 87-388) and H-16 (ISI VT Report 87-389) were visually examined during the 1987 Refueling Outage and were found to be deficient with regard to the as-built configuration not being in accordance with the documents used for examination.

A Design Engineering review determined that all 12 Component Supports on the 8-inch diameter portion of the lines were inadequately constructed and proceeded to upgrade the 12 Supports by modification.

The Supports modified are as follows:

Scram Discharge Header (South)

H-1	Preservice	ISI	٧T	Report	87-694
H-2	"	It	н	ii ii	87-695
H-3	II	It	ч	н	87-696
H-4	IL	It	11	It	87-697
H-5	u	11	н	11	87-698
H-6	11	31	н	11	87-699

Scram Discharge Header (North)

. . .

H-14	Preservice	ISI	VT	Report	87-700
H-15	11	11	11	16	87-701
H-16	н	11	11	16	87-702
H-17	6	31	U	It	87-703
H-18	Ц	u	11	16	87-704
H-19	18	11	H	88	87-705

Further, H-22 (Preservice ISI VT Report 87-706) and H-23 (Preservice ISI VT Report 87-707) were added to the Scram Discharge Header (South and North, respectively) lines. The above supports (excluding H-22 and H-23) utilized full and half pipe clamps welded to plates to transfer the pipe loads to the supporting steel. This design was initially evaluated as insufficient for the loads calculated for earthquake conditions. Reverification of original design conservatisms and installed configuration demonstrated the Scram Discharge Headers' design would have performed their pressure boundary function in a seismic event.

# Class 2 Component Supports Modified Due To DCP-1323/FCN-1323

Under IEB-79-14, deadweight, thermal, and seismic loads at some large bore supports were recalculated to incorporate as-built data. The reanalyses provided more accurate load information at the large bore seismic supports.

The reanalyses determined the existing design was adequate for operation under the new load data, but some supports required modification to restore recommended factors of safety. The required modifications were performed under DCP-1323 and FCN-1323, Sequence 1, 2, 3, 4 and 6.

The component supports modified in accordance with DCP-1323 and FCN-1323. Sequence 1, 2, 3, 4 and 6 are as follows:

SUPPORT NO.	ISI IDENT.	ISI REPORT	COMMENT
EBB-16-H-24	RHD-CE-13A	87-604	
EBB-16-H-25	RHD-CE-12	87-605	
GBB-5-H-19	RHF-CE-118	87-677	
GBB-13-SR-14	CSB-CE-17	87-602	
GBB-14-SR-22	CSE-CE-50	87-603	
HBB-23-H-15	RHB-CE-51	87-606	
HBB-23-H-16	RHB-CE-44	87-600	
HBB-24-H-5	RHC-CE-60	87-599	
HBB-24-H-6-1	RHC-CE-42	87-598	CMAR 83295
HBB-25-SA-179	RHM-CE-21	87-601	CMAR 80252

Component Support EBB-16-H-21 was removed by DCP-1323 and not replaced.

Class 1 RHR Headspray Modification (DCP-1385)

During the 1987 Refueling Outage, Design Change Package 1385 was generated to decommission and remove portions of the Class 1 RHR Headspray System, (Ref. Class 1 ISI Isometric 1.2-13).

The portion of the RHR Headspray System which was removed is from the 6-inch diameter flange located just beyond the Reactor Pressure Vessel to the 4-inch diameter flange at the well seal. Both the 4-inch and 6-inch diameter flanges have been blanked. RHR Headspray Reactor Pressure Vessel Nozzle "N6-A" becomes a Reactor Coolant Pressure Boundary per 10CFR50.55 and will remain in the ISI program. Pitting was found on the bottom face of the groove in the RHR Headspray Flange (6"-DBA-5). This was repaired by machining 0.040 inch from the groove and flange mating surface to remove the pitting in accordance with CMAR 75489A. The ASME Class 1 leakage test with VT-2 exam (ISI 87-692) was acceptable.

---- ---- ---

The portion of the RHR Headspray System which has been decommissioned is from the 4-inch diameter flange to valve MO-1901. Valves MO-1900 and MO-1901 have subsequently been locked in the closed position at the hand wheel.

Class 1 Component Support - DBA-1-SS-16A Removal (DCP-1341)

DCP-1341 was initiated to improve cooling in the drywell and steam tunnel. The work included, in part, installation of additional cooling units. This installation required permanent removal of interfering snubber 16-A on the 2 inch Reactor Vessel Vent Line DBA-1. Revision of the Class 1 stress report verified adequacy of the remaining supporting system.

Class 1 Component Support - DBA-1-PS-1 Modification (FCN-1341, Sequence 5)

Installation of the additional cooling units in accordance with DCP-1341 required modification of one of the PS-1, Detail C supports on the 2 inch Reactor Vessel Vent Line DBA-1 due to interference with cooling unit 1V-CC-7B. The modification included trimming of an angle brace and welded attachment of a 4" x 4" section of tube steel for reinforcement. (Refer to ISI 87-712)

Class 1 Component Support MSA-HA-1 (ISI I.D. MSA-BK-8) ISI Visual Report 87-026 and ISI Magnetic Particle Report 87-027 (CMAR 82489)

- The bill of material from the design drawing did not correspond to the asbuilt condition as spacers were welded to the inner frame of the restraint.
- The discrepancy was evaluated as acceptable as the spacers were determined to be part of the adjacent pipe rupture restraint.
- One linear indication approximately 1/2 inch long was detected by Magnetic Particle examination on one of four lug attachment welds.
- The linear indication was removed by grinding and re-examined (ISI Magnetic Particle Report 87-644. Component Support MSD-HD-1 was selected as an additional examination.

Class 1 Component Support MS-2-14 (ISI I.D. MSB-BK-40) ISI Visual Report 87-049 (CMAR 82492)

- Two of four anchor bolt nuts were found to be loose.
- The loose anchor bolt nuts were re-torqued in accordance with AISC, 8th edition, Para. 5-216.6 and were found to be acceptable after reexamination.
   Supports DBA-1-H-25 (ISI Visual Report 87-687) and DBA-1-HB-2 (ISI Visual Report 87-688) were selected as additional examinations.

-----

Class 1 Component Support DLA-2-H-2 (ISI I.D. FWB-BK-16) ISI Visual Report 87-055 (DDC-783)

- The weld detail between items 7 (I-beam) and 9 (2 inch  $\times$  1/2 inch  $\times$  12 inch plate) is not shown on the as-built drawing.
- Considering the fact that component support DLA-2-H-2 is a vertical support, Item 9 exists only for stability. The loads will be low. Therefore, the as-built weld configuration was evaluated as acceptable. The as-built drawing will be revised as part of DDC-783.

Class 1 Component Support DLA-2-H-3 (ISI I.D. FWB-BK-20) ISI Visual Report 87-056 (DDC-783)

- There is no weld on the underside of the beam at Item 9 connecting the vertical beam to the angle beam. The weld identified by the as-built is a 1/4 inch fillet weld, all around.
- The as-built weld configuration has been evaluated as acceptable, considering the loads at the weld joint will be low and Item 9 exists for stability only. The as-built drawing will be revised as part of DDC-783.

CLass 1 Component Support DLA-2-H-6 (ISI I.D. FWB-BK-26) ISI Visual Report 87-057 (DDC-783)

- Variable spring can VS-2B13 is installed, but the drawing requires VS-2B14.
- Due to geometry of the support, the spring can must be VS-2B13. The hot and cold settings are within the working range required.
- A beam clamp shown on the as-built drawing is not listed on the Bill of Material nor does it conform to the design drawing.
- The as-built drawing detail and Bill of Material will be revised as part of DDC-783 to include the beam clamp and the spring can required.

:

Class 1 Support DLA-7-H-1 (ISI I.D. CSA-BK-26) ISI Visual Report 87-071 (DDC-788)

- The support is leaning 2° to 3° from vertical.
- The support orientation is acceptable, as it is within the established acceptance criteria.
- The beam clips shown on the as-built drawing are not listed on the Bill of Material.
- The as-built Bill of Material will be revised to include the beam clips.
- Item 3 (2-1/2 inch sch. 80 pipe) centerline is offset 2 inches from the centerline of Item 4 (variable spring can).
- The support has been evaluated as operable as is since the load is transmitted to the spring can surface and the thermal movement is in the direction opposite to the direction the support is leaning. The as-built drawing will be revised as part of DDC-788.

Class 1 Component Support DLA-3-SS-3 (ISI I.D. PSA-BK-9A) ISI Visual Report 87-086 (DDC-784)

- The rear clevis ears have been notched 1/2 inch on each side.
- The distance between the center of the hole to the nearest free edge is 1-1/4 inches. This is greater than the 1 inch edge distance required by AISC 8th edition. Since both the bending stress and edge distance has been evaluated as satisfactory, the support is acceptable as is. The as-built drawing will be revised as part of DDC-784.

Class 1 Component Support DCA-6-SS-50 (ISI I.D. CUA-BK-20A) ISI Visual Report 87-094

- A portion of a plate is not identified on the Bill of Material.

• The location of the unidentified plate is not in a load bearing area. This support has been evaluated to use as is.

Class 1 Component Support DBA-5-H-5 (ISI I.D. RHA-BK-12A) ISI Visual Report 87-104

- Bottom pipe clamp is loose and a two bolt clamp was installed, not a three bolt clamp as shown on the as-built drawing.
- DCP-1385 decommissioned and removed the piping system from service of which Component Support DBA-5-H-5 was a part.

Class 2 Component Support GBB-4-SS-212 (ISI I.D. RHF-CE-92) ISI Visual Report 87-560 (CMAR 75440 and 75440A)

- The north corner anchor bolt was tilted, causing a 1/16 inch to 1/8 inch gap between the washer and nut ( $4^{\circ}-5^{\circ}$  tilt).
- A beveled washer was added. The bolt was re-torqued and is now acceptable.
   Due to the rejectable item, GBB-4-SS-213 (ISI Visual Report (87-661), DBB-1-H-20-A (ISI Visual Report 87-662) and GBB-4-SS-211 (ISI Visual Report 87-663) were selected as additional examinations.

Class 1 Component Support (DCA) SSA-8 (ISI I.D. RCA-BK-7) ISI Visual Report 87-142

- The rear pin to wall dimension is incorrect
- A 1/2 inch x 5 inch x 5 inch plate is not indicated on the as-built drawing.
- Evaluation determined that the above noted discrepancies are not a concern from a structural standpoint due to the direction of loads. The support has been evaluated to use as is. The as-built drawing will be revised as part of a DDC, however SSA-8 has yet to be assigned to a DDC.

Class 2 Six Inch Diameter Weldolet EBD-2-12-9-SW (ISI I.D. MSA-CF-39) ISI Magnetic Particle Report 87-319

- Examination of the weldolet revealed four linear indications ranging in length from 1/4 inch to 5/8 inch.
- The indications were removed by mechanical methods and re-examined. Reexamination revealed no indications (ISI Magnetic Particle Report 87-671). MSB-CF-35 was scheduled as an additional examination.

1

Class 2 Component Support HBB-24-SS-228 (A)(B) (ISI I.D. RHC-CE-38) ISI Visual Report 87-342 (CMAR 75420)

- The two bottom anchor bolts on the top plate are tilted approximately 5°.
- $\circ$  Beveled washers and two new anchor bolts, 1/2 inch longer, were installed.
- There is a 1/4 inch gap between the baseplate and the wall on the upper left hand corner.
- The 1/4 inch gap has been evaluated as acceptable.
- Due to the above rejectable conditions, additional examinations were scheduled as follows: Component Supports HBB-24-H-7 (ISI Visual Report 87-667), HBB-24-SS-227 (A) (B) (ISI Visual Report 87-668).

Class 2 Component Support EBB-16-H-26 (ISI I.D. RHD-CE-10) ISI Visual Report 87-345 (DDC-794)

- A 1/8 inch thick plate was found added to the bottom of the slide plate.
   The additional plate is welded to the slide plate with 1 inch long welds on all 4 corners.
- Some welds identified on the as-built drawing were not made, others not identified on the as-built drawing were made. Several welds were visually unacceptable.
- The discrepancies were evaluated as acceptable. The as-built drawing will be revised as part of DDC-794.

Class 2 Component Support EBB-16-H-25 (ISI I.D. RHD-CE-12) ISI Visual Report 87-346 (DDC-794), (DCP-1323)

- An additional weld is not identified on the as-built drawing.
- The discrepancy has been evaluated as acceptable. The as-built drawing will be revised as part of DDC-794 and DCP-1323.

Class 2 Component Support GBB-4-H-20D (ISI I.D. RHF-CE-88) ISI Visual Report 87-361

- The spring can cold-load setting does not comply with the specified asbuilt setting.
- The spring can setting is within 10% of the specified setting and has been evaluated as acceptable.

. . . . . . . . . . .

Class 2 Component Support GBB-4-SS-217 (ISI I.D. RHF-CE-52) ISI Visual Report 87-363 (CMAR 80742)

- Several 1/64-inch wide cracks were noted in the concrete of the upper base plate.
- The cracks have been evaluated as acceptable as the anchor bolts can be properly torqued.
- The upper snubber has a "bump" (corrosion) 1/8 inch high on the bottom of the piston rod 1-1/2 inches from the snubber housing.
- Calculations demonstrate that the thermal movement in the east to west direction is less than 1 inch, therefore, seal damage would not result from snubber movement. The corrosion was removed. This support has been evaluated as acceptable.

Class 2 Component Support GBB-4-SR-5 (ISI I.D. RHF-CE-49) ISI Visual Report 87-365 (CMAR 80744)

- The middle baseplate has a 1/4 inch gap between the wall and baseplate.
- The anchor bolts have been properly torqued, therefore, the support is acceptable as is.

Class 2 Component Support HBB-2-SR-3 (ISI I.D. CSA-CE-33) ISI Visual Report 87-372 (DDC-829)

- The weld symbol for Item 7 (beam) and Item 8 (beam) calls for a weld all around. Contrary to this, the flange tips and the top of the connection are not welded.
- The weld has been evaluated as acceptable.
- Item 1 (threaded rod) should be at 8°, but is actually at 5°.
- Support members may be within 15° of that shown on the drawing in accordance with engineering evaluation. The support is acceptable as is. The as-built drawing will be revised as part of DDC-829.

----

\_\_\_\_\_

Class 2 Component Support DBA-7-H-14-A (ISI I.D. RSB-BK-10A) ISI Visual Report 87-394 (DDC-775)

- The slide plate is 3/4 inch off center.
- The slide plate condition is acceptable since the load is transmitted to the spring can surface, the thermal movement would need to be 5-1/4 inches before the support would be inoperable.
- The grout is 5/8 inch instead of 1 inch as shown on the drawing.
- The concrete grout pads are used typically to distribute compressive loads and to allow the baseplate to sit level. Design Engineering has evaluated this condition as acceptable. The as-built drawing will be revised as part of DDC-775.

Class 1 Valve CV-4412-MSIV-"A" Loop - Inboard ISI Visual Report 87-452 (CMAR 75914)

- Junk ring and stem are badly galled, one cap screw is missing.
- The galled junk ring, stem, disc, body to bonnet gasket and packing have been replaced and the seat has been ground. The Class 1 leakage test with VT-2 exam (ISI 87-626) was acceptable. No additional examinations were scheduled as all MSIVs (8) were examined during the 1987 Refuel Outage.

Class 1 Component Support SSA-4 ISI Visual Report 87-559 (CMAR 75435)

- Snubber lug (motor end) is pressed tightly against the side weld on the south ear of the end attachment restricting movement.
- The snubber lug was coped and showed no indication of binding and is free to move after coping. Due to the unacceptable condition of Component Support SSA-4, Component Supports HA-5 (ISI Visual Report 87-664) and SSA-1 (ISI Visual Report 87-665) were selected as additional examinations.

-----

Class 2 Component Support H8B-25-SS-178 (ISI I.D. RHM-CE-9) ISI Visual Report 87-562 (CMAR 75421)

- Item 3 (8 inch pipe attachment) clamp has moved down 1-1/2 inches from original installation, also the outside bolt on the clamp is slightly loose.
- The clamp has been moved to its proper location and the bolts have been tightened.
- The bottom left anchor bolt located on the baseplate has tilted  $3^{\circ}$  to  $5^{\circ}$ . A 3/16 inch gap exists between the nut and washer.
- A beveled washer was added to the assembly at the tilted anchor bolt. The kwik bolts re-torqued satisfactorily. Due to the rejectable items additional examinations were scheduled as follows: Component Support HBB-25-H-165 (ISI VT Report 87-659) and Component Support HBB-25-H-166 (ISI VT Report 87-660).

Class 2 Component Support HBB-25-SA-179 (ISI I.D. RHM-CE-21) ISI Visual Report 87-601 (DCP-1323), (CMAR 80252)

- The south base plate has one anchor bolt which is tilted  $5^{\circ}$ .
- A beveled washer was installed and the bolt was re-torqued.

Class 1 Valve CV-2002 ISI Visual Report 87-615 with supplemental ISI Liquid Penetrant Examination Report 87-615 (CMAR 72409)

- Numerous transverse cracks were found throughout the stellite sealing surface of the disc.
- The transverse cracks in the stellite seat have been evaluated as acceptable.
- The VT-2 test with VT-2 exam (ISI 87-624) was acceptable.

Class 2 Component Support HBB-23-SS-220 (ISI I.D. RHB-CE-50) ISI Visual Report 87-682 (CMAR 80739)

- Paint drops were detected on the piston shaft by visual examination. The paint was outside of the stroke area. No gasket damage was detected.
- The paint was removed from the piston shaft and a light coating of lubricant was applied to the piston shaft.

Due to the amount of unacceptable visual (snubber) examinations on the Residual Heat Removal System (RHR), all nine remaining snubbers on the Class 2 RHR System which were not scheduled for examination during the 1987 Refueling Outage were examined by visual examination. Their identifications are:

SUPPORT NO.	ICI IDCNT	VISUAL	
SUPPORT NU.	ISI IDENT.	ISI REPORT	
HBB-24-SS-221	RHA-CE-42	87-713	CMAR 80816
HBB-24-SS-212	RHA-CE-50	87-714	CMAR 80814
EBB-16-SS-232	RHD-CE-27	87-715	
EBB-16-SS-233	RHD-CE-13	87-716	
GBB-7-SS-223	RHE-CE-53	87-717	
GBB-6-SS-226	RHI-CE-52	87-718	
GBB-3-SS-235	RHJ-CE-24	87-719	
GBB-3-SS-237	RHJ-CE-76	87-720	CMAR 80815
GBB-3-SS-236	RHJ-CE-43	87-721	

Class 2 Component Support HBB-24-H-6-1 (ISI I.D. RHC-CE-42) ISI Visual Report 87-598 (CMAR 83295) (DCP-1323)

- One anchor bolt on the southwest corner of the baseplate has a 3/32-inch gap between the nut and baseplate.
- o See below.
- Actual diameter of the anchor bolts are 1/2-inch diameter however, the drawing Bill of Material indicates 5/8-inch diameter are needed.
- The calculation record for Class 2 Component Support HBB-24-H-6-1 was reviewed and found acceptable for the 1/2-inch diameter anchor bolts. However, hardened washers were installed to satisfy AISC Code criteria for oversized holes which were drilled in the baseplate for bolts. (This resolution applys to both discrepencies listed above).

Class 2 Component Support HBB-24-SS-221 (ISI I.D. RHA-CE-56) ISI Visual Report 87-713 (CMAR 80816)

- The pin-to-pin dimension was found to be 40-1/4 inches as compared to 40-5/8 inches as indicated on the design drawing.
- This condition is acceptable since the discrepancy is 3/8 inch while the snubber has a 6-inch stroke and the thermal movement is only 1/2-inch.
- A washer on a baseplate connection bolt was found riding on a weld causing a gap between the washer and baseplate and between the washer and nut.

o The washer was coped and reinstalled in accordance with CMAR 80816.

Part D, Page 13 of 24

VICTAL

Class 2 Component Support HBB-24-SS-222 (ISI I.D. RHA-CE-50) ISI Visual Report 87-714 (CMAR 80814)

- The pin-to-pin dimension is 38 inches instead of the design drawing dimension of 3 feet 1-13/16 inches (37-13/16 inches).
- This condition is acceptable since the discrepancy is only 3/16 while the snubber has a 6 inch stroke and the thermal movement is less than 1/2 inch.
- The two (2) west bolts are tilted approximately 5°
- The nuts were removed one at a time and beveled washers were installed. The bolts were than re-torqued.

Class 2 Component Support EBB-16-SS-232 (ISI I.D. RHD-CE-27) ISI Visual Report 87-715

- The top snubber is near its full extension for EBB-16-SS-232.
- The geometry for EBB-16 in the area of EBB-16-SS-232 was analyzed and the conclusion was that any thermal growth would tend to compress the snubber, therefore this condition was evaluated as acceptable.

Class 2 Component Support EBB-16-SS-233 (ISI I.D. RHD-CE-13) ISI Visual Report 87-716

- The actual pin-to-pin dimension for EBB-16-SS-233 is 2 ft. 1 inch as compared to the design drawing requirements of 2 ft. 2-5/8 inches (cold setting) and 2 ft. 6-1/4 inches (hot setting).
- Since the snubber remains in its travel range, the as-found setting has been evaluated as acceptable since the thermal movement of the line will extend the snubber pin-to-pin dimension.

This was one of the group of remaining RHR snubbers already scheduled for examination as a result of previous unacceptable exam results, therefore no further additional examinations were scheduled. Class 2 Component Support GBB-3-SS-237 (ISI I.D. RHJ-CE-76) ISI Visual Report 87-720 (CMAR 80815) (DDC-798)

- A 1/16 inch to 3/16-inch gap was detected by visual examination between the base plate and concrete all the way around.
- The anchor bolts were re-torqued and the baseplate was re-grouted.
- The pipe clamp shows signs of minor corrosion.
- The pipe clamp was cleaned and repainted.
- The design drawing indicates that component supports GBB-3-SS-238 and GBB-3-SS-237 have a common pipe clamp. Actual conditions are that GBB-3-SS-238 has its own clamp.
- The as-built drawing will be revised as part of DDC-798.

Class 2 Component Support GBB-3-SS-236 (ISI I.D. RHJ-CE-43) ISI Visual Report 87-721

- Hole number four for a 3/4-inch x 12-inch x 15-inch plate is not in the location indicated on the design drawing.
- The reported condition is acceptable since the number of anchor bolts has not been reduced. A Design Engineering computer analysis was performed which indicated a sufficient factor of safety for the support.

Class 2 Component Support HBB-1-H-6 (ISI I.D. CSD-CE-33) ISI Visual Report 86-040 (CMAR 74610)

- One (1) loose nut was detected during routine non-ISI inspection the pipe clamp of Component Support HBB-1-H-6.
- The loose nut was tightened.

- - - .

Class 2 Component Support GBB-4-H-7 (ISI I.D. RHF-CE-56) ISI Visual Report 86-042

- Item 2 (6-inch x 1/2 x 6-inch long plate) is offset 3/4-inch of item 4 (14 V.S.) towards the wall.
- The non-centered loading experienced by Component Support GBB-4-H-7 does not affect operability of the Support. Component Support GBB-4-H-7 is acceptable as found.

Class 2 Component Support GBB-4-H-9 (ISI I.D. RHF-CE-65) ISI Visual Report 86-041 (CMAR 74588)

- There is a 1/8-inch deep indentation on the stantion portion of Component Support GBB-4-H-9.
- The dent in the stantion portion of the component support does not affect its operability.
- The ears on the pipe clamp are drawn in approximately 1-inch from 90°.
- Per engineering evaluation, the bent pipe clamp ears do not affect the operability of the support.
- Two (2) of the anchor bolts are stamped "J" (6-inch to 6-1/2-inch long). One-inch diameter x 9-inch long anchor bolts are required by the design drawing.
- Engineering evaluation indicates the support is acceptable as installed. The drawing will be revised by DDC-799 to show the as-built condition.

Class 2 Six Inch Diameter Weldolet EBD-2-16-7-SW (ISI I.D. MSB-CF-35) ISI Magnetic Particle Report 87-616 (CMAR 82975)

- Three linear indications were detected ranging from 1/2-inch to 1 3/8inches in length.
- Indications were removed by mechanical means. The blended areas were reexamined by Magnetic Particle examination (ISI 87-669) and found acceptable. The material thickness was checked by ultrasonic examination and found acceptable.

Class 1 Valve CV-4415 ISI Visual Report 87-617 (CMAR 79174 and 79174A)

- Approximately 6 inches of the disk is uneven and does not appear to be making contact to the valve seat. Excess wear on guide ribs and piston.
- The piston and disk were built up by weld deposit and stellite seat rebuilt by welding. The junk ring was replaced, all bolting and gasket surfaces were cleaned and the valve seat has been machined. The valve was reexamined after repair and found acceptable. Due to the rejectable condition, CV-4412 and CV-4413 were selected as additional items for examination. The VT-2 pressure test (ISI 87-618) was acceptable.

Class 1 Valve CV-4418 ISI Visual Report 87-619 (CMAR 79175)

- Junk ring badly galled, stem badly galled and the valve does not appear to be seating from the 7 o'clock to the 9 o'clock position. Excess wear on guide ribs and piston.
- O The stem and junk ring has been replaced, the disc and piston were built up by welding and stellite seat rewelded and the seating surfaces have been dressed. The valve was re-examined after repair and found to be acceptable. Due to the rejectable conditions, CV-4412 and CV-4413 were selected as additional items for examination. The VT-2 pressure test (ISI 87-620) was acceptable.

Class 2, Six Inch Diameter Weldolet EBD-2-4-9-SW (ISI I.D. MSC-CF-39) ISI Magnetic Particle Report 87-630 (CMAR 79150)

- Five linear indications ranging from 3/16-inch to 1 3/4 inch were detected by Magnetic Particle examination.
- The indications were removed by grinding and re-examined by Magnetic Particle examination (ISI 87-711) and found to be acceptable.

As this was the last of four 6-inch weldolets to be examined on the Main Steam System, no additional examinations were scheduled.

Class 2 Component Support MSD-HD-1 Lugs (ISI I.D. MSD-BK-7) ISI Magnetic Particle Report 87-645 (CMAR 82491)

- On the SW lug of four lugs, two linear indications were detected by Magnetic Particle examination, only one of which was rejectable.
- The SW lug (with the magnetic particle indications) was removed by grinding. The area was re-examined by the Magnetic Particle method (ISI 86-673) and found to be acceptable. Due to the unacceptable examination results, the remainder of similar lugs (MSB-HB-1 and MSC-HC-1) in the Main Steam system were scheduled for examination.

:

Part D, Page 18 of 24

ł

Class 2 Component Support MSB-HB-1 Lugs (ISI I.D. MSB-BK-8) ISI Magnetic Particle Report 87-655

- One linear indication 3/16 inch long was detected by Magnetic Particle examination. This examination was performed due to unacceptable exam (ISI-87-645) on HD-1 Lugs (above).
- The linear indication was evaluated as acceptable on NCR 87-067.

Class 2 Component Support HBB-23-SS-219 (ISI I.D. RHB-CE-57) ISI Visual Report 87-658 (CMAR 82513, 82513A)

- The snubber marginally passed its functional test. The fluid in the plunger assembly was found to be dirty and the plunger did not retract with the fluid.
- o The snubber was replaced with a refurbished snubber.
- Bottom right anchor bolt on base plate is tilted 5°.
- Beveled washers were installed and bolts were re-torqued.
- Actual pin to pin dimension is 3 ft. 3-1/4 inches (39-1/4 inches)
- The walkdown pin-to-pin dimension of 3 ft. 3-1/4 inches is acceptable since thermal movement is .28 inches and the minimum allowable pin-to-pin dimension is 36-7/8 inches. Due to the rejectable conditions, additional Snubber GBB-3-SS-238 was examined.

Class 2 Component Support GBB-4-SS-213 (ISI I.D. RHF-CE-92) ISI Visual Report 87-661 (CMAR 80736)

- An arc strike was detected by visual examination on the piston shaft. Approximate dimensions of the arc strike were 1-1/4 inches long by 1/64 to 1/32-inch deep and was approximately 2 inches from the piston seal.
- The maximum thermal movement for this snubber is 0.6 inches. Therefore, the condition is acceptable as is since the arc strike would not damage the piston seal during snubber movement, however, the arc strike has been removed by buffing and the affected area was Liquid Penetrant examined.

Results of the Liquid Penetrant examination were satisfactory. Due to the rejectable condition, the following additional examinations were performed. GBB-4-SS-210 (ISI VT Report 87-683), GBB-4-SS-216-A (ISI VT Report 87-684) and GBB-5-SS-215 (ISI VT Report 87-685).

. . . . . . . . . .

Class 2 Supports HBB-24-SS-277(A) & (B) (ISI I.D. RHC-CE-22) ISI Visual Report 87-668 (CMAR 80735)

- Entire snubber has general corrosion, spherical bearing on rear end of top snubber rusted in place, spherical bearings on both ends of bottom snubber rusted in place.
- Both snubbers have been cleaned, lubricated and painted. Visual examination results after cleaning were acceptable.
- Actual pin-to-pin dimension on both snubbers is 28-3/4 inches.
- The actual pin-to-pin dimension is less than the maximum allowed by the drawing and there is sufficient stroke to accommodate the calculated thermal movement.
- There is a 0.188-inch gap between each base plate and the concrete (at the bottom of the upper plate and at the top of the lower plate),
- The anchor bolts have been re-torqued, the gap still exists but the results are evaluated as acceptable. Additional examinations normally required were not scheduled since all component supports of the same design, type and function on this system were examined during the 1987 Refuel Outage.

Class 1 Valve PSV-4407, MSRV, Loop "D"-Inboard (CMAR 68871, and CMAR 76336A) (ISI 87-580) (ISI 87-522)

- In 1986, the tail pipe temperatures indicated the pilot value assembly was leaking past the seat.
- The pilot valve assembly was replaced with a spare in accordance with CMAR 68871. A leakage test and VT-2 examination was not performed. An NCR was generated to address the Code non-compliance.
- During the 1987 refueling outage, the pilot valve assembly failed to pass its seat-leakage test. In addition, ten (10) retaining bolts were damaged during the maintenance activity. (Ref. ISI 87-723) (ISI I.D. MSD-BG-22)
- The pilot valve was again replaced with a refurbished pilot valve in accordance with CMAR 76336A. The VT-2 pressure test (ISI 87-522) was acceptable.

------

Class 2 Valve PSV-2129 CMAR 68999 (ISI 87-398)

- Dirt and rust are in the valve. The disc is beyond repair.
- o The valve was cleaned and the disc was replaced. The VT-2 pressure test (ISI 87-398) was acceptable.

Class 2 Rupture Disc, PSE-2213 CMAR 71102 (ISI 87-586)

- The rupture disc needs to be replaced annully in accordance with manufacturers recommendations.
- o The rupture disc was replaced. The VT-2 pressure test (ISI 87-586) was acceptable.

Class 2 Component Support GBB-4-H-11 (ISI I.D. RHF-CE-72) CMAR 71734 (ISI 86-043)

- The hanger rod has evidence of slight elongation.
- o The hanger rod was replaced and visually examined.

Class 2 Component Support GBB-4-H-12 (ISI I.D. RHF-CE-74) CMAR 71735 (ISI 86-044)

- There is a slight bend in the spring can clevis pin.

o The clevis pin was replaced and visually examined.

Class 2 Valve MO-2030 CMAR 73106

- NCR 85-096 reports cracking on the valve stem and on the disc seating surface after machining.
- The disc, stem, retaining ring, packing and pressure seal gasket were replaced and the disc nut was tack welded to the disc. The VT-2 pressure test (ISI 87-693) was acceptable.

Class 2 Valve MO-1940 (CMAR 73107)

- Per Engineering Evaluation the disc nut should be tack welded to the disc.
- o The disc nut was tack welded to the disc. The VT-2 pressure test (ISI 87-643) was acceptable.

Class 1 Valve MO-2239 (CMAR 75472) (ISI 86-055), (ISI 86-056), (ISI 86-060)

- Valve MO-2239 was disassembled to repair a packing leak. A VT-3 examination found the stem badly pitted and stuffing box badly eroded. The valve internal surfaces were found acceptable.
- Indications in the stuffing box area were ground and weld repaired. The valve stem pressure seal and spacer were replaced. The VT-2 pressure test (ISI 86-055) was acceptable. The stuffing box area of another similar valve was VT-3 examined. The internal surfaces of the additional valve were not examined since the internal surfaces of MO-2239 were acceptable.

Class 1 Valve CV-4419 (CMAR 65258A)

- Relevant linear indications were detected by liquid penetrant examination on the disc seat.
- The linear indications on the disc seat were ground out and excavated areas have been weld repaired. Repaired areas were machined and liquid penetrant examined. The liquid penetrant examination was acceptable. The VT-2 pressure test (ISI 87-568) was acceptable.

Class 1 Valve MO-4423 (CMAR 73108), (ISI 87-592, VT-3)

- An excessive gap exists between the guide ribs due to disc movement.
- The guide ribs were machined and the disc was replaced. The VT-2 pressure test (ISI 87-593) was acceptable.

Class 2 Component Support GBB-13-H-1 (ISI I.D. CSB-CE-13) CMAR 78270 (ISI 87-379, VT-3), (DDC-806)

- As found condition was a loose washer on the base plate and a missing nut from the beam attachment. The support drawing does not identify the symbol for a weld.
- o Washers were added and the beam attachment nut was replaced. The drawing will be revised in accordance with DDC-806.

. . . . .

Class 1 Valve CV-2138 CMAR 79312A (ISI 87-631, VT-3)

- Valve failed leak rate test. The valve did not seat properly because the hinge pin may not fit properly. The hinge pin needs to be machined.
- The hinge pin has been machined (.007" removed). The valve now seats properly and passed the leak rate test. The ASME Class 1 leakage test with VT-2 exam (ISI 87-632) was acceptable.

Class 2 Component Support EBB-14-SS-14 (ISI I.D. HPC-CE-34) CMAR 80391A (ISI 87-646)

- The snubber failed its functional test.
- o The snubber was replaced with a refurbished snubber and visually examined.

Class 2 Component Support HBB-24-SS-222 (ISI I.D. RHA-CE-50) CMAR 80814 (ISI 87-714)

- Two anchor bolts are installed with a 5° tilt.
- o The anchor bolts were removed one at a time and the existing flat washers were replaced with beveled washers.

Class 2 Component Support EBB-14-SS-13 (ISI I.D. HPC-CE-27) CMAR 75437A (ISI 87-563)

- The snubber failed its functional test
- o The snubber was replaced with a refurbished snubber and visually examined.

Class 1 Valve MO-4424 CMAR 75608A

- The wedge was found to be eroded.
- o The wedge was replaced. The ASME Class 1 leakage test with VT-2 exam (ISI 87-708) was acceptable.

Class 1 Valve PSV-4404 CMAR 76108A (ISI 87-678, VT-3) (ISI 87-582, VT-2)

- Significant degradation of the disc was found during disassembly of PSV-4404.
- The disc was replaced. The ASME Class 1 leakage test with VT-2 exam (ISI 87-582) was acceptable. DCP-1341 will update the drawing to identify new disc material.

Class 2 Component Support GBB-4-SS-217A & B (ISI I.D. RHF-CE-52) CMAR 76109 (ISI 87-424, VT-3/VT-4)

- The snubber was found to be leaking.
- o The snubber was replaced and visually examined (ISI 87-424)

Class 1 Valve PSV-4401 CMAR 76331A (ISI 87-532)

- A damaged hex nut was found during installation.
- o The hex nut was replaced. The ASME Class 1 leakage test with VT-2 exam (ISI 87-532) was acceptable.

Class 2 Component Support EBB-14-SS-15 (ISI I.D. HPC-CE-59) CMAR 82509A (ISI 87-657)

- The snubber failed its functional test.
- o The snubber was replaced with a new snubber and visually examined.

Class 2 Component Support HBB-1-SS-10 (ISI I.D. CSD-CF-31) CMAR 75665 (ISI 87-425)

- -----

- The snubber was found to be in satisfactory condition. However, the snubber is approaching its expected serial life time.
- o The snubber was replaced with a refurbished snubber and visually examined.

Class 2 Six Inch Diameter Weldolet EBD-2-8-7-SW (ISI I.D. MSD-CF-34) ISI Magnetic Partical Report 87-629 (CMAR 82974)

- Three linear indications were detected ranging from 1/8 inch to 5/16 inch in length.
- The linear indications were removed by grinding (Reference: NCR-87-046). The blended areas were re-examined (ISI 87-670) by magnetic partical examination and accepted. The material thickness was checked by ultrasonic examination and found acceptable.

Class 1 Valve, CV-4413, MSIV - "A" Loop Outboard ISI Visual Report 87-588 (CMAR-84014)

- Valve failed LLRT. The VT-3 visual examination was performed upon disassembly. Slight oxidation was noted on the valve seat and disc seat, slight guide wear. One bonnet nut had been damaged by a torch. Two bonnet nuts were found with linear indications by liquid penetrant examination. Two non-pressure retaining cap-screws were found with missing threads and one non-pressure retaining cap screw was missing.
- Ground the seat, lapped the back-seat on bonnet, replaced the bonnet gasket, replaced 3 non-pressure retaining cap screws, replaced 3 pressure retaining bonnet nuts, replaced packing, replaced pnuematic control with new 'O'-rings and nitrogen flange gasket. The ASME Class 1 leakage test with VT-2 exam (ISI 87-587) was acceptable.

Class 1 Component Support DBA-6-H-1 (ISI I.D. CRA-BK-29) (CMAR 82479) (ISI 87-627)

- To allow MOVATS testing of nearby valve MO-2238-0, support DBA-6-H-1 needed temporary removal and reinstallation after completion of the valve test.
- o The spring can welded to the I-beam of the building structure was detached by removing the weld by grinding and the half-clamp with associated bolting to the piping were removed. The original half-clamp and bolting were reinstalled, and the spring can rewelded to the building structure I-beam in the "As-built" configuration and visually examined.

Class 2 Valve V19-0003 CMAR 68783 (ISI 87-447)

. .....

- Tack welds between hinge support and bonnet need to be repaired.
- Tack welds between the hinge support and bonnet, cap screws and hinge support and set screws and hinge support were repaired by tack welding. The VT-2 pressure test (ISI 87-447) was acceptable.





## Part E, Page 1 of 46

System or Component			*A	ugm I	ente I I		Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description			0313	0619			Description	Report No.	No.	Report No.		
- -	Accept	Reject	NUREG 03	1		Other						
PV System Leakage Test	X						RPV				ABBREVI	
lass 1 Piping Leakage est	x						Piping			IR - Nozz	tor Pressure le Inner Rad	ius
lass 1 Pumps Leakage est	x						Pumps		87-001	WOL - Weld	le to RPV We Overlaý Rep	air
est lass 1 Valves Leakage est	x	-					Valves				Seam Outer Seam Inner	
eactor Pressure Vessel											Sedm	
op Head Meridional	X						HMC-B2	87-009-0°				1.7 ft. examined
	X						HMC-B2	87-009-45°				11 61 16
	X						HMC-B2	87-009-60°			<u></u>	11 . 11 .1
ead to Flange Weld	X	·					HCC-C1	87-010-0°				17.4 ft. examined
	X						HCC-C1	87-010-45°				from studhole
	X						HCC-C1	87-010-60°				60 to 20
	X						HCC-C1			87-011		11 11
ircumferential	X						HCC-B2	87-012-0°				13.3 ft. examined
	X						HCC-B2	87-012-45°.			<del> </del>	£8 \$8
	X						HCC-B2	87-012-60°			····· ,,	11 11
lead Flang <b>e</b>	x						1T-201		87-443		····	VT-2

System or			*Ai	Jgme	nted	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description			0313	0619		Component Description	and Visual Report No.	Report No.	P <b>art</b> icle Report No.	Report No.	
		Accept Reject	NUREG 03		GL-84-11 Other						
ell to Flange Weld	X					VCB-C5	87-013-0°				17.4 ft. examined
	X					VCB-C5	87-013-45°				from studhole
	ı X					VCB-C5	87-013-60°				60 to 20
<u>/ Nozzles:</u> ad Vent (IR)	x					HVA-N7	87-015			• •	
R-Headspray (N-V)	X					RHA-BD-1	87-016-0°				·······
	x					RHA-BD-1	87-016-45°			····	
	x					RHA-BD-1	87-016-60°				
R <b>-Head</b> spray (IR)	X					RHA-N6-A	87-017				
n Steam "A" (N-V)	X					MSA-BD-1	87-018-0°			**********	
	X	~				MSA-BD-1	87-018-45°			<u></u>	
	х					MSA-BD-1	87-018-60°			WANE- 11	
in <b>Steam "A"</b> (IR)	X					MSA-N3-A	87-019			··· _ · · · · · · · · · · · · · · · · ·	
dwater "A" (N-V)	X					FWA-BD-1	87-02 <b>0</b> -L			<u> </u>	
	X	T				FWA-BD-1	87-020-45°				
	X					FWA-BD-1	87-020-60°				
dwater "A" (IR)	X	Τ				FWA-N4-A	87-021			<u> </u>	
e <b>dwater "A"</b> Thermal eve	x					FWA-N4-A	87-633				Feedwater Thermal Sleeve Attachment Weld

\* Otherwise ASME

**.** .

System or			*A1	ugm	ente	ed	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description			13	0619			Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
:	Accept	Reject	NUREC 0313	NUREG 06	CL-84-11	her						
Vessel Instrumentation N-V)	x						VIC-E1	87-022-L				
	x						VIC-E1	87-022-45°				
	x						VIC-E1	87-022-60°				
essel Instrumentation IR)	x						VIC-N12-A	87-023			•	
ecirc. Riser "E" (N-V)	x						RRE-BD-1	87-024-L				
	x						RRE-BD-1	87-024-45°				
	x						RRE-BD-1	87-024-60°				
ecirc. Riser "E" (I-R)	X						RRE-N2-E	87-025	· · · · · · · · · · · · · · · · · · ·			
ecirc. Riser "F" (N-V)	X					X	RRF-BD-1	87-407-L				"Other" defined
	. X					X	RRF-BD-1	87-407-45°				as examinations which were
	X					<b>X</b> .	RRF-BD-1	87-407-60°				performed as a self-imposed
ecirc. Riser "F" (IR)	X					X	RRF-N2-F	87-408				augmentation and where performed
ecirc. Riser "C" (N-V)	X					X	RRC-BD-1	87-409-L				within the guidelines of
	X					X	RRC-BD-1	87-40 <b>9-</b> 45°				NUREG-0313, Rev. 2 dated June 1986
	X					X	RRC-BD-1	87 <b>-409-</b> 60°				and EPRI NP-4720-LE dated October 1986.
ecirc. Riser "C" (IR)	X					Х	RRC-N2-C	87-410				1
Recirc. Riser "D" (N-V)	X					X	RRD-BD-1	87-411-L				1

, | i

System or				*Au	gmei	nté		Weld or	Ultrasonic	Visual	Magnetic	Penetrant Bonomt No	Comments
Component Description				0313	0619	11		Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
		Accept	Reject	NUREG	NUREG	GL-84-11	Other						
		. x					X	RRD-BD-1	87-411-45°				"Other" defined as examinations which
		x					X	RRD-BD-1	87-411-60°				were performed as a self-imposed
lecirc. Riser "D"	(IR)	х					X	RRD-N2-D	87-412				augmentation and were performed
Recirc. Pump Loop N-V)	"A"	x					x	RCA-BD-1	87-422-L			•	within the guidelines of NUREG-0313, Rev. 2
		X					X	RCA-BD-1	87 <b>-422-45°</b>				dated June 1986 and EPRI NP-4720-LD
		X					X	RCA-BD-1	87 <b>-422-60°</b>		·		dated October 1986
Recirc. Pump Loop (IR)	"A"	X			÷		X	RCA-N1A	87-423				
op Head Vent		X	•					N7-D-1	87-014-0° 87-014-45° 87-014-60°				
			•										
									T			. ag 2	
												······	
			1						1				



Part E, Page 5 of 46


System or Component			*A	ugme	ente	ed	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description	Accept	Reject	NUREG 0313	1	GL-84-11	Other	Description	Report No.	No.	Report No.	Report No.	
ass I Systems		Γ										· · · · · · · · · · · · · · · · · · ·
in Steam Loop "A"	x						MSA-BK-8		87-026	87-027		Lugs
	X						MSA-BJ-20	87-028		87-029	•	
	X						MSA-BG-37		87-030			CV-4412-Bolting
	X						MSA-BJ-41	87-031		87-032		.,
	x						MSA-BM-37	· · ·	87-626			CV-4412, VT-2
	X						MSA-BM-23		87-532			PSV-4401, VT-2
	X		ŀ				MSA-BM-18		87-533			PSV-4400, VT-2
	x	Ι.					MSA-BK-11		87-553			
	X	Γ					MSA-BM-42		87-587			CV-4413, VT-2

\* Otherwise ASME

(continued on next page)

	<del></del>		<del></del>	 <del></del>		·		····	Pa	art E, Page	6 of 46
System or Component Description			0313 *		ed	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Accept	Reject	NUREG 03		Other						
	X					MSA-BM-42		87-588			CV-4413, VT-3
	X					MSA-BM-37		87-452			CV-4412, VT-3
	X					MSA-BK-8			87-644		
										•••••	
Main Steam Loop "B"	X					MSB-BJ-4-OA	87-034		87-033	<u></u>	
	X					MSB-BJ-4-IA	87-036		87-035		
	Х					MSB-BJ-5	87-038		87-037	<b></b>	
	X					MSB-BJ-10	87-040		87-039		
•	X					MSB-BJ-10-IA	87-042		87-041		
1 1	X					MSB-BJ-10-0A	87-044		87-043		
	x					MSB-BG-47		87-045			CV-4416-Bolting
	x					MSB-BK-28		87-047	87-046		Lugs
	X					MSB-BK-40		87-049	87-048		Lugs
	X					MSB-BM-42		87-617			CV-4415, VT-3
	X					MSB-BM-42		87-618			CV-4415, VT-2
	X					MSB-BM-27		87-525			PSV-4402, VT-2
	X		$\square$		Τ	MSB-BM-23		87-583			PSV-4403, VT-2

System or		,	*Augm	ente		Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description			0313 0619			and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept		NUREG 03 NUREG 06		Other					
	Х				MSB-BK-8			87-655	<u> </u>	Lugs
	Х				MSB-BM-21		87-679			PSV-4403, VT-3
	х				MSB-BK-45		87 <b>-687</b>		<u>.</u>	
· · ·	Х				MSB-BK-19		87-688		•	
n Steam Loop "C"	x				MSC-BM-40		87-619			CV-4418, VT-3
	x				MSC-BM-40	•	87-620			CV-4418, VT-2
	X				MSC-BM-25		87-523			PSV-4405, VT-2
	x				MSC-BM-45		87-567			CV-4419, VT-3
	x	••			MSC-BM-45		87-568			CV-4419, VT-2
	x				MSC-BM-21		87-582			PSV-4404, VT-2
	x				MSC-BK-7			87-654		
	x				MSC-BM-21		87-678			PSV-4404, VT-2
	X				MO-4423		87-592			VT-3
	X				MO-4423		87-593			VT-2
n Steam Loop "D"	X				MSD-BM-22		87-522			PSV-4407, VT-2
	x				MSD-BM-17		87-524			PSV-4406, VT-2



1

\*\* Unacceptable indications were detected by Magnetic Particle Examination (ISI MT Report 87-645) ISI Magnetic Particle Report 87-673 is a re-MT after grinding to verify indications were removed.

Part E, Page 8 of 4

					<u></u>					Part E,	Page 9 of 4
System or Component Description					ented	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Partical Report No.	Penetrant Report No.	Comments
	Accept	Reject	NUREG 0313	NUREG 0619	GL-84-11	Octier					
dwater Loop "C"	х					FWC-BM-32		87-622			V-14-1, VT-2
	X					FWC-BM-32		87-621			V-14-1, VT-3
e Spray Loop "A"	X					CSA-BF-2	87-061			87-060	
	x					CSA-BF-2	87-061-A			·····	
	X		Х			CSA-BF-2A	87-063			87-062	
	X_		Х			CSA-BF-2A	87-063-A				
	X		X			CSA-BJ-3	87-065			87-064	
	х		Х			CSA-BF-4	87-067-A			87-066	
	x	•	x			CSA-BF-4	87-067 <b>-</b> B				
	Х					CSA-BJ-25	87-069		87-070		
	x					CSA-BK-26		87-071			
e Spray Loop "B"	x		x	-+		CSB-BF-2	87-072			87-073	
	x		х	$\neg$		CSB-BF-2	87-072-A				
	X		х	$\uparrow$		CSB-BF-2A	87-074			87-075	
	X		x			CSB-BF-2A	87-074-A	·····			

System or			*A	ugme	ente		Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description		<b></b>	0313	0619	_	- Component Description	and Visual n Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREG 0		GL-84-11	Other					
	х		x			CSB-BJ-3	87-076			87-077	
	X		Х			CSB-BF-4	87-078-A			87-079	
	X	ľ	x			CSB-BF-4	87-078-B				
	X					CSB-BJ-25	87-080		87-081	·	
i	X					CSB-BK-26		87-082			
	X					CSB-BM-15		87-631			CV-2138, VT-3
	X					CSB-BM-15		87-632			CV-2138, VT-2
	x					PSV-2129		87-398			VT-2
PCI-Steam	X					PSA-BK-9A		87-086			
	x	ł				PSA-BK-8		87-087			
	x		[			PSE-2213		87-586			VT-2
PCI-Water	х					PSB-BJ-8	87-090		87-091		
	Х					PSB-BK-6		87-092			
	X					PSB-BM-4		87-453	· ·		CV-2313, VT-2
	х					PSB-BM-4		87-454			CV-2313, VT-3
		Γ							1		
			<u> </u>						-	1	





Part E, Page 11 of 46

System or Component			*A1	ugm	ente	ed	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description			3	6				Report No.	No.	Report No.	Report No.	
	Accept	Reject	NUREG 0313	1		Other						
WCU - Suction	Х						CUA-BK-22		87-093			
	х						CUA-BK-20-A		87-094			Support ID DCA-6-SS-5
	х						CUA-BK-20-A		87-095			Support ID DCA-6-SR-5
	х				x		CUA-BJ-10	87-097			87-098	
	х						CUA-BJ-9	87-099			87-100	
	х				x		CUA-BJ-6	87-101			87-102	
	Х				x		CUA-BJ-14	87-426			87-428	
	Х				X		CUA-BJ-20	87-427			87-429	
WCU - Discharge	Х	•					CUB-BK-7		87-554		<b>_</b>	
control Rod Drive Return	x		-	x			CRA-BF-2	87-404				
	^ X			X		-	CRA-BJ-3	87-405				
	X	<u> </u>	-	X		-	CRA-BF-4	87-406				
	^ X			x			CRA-BF-4	87-406-A			· · · · · · · · · · · · · · · · · · ·	
	^ X	$\left  \right $	$\vdash$				CRA-BK-29		87-627			Preservice
	x	<u> </u>	$\left  \right $		$\vdash$	$\vdash$	CRA-BK-15-A		87-555		· · · · · · · · · · · · · · · · · · ·	

System or Component			*#	lugn	nent	ed	Weld or Component	Ultrasonic and Visual	Visual	Magnetic	Penetrant	Comments
Description				6			Description	Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREG 0313	NUREG 0619	GL-84-11	Other						
	х						N6A-Flange		86-062			VT-2, Functional
HR - Headspray	X						N6A-Flange		87-103			Bolting
	X						N6A-Flange		87-692			VT-2
	x						RHA-BK-12-A		87-104		•	
	X						RHA-BK-14-B		87-106			
IR-18B	x		Х				RHB-BJ-1-WOL	87-114-0°			87-390	
	Х		Х				RHB-BJ-1-WOL	87-114-60°				
	Х		X				RHB-BF-3	87-115			87-116	
	x		Х				RHB-BF-3	87-115-A				
	X	•					RHB-BJ-7	87-117		87-118		
	X						RHB-BK-15-A		87-119			Support ID DLA-4-SS-1
							RHB-BK-15-A		87-120			Support ID DLA-4-SS-1
IR-20-A	x		x				RHC-BJ-1	87-122				
1	x		х				RHC-BF-2	87-123				· · · · · · · · · · · · · · · · · · ·
· ·	x		х				RHC-BF-2	87-123-A				

Ó											Part E, Pag	e 13 of 💭
System or Component Description					ente		Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Accept	Reject	NUREG 0313	NUREG 0619	GL-84-11	Other						
	X					1	RHC-BK-5		87-124			
	Х					1	RHC-BK-7		87-125			
	Х					1	RHC-BJ-25	87-126		87-127		
	х					1	RHC-BM-10		87 <b>-6</b> 15		•	CV-2002, VT-3
	X					1	RHC-BM-10		87-624			CV-2002, VT-2
	X					1	RHC-BM-10		86-025			CV-2002, VT-3
	X						RHC-BM-10		86-026			CV-2002, VT-2
RHR-20-B	Х		х			1	RHD-BJ-1	87-129			· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
	х		х				RHD-BF-2	87-130			÷ -	
	х	•	х				RHD-BF-2	87-130-A				
	x						RHD-BJ-8	87-131		87-132		
,	x					.	RHD-BK-16		87-133			
	x						RHD-BK-20		87-134	1		· · · · · · · · · · · · · · · · · · ·
	x						RHD-BM-10		87-652			CV-1906, VT-3
	x						RHD-BM-10		87-653	1		CV-1906, VT-2
RCIC - Steam	x		1				RSA-BK-14		87~556	1		
	*	Othe	erw	ise	ASM	E					**************************************	**************************************





Part E, Page 14 of 46

System or Component			*A1	Jgme	ente	d	Weld or Component	Ultrasonic and Vi <b>s</b> ual	Vi <b>s</b> ual Report	Magnetic Particle	P <b>en</b> etrant R <b>ep</b> ort No.	Comments
Description			0313	0619			Description	Report No.	No.	Report No.		
	Accept	Reject	NUREC 03			Other						
RCIC - Water	х						RSB-BK-10A		87-394			
Recirc. Pump "A" Supports	х						HA-5		87 <b>-6</b> 64			
	х						SSA-4		87 <b>-</b> 559			
	х						SSA-1		87 <b>-66</b> 5			
	Х						SSA-5	· · · · · · · · · · · · · · · · · · ·	87-558		<u>.</u>	
Recirc. Pump Loop "A"	X		Х				RCA-BF-2	87-136			87-137	
	X		Х				RCA-BF-2	87-136-A				
	х		х				RCA-BJ-3	87-138				
	Х		X				RCA-BJ-4	87-139				
	<b>X</b> -		x				RCA-BJ-5	87-140				,
•	x		X				RCA-BJ-6	87-141				
	x						RCA-BK-7		87-142		87-143	Shock Lugs SSA-B
	X						RCA-BK-7		87-144		87-145	Shock Lugs SSA-9
	X		x				RCA-BJ-8	87 <b>-</b> 5 <b>9</b> 7				
	X		X				RCA-BJ-8	87 <b>-59</b> 7-A				

\* Otherwise ASME

/

System or			*A1	ugme	ente	ed	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description		<del></del>	0313	0619			Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREC 0			Other						
	X		х				RCA-BJ-12	87-146				
	X		х				RCA-BJ-23	87-147			<u>, 2</u>	
	X						RCA-BG-14		87-148			MO-4601-Bolting
	x						RCA-BJ-15	87-149			87-150°	
	X						RCA-BJ-15-LS	87-151			87-152	
	X		х				RCA-BJ-21	87-153				
1	X		Х				RCA-BJ-15-LS	87-153-A				Intersect at BJ-21
	X		Х				RCA-BJ-22	87-154				
	x						RCA-BK-31		87-155			
	X	-	х				RCA-BJ-24	87-159				
	X		х				RCA-BJ-28	87-160				
	X		х				RCA-BJ-30	87-161				
	X		х				RCA-BJ-32	87-162				
	X		<b>X</b>				RCA-BJ-38	87-163				
	X		х				RCA-BJ-41	87 <b>-</b> 1 <b>64</b>				
	X	-	Х				RCA-BJ-43	87-165				





Part E, Page 16 of 46

System or Component			ľ	*Au	gme	ente	ed	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description				0313	0619			Description	Report No.	No.	Report No.		
		Accept		NUREG 03	NUREG 06	GL-84-11	Other						
tirc. Pump Loop "A"	>	$\langle  $						RBA-BK-4		87-156			
)ass	>	(						RBA-BJ-7	87 <b>-</b> 157			87-158	
	×	(				Х		RBA-BJ-1	87-430			87-432	
	>	(				Х		RBA-BJ-12	87-431			87-433	
circ. Manifold "A"	X	(	;	Х				RMA-BJ-1	87-416				
	X	(	2	X				RMA-BJ-2	87-190				
	X	(	;	X				RMA-BJ-4	87-183				
	X	(		X				RMA-BJ-5	87-191				
		!						RMA-BJ-6	87-192	·		87-193	
	X	(		Х				RMA-BJ-7	87-194				
~	X	(	;	Х				RMA-BJ-8	87-211				
١	×	(						RMA-BK-9		87-195			
	X	(	;	Х				RMA-BJ-10	87-210				
	×	(	2	Х				RMA-BJ-11	87-209				
circ. Riser "E"		(						RRE-BF-2	87-172		87-173		• •

System or Component Description			*Aı	ugme	ente	d	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle	Part E, Page Penetrant Report No.	17 of 46 Comments
	Accept	Reject	NUREG 0313	NUREC 0619	GL-84-11	Other	Description	Report No.	NO.	Report No.		
· ·	X		~		Ŭ		RRE-BF-2	87-172-A	·····			
	x						RRE-BF-2A	87-170			87-171	
	x						RRE-BJ-3	87-168			87-169	
	X		X				RRE-BJ-4/ J4A-WOL	87-166-0°			87-167	
	X		Х				RRE-BJ-4/ J4A-WOL	87-166-60°			87-634	
	X		Х				RRE-BJ-5	87-200-A				
	x		Х				RRE-BJ-5	87-200 <b>-</b> 8				
	x		Х				RRE-BJ-7	87-201				
1	<u> </u>											
Recirc. Riser "F"	x		Х				RRF-BF-2	87-202				
	X		Х				RRF-BF-2	87-202 <b>-A</b>				
	x		Х				RRF-BF-2A	87-204				
	x		Х				RRF-BJ-3	87-203				
•	X		X				RRF-BJ-4/ J4A-WOL	87 <b>-174-</b> 0°			87-175	
	X		X				RRF-BJ-4/ J4A-WOL	87 <b>-174-6</b> 0°			8 <b>7-6</b> 35	
	X		Х				RRF-BJ-5	87-205-A				
	*	Othe	arwi	50	ASN	16						~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~

I	

ļ



Part E, Page 18 of 46

System or Component Description				*A	ugm	ento	ed	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
			L L	0313	0619	-11				100.	Report No.		
		Accept	Reject	NUREG	NUREG	GL-84-11	Other						
		Х		X				RRF-BJ-5	87-205-B				
	•	X		X				RRF-BJ-7	87-206				
Recirc. Riser "G"		x		x				RRG-BF-2	87-196			87-197	
		x		x				RRG-BF-2	87-196-A			· · ·	
		x		х				RRG-BF-2A	87-177				
		X	ŀ	Х				RRG-BJ-3	87-176			<u></u>	
		X		X				RRG-BJ-4/ J4A-WOL	87-178-0°			87-179	
		X	•	х				RRG-BJ-4/ J4A-WOL	87-178-60°			87-636	
		X	<b>†</b>	x				RRG-BJ-5	87-180				
		x		X				RRG-BJ-7	87-182				
Recirc. Riser "H"		X		X				RRH-BF-2	87-198			87-100	
		x		x				RRH-BF-2	87-198 87-198-A		+	87-199	
		x		X				RRH-BF-2A	87-198-A 87-184		· · · · · · · · · · · · · · · · · · ·		
		^ X	-	^ X				RRH-BJ-3	87-184				
		Ĺ		^				NKI-00-3	07-100				

									F	Part E, Page	19 of 4
System or Component Description				ente	d	Weld or Component Description	Ultra <b>son</b> ic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Accent	Rejert	NUREC 0313		Other						
	X		x			RRH-BJ-4∖ J4A-WOL	87-186-0°			87-187	
	X		X			RRH-BJ-4\ J4A-WOL	87-186-60°			87-637	
	X		х			RRH-BJ-5	87-188			•	
	X		х			RRH-BJ-7	87-189				
ecirc. Pump Loop "B"	X		X			RCB-BF-2	87-212				
	Х		x			RCB-BF-2	87-212-A			87-213	
	X		X			RCB-BJ-5	87-214				
	X		X			RCB-BJ-6	87-215				
	X		Х			RCB-BJ-7	87-216				
	Х					RCB-BK-8		87-217		87-218	
	X					RCB-BK-10		87-219		87-220	Shock Lugs SSB-8
	Х					RCB-BK-10		87-221		87-222	Shock Lugs SSB-9
	Х		x			RCB-BJ-15	87-223				
	X		Х			RCB-BJ-16	87-224				
	х					RCB-BJ-18	87-225			87-226	

											Part E, Pag	ge 20 of 40
System or Component			*A	ugm I	ento T	ed	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
<b>Description</b>			3 0313			L L	Description	Report No.	No.	Report No.		
	Accent	Reject	NUREC	NUREG	GL-84-11	Other						
	X						RCB-BJ-18-LS	87-227-A			87-228	
	X						RCB-BJ-18-LS	87-227 <b>-</b> B				
	X		X				RCB-BJ-24	87-229				
	X		Х				RCB-BJ-25	87-230			•	
	X						RCB-BJ-30	87-231			87-232	
	X	<u> </u>	X		<b> </b>		RCB-BJ-27	87-235				•
	X		x				RCB-BJ-31	87-236				
	Х		<u> </u>				RCB-BJ-33	87-237				
	X	<b>_</b>	X				RCB-BJ-35	87-238				
	X	•	x			 	RCB-BJ-41	87-239				
	X		X				RCB-BJ-44	87-240				
	x		X				RCB-BJ-46	87-241				
	X		X				RCB-BJ-3	87-417			87-419	
	x		X				RCB-BJ-9	87-421				
	x	<u> </u>	x				RCB-BJ-4	87-608				
	х						RCB-BK-45		87-557			
ecirc. Pump Loop "B" ypass	X				х		R88-BJ-1	87-233			87-234	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	*	0th	erw	ise	ASM	1E						

System or			*A	uam	entec	Weld or		T		Part E, Page	e 21 of 46
Component Description			0313	<u> </u>		Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle R <b>eport No</b> .	Penetrant Report No.	Comments
	Accent	Reject	NUREG 03			Other					
	X				x	RBB-BJ-8	87-611			87-596	
	X				Х	RBB-BJ-10	87-612			87-595	
ecirc. Manifold "B"	X		X			RMB-BJ-1	87-281			•	
	X		X			RMB-BJ-2	87-282				
	X					RMB-BJ-5	87-266		· ·	87-267	
	X		X			RMB-BJ-6	87 <b>-2</b> 83				
	X		X			RMB-BJ-7	87-284				· · · ·
	X		x			RMB-BJ-8	87-285				
	X	·	X			RMB-BJ-9	87-264				
	X		X			RMB-BJ-11	87-253				
	X		X			RMB-BJ-12	87-265-A				
	X		x	$\downarrow$		RMB-BJ-12	87-265-B				
•   •• • • •		-+	$\rightarrow$								
circ. Riser "A"	Х		$\downarrow$			RRA-BF-2	87 <b>-</b> 2 <b>42</b>			87-243	
•	X			$\bot$		RRA-BF-2	87-242-A				
	X					RRA-BF-2A	87-244			87-245	
	X					RRA-BJ-3	87-246				

-	
_	



Part E, Page 22 of 40

System or Component		*	Augm	mente	ad T	Weld or Component	Ultrasonic and Visual	Visual Report No.	Magnetic Particle Report No	Penetrant Report No.	Comments
Description		:	0313 0619	1		Description	Report No.		Report No.		
	Accept	Reject   NUREG 03	NUREG 03 NUREG 06	NUKEG 061 GL-84-11	Dther						
	X	X				RRA-BJ-4/ 4A-WOL	87-247-0°			87-248	
	X	x				RRA-BJ-4/ 4A-WOL	87-2 <b>4</b> 7-60°			87-638	
	X	X				RR <b>A-BJ-</b> 4/ 4A-WOL				87-656	
	X	+	$\uparrow$	1		RRA-BJ-5-IA	87-249			87-250	
	x	x		$\top$	$\Box$	RRA-BJ-5	87-251				
	X.	X	1	$\uparrow$		RR <b>A-</b> BJ-7	87-252				T.
		+	+	+	$\uparrow$						
Recirc. Riser "B"	×	x	$\langle \uparrow \rangle$	+	t	RRB-BF-2	87-254			87-255	
:	x	x	<b>1</b>	+	t	RRB-BF-2	87-254-A				
	x	$\uparrow$	+	+	$\uparrow$	RRB-BF-2A	87-256			87-257	
	x	· <b>†</b>	+	+	$\uparrow$	RRB-BJ-3	87-258				
	X	X		1		RRB-BJ-4/ J4A-WOL	87-259-0°			87-260	
	X	X	X		T	RRB-BJ-4/ J4A-WOL	87-259-60°			87-639	
	x	,,	x	+-	+	RRB-BJ-5	87-261	1			

C	·····	Τ.		 	T			rait E, rag	e 23 of 40	
System or Component Description			Augm 6190	ed	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Accept Refect	NUREC 0313		Other						
	X	X			RRB-BJ-7	87-263				
			<u> </u>							· ·
Recirc. Riser "C"	x	X			RRC-BF-2	87-270			•	
	X	X			RRC-BF-2	87-270-A			•	
	X	X			RRC-BF-2A	87-271				
	x	X			RRC-BJ-3	87-272				
	x	X			RRC-BJ-4	87-273				
	<b>X</b> .	X			RRC-BJ-4	87-273-I				· · · · · · · · · · · · · · · · · · ·
	x	x			RRC-BJ-4A	87-274				
	x -	x			RRC-BJ-5	87-420				
	X	x			RRC-BJ-7	87-275				
Recirc. Riser "D"	X	Х			RRD-BF-2	87-276				······
	X	x			RRD-BF-2	87-276-A				
	X	X			RRD-BF-2A	87-277				
	X	х			RRD-BJ-3	87-278				· · · · · · · · · · · · · · · · · · ·
	X	x			RRD-BJ-4/ J4A-WOL	87-268-0°			87-269	

1

-

											Part E, Pag	ge 24 of 4
System or Component		T	*	lugn	nent	ced	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description			0313	0619			Description	Report No.	No.	Report No.		
	Accept		NUREG 0		GL-84-11	Other						
	x		x				RRD-BJ-4/ J4A-WOL	87-268-60°	· · ·		87-640	
	х	Π	Х	Γ	Π	$\square$	RRD-BJ-5	87-279				
!	х		x	$\square$	Π		RRD-BJ-7-WOL	87-280-0V			87-418	Liquid Penetrant Report 87-641 is for PT
	x		x				RRD-BJ-7-WOL	87-280-0°			87-641	after weld preparation
:	X		X		$\Box$		RRD-BJ-7-WOL	. 87-280-45°				
RPV-Head Vent	x	 	<u> </u> _'	<u> </u>	$\vdash$	<b> </b>	HVA-BJ-2			87-287	+	
!	x	+.+	$\vdash$	$\vdash$		$\vdash$	N-7 Flg Bltg	1	87-288	+	+	
	x					F	N7-A Flg Blt		87-573		+	
Jet Pump Instrumentation	x		x		<u> </u> _'	╞	JPA-BF-2	87-434			87-435	
"A"	Х	+	X	$\square$			JPA-BF-2	87-434-A				
	X		X	<u> </u>			JPA-BJ-3	87-436			87-437	
Jet Pump Instrumentation "B"	x	+	x	+	+	╞	JPB-BF-2	87-438			87-439	
"В"	x	$\top$	X	$\uparrow$	$\left  \right $	$\top$	JPB-BF-2	87-438-A	1			

System or			*	Augr	nent	ted	Weld or	Ultrasonic	Visual	Magnetic	Part E, Page	Comments
Component Description	Accept	Reject	NUREC 0313		GL-84-11	Other	Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
:	X		X				JPB-BJ-3	87-440			87-441	
iquid Level Control	x						LCA-BK-6A		87 <b>-</b> 289		•	
	X						LCA-BJ-20				87-291	
	X						LCA-BJ-21				87-293	
essel Instrumentation	X X						LCA-BK-5A VIE-BF-2		87-294	·	87-295	· · ·
-16-A	Χ.						VIE-BJ-3				87-296	
ain Steam Drain - ommon	х						SDR-BJ-7	87-298		87-299		
	X						SDR-BM-1		87-708			MO-4424-VT-2




Part E, Page 26 of 46

System or Component			*A1	ugm	ente	ed	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description			13	19			Description		No.	Report No.		
	Accept	Reject	NUREG 0313	NUREC 0619	GL-84-11	Other						
a <mark>ss 2</mark> Systems												
R Heat Exchanger "A"	X		Ī				HEA-CA-3	87-333-L				Shell to Shell
	X						HEA-CA-3	87-333-5				Shell to Shell
	X						HEA-CC-7			87-334	****	
R Pump Suction (S.E.)	X						RHA-CE-42		87-598			DCP-1323 Preservice
~83~	X						RHA-CE-50		<b>8</b> 7-714			
1	X						RHA-CE-51		87-599			DCP-1323 Preservice
	X						RHA-CE-56		87-713			
R Pump Suction (N.E.)	X						RHB-CE-44		87-600			DCP-1323 Preservice
	X						RHB-CE-51		87-606			
	X						RHB-CE-57		87-658			
	X						RHB-CE-58		87-680			
	X						RH <b>B-</b> CE-50		87-682			
	X						RHB-CF-70			86-032		

							······				Part E, Pa	ge 27 of 🖤
System or Component Description			*/	Augi	men	ted	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
IR Pump Shutdown	Accept	Reject	NUREG 0313	1		Other						
HR Pump Shutdown	x						RHC-CF-82			87-335		
	X						RHC-CE-74		87-336			
	X	ŀ					RHC-CE-70	· · · · · · · · · · · · · · · ·	87-337			
	X						RHC-CF-47			87-338	•	
	x						RHC-CF-46			87-339		
	x						RHC-CF-43			87-340		
	x						RHC-CE-42		87-341			
	x	•					RHC-CE-38		87-342			
	х						RHC-CE-37		87-343			
	x	·					RHC-CE-34		87-344			
	x						RHC-CE-40		87-666			
	X						RHC-CE-31		87-667			
	X						RHC-CE-22		87-668			1







System or Component Description				*#	Augi	nent	ed:	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
				3	6			beschiption	Report No.	NO.	Report No.		
	_	Accept	Reject	NUREC 0313			Dther						
R Heat Exchanger													
eam Supply (SĔ/NW)	x							RHD-CE-12		87-605			DCP-1323 Preservice
	Γ	Τ						RHD-CE-10		87-345		•	
	X							RHD-CE-12		87-346			
	x							RHD-CE-13		87-716			Re-examination of RMD-CE-13
	Х							RHD-CE-19		87-347		······	
			·					RHD-CE-19	······	87-722			VT-3/VT-4
	X							RHD-CE-25		87-348			1
	X		•					RHD-CF-36			87-349		
	X							RHD-CF-37			87-350		
	X							RHD-CE-46		86-036		· · · · · · · · · · · · · · · · · · ·	
	X							RHD-CF-52	87-351		87-352		
	X	Τ						RHD-CE-57		87-353			
	X							RHD-CE-13A		87-604			DCP-1323 Preservice
	x							RHD-CE-27		87-715			



Part E, Page 29 of 46

.

System or Component Description	Accept	·	0313	0619	GL-84-11	her	Weld or Component Description	Ultrasonic and Visual Report No.	Visua] Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Х						RHD-CE-3		86-033			
	X						RHD-CE-5		86-034			
	х						RHD-CE-5			86-035		
											•	

\* Otherwise ASME

۰.

٠.

(continued next page)

System or		*Aug		ugme	ente	ed	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description			3	6			Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREC 0313		GL-84-11	Other						
R Pump Discharge (S.E.)	1	Re	NN	NN	GL		RHE-CE-49		87-354			
	x					-+	RHE-CE-43		07 334	07.255		
	x					-+	RHE-CE-16A		07.256	87-355		
	x								87-356		-	
							RHE-CE-7		87~357		•	
	Х				$\rightarrow$		RHE-CE-53		87-717			
R Heat Exchanger Scharge (S.E.)	Х						RHF-CF-127			87-358		
	X		]				RHF-CE-107		87-359	87-360		,
	x						RHF-CE-88		87-361	1		
	X						RHF-CF-79			87-362	·····	
	X	• •				F	RHF-CE-65		86-041			
	X					F	RHF-CE-52		87-363	87-364		
	X					F	RHF-CE-49		87-365	1 1		······································
	x					F	RHF-CE-72		86-043			
	X					F	RHF-CE-74		86-044			
· ·	x				1	4	RHF-CE-7		87-366			
	x			$\top$		R	RHF-CE-56		86-042			
	x					R	RHF-CE-52		87-424			
	X	Τ	T			R	HF-CE-92		87-560			

System or			*/	lug	nent	d Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description			3	9			and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREG 0313	NUREG 0619		Other					
	X					RHF-CE-81		87-561			
	X					RHF-CE-92		87-661			
	X					RHF-CE-98		87-662			
	X					RHF-CE-68		87-663		•	
	X					RHF-CE-38		87-683			
	X					RHF-CE-81		87-684			
	X					RHF-CE-119		87-685			
	Х					RHF-CD-18		87-693			MO-2030-Bolting
	Х					RHF-CE-118		87-677			DCP-1323-VT-3/4 Preservice
I	Х					RHF-CE-65		86-041			
	X					RHF-CE-56		86-042		,	
	X					RHF-CE-72		86-043			
	X					RHF-CE-74		86-044			
np Discharge (N.W.)	X					RHI-CE-56		86-037		······	
	Х					RHI-CE-73		86-038	86-039		
	X					RHI-CD-37		87-447			V-19-3, VT-2
	x				T	RHI-CE-52		87-718			

~

•						۲			Part E, Pag	e 32 of
System or Component Description	Accept Reject	EC 0313	REG 0619	GL-84-11 pate Other pate	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
RHR Heat Exchanger Discharge	X				RHJ-CD-17		87-643			MO-1940, VT-2
	X X				RHJ-CE-75 RHJ-CE-75		87-647 87-710		•	

۰.

1

ł

(continued on next page)

			·							Part E, Pag	e 33 of 4
System or Component Description					ente	d Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
	Accept	Reject	NUREG 0313	NUREG 0619	GL-84-11	Other					
	x					RHJ-CE-76		87-720			
	X					RHJ-CE-24		87-719			
	X					RHJ-CE-43		87-721			
										•	
HR Fuel Pool Cooling nd Cleanup	X					RHM-CE-9		87-562			
	X					RHM-CE-6		87-659			·····
	X					RHM-CE-11		87-660			
	x	• •				RHM-CE-21		87-601			DCP-1323 Preservice
PCI Pump Suction	x	•		_		HPA-CF-52	· · · · · · · · · · · · · · · · · · ·		87-367		
	х					HPA-CE-48		87-368		····	
	Х	-				HPA-CE-44		87-369			
-	X					HPA-CE-35		87-370			
PCI Pump Discharge	x					HPB-CE-72		87-623			
	x				-+-	HPB-CD-31		86-027			M0-2315 Repair-VT-2

										Part E, Pag	e 34 of
System or Component Description			*Aug	<u> </u>	1	Weld or Component Description	Ultrasonic and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
· ·	Accept	ke Ject	NUREG	GL-84-11	Other						
	X					HPB-CD-34		86-028		86-029	MO-2315 Repair-VT-2
	X					HPB-CF-32				86-045	MO-2315 Replacement
	X					HPB-CF-32	86-047				MO-2315 Replacement
	X					HPB-CF-32				•	MO-2315 Replacement 86-046-RT
	X					HPB-CF-32		86-049			VT-2
	x					11		86-050			VT-2
	X					"		86-051			VT-2
	X					"		86-053			VT-2
	X					EBB-7-1-2-FW	86-058			86-057	RT-86-059
1						х.					
HPCI Turbine Steam Inlet	X					HPC-CE-27		87 <b>-56</b> 3			
	X					HPC-CE-34		87 <b>-6</b> 46			
	Х					HPC-CE-59		87-657			
	Х					MO-2239		86-055		+	VT-2
	X					MO-2239		86-060			VT-3
		<u> </u>									
Core Spray Suction	X					CSA-CE-36		87-371			
	X					CSA-CE-33		87 <b>-3</b> 72			
	X					CSA-CE-20		87-373			
	+		•		-				. <del>.</del>		<b>.</b>

System or	[		*	Auan	ent.	d Weld or	Ultrasonic	Nie Z			
Component Description		T	0313	0619		Component Description	and Visual	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
****	Accept	Reject	NUREG 03	NUREG 06	GL-84-11	Other					
	х					CSA-CF-18			87-374		
Core Spray Discharge S.E.	X				-+	CSB-CE-48		87 <b>-3</b> 75			
	X					CSB-CE-35		87-376		•	
	X					CSB-CF-22			87-377		
:	Х					CSB-CE-17		87-378	·		DCP-1323 Preservice
	X					CSB-CE-13		87 <b>-3</b> 79	87-380		
	X					CSB-CE-11		87-381			
	X					CSB-CE-25		87-403			
	X	•			-+	CSB-CE-17		87-602			DCP-1323 Preservice
Core Spray Discharge S.E.	x					CSC-CE-3		87-382			
Core Spray Suction N.W.	X					CSD-CF-31		87-425			
	х					CSD-CE-33		86-040			





.

Part E, Page 36 of 46

System or Component				*A	ugm	ento	ed	Weld or Component	Ultrasonic and Visu <b>a</b> l	Visu <b>a</b> l Report	Magnetic Particle	Penetrant Report No.	Comments
Description				13	6			Description		No.	Report No.	Report No.	
		Accept	Reject	NUREG 031	NUREC 0619	GL-84-11	Other						
or <b>e Spray</b> Discharge N.W.)	- 315	Х						CSE-CE-50		87-603			DCP-1323 Preservice
	1	x						CSE-CE-26		87-648			···
ai <mark>n Steam Lo</mark> op "A"		Х						MSA-CF-3	87 <b>-3</b> 13		87-312		· · · · ·
		Х						MSA-CE-14		87-314			
		Х						MSA-CE-18		87 <b>-3</b> 15			
		Х						MSA-CE-21		87-316			
		Х						MSA-CF-22	87-318		87-317		
		Х	•					MSA-CF-39			87-319		
		Х						MSA-CF-39			87-671		
ai <b>n Stea</b> m Loop "B"		Х						MSB-CE-17		87-320			
		Х						MSB-CE-21		87-321			
		Х						MSB-CE-23	······································	87-322			
		х						MSB-CF-34			87-616		
	-	х						MSB-CF-35			87-669		



# Part E, Page 37 of 46

System or Component			*	Aug T	nent	ted I	Weld or Component	Ultrasonic and Visual	Visual Report	Magnetic Particle	Penetrant Report No.	Comments
Description		- <b>-</b>	0313	0619	1		Description	Rep <b>o</b> rt No.	No.	Report No.		
	Accept	Refect	NUREC 0	NUREG 0	GL-84-11	Other						
Main Steam Loop "C"	X						MSC-CF-39			87-630	······································	
	X	ļ					MSC-CF-39			87-711		
Main Steam Loop "D"	x						MSD-CF-34			87-629	•	
	x						MSD-CF-34			87-670		
Main Steam Bypass	x						MSE-CE-31		<b>87-3</b> 23			
	x						MSE-CE-25	**************************************	87-324			
	X			:			MSE-CF-14	87-325		87-326		<u> </u>
	X						MSE-CF-20	87-327		87-328	·	
	X						MSE-CF-7			87-329		
	X						MSF-CE-9		87-330			
	X						MSF-CF-29	87-332		87-331		
Sc <b>ram Discharge Hea</b> der (South)	x				$\rightarrow$		SDS-CE-13A		87-383		·····	Examinations were per-
(souch)	X						SDS-CE-12A		87-384		·····	formed before modifica tion of the Components Supports

\* Otherwise ASME

Į.

.

	1
	1
-	



## Part E, Page 38 of 46

· .

System or Component	T	<u> </u>	*	lugr	ment	ted	Weld or Component	Ultrasonic and Visual	Visual	Magnetic	Penetrant	Page 38 of 46 Comments
Description			6		۲		Description	Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Accept Reject	Keject   NUREG 0313		GL-84-11	Other	0,0,0,0					
	X						SDS-CF-1	87-385		87-386	[]	
	X						SDS-CF-3	1		87-387	/	
	X						SDS-CE-13A	1	87-694	++		Preservice **
	X		<u> </u>		$\Box'$		SDS-CE-10A	1	87-695			Preservice **
	X		$\perp$		$\Box$		SDS-CE-12A		87-696	1		Preservice **
	X	<b> </b> '		 			SDS-CE-9A		87-697	1	+	Preservice **
	X	<b>↓</b> '		<u> </u> '			SDS-CE-7A		87-698	1	+	Preservice **
I	X	•• ! 		<b>└</b>			SDS-CE-7B		87-699	1 1		Preservice **
I	X	<u>↓</u> _!	$\downarrow$	<b>↓</b> _′	$\bigsqcup$	Ц	SDS-H-22		87-706			New Support-Preservice
I		<u> _</u> '	Ш		Ц	$\square$	L			-		
Cram Discharge Header North)	X	$\square$	$\bigsqcup$		Ц	Ц	SDN-CE-9B		87 <b>-3</b> 88			Examinations were
	X						SDN-CE-9A		87-389			performed before modifications of the Component Supports
	x						SDN-CE-9B		87-700			Preservice **
	X		$\square$				SDN-CE-12B		87-701			Preservice **
	X		$\square$	]	$\square$	!'	SDN-CE-9A		87-702			Preservice **
	X					!	SDN-CE-12A		87-703			Preservice **

\* Otherwise ASME
\*\* (after modification)



Part E, Page 39 of 46

---

System or Component		*	Augr	nent	ted	Weld or Component	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Description		0313	0619			Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept Reject	NUREG 0	NUREG 0	GL-84-11	Other						
	Х					SDN-CE-6B		87-704			Preservice **
	x		_			SDN-CE-6A		87-705			Preservice **
	X		$ \rightarrow $		$\square$	SDN-H-23		87-707		•	New Support-Preserv
				_	$\downarrow$						
					_						
		_			-+						
	┝╌┽╌┽				-						
	┝─┿─┼				+						
- 1 	┝╌┼╌┼			+							
	┝╌┾╌┾			+	+						
		-		+	+						
	┝╌┼╌┼	+			+-						
			+		+						

\* Otherwise ASME \*\* (after modification)

System or			*A	ugme	ente	d	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Component Description		<b>.</b>	0313	0619			Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	
	Accept	Reject	NUREG 0		GL-84-11	Other						
RD Housing Flange Welds	X						1T-221(12)-D		87-458			VT-2
	Х						1T-221(07)-D		87-459			VT-2
	Х						1T-221(82)-D		87-460			VT-2
	Х						1T-221(59)-D		87-461		•	VT-2
	х						1T-221(10)-D		87-462			VT-2
	х						1T-221(46)-D		87-463		****	VT-2
	x						1T-221(45)-D		87-464			VT-2
	X						1T-221(33)-D		87-465		· · ·	·VT-2
1	х						1T-221(05)-D		87-466			VT-2
	x	•					1T-221(75)-D		87-467			VT-2
	X						1T-221(11)-D		87-468			VT-2
	х						1T-221(72)-D		87-469			VT-2
	Х						1T-221(47)-D		87-470			VT-2
	x						1T-221(48)-D		87-471			VT-2
	х						1T-221(31)-D		87-472			VT-2
	Х						1T-221(85)-D		87-473			VT-2

1

.



# Part E, Page 41 of 46

System or Component			*Au	Igme	ente	ed	Weld or Component	Ultrasonic	Visual	Magnetic	Penetrant	Comments
Description			13	9			Description	and Visual Report No.	Report No.	Par <b>t</b> icle Report No.	Report No.	
	Accept		NUREG 0313	NUREG 0619	GL-84-11	Other						
	х						1T-221(64)-D		87-474		· · · · · · · · · · · · · · · · · · ·	VT-2
	x						1 <b>T-221(37)-D</b>		87-475			VT-2
	X						1T-221(23)-D		87 <b>-</b> 4 <b>76</b>		•	VT-2
	X						1T-221(36)-D		87-477			VT-2
	X						1T-221(17)-D		87-478			VT-2
	X						1T-221(58)-D		87-479			VT-2
	X						1T-221(87)-D		87-480			VT-2
	X						1T-221(44)-D		87-481			VT-2
	X	·					1T-221(04)-D		87-482			VT-2
	X						1T-221(68)-D		87-483			VT-2
	X						1T-221(70)-D		87-484			VT-2
	X						1T-221(06)-D		87-485			VT-2
	X						1T-221(29)-D		87-486			VT-2
-27	X						1T-221(54)-D		87-487			VT-2
:	x						1T-221(14)-D		87-488			VT-2
	x						1T-221(35)-D		87-489			VT-2

\* Otherwise ASME

т



# Part E, Page 42 of 46

System or Component			*A	ugm	ent	ed	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	
Description	Accept	Reject	NUREC 0313	1	=	Other	Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	Comments
t.	X						1T-221(84)-D		87-490		······································	VT-2
	X						1T-221(63)-D		87-491			VT-2
	X						1T-221(19)-D		87-492			VT-2
	X						1T-221(21)-D		87-493		•	VT-2
	X						1T-221(20)-D		87-494			VT-2
	X						1T-221(56)-D		87-614			VT-2
	X						1T-221(56)-D		87-650	1		VT-2
Mounting Flange	x						1T-221(12)-D		87-495			VT-1
	x						1T-221(07)-D		87-496	<u> </u>		VT-1
	x	• •		T			1T-221(82)-D		87-497			VT-1
	- x						1T-221(59)-D	·	87-498			VT-1

\* Otherwise ASME

stem or				*A1	Jgme	ente	d Weld or	Ultrasonic	Visual	Magnetic	Part E, Pag Penetrant	Comments
Component Description				0313			Component Description	and Visual	Report No.	Particle Report No.	Report No.	comments
		Accept	Reject	NUREG 0	NUREG 06		Other					
		X					1T-221(10)-	D	87-499			VT-1
		X					1T-221(46)-	D	87-500			VT-1
		X					1T-221(45)-	D	87-501			VT-1
		X					1T-221(33)-	D	87-502		•	VT-1
		х					1T-221(05)-	D	87-503			VT-1
		X					1T-221(75)-	D	87-504		······································	VT-1
		X					1T-221(11)-	D	87-505		<u></u>	VT-1
	1	X			-		1T-221(12)-	D	87-506		· ·	VT-1
		X					1T-221(47)-	D	87-507			VT-1
		Х	·				1T-221(48)-	D	87-508			VT-1
		X					1T-221(31)-	D	87-509			VT-1
		Х					1T-221(85)-	D	87-510			VT-1
		Х					1T-221(64)-	D	87-511			VT-1
		X					1T-221(37)-	D	87-512			VT-1
		X					1T-221(23)-	D	87-513			VT-1
		х					1T-221(36)-1	D	87-514			VT-1

ystem or			*Au	ıgmer	nted	Weld or	Ultrasonic	Visual	Magnetic	Penetrant	Comments
omponent escription	Accent	Reject	NUREG 0313	REG	GL-84-11 Other	Component Description	and Visual Report No.	Report No.	Particle Report No.	Report No.	Comments
	X		╞╼╽			1T-221(17)-D		87-515			VT-1
	x					1T-221(58)-D		87-516			VT-1
-	X					1T-221(87)-D		87-517		······	VT-1
:	х					1T-221(44)-D		87-518	++	•	VT-1
	x					1T-221(68)-D		87-526			VT-1
	x					1T-221(04)-D		87-527			VT-1
	X					1T-221(70)-D		87-528			VT-1
	X					1T-221(06)-D		87-529			VT-1
	x					1T-221(29)-D		87-530			VT-1
	X					1T-221(54)-D		87-531			VT-1
	X					1T-221(14)-D		87-534			VT-1
	X					1T-221(35)-D		87-535			VT-1
	X					1T-221(84)-D		87-536			VT-1
	x					1T-221(63)-D		87-537			VT-1
	X	$ \rightarrow $				1T-221(19)-D		87-538			VT-1
	X					1T-221(21)-D		87-539			VT-1

System or		Γ		*A	uam	ente	ed	Weld or	Ultrasonic	Nine 3		Part E, Pa	1
Component Description	1	Accept	Reject	313	0619	11	Other	Component Description	and Visual Report No.	Visual Report No.	Magnetic Particle Report No.	Penetrant Report No.	Comments
		X						1T-221(20)-D		87-540	1		VT-1
		X						1T-221(56)-D		87-613			VT-1
		×						1T-221(56)-D		87-649		•	VT-1
												· · · · · · · · · · · · · · · · · · ·	
D Hydraulic cumulators		X						1 <b>S-220(</b> 01)		87-541			VT-2 HCU Unit 02-27
		X						1 <b>S-2</b> 20(03)		87-542			VT-2 HCU Unit 06-35
		X	•.					15-220(09)		87-543			VT-2 HCU Unit 18-03
		Х						18-220(51)		87-544			VT-2 HCU Unit 18-11
		X						15-220(11)		87-545			VT-2 HCU Unit 18-35
		X						15-220(76)		87-546			VT-2 HCU Unit 20-07
		X					1	18-220(55)		<b>87-</b> 547			VT-2 HCU Unit 22-19







### Part E, Page 46 of 46

System or Component Description

;

1

\*Augmented Weld or Ultrasonic Visual Magnetic Penetrant Comments Component and Visual Report Particle Report No. Description Report No. No. Report No. NUREC 0619 NUREC 0313 GL-84-11 Accept Reject Other Х 1**S**-220(33) 87-549 VT-2 HCU Unit 22-31 X 1S-220(37) 87-550 VT-2 HCU Unit 30-19 . Х 1**S**-220(61) 87-551 VT-2 HCU Unit 30-39 Χ 1S-220(21) 87-552 VT-2 HCU Unit 34-27

\* Otherwise ASME

٠.

INSERVICE INSPECTION REPORT November 1, 1985 through June 29, 1987

ł

. . .

:

. . \_\_\_\_\_

Part F - ISI FIGURES & ISOs







Figure No. 1.1-2



Part F, Page 2 of 60





HOLLEVALION




IOWA ELECTRIC LIGHT AND BUANE AMOUD ENERGY CENTER POWER COMPANY

> Part ч -Page **Ω**ω of **7**8








### IOWA ELECTRIC LIGHT AND FUWER COMPANY DUANE ARHOLD ENERGY CENTER





#### DUANE ARHOLD ENERGY CENTER






















5.18c 60 Cana Runne lo





















Ceono Rivide Ion










## OUANE ARHOLD ENERGY CENTER











2 ENUNOV cone.




HEAD VENT HVA-CS, 4" ISO. NO. <u>1.2-24</u> (REPLACES DWG 24 AND 124)



JET PUHP INSTRUMENTATION "A" JPA-SS, 4" Iso. No. 1.2-25 (REPLACES DWG = 25 AND 125)


81-438, 87-438, 87-439 NBB F2 D1 J3+ (37-440, 87-441)

JET RHP INSTRUMENTATION "B" JPB-SS Iso. No. <u>1.2-26</u> (REPLACES DWG 26 AND 126)



. DENOTES NONVELDED


FSK-37346 3992




VESSEL INSTRUMENTATION NIGA VIE-SS


.


Iso. No. <u>1.2-33</u> (REPLACES DWG 13 AND 133)



## CEDER REPIDE IONE











Part 7; Page  $\frac{3}{6}$ 0 60


• •














CIDA MARIDI


. \_\_\_\_\_ ...






RATION









Part 46 of 60

<u>т</u> Page







60

Ż

٠






;

WELD NO. PREFIX_	<u></u>
LINE SIZE 4 A	12-
MATERIAL CARBON	STEEL


ISO. NO. 2.2-50 (REMALES DUE SO AND 250)

2


K.....




ĝ



LEDNA KATO




.....



Came Rusios I

Q

60



Came Rusipe los

