CCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8911270084 DOC.DATE: 89/11/10 NOTARIZED: NO DOCKET # FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331 AUTH.NAME AUTHOR AFFILIATION PROBST, J.R. Iowa Electric Light & Power Co. HANNEN, R.L. Iowa Electric Light & Power Co. RECIPIENT AFFILIATION RECIP.NAME SUBJECT: LER 89-013-00:on 890915, MSIV have unacceptable leak test results due to misalignments & excessive clearances. ltr. W/8 DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR ENCL SIZE: TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc. NOTES: RECIPIENT COPIES RECIPIENT COPIES ID CODE/NAME ID CODE/NAME LTTR ENCL LTTR ENCL PD3-3 LA 1 1 PD3-3 PD 1 1 HALL, J.R. 1 1 AODO MEQUELCON MODITIED

INTERNAL	ACRS MICHELSON	T	T	ACRS MOELLER	2	2	
	ACRS WYLIE	1	1	AEOD/DOA	1	1 `	
	AEOD/DSP/TPAB	1	1	AEOD/ROAB/DSP	2	2	
	DEDRO	1,	1	NRR/DEST/ESB 8D	1	1	
	NRR/DEST/ICSB 7	1	1	NRR/DEST/MEB 9H	1	1	
•	NRR/DEST/MTB 9H	1	1	NRR/DEST/PSB 8D	1	1	
	NRR/DEST/RSB 8E	1	1	NRR/DEST/SGB 8D	1	1	
	NRR/DLPQ/HFB 10	. 1	1	NRR/DLPQ/PEB 10	1	1	
	NRR/DOEA/EAB 11	1	1	NRR/DREP/RPB 10	2	2	
	NUDOCS-ABSTRACT	1	1	REG_FILE 02	1	1	
	RES/DSIR/EIB	1	1	RGN3 FILE 01	1	1	•
EXTERNAL:	EG&G WILLIAMS.S	. 4	4	L ST LOBBY WARD	1	1	
	LPDR	1	1	NRC PDR	1	1	
	NSIC MAYS,G	1	1	NSIC MURPHY, G.A	1	1	
	NUDOCS FULL TXT	1 .	1	··· ·			

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL 38

F

I

E

S

1

A

Γ

Γ

ć

R

ł

Ľ

S

Α

D

D

S

November 10, 1989 DAEC-89-0793

Mr. A. Bert Davis Regional Administrator Region III U. S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

> Subject: Duane Arnold Energy Center Docket No: 50-331 Op. License DPR-49 Licensee Event Report #89-013

Gentlemen:

In accordance with 10 CFR 50.73 please find attached a copy of the subject Licensee Event Report, submitted for information.

Very truly yours,

Rick L. Hannen Plant Superintendent - Nuclear

RLH/JRP/gt

cc: Director of Nuclear Reactor Regulation Document Control Desk .U.S. Nuclear Regulatory Commission Mail Station P1-137 Washington, D. C. 20555

NRC Resident Inspector - DAEC

File A-118a

8911270084 891110 FDR / ADOCK 05000331

NRC For (9-83)	m 366	,		_			LIC	ENSE	E EVE		EPO	RT	(LER)	U.S. NI	APP EXP	AR REGULA ROVED OM IRES: 8/31/8	TORY CO B NO. 315 B	DAMAISSION 0-0104
FACILIT	Y NAME (1	1)						<u>.</u>					Ic		(2)		· · · · · ·	PAGE (3)
Duai	ne Ar	nold	Fne	rav	Center	۲)	AFC)							0 15 10 10	10	13131	1 1	0F1017
TITLE ("Main	Stea	um Is	sola	ition Va	alv	es Ha	ave U	nacce	ptab	le	Lea	k Test Re	sults Du	e	to Mis	alig	ments.
	Exce	ssive	e C1e	eara	nces a	nd	Valve	e Ori	entat	ion								
E۷	ENT DATE	(5)		L	ER NUMBER	6)		RE	PORT DAT	TE (7)			OTHER	FACILITIES INVO	LVE	(8) C		
MONTH	DAY	YEAR	YEAP		SEQUENTIAL NUMBER		NUMBER	MONTH	DAY	YEAR			FACILITY NAN	AES	000	CKET NUMB	ER(S)	
													None	<u></u>	0	15 0	0 0	
09	1 5	89	8 9) [0 1 3	-	00	1 1	10	89					0	15101	0 0	
OP			THIS P	EPORT	IS SUBMITTE	D PU	RSUANT	TO THE R	EOUIREM	ENTS OF	0 CFF	∎ §: /(Check one or more o	of the following) (1	11			
M	00E (9)	<u> </u>		10.402(6))			20,405	(c)				50.73(a)(2)(iv)			73.71(b)		
POWE LEVE		o 'o		0,405 (a	0(1)(i)			50.36(c)(1)				50,73(a)(2)(v)			73.71(c)		
(10)		010		10.405(a	()(1)(ii)			50.38(c)(2)				50.73(a)(2)(vii)		<u>X X</u>	OTHER /S	pecify in in Text, i	Abstract VRC Form
				10.405(a	HTRail)		-	50,73(a)(2)(i)				50.73(a)(2)(viii)(A	A)		366A)		
			\vdash	10.405 (a	7(4.75-) 3(1.1(14)			60.73(a	1(2)(#)				50.73(a)(2)(viii)(8	1)	+(JR INF	ORMA	IION
		<u>Christian - U</u>	1 1				<u> </u>	ICENSEE	CONTACT	FOR THU	IFR	(12)	60.73(a)(2)(X)			•		
NAME															TEL	EPHONE NU	MBER	
														AREA CODE				
Jame	es R.	Prob	st,	Tec	hnical	Su	pport	: Eng	ineer	•				3119	8	5111	-171	31018
	·				COMPLETE	ONE	LINE FOR	EACH CO	MPONEN	T FAILURI	OES	CRIBE	O IN THIS REPOR	T (13)				
CAUSE	SYSTEM	СОМРО	DNENT	м	TUREP	REPO	NPRDS			CAUSE	SYS	тем	COMPONENT	MANUFAC. TURER	R	EPORTABLE		tali Stali
Х	S _I B	I	<u> </u> S \	R	3 4 4		Y			В	S	B	I I S I V	R ₁ 3 ₁ 4 ₁ 4		Ŷ		
Х	SIB	ļΙ	S \		3 4 4		Y					1			T	-		
					SUPPLEME	NTAL	REPORT	EXPECTE	D (14)		-	±				MONT	- DAY	YEAR
YE	5 //f yes, co	omplete E.	XPECTE	D SUBN	ISSION DATE	J		X	7 ~0				<u></u>	SUBMISSI DATE 11	0 0N 51			
ABSTRAC	CT (Limit t	o 1400 sp	eces - e		imetery fifteen	single	SDACE THDE	written un	es/ (16)						<u> </u>	<u>-</u>	<u></u>	
	Duri on t prob Regu esta did test caus due b) e valva alio	ng a hree lems lator blis not r ing, es we to a xcess e's (rec Mai , in ry C hed ere sli sive 35 d	ent n Si omm crit the ibit four ght cle egre	plant i team Is cordanc ission. teria, e leaka ted exc misali earance e cant	mai ola e v f the ge ess e: gnm be ed	ntena ation vith s on crit sive a) nent etwee orie	ance Valv discu e of ainin eria, leaka incor of th n the ntati	outag ves (1 ussion the f g fiv and uge du rect e val on wh conta	ye, Lo MSIVs ns be three e MSI a th uring seat lve bo nich n ct wa) d twe Vs ird co re nak	l Lo en lve wer sec nta wi and es	eak Rate to previo Iowa Elec tested re also te which had cond test to t with 1 th respect valve in it more s	Testing w bus perfo tric and failed t sted. A passed t six days ack of c t to the ternals, usceptib	as rma tl or sec he la onc va ar le	perfo ance he Nuc neet t cond v initi ater. centrin alve so id c) to	rmed lear he alve al The city eat, the	

alignment problems. Only partial contact was noted at the top of the seat upon disassembly for this valve. Corrective actions taken included re-machining of valve discs and seats and installation of oversized internals. Long term upgrades to all MSIVs are planned for the 1990 refueling outage.

This LER is being submitted for information only.

NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (9-83)LICENSEE EVENT REPORT (LER) TEXT CONTINUATION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88 FACILITY NAME (1) DOCKET NUMBER (2) LER NUMBER(6) PAGE(3) SEQUENTIAL NUMBER REVISION NUMBER YEAR 0 5 0 0 0 3 3 1 8 9 Duane Arnold Energy Center 013 2 OF 7 00 TEXT (If more space is required, use additional NRC Form 366A's) (17) I. DESCRIPTION OF EVENT: On September 15, 1989, the plant was in cold shutdown to perform Main Steam Isolation Valve (MSIV) (EIIS System and Component Codes SB-ISV) Local Leak Rate Testing. In accordance with previous discussions between Iowa Electric and Nuclear Regulatory Commission Region III personnel, three MSIV's were to be tested initially. If any of these valves were found to have leakage exceeding the 11.5 Standard Cubic Feet per Hour (SCFH) specified in Technical Specification 4.7.A.2.c.3 for Type C tests, the remaining five MSIV's would also be tested, and corrective actions would be taken as appropriate. The tests were performed by pressurizing one side of a valve or valve(s) with air, and then monitoring the amount of air required to maintain the given pressure. The highest leak rate over a fifteen minute period was considered the as-tested leak rate. TEST RESULTS The three valves to be tested were CV4412 - the "A" Inboard MSIV, CV4413 - the "A" Outboard MSIV, and CV4419 - the "C" Outboard MSIV. Date: September 15, 1989 Acceptance Location As Tested Valve(s) Criteria SCFH SCFH CV4412 "A" Inboard & < 11.5 per valve "A" Outboard CV4413 < 5.3 total --combination test--CV4419 "C" Outboard < 11.5 25.4 SCFH = Standard Cubic Feet per Hour of Air Because CV4419 exceed the maximum leakage standard, the remaining five MSIVs were also tested: Date: September 16, 1989 Acceptance Valve(s) Location Criteria As Tested SCFH SCFH "B" Inboard CV4415 < 11.5 9.4 "B" Outboard CV4416* < 11.5 >173.7

NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (9-83)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88

FACILITY NAME (1)			DOCKET NUMBER (2)						LER NUMBER(6)							3)			
											YE	AR		SEQUENTIAL NUMBER		REVISION NUMBER			
Duane Arnold Ene	rgy Ce	nter	•	0	5	0 0	0 0	3	3 3	1	8	9	-	013	-	00	3	0F	7
TEXT (If more space is required, L CV4418	use addition "C"	nal NRC Form 366A's) (17) Inboard) <	11	. 5							4.	2				•	-	
CV4420	"D"	Inboard	<	11	. 5						·	6.	3						
CV4421	"D"	Outboard	<	11	.5							3.	7						

*A single stroke of CV4416 reduced the leakage to 7.8 SCFH

Corrective maintenance was subsequently performed on the two valves which failed the initial LLRTs. The main seat and disc were ground for a better fit on the "C" Outboard (CV4419) and internals on the "B" outboard (CV4415 were replaced. Post maintenance tests were performed with the following results.

Valve(s)	Location	Acceptance Criteria	As Tested	
		SCFH	SCFH	
CV4415	"B" Inboard	< 11.5	32.6-37.9	
CV4416	"B" Outboard	< 11.5	1.25	
CV4419	"C" Outboard	< 11.5	3.4	

Maintenance was then performed on the "B" inboard valve (CV4415), which, after passing its initial test, had failed a second test (being performed in combination with CV4416 by pressurizing between them). CV4415 had its main seat and disc ground. The "B" inboard valve was then tested alone, from the reactor side, by pressurizing the reactor vessel:

Valve(s)	Location	Acceptance Criteria	As Tested	
		SCFH	SCFH	
CV4415	"B" Inboard	< 11.5	1.0	

II. CAUSE OF EVENT:

A. CV4419 - "C" Outboard MSIV:

Upon testing on September 15th, this valve had an as-found leakage of 25.4 SCFH versus the maximum allowable leak rate of 11.5 SCFH. Subsequently, the valve's packing was adjusted and it was stroked, but no significant change in leak rate was noted. The valve was disassembled and inspected. No misalignment of the valve topworks or NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (9-83)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88

FACILITY NAME (1)		DOCKET NUMBER (2)						LER NUMBER(6)							PAGE(3)			
									YEA	۲ [Ι	SEQUENTIAL NUMBER		REVISION NUMBER				
Duane Arnold Energy Center	0	5	0	0	0	3	3	1	8	9	-	013	-	00	4	0F	7	
TEXT (If more space is required, use additional NRC Form 366A's) (17)								•		_								

actuator was observed. Inspection of the valve seat indicated a runout of 0.007 inches, versus a maximum acceptable value of 0.0035 inches. The pattern on the seat indicated the disc was hitting high on the bore (upward angle from the centerline), a conclusion corroborated by examination of the seat contact line on the disc and valve seat.

The primary cause of the failure of CV4419 to pass its LLRT test was incorrect seat contact, with lack of concentricity a contributing factor. Examination of the valve indicated the root cause of the leakage was a slight misalignment of the valve bore with respect to the valve seat, although the interaction of numerous moving components might also have contributed to the problem.

B. CV4416 - "B" Outboard MSIV:

CV4416, the "B" Outboard MSIV had an as-found leakage of greater than 173.7 SCFH. The valve was stroked, with leakage being reduced to 7.8 SCFH, below the maximum allowable value of 11.5 SCFH. The valve was disassembled for further inspection. Inspection of the valve seat indicated a 0.004 runout versus the acceptable value of 0.0035 inches. The valve seat pattern indicated the disc was hitting parallel to the centerline but shifted to one side. This lateral misalignment did not appear to be enough to prevent a good contact line from forming between the disc and valve seats. Measurements indicated that the disc to bore clearance, although in the middle of the manufacturer's recommended range, was larger by approximately 0.004 inches than that of any other MSIV.

Because CV4416 passed subsequent tests after stroking it is possible that the valve had something on its seat that prevented initial full closure, or that frictional forces played a factor, or that the valve clearances were open enough for it to seat differently during various cycles. Examination of the valve found some evidence of a foreign body in the form of scratches in the seat and disc, but neither appeared to be very deep and no particles were found in the valve body. Oxidation buildup and packing load were no different than normally experienced, indicating the frictional possibility unlikely. The valve bore was found to have a ridge at the top of the bottom rib, which may have affected the initial start of the stem travel. From the investigation into the problems with CV4416, it appears the most likely root cause of it failure to pass LLRT on the initial closure was excessive clearance between the valve bore and the valve internals.

C. CV4415 - "B" Inboard MSIV:

CV4415, the "B" Inboard MSIV, successfully passed its initial LLRT on September 16th with an as-found leak rate of 9.4 SCFH when tested in combination with CV4416, the "B" Outboard MSIV. Six days later, following repairs to CV4416, CV4415 was again tested in combination with NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (9-83)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88

FACILITY NAME (1)	•	DOCKET NUMBER (2)	LE	RN	UMBER(6)	·			PAGE(3)
			YEAR		SEQUENTIAL NUMBER		REVISION NUMBER			
Duane Arnold Energy Center	н И	0 5 0 0 0 3 3 1	89	-	013	-	00	5	OF	7

CV4416. CV4415 had not been cycled or worked on. At that time, leakage of 32.6 to 37.0 SCFH was noted for CV4415, versus the allowable maximum of 11.5 SCFH.

CV4415 was disassembled and inspected. This MSIV is canted 35 degrees clockwise, and a review of past history indicated this might be a reason for excessive leakage. The fact that the test CV4415 failed was performed with the valve "cold" (six days after the initial testing) also is believed to be a factor, as is the conservative nature of the test, which applied air pressure to the "outboard" side of the valve. The MSIVs are constructed so that reactor steam pressure against the "inboard" side of the valve will enhance the seating force. The valve seat was found to have a runout of 0.005 inches, versus the acceptable 0.0035 inches. Measurement of the valve bore and disc/piston assembly show the clearances are still at minimum clearances. The valve disc was found to be hitting low at the bottom of the bore, which is consistent with the valve's orientation. Good seat contact was observed on the bottom of the seat, but only partial contact at the top. The root cause of the failure of CV4415 to successfully pass an LLRT is the valve orientation itself, which results in the travel path of the internals not being in the bore centerline. Testing of the valve "cold" may have also been a factor in the markedly changed test results.

III. ANALYSIS OF EVENT:

Local Leak Rate Testing of the MSIVs in 1989 found that upon initial testing, two of the eight MSIVs had leak rates in excess of the required 11.5 SCFH. (The "C" outboard and the "B" outboard). The initial LLRT's demonstrated that each of the four steam lines had at least one of its two redundant MSIV's capable of maintaining the total leakage rate under the required 11.5 SCFH. Subsequently, excess leakage was noted through the "B" inboard valve six days later. A significant factor in this second test of the "B" MSIVs was the cooling down of the closed "B" inboard valve. The initial testing of the valve in the "hot" condition shortly after shutdown is considered a better indication of what the valve's performance would have been under real conditions.

IV. CORRECTIVE ACTION:

In addition to the specific corrective actions noted for each valve, MSIV upgrades to be undertaken during the 1990 refueling outage will also aid in preventing recurrence of leakage problems. These are discussed in Section IV.(D).

A. CV4419 - "C" Outboard MSIV:

In order to ensure proper sealing of the CV4419 ("C" Outboard MSIV) the valve disc and seat were re-machined. The valve was not re-bored as the

NRC Form 366A U.S. NUCLEAR REGULATORY COMMISSION (9-83)

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/88

,

FACILITY NAME (1)	DOCKET NUMBER (2)	LE	RN	UMBER(6)				PAGE(3)
		YEAR		SEQUENTIAL NUMBER		REVISION NUMBER			
Duane Arnold Energy Center	05000331	89	-	013	-	00	6	0F ⁻	7
TEXT (If more space is required, use additional NRC Form 366A's) (17)									

extent of leakage was only slightly over twice the maximum allowable and it was felt the effect of machining would be marginal because of the small amount of metal to be removed. The re-testing of the valve at 3.4 SCFH versus the maximum allowable value of 11.5 SCFH required demonstrated the effectiveness of corrective actions. As an additional corrective action, the bore of this valve will be re-machined during the upcoming refueling outage as part of IV.(D).

B. CV4416 - "B" Outboard MSIV:

The ridge on the valve bore was smoothed. The valve internals were oversized to reduce clearance and the valve and disc seats were re-machined. These actions were proven effective by the subsequent test results of 1.25 SCFH versus the required 11.5 SCFH. The bore of this valve will be re-machined during the upcoming refueling outage, which should aid in reducing any concentricity problems.

C. CV4415 - "B" Inboard MSIV:

Immediate corrective actions were to re-machine the valve disc and seat to within acceptable runout values. Retesting of this valve following its reassembly indicated an as-left leakage of 1.0 SCFH versus the required 11.5 SCFH. Additional upgrades planned for the 1990 refuel outage (see Section IV.(D)) are expected to provide adequate long-term compensation for the values's orientation.

D. Additional Long-Term Corrective Actions:

Upgrades to all the MSIVs to be performed next outage should provide additional long-term corrective actions. Short guide pads will be added to provide local guiding as the disc enters the seat. Harder valves stems will be installed to reduce stem galling. A stiffer top works assembly to be provided will aid in preventing misalignments during valve closure. The new, lighter one piece (versus two) disc/piston assembly to be installed should reduce inertial forces during valve closure, and also help minimize cocking of the valve internals by moving their center of gravity. A larger actuator and stronger springs will be installed, which will increase seating force and minimize the likelihood of a valve seating differently upon subsequent stroking.

V. ADDITIONAL INFORMATION:

A. Failed Component Identification

The MSIVs are 20X16X20 inch Y-pattern stop valves built by the Rockwell Manufacturing Company, Figure No. 1612 JMMNY.

NRC FORM 366a (9-83)

APPROVED OMB NO. 31 EXPIRES: 8/31/88	50-0104	CENSEE EV	ENT RE	PORT	(LER) 1	EXT	COI	NTINU	ATI	ON				
FACILITY NAME (1)			-	DOCKET	NUMBER	(2)		LE	RNU	MBER(6)			PAGE((3)
Duane Arnold Fu	nerav (en	tor			nlolol	3 3	1	YEAR		NUMBER				7
TEXT (If more space is require	d, use additional	NRC Form 366A's)	(17)			5 5	1	0)	LI,	015				
B. Prev	ious Simi	ilar Event	S			•								
The Duan allowabl have bee Electric	e Arnold e leakage n reporte 10 CFR 5	Energy Cen e through l ed via LER 50 submitt	nter ha MSIV's s 85-0 al (NG	as, in durin 105, 87 1-89-07	the p ig loca 7-005 723).	ast, al le Rev 1	ex ak , a	perien rate nd in	nce tes tł	d grea sting. ne 1988	ter Tł Id	than nese owa		
Regardin in the f results	g the val ive previ were note	lves which ious LLRTs ed:	were (1981	repair , 1983	ed fo 9, 198	llowi 5, 19	ng 87,	the r 1988	ece) t	ent tes the fol	tir lov	ng, ving	,	
CV4419:	Passed i & 1988	in 1983 & 1	1987,	failed	l to me	eet c	rit	eria.	in	1981,	198	85		
CV4416:	Passed i	in 1985, 19	987 &	1988,	failed	t to	mee	t cri	ter	ria in	198	31		
CV4415:	& 1983 Passed i & 1988	in 1981, fa	ailed	to mee	t crit	eria	in	1983	, 1	985, 1	987	7		
Leakage	values ir	SCFH.		• .										
This LER	is being	g submitted	d for	inform	ation	only	•							
										•			·	
												•		
										•				
					•									