

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9001190243 DOC. DATE: 90/01/09 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME AUTHOR AFFILIATION
 MCGEE, R. Iowa Electric Light & Power Co.
 HANNEN, R. L. Iowa Electric Light & Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 89-016-00: on 891212, HPCI sys inoperability due to
 failure to obtain adequate flow in required time.

W/8 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL	RECIPIENT ID CODE/NAME	COPIES	L	T	R	ENCL
	PD3-3 LA	1				1	PD3-3 PD	1				1
	HALL, J.R.	1				1						
INTERNAL:	ACRS MICHELSON	1				1	ACRS MOELLER	2				2
	ACRS WYLIE	1				1	AEOD/DOA	1				1
	AEOD/DSP/TPAB	1				1	AEOD/ROAB/DSP	2				2
	DEDRO	1				1	NRR/DET/ECMB 9H	1				1
	NRR/DET/EMEB9H3	1				1	NRR/DET/ESGB 8D	1				1
	NRR/DLPQ/LHFB11	1				1	NRR/DLPQ/LPEB10	1				1
	NRR/DOEA/OEAB11	1				1	NRR/DREP/PRPB11	2				2
	NRR/DST/SELB 8D	1				1	NRR/DST/SICB 7E	1				1
	NRR/DST/SPLB8D1	1				1	NRR/DST/SRXB 8E	1				1
	NUDOCS-ABSTRACT	1				1	REG FILE 02	1				1
	RES/DSIR/EIB	1				1	RGN3 FILE 01	1				1
EXTERNAL:	EG&G WILLIAMS, S	4				4	L ST LOBBY WARD	1				1
	LPDR	1				1	NRC PDR	1				1
	NSIC MAYS, G	1				1	NSIC MURPHY, G.A	1				1
	NUDOCS FULL TXT	1				1						

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
 ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
 LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 38 ENCL 38

Iowa Electric Light and Power Company

January 9, 1990
DAEC-90-0022

Mr. A. Bert Davis
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Duane Arnold Energy Center
Docket No: 50-331
Op. License DPR-49
Licensee Event Report #89-016

Gentlemen:

In accordance with 10 CFR 50.73 please find attached a copy of the subject Licensee Event Report.

Very truly yours,

Rick L. Hannen 1-9-90

Rick L. Hannen
Plant Superintendent - Nuclear

RLH/RMM/gt

cc: Director of Nuclear Reactor Regulation
Document Control Desk
U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D. C. 20555

NRC Resident Inspector - DAEC

File A-118a

9001190243 900109
PDR ADDOCK 05000331
S FDC

JE22
111

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1) Duane Arnold Energy Center (DAEC)	DOCKET NUMBER (2) 050003131	PAGE (3) 1 OF 05
---------------------------------------------------------------	---------------------------------------	----------------------------

TITLE (4) **High Pressure Coolant Injection System Inoperability Due to Failure to Obtain Adequate Flow in Required Time**

EVENT DATE (5)			LER NUMBER (6)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (8)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
									None		
1	2	12	8	9	016	0	1	09	DOCKET NUMBER(S) 05000		

OPERATING MODE (8) N	THIS REPORT IS SUBMITTED PURBUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)				
POWER LEVEL (10) 1100	<input type="checkbox"/> 20.402(b)	<input type="checkbox"/> 20.406(e)	<input type="checkbox"/> 50.73(e)(2)(w)	<input type="checkbox"/> 73.71(b)	OTHER (Specify in Abstract below and in Text, NRC Form 366A)
	<input type="checkbox"/> 20.406(a)(1)(i)	<input checked="" type="checkbox"/> 50.38(e)(1)	<input type="checkbox"/> 50.73(e)(2)(v)	<input type="checkbox"/> 73.71(e)	
	<input type="checkbox"/> 20.406(a)(1)(ii)	<input type="checkbox"/> 50.38(e)(2)	<input type="checkbox"/> 50.73(e)(2)(w)		
	<input type="checkbox"/> 20.406(a)(1)(iii)	<input type="checkbox"/> 50.73(a)(2)(i)	<input type="checkbox"/> 50.73(e)(2)(viii)(A)		
	<input type="checkbox"/> 20.406(a)(1)(iv)	<input type="checkbox"/> 50.73(a)(2)(ii)	<input type="checkbox"/> 50.73(e)(2)(viii)(B)		
	<input type="checkbox"/> 20.406(a)(1)(v)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(e)(2)(x)		

LICENSEE CONTACT FOR THIS LER (12)	
NAME Ron McGee, Technical Support Specialist	TELEPHONE NUMBER AREA CODE: 311985 NUMBER: 11-761012

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)										
CAUSE	SYSTEM	COMPONENT	MANUF. TURER	REPORTABLE TO NPROS	CAUSE	SYSTEM	COMPONENT	MANUF. TURER	REPORTABLE TO NPROS	

SUPPLEMENTAL REPORT EXPECTED (14)	EXPECTED SUBMISSION DATE (15)	MONTH DAY YEAR
<input checked="" type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE)	<input type="checkbox"/> NO	09 30 90

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (18)

On December 12, 1989 at 1410 hours, the High Pressure Coolant Injection (HPCI) system was declared inoperable during performance of surveillance testing. The reactor was at 100% power. During the surveillance testing, the HPCI system failed to reach 3000 gallons per minute flowrate within the required 30 seconds during a cold quick start. Actual start time was 30.52 seconds. The required Emergency Core Cooling Systems were proven operable per Technical Specifications Limiting Conditions for Operation.

The cause of the event was determined to be inadequate HPCI turbine electro-hydraulic response during the turbine startup sequence. The electronic portion of the Turbine Governor (EG-M) was adjusted within allowable tolerances and a satisfactory start time was achieved. Oil system improvements have been identified and incorporated in a Design Change Package scheduled for the next refuel outage.

In the interim, a new EG/R unit is being tested and installed to allow a modification, previously scheduled as part of the DCP, to be completed prior to the refuel outage. A supplementary report detailing results of the system improvements will be provided by September 30, 1990, following the refueling outage.

The HPCI system was declared operable at 1034 hours on December 19, 1989.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 05000331	LER NUMBER(6)			PAGE(3)	
		YEAR 89	SEQUENTIAL NUMBER - 016	REVISION NUMBER - 00	2	OF 5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. DESCRIPTION OF EVENT:

On December 11, 1989, the High Pressure Coolant Injection System (HPCI, EIIS System Code BJ) was being tested per the scheduled Surveillance Test Procedure (STP). During the cold fast start portion of the STP, HPCI obtained required flow in 26.4 seconds.

During the second portion of the STP (system leakage walkdown), an annunciator for HPCI low lube oil pressure alarmed on system start and failed to clear as the turbine (Terry Steam Turbine Component Type CS) was brought up to speed. The annunciator response procedure was carried out, including monitoring HPCI bearing temperatures. No adverse effects were noted and the turbine was manually tripped shortly after the alarm was received and investigated.

Manual lube oil pressure supply valves were adjusted per Operating Instructions to suggested ranges. The HPCI turbine was then allowed to cool down overnight to meet the intention of a "cold fast start" to verify the lube oil pressure adjustments had not affected HPCI operability.

On December 12, 1989, with the reactor at 100% power, the HPCI surveillance test was performed. The system failed to deliver 3000 gallons per minute within 30 seconds as required. Actual time was 30.52 seconds. Additionally, the turbine stop valve opening stroke time was 30.6 seconds (it is required to be ≤ 30 seconds). The HPCI System was declared inoperable at this time.

A seven day Limiting Condition for Operation (LCO) was entered at 1410 on December 12, 1989, as required by Technical Specifications. Required testing was initiated to verify operability of the redundant systems: Automatic Depressurization System (ADS, EIIS System Code SB), Low Pressure Coolant Injection System (LPCI, EIIS System Code BO), Core Spray System (CS, EIIS System Code BM), and Reactor Core Isolation Cooling System (RCIC, EIIS System Code BN).

II. CAUSE OF EVENT:

The results of testing/maintenance from December 12 to December 19, 1989, are as follows:

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 0 5 0 0 0 3 3 1	LER NUMBER(6)			PAGE(3)		
		YEAR 8 9	SEQUENTIAL NUMBER - 016	REVISION NUMBER - 00	3	OF	5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

- a. Management was informed early in the testing that adjustments within tolerances could be made to the starting circuitry (Component Type BJ-65) that would improve starting times. The decision was made to test for other possible causes prior to making these adjustments.
- b. Evidence that oil system drain down/air accumulation was a contributing factor to slow start times was noted. The cause of system drain down could not be determined. Conversations with the Manufacturer Technical Representative revealed that oil drain down is a common occurrence. Design Change Package (DCP) 1491, initiated prior to this event, will address system oil drain down. Results of this design change, scheduled for completion during the upcoming refueling outage, will be included in the supplementary report.
- c. An engineering design change, previously scheduled for completion during the upcoming refuel outage, as described in General Electric Service Information (SIL) #480 was installed. This modification installed a supply oil bypass line around the Woodward EG-R hydraulic actuator gear pump and reduced the electronic control idle voltage from -1.0 to -4.5 vDC. The expected results of the modification should have been to smooth out the startup transient speed peaks thereby allowing a more controlled ascension to rated turbine speed. The modification did not work as expected and the idle voltage was reset to the original setting. The additional oil bypass line which was left installed has no effect when the idle voltage is at the original setting. The Technical Representative has advised that the installation of a new EG-R unit may allow the modification to work. Testing and installation of a new unit are currently being conducted. Results of this action will be reported in the supplementary report.
- d. A new auxiliary oil pump was obtained and installed. The performance of the new pump did not drastically differ from the originally installed pump.
- e. All system oil pressure gauges were calibrated to ensure data was accurate.
- f. The repositioning of lube oil supply valves on December 11, 1989, was ruled out as a possible cause for the slow start times as these valves are downstream of the governor control supply and any oil pressure changes due to valve repositioning would have been compensated for by a system pressure regulating valve. Flow orifices and a locking throttle valve in place of the present lube oil supply valves will be installed as part of DCP 1491. Completion of this action will be included in the supplementary report.
- g. Suspected control oil leakage locations that could cause slow start times were inspected. No leakage was detectable.
- h. The adjustments to the starting circuitry (see a. above) were completed on 12/17/89.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 05000331	LER NUMBER(6)			PAGE(3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		89	016	00	4	OF	5

TEXT (If more space is required, use additional NRC Form 366A's) (17)

On December 18, 1989, another cold fast start test was performed. The elapsed time to obtain 3000 gpm flow was approximately 17 seconds. Traces were obtained from the recently installed HPCI transient recorder which monitors several parameters to provide a more in-depth analysis of HPCI performance. Review of these traces revealed that the steam stop valve started to open normally, however during the opening sequence the valve went rapidly full open, then returned to its expected partially open position and completed its ramp to the full open position. The uncontrolled opening of the stop valve occurred due to inadequate balance chamber pressure being established internal to the valve prior to its internal pilot assembly causing main valve actuation. The stop valve was inspected for damage and none was noted. Balance chamber pressure was adjusted and the turbine was left idle overnight to establish cold conditions for a cold fast start the following day.

On December 19, 1989, the HPCI surveillance test was satisfactorily performed, obtaining required flow in 26.03 seconds and providing satisfactory transient traces. The HPCI System was declared operable at 1034 and the LCO was exited.

III. ANALYSIS OF EVENT:

Although declared inoperable, the HPCI System was maintained in an available status during most of the testing period. Redundant systems were operable throughout this event and the previous surveillance interval. With the reactor in Run mode, the worst case effect of the failure or inability of the HPCI System to operate would be loss of the ability to maintain reactor vessel inventory after small line breaks that do not rapidly depressurize the vessel. ADS, in conjunction with the LPCI or CS Systems, provides full redundancy for HPCI. The RCIC System was also available to mitigate the loss of HPCI, but is not considered fully redundant to HPCI. The inoperability of the HPCI System had a minimal impact on the safe operation of the plant.

IV. CORRECTIVE ACTIONS:

The HPCI Turbine Electric-Governor circuitry was adjusted within allowable tolerances to improve turbine start times and reduce the time from initiation to achieving required flowrate. Additional governor oil system improvements will be installed as part of DCP 1491 during the next refueling outage. In the interim, a new EG/R unit is being tested and installed to allow the oil system bypass modification (SIL #480), previously scheduled as part of the DCP, to be completed prior to the refueling outage.

The HPCI System will remain on increased surveillance frequency. Subsequent information will be reported in a supplemental report to be issued by 9/30/90, following the refueling outage.

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

APPROVED OMB NO. 3150-0104
EXPIRES: 8/31/88

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 0 5 0 0 0 3 3 1	LER NUMBER(6)			PAGE(3)		
		YEAR 8 9	SEQUENTIAL NUMBER - 016	REVISION NUMBER - 00			

TEXT (If more space is required, use additional NRC Form 366A's) (17)

V. ADDITIONAL INFORMATION:

a. Equipment:

Terry Steam Turbine (Dresser-Rand Corporation)
Woodward Governor Control System

b. Previous Similar Events:

The failure of HPCI to reach its desired discharge flow rate/pressure, slow start times and governor oil problems have been previously reported in LERs 75-057, 76-089, 77-077, 77-095, 77-096, 78-025, 83-018, 83-022, 83-056, 86-010, 88-002, 88-004, 89-002 and 89-007.

This event is being reported pursuant to 10 CFR 50.73(a)(2)(v).