

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9010170065 DOC. DATE: 90/10/10 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME AUTHOR AFFILIATION
 MCGEE, R.M. Iowa Electric Light & Power Co.
 HANNEN, R.L. Iowa Electric Light & Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 90-014-00: on 900910, high pressure reactor scram following MSR high level turbine trip. W/901010 ltr.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL	RECIPIENT ID CODE/NAME	COPIES	LTTR	ENCL
	PD3-3 LA	1		1	PD3-3 PD	1		1
	HALL, J.R.	1		1				
INTERNAL:	ACNW	2		2	ACRS	2		2
	AEOD/DOA	1		1	AEOD/DSP/TPAB	1		1
	AEOD/ROAB/DSP	2		2	NRR/DET/ECMB 9H	1		1
	NRR/DET/EMEB 7E	1		1	NRR/DLPQ/LHFB11	1		1
	NRR/DLPQ/LPEB10	1		1	NRR/DREP/PRPB11	2		2
	NRR/DST/SELB 8D	1		1	NRR/DST/SICB 7E	1		1
	NRR/DST/SPLB8D1	1		1	NRR/DST/SRXB 8E	1		1
	REG FILE 02	1		1	RES/DSIR/EIB	1		1
	RGN3 FILE 01	1		1				
EXTERNAL:	EG&G BRYCE, J.H	3		3	L ST LOBBY WARD	1		1
	NRC PDR	1		1	NSIC MAYS, G	1		1
	NSIC MURPHY, G.A	1		1	NUDOCS FULL TXT	1		1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTTR 32 ENCL 32

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S

DCD

Iowa Electric Light and Power Company

October 10, 1990
DAEC-90-0853

Mr. A. Bert Davis
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Duane Arnold Energy Center
Docket No: 50-331
Op. License DPR-49
Licensee Event Report #90-014

Gentlemen:

In accordance with 10 CFR 50.73 please find attached a copy of the subject Licensee Event Report.

Very truly yours,

Rick L. Hannen 9-10-90
Rick L. Hannen
Plant Superintendent - Nuclear

RLH/RMM/sjo

cc: Director of Nuclear Reactor Regulation
Document Control Desk
U.S. Nuclear Regulatory Commission
Mail Station P1-137
Washington, D. C. 20555

NRC Resident Inspector - DAEC

Dr. William R. Jacobs, Jr.
GDS Associates, Inc.
Suite 720
1850 Parkway Place
Marietta, GA 30068-8237

File A-118a

9010170065 901010
PDR ADOCK 05000331
S FDC

IE22
OCT 12 1990
11

IEC/

LICENSEE EVENT REPORT (LER)

EXPIRES: 4/30/82

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530) U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 0 5 0 0 0 3 3 1	PAGE (3) 1 OF 0 3
--	---	-----------------------------

TITLE (4)
High Pressure Reactor Scram Following MSR High Level Turbine Trip

EVENT DATE (5)			LER NUMBER (8)			REPORT DATE (7)			OTHER FACILITIES INVOLVED (6)		
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	MONTH	DAY	YEAR	FACILITY NAMES		
									None		
0	9	10	9	0	14	1	0	10	0 5 0 0 0		
0	9	10	9	0	14	1	0	10	0 5 0 0 0		

OPERATING MODE (9) N	THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following) (11)									
POWER LEVEL (10) 0 2 7	20.402(b)	20.406(c)	<input checked="" type="checkbox"/>	50.73(a)(2)(iv)	73.71(b)					
	20.406(a)(1)(i)	50.38(e)(1)	<input type="checkbox"/>	50.73(a)(2)(v)	73.71(c)					
	20.406(a)(1)(ii)	50.38(e)(2)	<input type="checkbox"/>	50.73(a)(2)(vii)	OTHER (Specify in Abstract below and in Text, NRC Form 355A)					
	20.406(a)(1)(iii)	50.73(a)(2)(i)	<input type="checkbox"/>	50.73(a)(2)(viii)(A)						
	20.406(a)(1)(iv)	50.73(a)(2)(ii)	<input type="checkbox"/>	50.73(a)(2)(viii)(B)						
20.406(a)(1)(v)	50.73(a)(2)(iii)	<input type="checkbox"/>	50.73(a)(2)(ix)							

LICENSEE CONTACT FOR THIS LER (12)				TELEPHONE NUMBER			
NAME Ronald M. McGee, Technical Support Specialist				AREA CODE			
				3 1 9 8 5 1 - 7 6 0 2			

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)									
CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO NRRDS

SUPPLEMENTAL REPORT EXPECTED (14)				EXPECTED SUBMISSION DATE (15)		MONTH	DAY	YEAR
<input type="checkbox"/> YES (if yes, complete EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO								

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

On September 10, 1990 with the reactor at approximately 27% power, a turbine trip occurred as a result of a sensed high level in a Moisture Separator Reheater. Reactor steam production at the time of the turbine trip was slightly in excess of the bypass valve capacity, resulting in a rising reactor pressure, and a reactor scram approximately one minute later.

Plant response to the conditions present occurred appropriately. Primary Containment Isolation Groups 2-5 responded in accordance with design when reactor water level decreased as a result of void reduction in response to the reactor scram.

The root cause of the event was valve misalignment following maintenance. The corrective actions included an immediate valve lineup verification and enhancements to the valve lineup procedure.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

EXPIRES: 4/30/92

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 0 5 0 0 0 3 3 1	LER NUMBER(6)			PAGE(3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		90	- 014	- 00	2	OF	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

I. DESCRIPTION OF EVENT:

On September 10, 1990 at 21:56:43 with the reactor at approximately 27% power, a Turbine Trip occurred as a result of a sensed high level in a Moisture Separator Reheater (MSR). Turbine bypass valves opened in response to the rising main steam pressure. A direct scram from the Turbine Trip was not required as this input to the Reactor Protection System (RPS) is bypassed at reactor powers less than 30%. Reactor pressure increased at a rate of approximately 100 psi/minute due to steam production in excess of the Turbine bypass capacity. This resulted in a high pressure Reactor Scram at 21:57:47. Reactor pressure was promptly restored to normal with bypass valves as reactor power decreased in response to the scram. Reactor level was controlled between 199 and 163 inches (above TAF) with normal feedwater. Primary Containment Isolation System (PCIS) Groups 2-5 responded in accordance with design when reactor level decreased to less than 170 inches as a result of void reduction in response to the reactor scram. No other safety systems actuated in response to the event.

II. CAUSE OF EVENT

Following calibration of the MSR Level instrument, a manual isolation to the instrument could not be reopened due to a worn stem - handwheel connection. The valve was replaced prior to startup from the current refueling outage, but left in the nearly closed position. Post Maintenance operability testing was deferred until after startup in order to have pressure available at the valve to check for leakage. The testing did not include a valve lineup check as it was assumed that this valve would be included in the Pre-Startup valve lineup.

It was subsequently determined that the Pre-Startup valve lineups did not include this non-safety related instrument's isolations.

Following reactor startup, the level sensing chamber slowly filled with condensing steam and eventually obtained a sensed high level causing a direct Turbine Trip.

The cause of the scram is a non-single failure tolerant design of the Turbine Trip logic. The intermediate cause was a sensed high MSR level caused by an erroneous indication. The root cause was instrument sensing line valve misalignment following maintenance.

III. ANALYSIS OF EVENT

Turbine trips at low and high power are analyzed events with no adverse safety consequences. All automatic actions occurred as expected. Operator actions were appropriate and promptly restored the plant to a stable condition.

**LICENSEE EVENT REPORT (LER)
TEXT CONTINUATION**

EXPIRES: 4/30/92

ESTIMATED BURDEN PER RESPONSE TO COMPLY WITH THIS INFORMATION COLLECTION REQUEST: 50.0 HRS. FORWARD COMMENTS REGARDING BURDEN ESTIMATE TO THE RECORDS AND REPORTS MANAGEMENT BRANCH (P-530), U.S. NUCLEAR REGULATORY COMMISSION, WASHINGTON, DC 20555, AND TO THE PAPERWORK REDUCTION PROJECT (3150-0104), OFFICE OF MANAGEMENT AND BUDGET, WASHINGTON, DC 20503

FACILITY NAME (1) Duane Arnold Energy Center	DOCKET NUMBER (2) 0 5 0 0 0 3 3 1	LER NUMBER(6)			PAGE(3)		
		YEAR	SEQUENTIAL NUMBER	REVISION NUMBER			
		9 0	- 014	- 00	3	OF	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

IV. CORRECTIVE ACTIONS

The MSR level instrument valve lineup was corrected. All other Turbine Trip instrument valve lineups were verified to be correct.

The MSR level instrument performance was verified to be satisfactory.

The non-nuclear instrument valve lineup has been expanded to include all identified Turbine Trip instrumentation.

Additional resources have been allocated for the Scram Frequency Reduction program.

Supplemental valve lineup categories will be created to minimize the probability of Reactor Scram events due to instrument valve mispositioning. This will be accomplished by 5/31/91.

A verification of instrument isolations to ensure inclusion in valve lineups will be completed by 12/31/91.

V. ADDITIONAL INFORMATION

- A. There were no failed components in this event.
- B. No previous Licensee Event Reports concerning High Pressure Reactor Scrams or Turbine Trips due to valve mispositioning were located.
- C. Applicable EIIS System Codes
 - 1. Reactor Protection system - JD
 - 2. Containment Isolation Control System - JM
 - 3. Main/Reheat Steam System - SB
 - 4. Main Turbine System - TA