MEMO ROUTE SL Form AEC-93 (Rev. May 14, 1947	M 0240	See me about this. For surrence. For action. Note and return. For sture. For Information.
TO (Name and unit) RO Chief, FS&EB RO:HO (4)	INITIALS	REMARKS IOWA ELECTRIC LIGHT & POWER COMPANY Docket 50-331
Licensing (4) DR Central Files Region I	DATE	
TO (Name and unit) Region II PDR	INITIALS	REMARKS
Local PDR NSIC DTIE	DATE	
TO (Name and unit) OGC, Beth, P-506A	INITIALS	REMARKS
	DATE	
FROM (Name and unit) W. E. Vetter RO:III	REMARKS Attached dtd 7-26	is applicant's reply dtd 8-15-73 to RO letter -73 re possible inverted tubes in control blades.
		•
PHONE NO. BATE 8-28-73		

USE OTHER SIDE FOR ADDITIONAL REMARKS

GPO: 1971 O - 445-469

LB

IOWA ELECTRIC LIGHT AND POWER COMPANY

General Office Cedar Rapids, Iowa

> August 15, 1973 IE-73-1208

C. W. SANDFORD VICE PRESIDENT

> Mr. Boyce Grier Regional Director U. S. Atomic Energy Commission Directorate of Regulatory Operations Region III 799 Roosevelt Road Glen Ellyn, Illinoiş 60137

> > Re: Duane Arnold Energy Center Subject: Control Rod Blade Absorber Tubes File: A-110, Q-614

Dear Mr. Grier:

This is in response to your letter of July 26, 1973 concerning control blades containing possible inverted B_4C tubes in the DAEC reactor. The necessary inspection has been completed and preliminary results phoned to Mr. Hayes of your office on August 7, 1973.

Prior to receipt of your letter, plans had been made to remove the control blades from the vessel to examine them to verify the orientation of the B_4C tubes. A procedure covering the examination, cleaning and reinstallation of the blades was prepared by General Electric and approved by Iowa Electric personnel on August 3, 1973. All blades received a preliminary check on August 4 and 5, 1973 using a magnetic indicator on the top (lifting handle) end. Twenty-three (23) blades were rejected as a result of this review.

The remaining blades were X-rayed at the velocity limiter end to verify the presence of steel wool at that location. Thirteen (13) blades were rejected as a result of this examination. The X-rays revealed only individual B_4C tubes inverted, not entire sheaths.

The remaining blades underwent a detailed visual examination before cleaning and reinstallation in the reactor. Nine (9) blades were rejected on visual inspection for minor abnormalities, including bent lifting bails, rough machining and a missing tack weld.

The remaining forty-four (44) blades were reinstalled in the vessel for use. The forty-five (45) rejected blades were returned to General Electric at Wilmington, North Carolina. Mr. Boyce Grier

. . .

August 15, 1973

Forty-five (45) replacement blades were supplied by General Electric. The X-rays of the velocity limiter end of the B_4C rods in the replacement blades furnished with these blades were reviewed and accepted by Iowa Electric personnel before their installation.

The X-ray examination method provides an extremely reliable method of determining B_4C rod orientation. Acceptance or rejection is determined by the presence or absence of identifiable characteristics which demonstrate clearly the orientation of the B_4C rods.

Documentation of the examination is on site for your review. If you have any questions, please do not hesitate to call.

Very truly yours,

C.W. San C. W. Sandford

Vice President

CWS:ar

c.c. Mr. L. D. Root Mr. G. A. Cook Mr. C. S. Darrow Mr. J. H. M. Miller Mr. J. R. Newman Mr. M. R. Muir Mr. M. J. Jacobson