

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8101120336 DOC.DATE: 81/01/06 NOTARIZED: NO DOCKET #
 FACIL:50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH.NAME AUTHOR AFFILIATION
 RAGER,M.S. Iowa Electric Light & Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: LER 80-061/03L-0: on 801207, drywell pressure & torus water level record PR/LR-4384 began giving erratic & unreliable data. Caused by poor ventilation in recorder cabinet resulting in excessive temp so power supply output varied.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR L ENCL L SIZE: 1+1
 TITLE: Incident Reports

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
ACTION:	IPPOLITO, T. 04	3 3		
INTERNAL:	A/D COMP&STRU06	1 1	A/D ENV TECH 07	1 1
	A/D MATL & QU08	1 1	A/D OP REACT009	1 1
	A/D PLANT SYS10	1 1	A/D RAD PROT 11	1 1
	A/D SFTY ASSE12	1 1	A/D TECHNOLOG13	1 1
	ACC EVAL BR 14	1 1	AEOD	2 2
	ASLBP/J.HARD	1 1	AUX SYS BR 15	1 1
	CHEM ENG BR 16	1 1	CONT SYS BR 17	1 1
	CORE PERF BR 18	1 1	D/DIR, HUM FAC19	1 1
	DIR, DIV OF LIC	1 1	DIR, ENGINEERI20	1 1
	DIR, HUM FAC S21	1 1	DIR, SYS INTEG22	1 1
	EFF TR SYS BR23	1 1	EQUIP QUAL BR25	1 1
	GEOSCIENCES 26	1 1	I&C SYS BR 29	1 1
	I&E 05	2 2	JORDAN, E./IE	1 1
	LIC GUID BR 30	1 1	LIC QUAL BR 31	1 1
	MATL ENG BR 32	1 1	MECH ENG BR 33	1 1
	MPA	3 3	NRC PDR 02	1 1
	OP EX EVAL BR34	3 3	OR ASSESS BR 35	1 1
	POWER SYS BR 36	1 1	RAD ASSESS BR39	1 1
	REACT SYS BR 40	1 1	REG FILE 01	1 1
	REL & RISK A 41	1 1	SFTY PROG EVA42	1 1
	STRUCT ENG BR44	1 1	SYS INTERAC B45	1 1
EXTERNAL:	ACRS 46	16 16	LPDR 03	1 1
	NSIC 05	1 1	TERA:DOUG MAY	1 1

JAN 13 1981

AO 4

TOTAL NUMBER OF COPIES REQUIRED: LTR 70 ENCL 70

5

I LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 11A0A C 1 2 000-000000-000 3 4 1 1 1 1 4 5

01 REPORT SOURCE 6 0 1 5 0 0 0 3 3 1 7 1 2 0 7 8 0 3 0 1 0 6 8 1 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
012 During power operation the Drywell Pressure and Torus Water Level Record
013 er PR/LR-4384 began giving erratic and unreliable data. Tech Spec Table
014 13.2-F requires two suppression chamber water level and two drywell press
015 ure recorders be operable. Redundant recorder was indicating normally.
016 Two previous occurrences with PR/LR-4384. See RO 79-038 and 80-057.
017
018

019 SYSTEM CODE CAUSE CODE CAUSE SUBCODE COMPONENT CODE COMP. SUBCODE VALVE SUBCODE
S B 11 B 12 A 13 I N S I T R U I 14 R 15 Z 16
17 LER/RO REPORT NUMBER 18 8 0 19 20 21 22 23 24 25 26 27 28 29 30 31 32
ACTION TAKEN FUTURE ACTION EFFECT ON PLANT SHUTDOWN METHOD HOURS ATTACHMENT SUBMITTED APPROX. FORM SUB. PRIME COMP. SUPPLIER COMPONENT MANUFACTURER
X 18 F 19 Z 20 Z 21 0 0 0 0 0 0 N 22 N 24 A 25 H I 2 6 0 25

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS 27
110 Poor ventilation in the recorder cabinet resulted in excessive temps whi
111 ch caused the power supply output to vary. Unit allowed to cool, recalib
112 rated and tested sat. A design review will be initiated to determine if
113 ventilation can be improved through the cabinets. The results of this re
114 view to be presented in an update report. Honeywell Vultronik recorder.

115 FACILITY STATUS % POWER OTHER STATUS 30 METHOD OF DISCOVERY DISCOVERY DESCRIPTION 32
E 23 0 9 8 29 NA LA 31 Operator Observation 32

116 ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36
Z 33 Z 34 NA NA 36

117 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION 39
0 0 0 0 37 Z 38 NA 39

118 PERSONNEL INJURIES NUMBER DESCRIPTION 41
0 0 0 0 40 NA 41

119 LOSS OF OR DAMAGE TO FACILITY TYPE DESCRIPTION 43
Z 42 NA 43

120 ISSUED DESCRIPTION 45 PUBLICITY 46
N 44 NA 45

8101120 336

NAME OF PREPARER Matthew S. Rager PHONE: 319-851-5611