

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8105040442 DOC. DATE: 81/04/28 NOTARIZED: NO DOCKET #
 FACIL: 50-331 Duane Arnold Energy Center, Iowa Electric Light & Pow 05000331
 AUTH. NAME AUTHOR AFFILIATION
 RAGER, M.S. Iowa Electric Light & Power Co.
 RECIP. NAME: RECIPIENT AFFILIATION
 Region 3, Chicago, Office of the Director

SUBJECT: Updated LER 80-030/01X-1: on 800722, during normal surveillance testing of river water sys, traveling screen 1F-36B found inoperable. Caused by improperly secured & latched draw-out portion of motor control ctr cubicle.

DISTRIBUTION CODE: A002S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1/2
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	IPPOLITO, T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J, HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR, ENGINEERI20	1	1
	DIR, HUM FAC S21	1	1	DIR, SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN, E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	<u>REG FILE</u> 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	LPDR 03	1	1
	NSIC 05	1	1			

MAY 05 1981

AO/1
4
[Signature]

TOTAL NUMBER OF COPIES REQUIRED: LTR 61 ENCL 61

DUANE ARNOLD ENERGY CENTER

Iowa Electric Light and Power Company

Licensee Event Report - Supplemental Data

Docket No. 050-0331

Licensee Event Update Report Date: April 28, 1981

Reportable Occurrence No: 80-030 UPDATE REPORT: Previous
Report Date 8-5-80

Event Description

During normal surveillance testing of the River Water Supply System, Traveling Screen 1F-36B was found inoperable. This made the "B" River Water Supply System inoperable. The redundant River Water Supply System and associated Traveling Screen, 1F-36A, had previously been made inoperable for maintenance, thus putting the plant in a 24 hour LCO. This is in accordance with Technical Specification 3.5.J.3. Traveling Screen 1F-36B was returned to service within the hour to cancel the 24 hour LCO. No previous occurrences have been noted.

Cause Description

The main stabs for MCC 1B2107 were not making contact with the bus due to the draw-out portion of the main control center cubicle not being properly secured and latched. The tray and components were manufactured by Allis Chalmers. It is believed the tray was never properly secured following maintenance on the Traveling Screens during the 1980 refuel outage and finally vibrated loose far enough to separate the stabs from the bus.

Corrective Action

The draw-out portion of the MCC cubicle was secured and latched in its proper position. This returned the River Water Supply System and Traveling Screen 1F-36B to operability. The screen was tested satisfactorily and returned to normal mode. No further corrective action is planned at this time.