

September 29, 2011

Stephen E. Hedges Site Vice President

WO 11-0078

U. S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555

- Reference: Letter WO 11-0024, dated May 18, 2011, from S. E. Hedges, WCNOC, to USNRC
- Subject: Docket No. 50-482: Licensee Event Report 2011-004-01, "Automatic Safety Injection Actuation Due to Operating Crew Failure to Follow Procedure"

Gentlemen:

The Reference submitted Licensee Event Report (LER) 2011-004-00, "Automatic Safety Injection Actuation Due to Operating Crew Failure to Follow Procedure," which described an event involving a safety injection actuation and steam line isolation on March 19, 2011, when a main steam isolation valve was opened. Enclosed is supplemental LER 2011-004-01. The supplemental report is being issued to indicate that this event is not reportable in accordance with 10 CFR 50.73(a)(2)(v)(D).

The Attachment provides the regulatory commitments made in this submittal. If you have any questions concerning this matter, please contact me at (620) 364-4190, or Mr. Gautam Sen at (620) 364-4175.

Sincerely, Stephen E. Hedges

SEH/rlt

Attachment Enclosure

cc: E. E. Collins (NRC), w/a, w/e J. R. Hall (NRC), w/a, w/e G. B. Miller (NRC), w/a, w/e Senior Resident Inspector (NRC), w/a, w/e

P.O. Box 411 / Burlington, KS 66839 / Phone: (620) 364-8831 An Equal Opportunity Employer M/F/HC/VET

LIST OF REGULATORY COMMITMENTS

The following table identifies those actions committed to by Wolf Creek Nuclear Operating Corporation (WCNOC) in this document. Any other statements in this submittal are provided for information purposes and are not considered to be regulatory commitments. Please direct questions regarding these commitments to Mr. Gautam Sen at (620) 364-4175.

REGULATORY COMMITMENT	DUE DATE/EVENT
Accountability on procedure use and adherence will be reinforced through evaluation of operating crews on the simulator and during normal plant operations. These actions will be completed by December 1, 2011.	December 1, 2011

NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION						APPRO	APPROVED BY OMB: NO. 3150-0104 EXPIRES: 10/31/2013											
(10-2010)	LICEN (Se	SEE EVE	ENT REPOR	T (LE	R)		Estimate request: licensing burden e U.S. Nu internet Informati Manager impose a number, to respo	ed burden per 80 hours. F process and estimate to the clear Regulato e-mail to infor ion and Regu nent and Bud an information the NRC may not to, the infor	response to ca Reported lesson I fed back to i Records and FC ry Commission, collects@nrc.goo ulatory Affairs, I get, Washington collection does n not conduct or s mation collection	omply with the s learned arr ndustry. Sen DIA/Privacy Se Washington, r, and to the NEOB-10202, n, DC 20503 of display a cu sponsor, and	is mandator e incorporat d comments ervice Branc Desk Office (3150-0104) If a mea irrently valid (a person is r	y collection ed into the s regarding n (T-5 F52), 0001, or by r, Office of ns used to DMB control not required					
1. FACIL WO	ITY NA	ME REEK G		TING STAT	ION			2. DOC	2. DOCKET NUMBER 3. PAGE 05000 482 1 OF 6									
4. TITLE Auto	: omatio	c Safet	/ Injectio	n Actuation	Due	to Oper	rating C	rew Fai	lure to Fo		edures							
5. EVENT DATE 6. LER NUMBER 7. REPORT DATE							8.	OTHER FACIL	ITIES INVO	DLVED								
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAMI	2		DOCKET 1	NUMBER					
3	19	2011	2011	004	01	9	29	2011	FACILITY NAMI			оскет 1 05000	10/31/2013 y collection a regarding (T-5 F52), 0001, or by r, Office of ns used to DMB control not required UMBER) UMBER) UMBER) UMBER) UMBER) UMBER) UMBER) VEAR S >)					
9. OPER	ATING	MODE	11. TI	HIS REPORT IS	SUBN	AITTED PL	JRSUANT	TO THE F	REQUIREME	NTS OF 10 C	FR§: (Che	ck all that a	pply)					
$\begin{array}{c c c c c c c c c c c c c c c c c c c $)))	□ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a) □ 50.73(a)	(2)(i)(C) (2)(ii)(A) (2)(ii)(B) (2)(ii)(A) (2)(iv)(A) (2)(v)(A) (2)(v)(B) (2)(v)(C) (2)(v)(D)	 ☐ 50.7 ☐ 50.7 ☐ 50.7 ☐ 50.7 ☐ 50.7 ☐ 73.7 ☐ 73.7 ☐ 0TI Specoria or in 	73(a)(2)(vii) 73(a)(2)(viii) 73(a)(2)(viii) 73(a)(2)(ix)(73(a)(2)(x)(73(a)(2)(x) 71(a)(4) 71(a)(5) HER cify in Abstra NRC Form 3)(A))(B) (A) ct below 366A								
					12. LIC	CENSEE C	ONTACT	FOR THIS	LER									
FACILITY N Gal	iame Itam S	Sen, Ma	anager R	egulatory A	fairs	3				TELE	рноме NUMB 0) 364-4	ER (Include Ar 175	ea Code)					
			3. COMPL	ETE ONE LINE	FOR	EACH CO	MPONEN	T FAILURE	DESCRIBE	D IN THIS RE	PORT							
CAUS	SE	SYSTEM	COMPONE	NT MANU- FACTURER	R	EPORTABLI TO EPIX	E	CAUSE	SYSTEM	COMPONENT	MANU- FACTURE	R REPO	ORTABLE DEPIX					
U YES	(If yes, d	14. complete	SUPPLEN	IENTAL REPOI	RT EXF	PECTED		🛛 NO	15. E SUB	XPECTED MISSION DATE	MONTH	DAY	YEAR					
ABSTRA	CT (Lin	nit to 1400	spaces, i.e	., approximatel	y 15 sir	ngle-space	d typewrit	ten lines)					<u> </u>					
	On Ma efuelin valve (steam apid e alone, bistabl Contro of the resulte signal withou bart of	Irch 19, ng outag MSIV), flow an enough with the es clear of room event an ed in act closed t tying t the cor	2011 at 0 ge. At 04 a safety i d pressuit to actuate lowest s red prior operators nd EMG uation of the only o o the eng introlled si	0000 Centra 104 CDT wit injection (SI re drop were all three ra steam press to MSIV close s utilized pro ES-03, "SI T both trains open MSIV. gineered saf hutdown; ho tion termina	I Day h the) actu e obse ate-se ure si sure. cedu cermin of En Both ety fe weve	light Tin plant in ation an erved in nsitive lo till well a re EMG nation," nergency diesel g eatures b er, the SI	E-0, "R bove th E-0, "R to termi y Core (generate busses. actuati b the Re	F), the un B, while on n line ison ected stepsion m generic m	nit was tal opening the plation occean generator present int. The location SI. The Systems. ed and operol rods we ted in operol ant Systems.	ken offline be "C" main curred. A r rator. The sure bistab ow steam g rety Injectio SI and stea The stean berated in s vere previou rning of the	for the st steam is nomenta pressure les base enerator n," at the im line isol tandby m usly inser reactor fo o prior to	art of a solation ry large drop wa d on rate pressure initiation olation ation node ted as	is e n					

I

pressurizer overfill at 0411 CDT.

NRC FORM 366 (10-2010)

NRC FORM 366A (10-2010)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT (LER)

1. FACILITY NAME	2. DOCKET	6	6. LER NUMBER			3. PAGE	
1. FACILITY NAME	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF	6
		2011	004	01		0.	0

PLANT CONDITIONS PRIOR TO EVENT

Mode 3

On March 19, 2011 at 0000 CDT, the unit was taken offline for the start of a refueling outage. At 0054 CDT the unit entered Mode 3. No inoperable systems, structures, or components (SSCs) contributed to this event on March 19, 2011.

EVENT DESCRIPTION

On March 19, 2011, with reactor power less than 25 percent, after transitioning from procedure GEN 00-004, "Power Operation," to GEN 00-005, "Minimum Load to Hot Standby," control room operators implemented procedure SYS AE-200, "Feedwater Preheating During Plant Startup and Shutdown," for establishing the feedwater preheating system [EIIS codes: SB] for plant cooldown. At 0100 CDT, following Mode 3 entry, the main steam isolation valves (MSIVs) [EIIS codes: SB, ISV] were closed to terminate a cooldown of the reactor coolant system (RCS) [EIIS codes: AB].

Closing the MSIVs to stop the cooldown isolated main steam to secondary systems. The "A" main feedwater pump (MFP) [EIIS codes: SB, P] had not been tripped when the MSIVs were closed. The MFP was subsequently tripped during warmup of the main steam lines for opening the MSIVs. This condition contributed to the inadequate warming of the steam lines.

Procedure SYS AB-120, "Main Steam and Steam Dump Startup and Operation," was implemented for opening the MSIVs when it was determined to continue with the plant cooldown on the steam dump valves to establish the preferred cooldown configuration. All four MSIV bypass valves were opened to warm and pressurize the main steam header. The procedure specifies to ensure the differential pressure across the MSIVs is less than 20 psid using temporary gauges. The procedure indicates that temporary gauges with a range of 0 - 300 psig be installed. This procedure step was marked as "not applicable" since steam generator pressure was approximately 1100 psig and the range of the temporary gauges was much less than current plant conditions. The differential pressure across the MSIVs was determined to be less than 20 psid across the valves using control room installed instrumentation (AB PI-507 and steam generator pressures).

At 0404 CDT, while opening the "C" MSIV, a safety injection (SI) actuation and steam line isolation occurred. A momentary large steam flow and pressure drop were observed in the affected steam generator. The pressure drop was rapid enough to actuate all three rate-sensitive low steam generator pressure bistables based on rate alone, with the lowest steam pressure still well above the setpoint. The low steam generator pressure bistables cleared prior to MSIV closure.

Control room operators utilized procedure EMG E-0, "Reactor Trip or Safety Injection," at the initiation of the event and EMG ES-03, "SI Termination," to terminate the SI. The SI and steam line isolation resulted in actuation of both trains of Emergency Core Cooling Systems (ECCS) [EIIS codes: BQ/BP] and injection into the reactor vessel [EIIS codes: AB, RPV]. The steam line isolation signal closed the only open MSIV. Both diesel generators [EIIS codes: EK] started and operated in standby mode without tying to the engineered safety features busses [EIIS codes: EB, BU]. All control rods were previously inserted as part of the controlled shutdown; however, the SI actuation resulted in opening of the reactor trip breakers. Operator action terminated the SI into the RCS prior to pressurizer overfill at 0411 CDT.

NRC FORM 366A (10-2010) LICENSEE EVENT REPORT (LER)			U.S. NUCLE	AR REGUL	ATORY	COMMISS	SION
1. FACILITY NAME	2. DOCKET		3. PAGE				
WOLE CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	3	OF	6
	00000 402	2011	004	01	3.	01	0

Subsequent review determined that when the "C" MSIV was opened, temperature points from the plant computer for the main steam line were indicating an average temperature of 533.9 degrees F. The steam table pressure conversion for this temperature is approximately 900 psig. When the MSIV was opened existing steam generator pressures were approximately 1100 psig, which equates to a differential pressure of approximately 200 psig across the MSIVs.

BASIS FOR REPORTABILITY

This event is reportable pursuant to 10 CFR 50.73(a)(2)(iv)(A) as an event or condition that resulted in a valid automatic actuation of systems listed in paragraph (a)(2)(iv)(B) of this section of 10 CFR 50.73. The actuation was not part of a pre-planned sequence during testing or reactor operation.

Control room operators utilized procedure EMG E-0, "Reactor Trip or Safety Injection," at the initiation of the event and EMG ES-03, "SI Termination," to terminate the SI. The actions of these procedures result in the operators performing a manual reset of SI. The manual reset of SI following a 60 second time delay, in conjunction with Reactor Trip, P-4 interlock, generates an automatic block of SI. Manual reset of SI is necessary to restore the actuated equipment to standby as appropriate. TS 3.3.2, Function 1.b, Safety Injection - Automatic Actuation Logic and Actuation Relays, requires 2 channels operable in Modes 1, 2, and 3. Once SI is blocked, automatic actuation of SI cannot occur until the reactor trip breakers have been manually closed. The reactor trip breakers were closed 2 hours and 39 minutes after the initiation of the event. The manual reset of SI to terminate the safety injection is necessary to prevent overfilling the pressurizer when a steam line break was not present. However, this results in blocking both channels of SI automatic actuation logic. LER 2011-004-00 reported this event under 10 CFR 50.73(a)(2)(v)(D) as an event or condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident. Upon further review, WCNOC determined this event was not reportable under this criterion as the operation to manually reset SI to terminate the safety injection is within the specified function of the system. The manual reset of SI was performed in accordance with plant procedures and TSs. The capability to manually initiate SI was still available.

This event is also reportable under 10 CFR 50.73(a)(2)(vii) as an event where a single cause resulted in two independent trains or channels to become inoperable in a single system designed to mitigate the consequences of an accident. The manual reset of SI is a single action taken that results in the automatic block of both channels of the SI actuation logic.

An initial 50.72 notification (EN 46685) was made under 10 CFR 50.72(b)(2)(iv)(A) for an event that resulted in an ECCS discharge into the RCS as a result of a valid signal. A followup notification was made to indicate that the event was reportable under 10 CFR 50.72(b)(3)(iv)(A) as an event that results in a valid actuation of the Reactor Protection System, ECCS, and emergency ac power systems, and 10 CFR 50.72(b)(3)(v) as an event that could have prevented the fulfillment of the safety function of SSCs that are needed to mitigate the consequences of an accident.

ROOT CAUSE

The root cause of this event was the failure of the operating crew to follow procedure SYS AB-120. The operating crew did not follow the guidance in procedure AP 15C-002, "Procedure Use and Adherence," when a SYS AB-120 step that was tied to a precaution and limitation step was marked "not applicable." Because the SYS AB-120 procedural guidance was not followed, a SI occurred when the "C" MSIV was opened. Differential pressure across the valves was not equalized and was greater than 20 psid.

NRC FORM 366A 10-2010)			U.S. NUCLE	AR REGUL	ATORY	COMMISS	SION
LICENSEE EVENT REPORT (LER)	2 DOCKET					2 0405	
	2. DUCKET			REV		3. PAGE	.
NOLF CREEK GENERATING STATION	05000 482	YEAR	NUMBER	NO.	4	OF	6
		2011	004	01			
The gauges available in the control room did reached. Assumptions were made without u been reached. Instead of following procedu performance (October 15, 2010) of SYS AB- though the plant conditions were different.	d not provide th utilizing the stea ral guidance th -120, which ope	e required am tables t e crew wa ened the N	resolution to to validate who s influenced b ISIVs at appro	ensure 2 ether the by the pre oximately	0 psid 20 psi vious 30 psi	had bee d had d even	'n
A contributing cause was procedure SYS As guidance (e.g. time, temperature, and conder warmed prior to opening the MSIVs. SYS A system, opening the MSIVs, aligning the stee on the MSIVs. The procedure step for insta operating criteria established because it was	B-120 did not p ensate removal B-120 provides am dump syste Iling the gauge s not written for	rovide the) for ensur s instructio em for ope prior to op the plant	operating crew ing main stea ns for warmup ration, and the pening the "C" conditions tha	w with the m lines w o of the m e use of a MSIV did t existed	e neces vere ad nain ste auxiliar d not m (1100	ssary lequately am y mediu neet the psig).	y m
A second contributing cause was the operat when problems were encountered; instead the personnel. The principal function of the ove encountered. The operations management oversight manager stepped out of the prima problems were encountered.	tions managem he allowed ther rsight manager oversight was ry role to facilita	ent oversig n to proce is to chall present for ate moving	ght individual (ed without invo lenge the evol r the plant coo g forward inste	did not cl olving ad ution if p Idown; h ad of sto	nalleng ditiona roblem owever opping v	e the cro I plant s are r, the when	ew
A third contributing cause for this event was the main steam flow to feedwater heaters we to the cooldown requiring MSIV closure. Th and indicates that adjustment of the setpoint approached. Adjustment of the setpoint is p control thumbwheel.	the guidance in as to be adjuste to procedure dir t is allowed if th performed with	n procedured using the rects the control t	re SYS AE-20 ne controller se ontroller be pla er heater tem ller in automat	0 did not etpoint w aced in a perature ic by usir	clearly hich co lutoma limit is ng the s	v state th ontribute tic contr setpoint	nat ed ol
CORRECTIVE ACTIONS							
Transient event walkdowns of RCS equipme performed. Actions were taken to resolve d	ent in containm iscrepancies id	ent and se entified fro	econdary plant om these walk	t equipme downs.	ent wei	e	
Essential reading was issued on March 25, "Procedure Use and Adherence," and the ad procedure usage.	2011 to operati cceptable use c	ons perso of identifyir	nnel for proce ng steps as "n	dure AP ot applica	15C-00 able" d)2, uring	
Procedure AP 15C-002, "Procedure Use a guidance on procedure adherence includin indicated that the WCNOC practices were procedure use and adherence will be reint and during normal plant operations. These	and Adherence ng the use of " consistent wit forced through se actions will b	e," was be not applic h industry evaluatio be comple	nchmarked a able." The be practices. A n of operating ted by Decen	gainst cu enchmar ccountal g crews o nber 1, 2	urrent i king re bility of on the 2011.	ndustry esults n simulat	or

NRC FORM 366A (10-2010) LICENSEE EVENT REPORT (LER)			U.S. NUCLE	AR REGUI	EGULATORY COMMISSION					
1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE					
WOLE CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	5	OF	6			
	00000 402	2011	004	01	Ŭ					

Revision 28 (May 23, 2011) and On-the-Spot Change (OTSC) 11-0146 (May 24, 2011) to procedure SYS AB-120, "Main Steam and Steam Dump Startup and Operation," provide guidance for the appropriate thermal conditions (i.e., temperature, pressure, differential pressure) that must be met before opening an MSIV. These changes also identify the appropriate instrumentation to be used based on plant conditions.

Procedure SYS AE-200, "Feedwater Preheating During Plant Startup and Shutdown," was revised on April 12, 2011 to clarify the notes and step to ensure the controller is maintained in automatic when adjustments are required to prevent exceeding feedwater heater differential temperatures.

SAFETY SIGNIFICANCE

The SI produced a transient to the RCS. All major equipment functioned within its design capability. The SI transient is bounded by accident analyses discussed in Updated Safety Analysis Report (USAR) Section 15.5.1, "Inadvertent Operation Of the Emergency Core Cooling System During Power Operation." The primary concern that results from an inadvertent actuation of the ECCS at power is that associated with pressurizer overfill. The pressurizer water volume increases as a result of the SI flow. This may eventually lead to filling of the pressurizer and subsequent water relief through the safety or relief valves. The passing of liquid through the pressurizer safety or relief valves could result in rupture of the pressurizer relief tank rupture disks, spilling radioactive coolant into the containment building, thereby escalating a Condition II event to a Condition III or IV event. To prevent the pressurizer from becoming water-solid operator action is ultimately required to terminate SI or mitigate the consequences of this event. In this specific event, the SI occurred with the reactor in shutdown conditions, all rods inserted, and shutdown boration completed. Turbine trip signals and reactor trip signals were generated, but both the turbine and reactor were shutdown. The pressurizer power operated relief valves (PORVs) operated to mitigate the pressurizer insurge pressure transient. Operator action terminated the SI into the RCS prior to pressurizer overfill. Pressurizer level reached 87.5 percent during the SI event. As such, this transient was bounded by the analysis described in USAR Section 15.5.1.

When the "C" MSIV was opened, a rapid decrease in main steam line pressure occurred. The transient is bounded by the analyzed condition of a steam line break (SLB) while the plant is at hot zero power (HZP). The postulated SLB at HZP accident analysis most closely represents the plant conditions that existed during this event. Opening the MSIV gave a rapid change in steam header pressure, as would a SLB and the plant was at HZP conditions. The postulated SLB at HZP accident analysis results in a rapid loss of pressure and an excessive cooldown of the RCS. The postulated SLB at HZP as analyzed in USAR Section 15.1 represents a greater than 100 degree/hour cooldown, and it also assumes that the most reactive control rod is stuck out. The SLB at HZP bounds the transient for this event since the reactor was shut down with all control rods inserted and boron had been added during the shutdown. There was no actual failure of the main steam line piping. An actual SLB event from HZP would produce a cooldown in excess of 150 degrees/hour. For this event the cooldown was only four degrees on the affected loop and there was no prolonged steam flow. Steam generator pressure was restored when the MSIV reclosed as a result of the steam line isolation signal.

LICENSEE EVENT REPORT (LER)							
1. FACILITY NAME	2. DOCKET	6	6. LER NUMBER			3. PAGE	
VOLE CREEK GENERATING STATION	05000 482	YEAR	SEQUENTIAL NUMBER	REV NO.	6	OF	6
	00000 402	2011	004	01	0	01	
OPERATING EXPERIENCE/PREVIOUS E	VENTS						
LER 2010-012-00: On October 17, 2010 a 15 percent power during a startup when a thigh steam generator level. The MSIVs we subsequently reopened. Difficulty was exp handswitches were first depressed. It was guidance for opening a MSIV at normal operators.	t 0952 CDT, Wo turbine trip and f ere closed due to perienced in gett noted at the tim erating tempera	olf Creek G eedwater cooldowr ing the MS e that proo ture and p	Generating Stat isolation signa n after the plan SIVs to immedi cedure SYS Af ressure.	tion was l occurre t trip and ately reo 3-120 dio	at appr d due t d were pen wh d not ins	roximate to high- nen the clude	∍ly
On March 5, 2010, while in Mode 4, a feed steam generator. The high water level occ of this event, changes were made to proce to ensure differential pressure limits were a the MSIV. At the time the MSIV was open constant for some period of time, equalizat	water isolation s curred due to sw dure SYS AB-12 actually met and ed, the RCS was tion of pressure	ignal occu ell caused 20 to use to to lower s s in heatup cannot be	rred due to a l by opening the emporary gaug team generato b. If the RCS to assured.	nigh wate e "A" MS ges with or levels emperate	er level IV. As higher prior to ure is n	on "A" a result accurac opening ot held	t ÿ g
LER 85-021-00: On April 28, 1985, an enginjection actuation and main steam line iso "D" steam generator. The cause of the low trip generated by the rate sensitive steam of pressure when a MSIV was opened before time of the event, the plant was in Mode 3	gineered safety f lation. The initia v steam line pres generator pressu pressure was e prior to initial cri	eatures ac ating signa ssure signa ure circuitr qualized t ticality.	tuation occurr I was low stea al was determi y due to a deci hrough the MS	ed result m line pr ned to be rease in IV bypas	ing in a essure e an an steam l ss valve	a safety on the hticipato line es. At th	ry he
Prior corrective actions for the above event and instrumentation necessary to prevent a corrective actions from the March 5, 2010 preventing a reoccurrence of a feedwater i	ts did not adequ an increased po event primarily f solation when o	ately asse tential for a ocused on pening a N	ss the necessa a safety injectio steam genera 1SIV.	ary proce on to occ tor wate	edural g sur. Th r level a	guidance e and	Э