NRC FORM 195	U.S.	NUCLEAR REGULATORY CONISSION	50-263	
NRC DISTRIBUTION F	OR PART 50 DOCKE	TMATERIAL	FILE NUMBER	
NAC DISTRIBUTION			INCIDENT REPORT	
TO:	FROM:	States Power Company	11/30/77	
Mr. J. G. Keppler	•	lis, Minnesota	DATE RECEIVED 12/9/77	
		INPUT FORM	NUMBER OF COPIES RECEIVED	
GLETTER UNOTORIZED	•	INPOT FORM	1,0,1,0,1	
□ORIGINAL □UNCLASSIFII	ED		100	
DESCRIPTION		ENCLOSURE		
PLANT NAME: Monticello			t (RO 50-263/77-33) on the automatic transfer ency Bus #15 not	
RJL 12/9/7	7 (1 <b>-</b> P)	(1-P)		
		SEND DIRECTI	L EXPOSURE IS INVOLVED LY TO KREGER/J. COLLINS	
		DN/INFORMATION		
BRANCH CHIFF: C4	DAUIS -			
W7 S CYS FOR ACTION				
KIG-ASST.:				
INTERNAL DISTRIBUTION				
PEC FILE				
NRC PDR				
T S F (2)				
MIPC				
SCHROEDER/IPPOLITO				
HOUSTON				
NOVAK/CHECK				
CRIMES				
SUTT ED				
HANAIIFR				
TEDESCO				
FISENHUT				
BAER	<u></u>			
SHAO				
VOLLMER/BUNCH				
KRFGER/ J. COLLINS				
L CROCKER				
	EXTERNAL DISTRIBUTI	ON	CONTROL NUMBER	
LPDR: MINNEGFOLIS	NIN		A 0 4	
TIC:			' ·	
VSTC.			773430028	
ACRS (16) SENT AS CAT	В.		m	



## NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

November 30, 1977

Mr J G Keppler, Director, Region III Office of Inspection & Enforcement U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 263 License No. DPR-22

Loss of 4 KV Safeguards Bus Automatic Transfer Capability

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are 3 copies.

Yours very truly,

M & Voth for

L O Mayer, PE

Manager of Nuclear Support Services

LOM/MHV/ak

cc: Director, IE, USNRC

(30)

Director, MIPC, USNRC

(3)

G Charnoff

MPCA

Attn: J W Ferman

DEC 2 1977

## LICENSEE EVENT REPORT

	CONTROL BLOCK: (PLEASE PRINT ALL REQUIRED INFORMATION	ON]
01 7 B	LICENSEE NAME  M N M N P 1 0 0 - 0 0 0 0 0 0 4 1 1 1 1 1 0 3 3 31 32	
01 7 6	CON'T	7 80
02	EVENT DESCRIPTION  During emergency diesel generator surveillance test, the automatic transfer	لِـــ
7 8	circuitry for emergency Bus #15 did not function. Transfer circuitry for Bus #16	80
7 B	operable. No previous occurrences. Failed due to blown control fuses caused by	
7 B	short circuit. Short removed and fuses replaced. (M-RO-77-33)	80
7 B 06 7 8	9	80
7 8 07 7 8		80
08	During installation of new 480V load center, wires were incorrectly landed on	1
7 6	terminals supplying emergency Bus 15 automatic transfer circuitry, resulting in	80
	short circuit through the fuses. Wires relanded on spare terminals and fuses	80
7 8 111 7 8	FACILITY STATUS % POWER OTHER STATUS DISCOVERY DISCOVERY DESCRIPTION  G 0 0 0 NA B NA	80
12	FORM OF ACTIVITY CONTENT RELEASED OF RELEASE AMOUNT OF ACTIVITY  Z Z NA NA NA  10 11 11 144 45	
13 7 8	PERSONNEL EXPOSURES  NUMBER TYPE DESCRIPTION  O O O O Z NA  9 11 12 13	60
14	PERSONNEL INJURIES NUMBER DESCRIPTION  O O O NA  11 12	80
15 7 8	OFFSITE CONSEQUENCES  NA	80
16	LOSS OR DAMAGE TO FACILITY  TYPE DESCRIPTION  Z NA	80
_	PUBLICITY NA	## N
_	ADDITIONAL FACTORS  (Cause Description Continued) replaced.	80
7 8 9		80
8 9	PHOE: 612/295-5151  GPO 881-6	80