

50-263

NRC DISTRIBUTION FOR PART 50 DOCKET MATERIAL

FILE NUMBER

INCIDENT REPORT

DATE OF DOCUMENT

12/21/77

DATE RECEIVED

1/4/78

NUMBER OF COPIES RECEIVED

100

TO:

Mr. J. G. Keppler

FROM:

Northern States Power Company
Minneapolis, Minnesota
L. O. Mayer☒ LETTER☐ NOTORIZED

PROP

INPUT FORM

☐ UNCLASSIFIED☒ ORIGINAL☒ COPY

DESCRIPTION

ENCLOSURE

Licensee Event Report (RO 50-263/77-34) on
12/07/77 concerning Secondary Containment
Isolation Damper - Inoperable....

PLANT NAME: Monticello

RJL 1/4/78

(1-P)

(1-P)

NOTE: IF PERSONNEL EXPOSURE IS INVOLVED
SEND DIRECTLY TO KREGER/J. COLLINS

1 ENC

FOR ACTION/INFORMATION

BRANCH CHIEF: (4)

DAVIS

BY: CYS FOR ACTION

LTC ASST:

INTERNAL DISTRIBUTION

REG FILE

NRC PDR

T & E (2)

WIPC

SCHROEDER/IPPOLITO

HOUSTON

NOVAK/CHECK

CRIMES

TOLIGHT

BUTLER

HANAUER

TEDESCO

EISENHUT

BAER

SHAO

VOLLMER/BUNCH

KREGER/J. COLLINS

BOGA

L. CRICKER

EXTERNAL DISTRIBUTION

LEDR: MINNEAPOLIS MIN

TIC:

NSIC:

ACRS (16) SENT AS CAT. B

CONTROL NUMBER

A04

780040160

D. Latham

NSP


REGULATORY DOCKET FILE COPY

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

December 21, 1977

Mr J G Keppler, Director, Region III
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137



Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Secondary Containment Isolation Damper - Inoperable

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,

M H Oath / for

L O Mayer, PE
Manager of Nuclear Support Services

LOM/MHV/deh

cc: Director, IE, USNRC (40)
Director, MIPC, USNRC (3)
G Charnoff
MPCA
Attn: J W Ferman

DEC 27 1977

780040160

over

LICENSEE EVENT REPORT

CONTROL BLOCK:

1					6

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME						LICENSE NUMBER								LICENSE TYPE					EVENT TYPE					
01		M	N	M	N	P	1	0	0	-	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9					14	15								25	26					30	31	32

CONT		CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER							EVENT DATE					REPORT DATE							
01			T	L	0	5	0	-	0	2	6	3	1	2	0	7	7	7	1	2	2	1	7	7
7	8	57	58	59	60	61						68	69					74	75					80

EVENT	DESCRIPTION

02 During normal operation, secondary containment isolation dampers associated with
7 8 9
03 reactor building vent supply unit V-AH-4A were found blocked in the open position
7 8 9
04 by ice. Condensate leaking from reputured steam coil froze in presence of sub-zero
7 8 9
05 outside air. No previous reportable occurrence. Ice was thawed using steam lance.
7 8 9
06 Coil was repaired and isolation dampers were returned to service (M-RO-77-34)
7 8 9

PRIME

SYSTEM CODE		CAUSE CODE	COMPONENT CODE						PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	S	D	E	X	X	X	X	X	X	A	A	2	2	0	Y	
7	8	9	10	11	12					17	43	44				47	48

CAUSE DESCRIPTION

08	Corrosion of preheat coil's inner steam-distribution tube resulted in the stagnation and freezing of condensate within coil causing tube rupture. American Air	80
09	Filter Model V2270MPHVZA. Coil repaired. Replacement coils on order.	80

FACILITY STATUS		% POWER		OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	E	1	0	0	NA	C	NA		
7	8	10	12	13	44	45	46		80
FORM OF ACTIVITY RELEASED		CONTENT OF RELEASE		AMOUNT OF ACTIVITY		LOCATION OF RELEASE			
12	Z	Z	NA			NA			
7	8	9	10	11	44	45			80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION			
1	3	0	0	0	Z	NA		

RECEIVED
 JAN 1968

PERSONNEL INJURIES

NUMBER			DESCRIPTION
14	000		NA

7 8 9 11 12

AM

OFFSITE CONSEQUENCES

1	5	NA	28
---	---	----	----

LOSS OR DAMAGE TO FACILITY

TYPE			DESCRIPTION
16	Z		NA

PUBLCITY

1	7	NA
7	8	9

ADDITIONAL FACTORS

18 NA

19. _____

NAME: O N Iverson

PHONE: 612/295-5151

GPO 881-667