DISTR	TION	FOR	PART	50	DOCKET	MATERI			
			ARY 1				CONTROL	NO:	6774
								1/1	,

						FIL	E: <u>\U</u>	U	
FROM:	DATE OF DOC	DATE REC'D		LTR	TWX	RPT	OTHER		
Northern States Por Minneapolis, Minnes L. O. Mayer		7-22-74	7-25-74		х				
TO: J. F. O'Leary		ORIG NONE (CC OTHER		SENT AEC PDR X SENT LOCAL PDR X				
LASS UNCLASS PROP INFO		INPUT	NO CYS REC'D			DOCKE' 50-26			

DESCRIPTION:

Ltr reporting abnormal occurrence AO 263/74-20 on 7-12-74, regarding a malfunction of the #11 Residual Heat Removal (RHR) Service Water pump motor breaker.....

ENCLOSURES:

ACKNOWLEDGED

DO NOT REMOVE

PLANT NAME: Monticello

		FOR ACTION/INFORM	IATION	7-25-74 GC		
BUTLER(L) W/ Copies CLARK(L) W/ Copies PAGE(:) W/ Copies KNIEL(L) W/ Copies	SCHWENCER(L) W/ Copies STOLZ(L) W/ Copies VASSALLO(L) W/ Copies PURPLE (L) W/ Copies	ZIEMANN(L) W/7 Copies DICKER(E) W/ Copies KNIGHTON(E) W/ Copies YOUNGBLOOD(E) W/ Copies	REGAN(E) W/ Copies LEAR(L) W/ Copies W/ Copies			
		INTERNAL DISTRIBU	UTION	·····································		
AEC FILE AEC PDR OGC, ROOM P-506A MUNTZING/STAFF CASE GIAMBUSSO BOYD MOORE (L) (EWR) DEYOUNG(L) (PWR) SKOVHOLT (L) P. COLLINS DENISE REG OPR FILE & REGION(3) MORRIS STEFLE	TECH REVIEW MENDRIE SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA VOLLMER	DENTON GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR	LIC ASST DIGGS (L) GEARIN (L) GOULBOURNE (L) KREUTZER (E) LEE (L) MAIGRET (L) REED (E) SERVICE (L) SHEPPARD (L) SLATER (E) SMITH (L) TEETS (L) WILLIAMS (E) WILSON (L)	A/T IND BRAITMAN SALTZMAN B. HURT PLANS MCDONALD CHAPMAN DUBE W/input E. COUPE D. THOMPSON (2) KLECKER EISENHUT		
To allow the restriction of their reference proposed by proposition of the supplier of the state of the second sec	ri (1900) - Malain American A	EXTERNAL DISTRIBU	TION	86		

✓ - LOCAL PDR Minneapolis, Minn.

1 - TIC (ABERNATHY)

✓ - NSIC(BUCHANAN)

1 - ASLB

1 - P. R. DAVIS (AEROJET NUCLEAR)

16 - CYS ACRS XXXXXXXXX SENT TO LIC. ASST.

7-25-74 DIGGS

(1)(2)(10)-NATIONAL LAB'S

1-ASLBP(E/W Bldg, Rm 529) 1-W. PENNINGTON, Rm E-201 GT

1-CONSULTANT'S


NEWMARK/BLUME/AGBABIAN 1-GERALD ULRIKSON... ORNL BROOKHAVEN NAT. LAB 1-AGMED (Ruth Gussman)

RM-B-127, GT. 1-RD..MULLÉR.,F-309 GT

1-PDR-SAN/LA/NY

1-LIBRARIAN

1-B & M SWINEBROAD, Rm E-201 GT



NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

Mr. J F O'Leary, Director Directorate of Licensing Office of Regulation U S Atomic Energy Commission Washington, DC 20545



ABNORMAL OCCURRENCE REPORT TO THE AEC

Malfunction of No. 11 RHR Service Water Pump Motor Breaker

- 1. Report Number: AO 263/74-20
- 2A. Report Date: July 22, 1974
- 2B. Occurrence Date: July 12, 1974
- 3. <u>Facility</u>: Monticello Nuclear Generating Plant (DPR-22) Monticello, Minnesota 55362
- 4. Identification of Occurrence:

This report concerns a malfunction of the No. 11 Residual Heat Removal (RHR) Service Water pump motor breaker.

5. Conditions Prior to Occurrence:

Steady State Power - The Plant was at 87% of rated power at the time of the occurrence.

6. Description of Occurrence:

On July 12, 1974, during attempts to start the No. 11 RHR SW pump for torus cooling, the motor breaker would not close. The redundant pump in "A" loop and the pumps in the redundant "B" loop were demonstrated to be operable. The breaker was replaced with a spare and the No. 11 RHR SW pump was demonstrated operable.

7. Designation of Apparent Cause of Occurrence:

Component Failure - Inspection revealed that one contact of a spring charging motor limit switch did not close when the closing spring was fully charged. With this contact open, the closing relay could not be energized and the breaker was prevented from being closed wither remotely or locally. Further investigation revealed that the limit switch (the third in a stack of three limit switches which comprise the spring charging motor limit switch assembly) contacts would not close due to foreign material in the switch assembly.



NORTHERN STATES POWER COMPANY

8. Analysis of Occurrence:

This occurrence had no effect on the public health and safety. The remaining three operable RHR SW pumps provided more than sufficient cooling capacity.

9. Corrective Action:

The breaker for the No. 11 RHR Service Water pump motor was replaced with a spare breaker. The faulty spring charging motor limit switch assembly was cleaned. The breaker was operated several times and the subject limit switch functioned properly each time. It is noted the Preventive Maintenance (PM) procedure for this breaker specifically calls for inspecting, cleaning and adjusting these and all other auxiliary switches associated with the breaker. The PM procedure for this breaker was performed during the Spring 1974 refueling outage. The breaker was operated successfully several times since the PM was performed and prior to the occurrence. It is believed that the malfunction of this limit switch is an isolated occurrence and the existing program will minimize the probability of similar future occurrences.

10. Failure Data:

There have been no previous similar failures or malfunctions of this or similar components.

Spring charging motor limit switch
GE Model CR 29400301 in
Breaker Type:
GE Magna-Blast Circuit Breaker
AMH-4,76-250-OD

L O Mayer, PE

Director of Nuclear Support Services

LOM/kn

cc: J G Keppler
 G Charnoff
 Minnesota Pollution Control Agency
 Attn. E A Pryzina