CONTROL	NO:	3677

7	•	•		*			FIL	E: <i>A</i>	10
FROM:		•	DATE OF DOC	DATE	REC'D	LTR	MEMO	RPT	OTHER
l år t her	n States Pow	er Company	1				1		
linneap	olis, Minnes	ota					ŀ	ł	1
L. O. Mayer			4-22-74	4-2	6 - 74	Х		l	
TO:		ORIG	CC	OTHER	SENT AEC PDR XXXX SENT LOCAL PDR XXXX			XXXX	
J. F. O'Leary		1 signed	39					DRXXXX	
CLASS UNCLASS PROP INFO		INPUT	ио сл	S REC'D	DOCKET NO:				
	XXX				40	50	- 263		
DESCRI	PTION:			ENCL	SURES:	·			

Ltr furn info re abnormal occurrence discovered 4-12-74 in which two indications were found in the stainless steel tee associated with the flow switch

DO NOT REMOVE ACKNOWLEDGED

MONTICELLO PLANT NAME:

		FOR ACTION/INFORMAT	TION 4-26-74 GMC	
BUTLER(L)	SCHWENCER(L)	JZIEMANN(L)	REGAN(E)	
W/ Copies CLARK(L)	W/ Copies S T OLZ(L)	W/7 Copies DICKER(E)	W/ Copies	
W/ Copies PARR(L)	W/ Copies VASSALLO(L)	W/ Copies KNIGHTON(E)	W/ Copies	
W/ Copies KNIEL(L)	w/ Copies PURPLE (L)	W/ Copies YOUNGBLOOD(E)	w/ Copies	
W/ Copies	W/ Copies	W/ Copies	W/ Copies	

	·				
			INTERNAL DISTRI	BUTION	
	REG FILE	TECH REVIEW	DENTON		A/T IND
V	AEC PDR	HENDRIE	GRIMES	LIC ASST	BRAITMAN
	OGC, ROOM P-506A	SCHROEDER	GAMMILL	✓DIGGS (L)	SALTZMAN
	MUNTZING/STAFF	✓ MACCARY	KASTNER	GEARIN (L)	B. HURT
	/ CASE	/KNIGHT	BALLARD	GOULBOURNE (L)	PI.ANS
	GIAMBUSSO	JPAWLICKI	SPANGLER	LEE (L)	MCDONALD
	BOYD	SHAO		MAIGRET (L)	DUBE w/Input
	MOORE (L)(BWR)	STELLO	ENVIRO	REED (E)	•
	DEYOUNG(L)(PWR)	HOUSTON	MULLER	SERVICE (L)	INFO
	SKOVHOLT (L)	NOVAK	DICKER	SHEPPARD (L)	C. MILES
٧	GOLLER(L)	√ ROSS	KNIGHTON	SLATER (E)	/B. KING (E/W-358)
	P. COLLINS	/IPPOLITO	YOUNGBLOOD	SMITH (L)	KLECKER
	DENISE	√TEDESCO	REGAN	TEETS (L)	√EISENHUT
	/REG OPR	LONG	PROJECT LDR	WADE (E)	
	FILE & REGION(3)	LAINAS		WILLIAMS (E)	
	MORRIS	√BENAROYA	HARLESS	WILSON (L)	
·	STEELE	√ VOLLMER		• •	

1	- LOC	AT.	פחפ	MTNNEA	POT.TS	MTNN

1 - TIC (ABERNATHY)

√1 - NSIC(BUCHANAN)

1 - ASLB

1 - P. R. DAVIS (AEROJET NUCLEAR)

16 - CYS ACRS HOLDING

Sent to Lic Asst Diggs 4-26-74

(1)(2)(10)-NATIONAL LAB'S_

EXTERNAL DISTRIBUTION

1-ASLBP(E/W Bldg, Rm 529)

1-W. PENNINGTON, Rm E-201 GT

1-CONSULTANT'S

NEWMARK/BLUME/AGBABIAN

1-GERALD ULRIKSON...ORNL

1-B & M SWINEBROAD, Rm E-201 GT

1-PDR-SAN/LA/NY

1-GERALD LELLOUCHE

BROOKHAVEN NAT. LAB

1-AGMED (Ruth Gussman) RM-B-127, GT.

1-RD..MULLER. F-309 GT

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 22, 1974

Mr. J F O'Leary
Directorate of Licensing
Office of Regulation
U S Atomic Energy Commission
Washington, DC 20545

Dear Mr. O'Leary:



APR 26 1974

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Cracked Tee in Standby Liquid Control System

A condition occurred at the Monticello Nuclear Generating Plant which we are reporting to your office in accordance with Section 6.7.B.1, Abnormal Occurrence Reports, of Appendix A, Technical Specifications, of Provisional Operating License DPR-22.

On April 12, 1974, while performing a non-destructive examination (Dye Penetrant test) of a socket weld on a Standby Liquid Control PEECO flow switch (following removal of the flow switch actuator paddle) two indications were found in the stainless steel tee associated with the flow switch.

The depth of the indications was explored and it was determined that they were non-injurious (as defined in the Specification for Wrought Austentic Stainless Steel Piping Fittings, SA-403, in the ASME Boiler and Pressure Vessel Code, Section II). The indications were removed during the exploration. It is postulated that the indications were created in the manufacturing process.

No other indications have been detected in Standby Liquid Control System piping in the past and, because of the non-injurious nature of the indications discovered on April 12, no further inspection is considered necessary.

Very truly yours,

L O Mayer, PE

Director of Nuclear Support Services

LOM/1h

cc: J G Keppler

G Charnoff

Minnesota Pollution Control Agency

Attn. E A Pryzina

3677

REGULATORY DOCKET FILE COPY

(TEMPORARY FORM) CONTROL NO:

						FILE: MID				
FROM:			DATE OF DOC DA		REC'D	LTR	MEMO	RPT	OTHER	
Northern States Power Company Minneapolis, Minnesota 55401 L. O. Mayer		4-18-74	4	-22-74	х					
TO: J. F. O'Leary		ORIG 1 signed	СС	OTHER		SENT AEC PDR X SENT LOCAL PDR X				
CLASS	UNCLASS	PROP INFO	INPUT	NO CYS REC'D		DOCKET NO: 50-263				·
2110022	OMTON.	• • • • • • • • • • • • • • • • • • • •		73307	CHINES					

DESCRIPTION:

Ltr reporting: abnormal occurrence on 4-10-74, regarding a broken stem on RHR service water control valve, CV-1728.....

ENCLOSURES:

DO NOT REMOVE ACKNOWLEDGED

PLANT NAME: Monticello

P. COLLINS IPPOLITO YOUNGBLOOD SMITH (L) DENISE TEDESCO REGAN TEETS (L) REG OPR / LONG PROJECT LDR WADE (E) FILE & REGION(3) LAINAS WILLIAMS (E) MORRIS BENAROYA HARLESS WILSON (L)						
W/ Copies W/ Cop	***************************************		FOR ACTION/INFO	RMATION	4-22-74	GC
W/ Copies W/ Cop	W/ Copies CLARK(L) W/ Copies	W/ Copies STOLZ(L) W/ Copies	V W/7Copies DICKER(E) W/ Copies	W/	Copies	
AEC FILE TECH REVIEW DENTON AEC PDR HENDRIE GRIMES LIC ASST BRAITMAN OGC, ROOM P-506A SCHROEDER GAMMILL DIGGS (L) SALTZMAN MUNTZING/STAFF MACCARY KASTNER GEARIN (L) CASE KNIGHT BALLARD GOULBOURNE (L) BOYD FAWLICKI SPANGLER LEE (L) MOORE (L)(EWR) STELLO ENVIRO REED (E) DEYOUNG(L)(PWR) HOUSTON MULLER SERVICE (L) SKOVHOLT (L) NOVAK DICKER SHEPPARD (L) COLLER(L) KOSS KNIGHTON SLATER (E) P. COLLINS PPOLITO YOUNGBLOOD SMITH (L) DENISE TEDESCO REGAN TEETS (L) REG OPR LONG PROJECT LDR WADE (E) FILE & REGION(3) LAINAS MORRIS BENAROYA HARLESS WILSON (L) STEELE VOLLMER	W/ Copies KNIEL(L)	W/ Copies PURPLE (L)	W/ Copies YOUNGBLOOD(E)	-	•
AEC PDR HENDRIE GRIMES LIC ASST BRAITMAN GGC, ROOM P-506A MUNTZING/STAFF MACCARY KASTNER GEARIN (L) CASE KNIGHT BALLARD GOULBOURNE (L) BOYD MOORE (L)(BWR) DEYOUNG(L)(PWR) STELLO ENVIRO MULLER SCHVIRO MULLER SERVICE (L) SKOVHOLT (L) MOOSS KNIGHTON SKOVHOLT (L) COLLINS P. COLLINS P. COLLINS P. COLLINS P. COLLINS FILE & REGION(3) MAIGRET MACCARY MACCARY KASTNER GEARIN (L) GOULBOURNE (L) MAIGRET LEE (L) MAIGRET MACDONALD DUBE W/INPUT MAIGRET MACCONALD MULLER SERVICE (L) SERVICE (L) C. MILES M. KING (E/W-358) KLECKER MADE (E) WADE (E) WILLIAMS (E) MORRIS MENAROYA HARLESS WILSON (L)			INTERNAL DISTRI	BUTTON		
	AEC PDR OGC, ROOM P-506A MUNTZING/STAFF CASE GIAMBUSSO BOYD MOORE (L)(EWR) DEYOUNG(L)(PWR) SKOVHOLT (L) COLLER(L) P. COLLINS DENISE REG OPR FILE & REGION(3) MORRIS	HENDRIE SCHROEDER MACCARY KNIGHT PAWLICKI SHAO STELLO HOUSTON NOVAK ROSS IPPOLITO TEDESCO LONG LAINAS BENAROYA	GRIMES GAMMILL KASTNER BALLARD SPANGLER ENVIRO MULLER DICKER KNIGHTON YOUNGBLOOD REGAN PROJECT LDR	GEARIN (GOULBOUR LEE (L) MAIGRET REED (E) SERVICE SHEPPARD SLATER (SMITH (L TEETS (L WADE (E) WILLIAMS	(L) (L) (L) (L) () (E)	BRAITMAN SALTZMAN B. HURT PLANS MCDONALD DUBE w/Input INFO C. MILES B. KING (E/W-358) KLECKER
EXTERNAL DISTRIBUTION			EXTERNAL DISTRI	BUTION		A G

✓1 - LOCAL PDR Minneapolis, Minnesota

✓ - TIC (ABERNATHY)

✓ - NSIC(BUCHANAN)

1 - ASLB

1 - P. R. DAVIS (AEROJET NUCLEAR)

√16 - CYS ACRS XNOWXXXX SENT TO LIC ASST. 4-22-74 DIGGS

(1)(2)(10)-NATIONAL LAB'S 1-ASLBP(E/W Bldg, Rm 529)

1-W. PENNINGTON, Rm E-201 GT

1-CONSULTANT'S

NEWMARK/BLUME/AGBABIAN 1-GERALD ULRIKSON...ORNL 1-PDR-SAN/LA/NY 1-GERALD LELLOUCHE

BROOKHAVEN NAT. LAB

1-AGMED(Ruth Gussman)

RM-B-127, GT.

1-RD..MULLER..F-309 GT

1-B & M SWINEBROAD, Rm E-201 GT



NSP


NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

April 18, 1974

Mr. J F O'Leary, Director Directorate of Licensing Office of Regulation U S Atomic Energy Commission Washington, DC 20545

Dear Mr. O'Leary:





MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Broken Stem on RHR Service Water Control Valve, CV-1728

A condition occurred at the Monticello Nuclear Generating Plant which we are reporting to your office in accordance with Section 6.7.B.1, Abnormal Occurrence Reports, of Appendix A, Technical Specifications, of Provisional Operating License DPR-22.

On April 10, 1974, an inspection of the RHR Service Water Control Valve, CV-1728, revealed that the lower valve stem was broken. Further inspection revealed significant metal erosion below the lower port disc. (See attached figure) The nature of these failures and the design of the valve are such that the valve was still able to perform its function of controlling differential pressure between the RHR and RHR Service Water. The valve operator withdraws the stem to a given position and maintains that position through a position feedback device. The inner valve is designed to open when either normal flow or normal differential pressure forces are appled across the valve ports. Consequently, the inner valve will be forced open by hydraulic forces until it is restrained at the required position by the severed lower stem.

This is the first failure of this type which has been experienced. Metallurgical and mechanical investigations to determine the cause of the stem fracture and the erosion are continuing. The control valve in the redundant system will be inspected during the current outage. Following the completion of the metallurgical and mechanical tests and the inspection of the redundant system, a report on the final resolution of the problem will be submitted.

Yours very truly,


L O Maver, PE

Director of Nuclear Support Services

LOM/kn

3515

cc: J G Keppler
 G Charnoff
 Minnesota Pollution Control Agency
 Attn. E A Pryzina



__ Indicates Recommended Spare Parts

Figure 1. Typical Double Port Valve