t		(TEMPORARY FORM)					CONTROL NO: 6387			
							FILE:			
FROM:	<del></del>		DATE OF DOC	DATE	REC'D	LTR	MEMO	RPT	OTHER	
Norther	n States P	ower Company					İ	}		
Minneapolis, Minn. 55401			8-17-73	8-22-73		Х	j			
L. O. Moyer				<u> </u>			<u> </u>	<u> </u>		
TO: John F. O'Leary			ORIG	CC OTHER			SENT AEC PDR X SENT LOCAL PDR X			
			l signed							
CLASS	UNCLASS	PROP INFO	INPUT	NO C	S REC'	D	DOCKE'	T NO:	<del>,</del>	
	XXXX			40		ļ	50 <b>-26</b> 3			
						ļ	• •			
DESCRIPTION:				ENCLOSURES:						
		abnormal occurren								
regarding failure of Main Steam Line Drain Valv				, and the second						
MO-2374, to close				1	ACKNOWLEDGED					
					110-	<del></del>				
•		•		ļ					•	
				(	-	3.T.O.M. T	TINE	7777		
PLANT NAME: Monticello Plant				DO NOT REMOVE				VE		
PLANI I	NAME: MONC	icello Flanc		-						
			FOR ACTION/IN	VFORMA:	rion	8-23-	-73 GC			
BUTLER (L)		SCHWENCER(L)	ZIEMANN(L)	)	REG	AN(E)		•		
W/ Cor		W/ Copies	W/7 Copies			Copies				
CLARK(L)		STOLZ(L)	DICKER(E)		•	•				
W/ Copies		W/ Copies	W/ Copies	3	W/	Copies				
GOLLER(L)		VASSALLO(L)	KNIGHTON (	E)						
W/ Copies		W/ Copies	W/ Copies	5	W/	Copies				
KNIEL(L)		SCHEMEL(L)	YOUNGBLOOL						•	
W/ Cop	pie <b>s</b>	W/ Copies	W/ Copies	3	W/	Copies				
·			INTERNAL DIST	PRT RUT	TON	<del> </del>				
REG FI	LE )	TECH REVIEW	DENTON	IKE DO I.	10.11	,	A	/T IND		
AEC PDI	The state of the s	HENDRIE	GRIMES	LIC ASST		Γ		RAITMAN	1	
OGC, ROOM P-506A			GAMMILL		DIGGS (L)			ALTZMAN		
MUNTZING/STAFF		MACCARY	KASTNER		GEARIN (L)					
CASE		KNIGHT	BALLARD		GOULBOURNE		P	LANS	_ 1	
GIAMBUSSO		PAWLICKI	SPANGLER	LEE (L)			M	CDONALD	,	
BOYD		<b>∽</b> SHAO		1	MAIGRET (L		Di	UBE		
MOORE (L)(BWR)		✓STELLO	ENVIRO	5	SERVICE	(L)				
DEYOUNG(L)(PWR)		<b>✓</b> HOUS TON	MULLER		SHEPPAR		_	NFO	•	
SKOVHOLT (L)		<b>→</b> NOVAK	DICKER	SMITH (L)			Ç	. MILES		

- LOCAL PDR Minneapolis, Minn.

- DTIE (ABERNATHY)

FILE & REGION(3)

P. COLLINS

REG OPR

**✓**MORRIS

**√**STEELE

1 - NSIC (BUCHANAN)

1 - ASLB(YORE/SAYRE/ WOODARD/"H" ST.

✓16 - CYS ACRS EXXXXXXX SENT TO LIC. ASST.

ROSS

LONG

**ALAIN**AS

**BENAROYA** 

VOLLMER

**⊀**PPOLITO

**TEDESCO** 

8-23-73 DIGGS

(1)(2)(10)-NATIONAL LAB'S

EXTERNAL DISTRIBUTION

KNIGHTON

REGAN

HARLESS

YOUNGBLOOD

PROJECT LDR

1-R.Schoonmaker, OC, GT, D-323

TEETS (L)

WILSON (L)

WADE (E) WILLIAMS (E)

1-R. CATLIN, E-256-GT

1-CONSULTANT'S NEWMARK/BLUME/AGBABIAN

1-GERALD ULRIKSON...ORNL

1-PDR-SAN/LA/NY

8. King (RO)


1-GERALD LELLOUCHE

BROOKHAVEN NAT. LAB

1-AGMED (WALTER KOESTER

RM-C-427-GT

1-RD..MULLER..F-309 GT





## NSP

## NORTHERN STATES POWER COMPANY

Minneapolis, Minnesota 55401

DOCKETED USAEC

AUG 22 1973

MAIL SECTION DOCKET CLERK

August 17, 1973

Mr. J. F. O'Leary, Director Directorate of Licensing United States Atomic Energy Commission Washington, D. C. 20545

Dear Mr. O'Leary:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Failure of Main Steam Line Drain Valve, MO-2374, to Close

A condition occurred at the Monticello Nuclear Generating Plant which we are reporting to your office in accordance with Section 6.7.B.1, Abnormal Occurence Reports, of the Technical Specifications, of Provisional Operating License DPR-22.

On August 10, 1973, during a routine plant startup, the outboard main steam line drain valve, MO-2374, a primary containment isolation valve, could not be closed using the control room handswitch.

Investigation revealed that the valve motor closing contactor was properly energized but that its main contact was not closed. It was determined that the mechanical interlock with the corresponding opening contactor was preventing the closing contactor main contact from properly closing. The interlock is constructed such that it blocks the opening contactor armature when the closing contactor is picked up, or conversely, blocks the closing contactor armature when the opening contactor is picked up. The interlock was adjusted to allow proper operation of the closing contactor. The valve was then successfully operated.

Similar contactors for the other DC motor-operated valves were inspected to verify proper adjustment of the mechanical interlocks. One other contactor interlock was found out of adjustment although it was functioning properly. The remainder of the contactors inspected were found to be satisfactory. The outboard head spray isolation valve contactors were not inspected since this valve is held closed by a reactor pressure interlock and cannot be cycled during normal power operation. The contactors for this valve will be inspected at the first opportunity. Adjustment of the contactor interlocks will be incorporated into the breaker maintenance procedure.

This occurrence did not affect safe operation since the redundant inboard main steam line drain valve was fully operable.

One previous malfunction has occurred due to improper assembly of a mechanical interlock, however, no previous malfunctions due to improper adjustment have been experienced. It is felt that the corrective actions taken as a result of this occurrence are sufficient to insure reliable operation of the DC motor operated valves.

Yours very truly,

S. O. Mayer MXV

L O Mayer, PE Director of Nuclear Support Services

LOM/mmm

cc: B H Grier

G Charnoff

Minnesota Pollution Control Agency

Attn: Ken Dzugan