REGULATORY STORMATION DISTRIBUTION STORM (RIDS)

ACCESSION NBR:8007010542 DOC.DATE: 80/06/26 NOTARIZED: NO DOCKET # FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263 AUTH.NAME AUTHOR AFFILIATION SHURTS,S.J. Northern States Power Co. RECIP.NAME RECIPIENT AFFILIATION Region 3, Chicago, Office of the Director

SUBJECT: LER 80-022/03L-0:on 800529,primary containment oxygen concentration exceeded 5% by weight Tech Spec limit.Caused by open svc air isolation valve to drywell.Procedures have been revised to assure proper valve positioning.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR _/ ENCL _/ SIZE: _/+/____ TITLE: Incident Reports

NOTES:_	angan menga angan angan mengan dari pengan di Para angan dipara di pengan dipara di pengan dipara dipara dipar	alata alata anis titis altit a		न कार त्या देवर सम्ब कीत की	विट्रोटन राज्यान स्थिति भोजवान प्रत्यांत्रां स्थाना राज्याने स्थापन स्थापन स्थापन स्थापन स्थापन स्थापन स्थापन	a and and and a state of a		a namata adalah dalam dalam dalam dalam	a nigagan salahan digilak dangan salahin dangan salah
	RECIPIENT		COPIE	ES	RECIPIEN	IT	COPI	ES	
	ID CODE/NAM	Ε	LTTR	ENCL	ID CODE/N	IAME	LTTR	ENCL	
ACTION:	BC IPPOLITO,	T. 05	1	1	PM	06	2	2	
INTERNAL:	A/D CORE & C	s	1	1	A/D RAD PR	TOT	1	1	
	A/D REACT SY	s	1	1	A/D TECHNO	LOGY	1	1	
	AEOD		10	10	AUX SYS BR		1	1	
	CHEM ENG BR		1	1	CONT SYS B	IR	1	1	
	CORE PERF BR		1	1	EMERG PREF	•	1	1	
	EQUIP QUAL B	R	1	1	HANAUER, S.		1	1	
	I&C SYS BR		1	1	I&E	09	2	2	
*	JORDAN, E./IE		1	1	MOORE, V.		1	1	
	MPA	11	3	3	NRC PDR	50	1	1	
	OP EX EVAL B	R	3	3	OR ASSESS	BR	1	1	
	PPAS		1 .	1	QA BR		1	1	
4	REG FILE	01	1	1	SIT ANAL B	R	1	1	
	Contraction of the second s	BR	1	1	TERA:DOUG	ΜΑΥ	1	1	
EXTERNAL:	ACRS		16	16	LPDR	03	1	1	
	NSIC	04	1	1					

NICI in .590

NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

June 26, 1980

Mr J G Keppler Office of Inspection & Enforcement U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

Excessive Oxygen in Containment

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b. in that it represents operation in a degraded mode for a short period of time as allowed by the Limiting Conditions for Operation.

Yours very truly,

David Mussel For

L O Mayer, PE Manager of Nuclear Support Services

LOM/DMM/jh

800701053/

cc: Director, IE, USNRC (30) Director, MIPC, USNRC (3) MPCA Attn: J W Ferman

A002



NRC	FOHM	1 :	366
(7.77)	·	

.

U.S. NUCLEAR REGULATORY COMMISSION

,

(7-77)	LICENSEE EVENT REPORT
	CONTROL BLOCK:
01	$ \begin{array}{ c c c c c c c c } \hline M & N & P & 1 \\ \hline 9 & \text{Licensee code} & 14 \\ \hline 15 & \text{License number} & 25 \\ \hline 26 & \text{License type } 30 \\ \hline 26 & \text{License type } 30 \\ \hline 26 & \text{License type } 30 \\ \hline 37 & \text{CAT } 58 \\ \hline 38 & \text{CAT } 58 \\ \hline 58 & \text{CAT } 58 \\ \hline 58 & \text{CAT } 58 \\ \hline 58 & \text{CAT } $
	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
10131	1 limit specified in Technical Specification 3.7.A.5.a during the weekly surveillance
	test. The oxygen concentrations in the drywell and suppression chamber were 5.75% and
	5.3% respectively. There has been one previous similar occurrence (RO-76-14). This
06	occurrence had negligible affect on public health and safety.
07	
08	80
7 8 09 7 8	$\begin{array}{c ccccccccccccccccccccccccccccccccccc$
10	CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27) Upon discovery, actions taken to reduce 0_2 to less than 5% (accomplished within 8 hrs.)
11	Service air isolation valve to drywell found open. Leakage at drywell air stations
12	caused gradual increase in O2 over several week period. Procedures and checklists have
13	been revised to assure proper positioning of service air isolation valve during opera-
15 78	$ \begin{array}{c c c c c c c c c c c c c c c c c c c $
$\begin{bmatrix} 1 & 7 \\ 7 & 8 \end{bmatrix}$ $\begin{bmatrix} 1 & 3 \\ 7 & 8 \end{bmatrix}$ $\begin{bmatrix} 1 & 3 \\ 7 & 8 \end{bmatrix}$	PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (31) 0 0 0 (37) Z (38) NA 9 11 12 13 80 9 11 12 13 80 9 11 12 13 80 9 11 12 13 80 9 11 12 80 80 9 11 12 80 80 10 0 0 40 NA 80 9 11 12 80 80 10 0 0 43 80 10 0 0 43 80 10 12 13 80 80 11 12 13 80 80 12 13 14 14 14 13 14 14 14 14 14 15 16 16 16 15 16 17 16 16 16
7 8 20 7 8 800	$\begin{array}{c} \begin{array}{c} 10 \\ PUBLICITY \\ ISSUED \\ 9 \\ 10 \\ \hline \\ 9 \\ 10 \\ \hline \\ 80 \\ \hline \\ \\ \\ 80 \\ \hline \\ \\ \\ 80 \\ \hline \\ \\ \\ 80 \\ \hline \\ \\ \\ \\ 80 \\ \hline \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ $

	NRC FGR (7-77)	
-	(1-11)	LICENSEE EVENT REPORT
٦		CONTROL BLOCK:
	0 1	M N M N P 1 0 0 0 - 0 0 0 0 - 0 0 0 0 - 0 0 0 0 0
	CON'T	REPORT L 6 0 5 0 0 2 6 3 7 0 5 2 9 8 0 8 0 6 2 6 8 0 9 SOURCE 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80 9 EVENT DESCRIPTION AND PROBABLE CONSEQUENCES 10
	02	The oxygen concentration of primary containment was found to exceed the 5% by weight
	03	limit specified in Technical Specification 3.7.A.5.a during the weekly surveillance
	04	test. The oxygen concentrations in the drywell and suppression chamber were 5.75% and
	0 5	5.3% respectively. There has been one previous similar occurrence (RO-76-14). This
	06	occurrence had negligible affect on public health and safety.
	0 7	
	08	80
	7 8 09 7 8	9 SYSTEM CAUSE CAUSE CAUSE COMPONENT CODE SUBCODE SU
•. •	•	$\begin{array}{c c c c c c c c c c c c c c c c c c c $
	1 0	Upon discovery, actions taken to reduce 0, to less than 5% (accomplished within 8 hrs.)
	11	Service air isolation valve to drywell found open. Leakage at drywell air stations
	12	caused gradual increase in 0, over several week period. Procedures and checklists have
	13	been revised to assure proper positioning of service air isolation valve during opera-
	$\begin{bmatrix} 1 \\ 4 \end{bmatrix}$	L tion and assure that greater margins to 0, limit are maintained.
	15	FACILITY % POWER OTHER STATUS (30) METHOD OF DISCOVERY DISCOVERY DISCOVERY DESCRIPTION (32) $E[28]$ 1 0 0 (29) NA B (31) Operator Observation (32) 9 10 12 13 44 45 46 80
		ACTIVITY CONTENT IELEASED OF RELEASE AMOUNT OF ACTIVITY 35 LOCATION OF RELEASE 36 2 (33) Z (34) NA NA
· .	7 8	9 10 11 44 45 80 PERSONNEL EXPOSURES NUMBER TYPE DESCRIPTION (3)
	1 7 7 8	$\begin{bmatrix} 0 & 0 & 0 \\ 1 & 1 \end{bmatrix} \begin{bmatrix} 2 & 32 \\ 13 \end{bmatrix} \begin{bmatrix} 38 & NA \\ 13 \end{bmatrix} $
	1 8 7 8	PERSONNEL INJURIES NUMBER DESCRIPTION (4) 0 0 0 (4) NA 9 11 12 LOSS OF OR DAMAGE TO FACILITY (43) 80
	19 7 8	ype Description (2) 9 10 80
4 -	20	PUBLICITY NRC USE ONLY
	7 8	9 10 68 69 80 5 NAME OF PREPARER <u>S. J. Shurts</u> PHONE <u>612/295-5151</u>
	80 C	TO TO SHE

,