

FROM: Northern States Power Company
 Minneapolis, Minnesota 55401
 R.G. Duncanson, Jr. P.E.

DATE OF DOCUMENT: Nov. 16, 1971	DATE RECEIVED: Nov. 22, 1971	NO.: 50
LTR. <input checked="" type="checkbox"/>	MEMO: <input type="checkbox"/>	REPORT: <input type="checkbox"/>
OTHER: <input type="checkbox"/>		

TO: **Dr. Peter A. Morris**

ORIG.: CC: OTHER:

1 signed & 2 conf'd

ACTION NECESSARY <input type="checkbox"/>	CONCURRENCE <input type="checkbox"/>	DATE ANSWERED:
NO ACTION NECESSARY <input type="checkbox"/>	COMMENT <input type="checkbox"/>	BY:

CLASSIF: **U** POST OFFICE REG. NO:

FILE CODE: **50-263**

DESCRIPTION: (Must Be Unclassified)
Ltr reporting on 10-20-71 failure of an ECCS pump start permissive switch to trip within the specified settings.

REFERRED TO	DATE	RECEIVED BY	DATE
Knuth w/9 cys for ACTION	11-22-71	Ross	
DISTRIBUTION:		Dr. Hansuer	
Reg File Cy		Dr. Mann	
AEC PDR		Rosen	
OGC-Rm-P-506-A Compliance (2)		N. Lauben	
Muntzing & Staff		B. Colmar	
Morris/Schroeder		DO NOT REMOVE ACKNOWLEDGED	
D. Thompson			
Skovholt			
DTIB (Laughlin)		5080	
NSIC (Buchanan)			
Boyd			
E.G. Case			
Novak			DL

ENCLOSURES:

REMARKS:

NSP

Regulatory

File Cy.

NORTHERN STATES POWER COMPANY

Minneapolis, Minnesota 55401

November 16, 1971

Dr. Peter A. Morris, Director
Division of Reactor Licensing
United States Atomic Energy Commission
Washington, D.C. 25045

Dear Dr. Morris:

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22



Failure of an ECCS Pump Start Permissive
Switch to Trip Within the Specified Settings

During the performance of a monthly surveillance test on October 20, 1971, it was discovered that an ECCS pump start permissive pressure switch tripped below the trip settings specified in the Technical Specifications. This occurrence is being reported in accordance with Section 6.6.B.3, of the Technical Specifications. The Region III Compliance Office has been notified of the occurrence.

Summary Description of Occurrence

On October 20, 1971, a trip setting of a low reactor pressure pump start permissive switch (switch #2 of PS 2-3-53A) was found to be approximately 12.5 psig below the trip setting of ≥ 450 psig specified in Table 3.2.2 of the Technical Specifications. (The allowable deviation for this trip setting, as specified in Table 3.2.5 of the Technical Specifications is -10 psi.) The #2 switch of PS 2-3-53A is used in the LPCI start permissive logic; however, automatic initiation of the LPCI system would have occurred, if required, at the specified reactor pressure by action of the redundant pump start permissive switch PS 2-3-53B.

The investigation of the occurrence shows that switch PS 2-3-53A operates properly. As a result of this finding, the low setpoint problem has been attributed to setpoint drift and/or calibration inaccuracies. To prevent similar occurrences from happening, the low reactor pressure pump start permissive switches will be set at 460 psig prior to further plant operations. Increasing the setpoint will not present any operational difficulties since the core spray and RHR pumps are provided with minimum flow lines so that the pumps will not be damaged by early starts.



Misc
5028

LB

The unusual occurrence report has been written for this occurrence and will be available to the Region III Compliance Inspector for review during his next visit.

Yours very truly,

RO Duncanson /CEL

R.O. Duncanson, Jr. P.E.
Manager of Power Production
Chairman - Monticello Safety Audit Committee

ROD/CEL/caf

Faint, illegible text at the top of the page, possibly a header or title.

Second line of faint, illegible text.

Third line of faint, illegible text.

Fourth line of faint, illegible text.

Fifth line of faint, illegible text.

Sixth line of faint, illegible text.

Seventh line of faint, illegible text.

Eighth line of faint, illegible text.