

# NSP

NORTHERN STATES POWER COMPANY

MINNEAPOLIS, MINNESOTA 55401

October 20, 1980

Mr J G Keppler  
Office of Inspection & Enforcement  
U S Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr Keppler:

MONTICELLO NUCLEAR GENERATING PLANT  
Docket No. 50-263 License No. DPR-22

"A" Outboard MSIV Inoperable - Update Report

An updated Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

Yours very truly,



L O Mayer, PE  
Manager of Nuclear Support Services

LOM/DMM/bd

cc: Director, IE, USNRC (30)  
✓ Director, MIPC, USNRC (3)  
NRC Resident Inspector  
MPCA  
Attn: J W Ferman

-over-

A002  
S  
1/1

S 8010280 526

LICENSEE EVENT REPORT

CONTROL BLOCK: [ | | | | | ] ① (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 M N M N P 1 ② 0 0 - 0 0 0 0 0 0 - 0 0 ③ 4 1 1 1 ④ ⑤

CON'T 7 8 REPORT SOURCE ⑥ L 0 5 0 0 0 2 6 3 ⑦ 0 8 1 7 8 0 ⑧ 1 0 2 0 8 0 ⑨

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES ⑩

0 2 | During normal power operation while performing surveillance tests, A0-2-86A,
0 3 | outboard MSIV, exceeded the T.S.4.7.D.1.c.(2) required closure time and failed
0 4 | to close as required by T.S.3.7.D.1 during a later special test. A0-2-86D also
0 5 | exceeded the closure time during the special test. Redundant valves closed during
0 6 | repair and testing. No previous similar event. No affect on public health of
0 7 | safety.

7 8 9 SYSTEM CODE [ C D ] ⑪ CAUSE CODE [ B ] ⑫ CAUSE SUBCODE [ A ] ⑬ COMPONENT CODE [ V A L V E X ] ⑭

17 LER/RO REPORT NUMBER [ ] ⑰ EVENT YEAR [ 8 0 ] ⑱ SEQUENTIAL REPORT NO. [ 0 2 6 ] ⑲ OCCURRENCE CODE [ 0 3 ] ⑳ REPORT TYPE [ L ] ㉑ REVISION NO. [ 1 ] ㉒

ACTION TAKEN [ A ] ⑳ FUTURE ACTION [ G ] ㉑ EFFECT ON PLANT [ B ] ㉒ SHUTDOWN METHOD [ Z ] ㉓ HOURS [ 0 0 2 7 ] ㉔ ATTACHMENT SUBMITTED [ N ] ㉕ NPRD-4 FORM SUB. [ Y ] ㉖ PRIME COMP. SUPPLIER [ N ] ㉗ COMPONENT MANUFACTURER [ A 5 8 5 ] ㉘

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS ㉚

1 0 | Slow closures caused by lubricant in AVC actuator becoming sticky from prolonged
1 1 | heat exposure. Replaced actuator. Failure to close caused by particulate in plunger
1 2 | of AC solenoid. All outboard AC solenoids cleaned and plungers replaced. Valves
1 3 | being tested weekly pending actuator rebuild during next scheduled outage
1 4 | Maintenance program to be initiated.

1 5 FACILITY STATUS [ E ] ㉙ % POWER [ 0 7 5 ] ㉚ OTHER STATUS [ NA ] ㉛ METHOD OF DISCOVERY [ C ] ㉜ DISCOVERY DESCRIPTION [ Special Surveillance Test ] ㉝

1 6 ACTIVITY CONTENT [ Z ] ㉞ AMOUNT OF ACTIVITY [ NA ] ㉟ LOCATION OF RELEASE [ NA ] ㊱

1 7 PERSONNEL EXPOSURES NUMBER [ 0 0 0 ] ㊲ TYPE [ Z ] ㊳ DESCRIPTION [ NA ] ㊴

1 8 PERSONNEL INJURIES NUMBER [ 0 0 0 ] ㊵ DESCRIPTION [ NA ] ㊶

1 9 LOSS OF OR DAMAGE TO FACILITY TYPE [ Z ] ㊷ DESCRIPTION [ NA ] ㊸

2 0 ISSUED [ N ] ㊹ DESCRIPTION [ NA ] ㊺ PUBLICITY [ ] ㊻ NRC USE ONLY