



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

May 20, 1981

Mr J G Keppler
Office of Inspection & Enforcement
U S Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

RHR SW CV-1778 Uncoupled

The Licensee Event Report for this occurrence is reproduced on the back of this letter. Enclosed are three copies.

This event is reported in compliance with Technical Specification 6.7.B.2.b since it represents operation in a degraded mode permitted by the Limiting Conditions for Operation.

L O Mayer, PE
Manager of Nuclear Support Services

LOM/TMP/bd

cc: Director, IE, USNRC (30)
Director, MIPC, USNRC (3)
NRC Resident Inspector
MPCA
Attn: J W Ferman

-over-

Handwritten: 1002 5/1

8105220 210.

5

LICENSEE EVENT REPORT

CONTROL BLOCK: _____ (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

7 8 9 M N M N P 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9
 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58 (E)

CON'T
 7 8 9 REPORT SOURCE (L) 0 1 5 0 0 0 2 6 3 7 0 4 2 0 8 1 8 0 1 5 2 0 8 1 9
 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During startup of A Loop of shutdown cooling the valve operator stem on the
 0 3 RHR SW Heat Exchanger Discharge Control Valve, CV 1728, uncoupled from the valve
 0 4 stem causing loop to be inoperable (T.S.6.7.B.2.b). Redundant loop
 0 5 available for shutdown cooling. No previous similar events. No effect on
 0 6 public health and safety.
 0 7
 0 8

7 8 9 SYSTEM CODE S B (11) CAUSE CODE A (12) CAUSE SUBCODE C (13) COMPONENT CODE V A L V E X (14) COMP. SUBCODE F (15) VALVE SUBCODE G (16)

17 LER/RO REPORT NUMBER 8 1 1 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9 0 1 2 3 4 5 6 7 8 9
 EVENT YEAR 21 22 SEQUENTIAL REPORT NO. 24 26 OCCURRENCE CODE 27 29 REPORT TYPE L (30) REVISION NO. 32 0
 ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS 22 0 0 0 0 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. Y (24) PRIME COMP. SUPPLIER L (25) COMPONENT MANUFACTURER F 1 3 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 8" control valve, Model 657ED. Improper coupling of the valve operator stem and
 1 1 the valve stem caused the event. Coupling component was replaced and coupling
 1 2 verified correct by I&C Specialist. Similar valve in redundant loop inspected
 1 3 to insure no similar problem.
 1 4

7 8 9 FACILITY STATUS H (28) % POWER 0 0 0 (29) OTHER STATUS NA (30) METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION Operator Observation (32)

7 8 9 ACTIVITY CONTENT Z (33) Z (34) NA AMOUNT OF ACTIVITY (35) LOCATION OF RELEASE (36) NA

7 8 9 PERSONNEL EXPOSURES NUMBER 0 0 0 (37) TYPE Z (38) DESCRIPTION (39) NA

7 8 9 PERSONNEL INJURIES NUMBER 0 0 0 (40) DESCRIPTION (41) NA

7 8 9 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) NA

7 8 9 PUBLICITY ISSUED N (44) DESCRIPTION (45) NA

NAME OF PREPARER P. A. Tobin

8105220237

(612)295-5151