

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8105270432 DOC.DATE: 81/05/20 NOTARIZED: NO DOCKET #
 FACIL:50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH.NAME AUTHOR AFFILIATION
 TOBIN,P.A. Northern States Power Co.
 RECIP.NAME RECIPIENT AFFILIATION
 KEPPLER,J.G. Region 3,Chicago, Office of the Director

SUBJECT: LER 81-007/01T-0:on 810420,during local leak rate testing,
 outboard MSIV AU-2-860 found to exceed Tech Specs.Caused by
 leakage through valve packing.Valve repacked,stroked &
 retested satisfactorily.

DISTRIBUTION CODE: A002S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+4
 TITLE: Incident Reports

NOTES:

ACTION:	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTTR	ENCL		LTTR	ENCL
	IPPOLITO,T. 04	3	3			
INTERNAL:	A/D COMP&STRU06	1	1	A/D ENV TECH 07	1	1
	A/D MATL & QU08	1	1	A/D OP REACT009	1	1
	A/D PLANT SYS10	1	1	A/D RAD PROT 11	1	1
	A/D SFTY ASSE12	1	1	ACC EVAL BR 14	1	1
	AEOD	3	3	AEOD/DMU	3	3
	ASLBP/J.HARD	1	1	AUX SYS BR 15	1	1
	CHEM ENG BR 16	1	1	CONT SYS BR 17	1	1
	CORE PERF BR 18	1	1	DIR,ENGINEER120	1	1
	DIR,HUM FAC S21	1	1	DIR,SYS INTEG22	1	1
	EFF TR SYS BR23	1	1	EQUIP QUAL BR25	1	1
	GEOSCIENCES 26	1	1	I&C SYS BR 29	1	1
	I&E 05	1	1	JORDAN,E./IE	1	1
	LIC GUID BR 30	1	1	MATL ENG BR 32	1	1
	MECH ENG BR 33	1	1	NRC PDR 02	1	1
	OR ASSESS BR 35	1	1	POWER SYS BR 36	1	1
	RAD ASSESS BR39	1	1	REACT SYS BR 40	1	1
	REG FILE 01	1	1	REL & RISK A 41	1	1
	SFTY PROG EVA42	1	1	STRUCT ENG BR44	1	1
EXTERNAL:	ACRS 46	16	16	INPO,J.STEARNS	1	1
	LPDR 03	1	1	NSIC 05	1	1

LICENSEE EVENT REPORT

CONTROL BLOCK: (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

LICENSEE CODE: M N M N P 1; LICENSE NUMBER: 0 0 - 0 0 0 0 0 0 - 0 0 0; LICENSE TYPE: 4 1 1 1 1; CAT: 4

REPORT SOURCE: L; DOCKET NUMBER: 0 5 0 0 0 2 6 3; EVENT DATE: 0 4 2 0 8 1; REPORT DATE: 0 5 2 0 8 1

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES

0 2 | During local leak rate testing, outboard MSIV A0-2-86D was found to exceed
0 3 | T.S.4.7.A.2.f. acceptance criteria for LLRT (16.7 scfh vs. 11.5 scfh). Inboard
0 4 | MSIV was operable and within the acceptance criteria for LLRT. Two previous
0 5 | similar events for this valve (RO-78-19, RO-80-03). No effect on public health
0 6 | and safety.

SYSTEM CODE: C D; CAUSE CODE: E; CAUSE SUBCODE: B; COMPONENT CODE: V A L V E X; COMP. SUBCODE: F; VALVE SUBCODE: D

LER/RO REPORT NUMBER: 8 1; EVENT YEAR: 8 1; SEQUENTIAL REPORT NO.: 0 0 7; OCCURRENCE CODE: 0 1; REPORT TYPE: T

ACTION TAKEN: B; FUTURE ACTION: G; EFFECT ON PLANT: Z; SHUTDOWN METHOD: Z; HOURS: 0 0 0 0; ATTACHMENT SUBMITTED: N; NPD-4 FORM SUB.: Y; PRIME COMP. SUPPLIER: N; COMPONENT MANUFACTURER: A 5 8 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS

1 0 | 18" Y Type Globe Valve, drawing 20786-H. Leakage through valve packing. Valve
1 1 | repacked, stroked, and retested satisfactorily. Maintenance procedure to be
1 2 | revised to include inspection/replacement of packing.

FACILITY STATUS: H; POWER: 0 0 0; OTHER STATUS: NA; METHOD OF DISCOVERY: B; DISCOVERY DESCRIPTION: Local Leak Rate Testing

ACTIVITY CONTENT: Z; AMOUNT OF ACTIVITY: NA; LOCATION OF RELEASE: NA

PERSONNEL EXPOSURES: NUMBER: 0 0 0; TYPE: Z; DESCRIPTION: NA

PERSONNEL INJURIES: NUMBER: 0 0 0; DESCRIPTION: NA

LOSS OF OR DAMAGE TO FACILITY: TYPE: Z; DESCRIPTION: NA

PUBLICITY ISSUED: N; DESCRIPTION: NA

NAME OF PREPARER: P. A. Tobin

PHONE: (612) 295-5151

8105270432