

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712280067 DOC. DATE: 87/12/14 NOTARIZED: NO DOCKET #
 FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States 05000263
 AUTH. NAME AUTHOR AFFILIATION
 IVERSON, O.N. Northern States Power Co.
 MUSOLF, D. Northern States Power Co.
 RECIP. NAME RECIPIENT AFFILIATION

SUBJECT: LER 87-022-00: on 871112, latches on two fire doors made inoperable due to inadequacies in procedure & training.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 4
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 LA	1 1	PD3-3 PD	1 1
SCALETTI, D	1 1		
INTERNAL: ACRS MICHELSON	1 1	ACRS MOELLER	2 2
AEOD/DOA	1 1	AEOD/DSP/NAS	1 1
AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1
ARM/DCTS/DAB	1 1	DEDRO	1 1
NRR/DEST/ADS	1 0	NRR/DEST/CEB	1 1
NRR/DEST/ELB	1 1	NRR/DEST/ICSB	1 1
NRR/DEST/MEB	1 1	NRR/DEST/MTB	1 1
NRR/DEST/PSB	1 1	NRR/DEST/RSB	1 1
NRR/DEST/SGB	1 1	NRR/DLPQ/HFB	1 1
NRR/DLPQ, QAB	1 1	NRR/DOEA/EAB	1 1
NRR/DREP/RAB	1 1	NRR/DREP/RPB	2 2
NRR/DRIS/SIB	1 1	NRR/PMAS/ILRB	1 1
REG FILE 02	1 1	RES DEPY GI	1 1
RES TELFORD, J	1 1	RES/DE/EIB	1 1
RGN3 FILE 01	1 1		
EXTERNAL: EG&G GROH, M	5 5	FORD BLDG HOY, A	1 1
H ST LOBBY WARD	1 1	LPDR	1 1
NRC PDR	1 1	NSIC HARRIS, J	1 1
NSIC MAYS, G	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTTR 46 ENCL 45

R
I
D
S
/
A
D
D
S
/
A
D
D
S

LICENSEE EVENT REPORT (LER)

FACILITY NAME (1)										DOCKET NUMBER (2)										PAGE (3)									
Monticello										0 5 10 0 0 2 6 3 1										OF 0 3									

TITLE (4)
Latches on Two Fire Doors Made Inoperable Due to Inadequacies in a Procedure and Training

EVENT DATE (5)				LER NUMBER (6)				REPORT DATE (7)				OTHER FACILITIES INVOLVED (8)												
MONTH	DAY	YEAR	YEAR	SEQUENTIAL	REVISION	MONTH	DAY	YEAR	FACILITY NAMES															
				NUMBER	NUMBER				DOCKET NUMBERS															
									0 5 0 0 0 0															
1	1	1	2	8	7	8	7	-	0	2	2	-	0	0	1	2	1	4	8	7	0 5 0 0 0 0			

OPERATING MODE (9) | THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check one or more of the following)(11)

POWER			20.402(b)		20.405(c)		50.73(a)(2)(iv)		73.71(b)		
LEVEL			20.405(a)(1)(i)		50.38(c)(1)		50.73(a)(2)(v)		73.71(c)		
(10)	0	0	0		20.405(a)(1)(ii)		50.36(c)(2)		50.73(a)(2)(vii)		OTHER
					20.405(a)(1)(iii)	X	50.73(a)(2)(i)		50.73(a)(2)(viii)(A) (Specify in		
					20.405(a)(1)(iv)		50.73(a)(2)(ii)		50.73(a)(2)(viii)(B) Abstract		
					20.405(a)(1)(v)		50.73(a)(2)(iii)		50.73(a)(2)(x) below and		
in Text, NRC Form 366A)											

LICENSEE CONTACT FOR THIS LER (12)

NAME										TELEPHONE NUMBER									
Oliver N. Iverson, Sr. Production Engineer										6 1 2 2 9 5 - 5 1 5 1									

COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT (13)

CAUSE	SYSTEM	COMPONENT	MANUFAC	REPORTABLE	CAUSE	SYSTEM	COMPONENT	MANUFAC	REPORTABLE
			TURER	TO NPRDS				TURER	TO NPRDS

SUPPLEMENTAL REPORT EXPECTED (14)

YES (If yes, complete EXPECTED SUBMISSION DATE)	X	NO	EXPECTED SUBMISSION DATE (15)				
---	---	----	-------------------------------	--	--	--	--

ABSTRACT (Limit to 1400 spaces, i.e., approximately fifteen single-space typewritten lines) (16)

During plant inspections, two fire doors located in Appendix R fire barriers were found inoperable due to latches held open with tape. These fire doors are required to be operable per Tech. Spec. 3.13.G.1. Upon discovery, the tape was removed and the doors made operable.

The root cause of these two events was determined to be inadequacies in a procedure and training. One of the latches was taped open to prevent the door from locking, while performing a radiation protection procedure which required this door to be unlocked in preparation for the refueling outage. The other door is believed to have been taped by construction personnel who were not aware that taping the latch open makes the fire door inoperable.

The radiation protection procedure will be revised to instruct personnel not to tape open the door latches. The training program will be upgraded to provide training on what will make a fire door inoperable. Also, the Daily Fire Door Inspection procedure will be revised to provide a more thorough daily inspection.

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)		
		YEAR		SEQUENTIAL		REVISION				
		NUMBER		NUMBER		NUMBER				
Monticello	05000263	87	0	2	2	0	0	02	0	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

DESCRIPTION

While making a plant inspection on November 12, 1987, during a refueling outage, the Plant Manager found a latch taped open on fire door #18 (DR) providing access to the condenser room. This taping allowed the door to close, but prevented the latch from engaging the strike plate. This door is located in an Appendix R fire barrier which is required to be operable per Tech. Spec. 3.13.G.1. Another fire door with a taped latch was discovered on December 1, 1987, during a refueling outage by the NRC Senior Resident Inspector. This door (#42) provides access to the Torus Area and is also located in an Appendix R barrier. Upon discovery of these taped latches, the tape was removed and the doors were returned to operable status.

CAUSE

An investigation was conducted to determine the cause of the latch taping. In the case of door #18, it was determined that a Radiation Protection Specialist had taped the latch at the beginning of the refueling outage when performing Procedure R.1.4, "Outage Temporary Extended RWP Revisions". As part of this procedure, various doors are unlocked which are normally locked during power operation. The door was unlocked by taping the latch open. Door #42 is believed to have been taped by construction personnel who were not aware that taping the latch open makes the door inoperable. The root causes of these two events was determined to be inadequacies in a procedure and training.

ANALYSIS

The two door latches are believed to have been taped open during the current refueling outage and were discovered during the outage. Door latch #18 was taped on Oct. 22, 1987, the first day of the outage, and existed until Nov. 12, 1987, when discovered. Door latch #42 taping cannot be determined but is believed to have been done during the outage when there was extensive construction activities.

The period while the fire doors were inoperable did not have any effect on safety because the shutdown equipment these doors protect was not required to be operable. This event could have occurred under worse conditions such as power operation. However, it is unlikely this would happen because the activities that lead to the latch taping do not normally occur during power operation. Also, the fire loading in the area of the doors is minimal and the doors do close with the latches taped open. Therefore, there was no effect on public health and safety during this event.

CORRECTIVE ACTIONS

Procedure R.1.4 will be revised to require that any fire doors that are unlocked be left in a closed and latched condition. The training program will be upgraded to provide training on what will make a fire door inoperable. The fact that taping the latch open disables the fire door is a subtle point that is not recognized by most

LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)						PAGE (3)		
		YEAR	SEQUENTIAL	REVISION						
			NUMBER	NUMBER						
Monticello	05000263	8	7	-	0	2	2	-	0	0
									0	3

TEXT (If more space is required, use additional NRC Form 366A's) (17)

people (NFPA 80-1983 Chapter 14 - 1.2 requires that fire doors "be kept closed and latched or arranged for automatic closing"). Also, the Fire Door Daily Inspection procedure will be revised to require that the operator check the latch on each fire door by attempting to pull the door open in addition to the present visual inspection which verifies the door is closed.

A Tech. Spec. amendment has been submitted to the NRC on March 31, 1986 which proposes that "All penetration fire barriers in fire area boundaries shall be operable whenever safe shutdown equipment in that fire area is required to be operable." These two events would not be reportable under the proposed amendment.

ADDITIONAL INFORMATION

No previous similar reportable events have occurred.



Northern States Power Company

414 Nicollet Mall
Minneapolis, Minnesota 55401
Telephone (612) 330-5500

December 14, 1987

Report Required by
10 CFR Part 50, Section 50.73

US Nuclear Regulatory Commission
Attn: Document Control Desk
Washington DC 20555

MONTICELLO NUCLEAR GENERATING PLANT
Docket No. 50-263 License No. DPR-22

Latches on Two Fire Doors Made Inoperable Due to
Inadequacies in a Procedure and Training

The Licensee Event Report for this occurrence is attached.

Monica Vek

for David Musolf
Manager - Nuclear Support Services

c: Regional Administrator-III, NRC
NRR Project Manager, NRC
Resident Inspector, NRC
MPCA
Attn: J W Ferman

Attachment

IE22
1/1