REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8705110198 DOC. DATE: 87/04/14 NOTARIZED: NO FACIL: 50-263 Monticello Nuclear Generating Plant, Northern States

DDCKET # 05000263

AUTH. NAME

AUTHOR AFFILIATION

SON, C. E. ECIP. NAME Northern States Power Co. RECIPIENT AFFILIATION

GUL DEMOND, W. G.

Region 3. Office of Director

SUBJECT: Responds to NRC 870312 ltr re violations noted in Insp Rept 50-263/87-03: Corrective actions: procedure revised to clarify prerequisits on Tech Spec 3.3.4 insuring adequate shutdown

margins prior to performance of isolations.

DISTRIBUTION CODE: IEO1D COPIES RECEIVED: LTR 1 ENCL 2 SIZE: 3

TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTTR	ENCL	ID CODE/NAME	LTTR	ENCL
	PD3-3 LA	1	P	PD3-3 PD	1	1
	SCALETTI, D	5	₽.			
INTERNAL:	AEOD	1	h i	DEDRO	1 .	1
	ENF LIEBERMAN	1	i	NRR ROE, M. L	1	i i
	NRR/DOEA DIR	1	1	NRR/DREP/EPB	1 ,	1
	NRR/DREP/RPB	2	2	MRR/DRIS DIR	1	
	NRR/PMAS/ILRB	1	1	GGC/HDS1	· 1	.].
	REG FILE	· 1	1	RES SPEIS, T	. 1	1
	RGN3 FILE 01	1	li i		* .	1
EXTERNAL:	LPDR	· 1	k .	NRC PDR	1	4
	NSIC	1	1			•





April 14, 1987

Northern States Power Company

414 Nicollet Mall Minneapolis, Minnesota 55401 Telephone (612) 330-5500

W G Guldemond, Chief Reactor Projects Branch 2 Region III U S Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

MONTICELLO NUCLEAR GENERATING PLANT Docket No. 50-263 License No. DPR-22

In response to your letter of March 12, 1987, concerning Inspection Report No. 50-263/87003(DRP), the following information is offered regarding the violation cited:

Violation

Technical Sepcification (TS) 3.3.A.l requires that shutdown margin be available to make the reactor subcritical in the most reactive condition during the operating cycle with the strongest operable control rod in its full-out position and all other operable rods fully inserted.

TS 6.5.C.3 requires that detailed written procedures shall be prepared and followed for areas including preventive or corrective maintenance of plant and systems that could have an effect on nuclear safety.

Contrary to the above, Operations Controlling Document (OCD) 4201 was prepared in a manner whereby its use could result in not satisfying TS 3.3.A.l when performing preventive maintenance on one or more hydraulic control units (HCU) for a control rod. This procedure did not satisfy the requirements of TS 6.5.C.3.

Reason for Violation

OCD 4201 included a prerequisite to verify compliance with TS 3.3.A. At the time the procedure was written this was felt to be sufficient guidance to meet the requirements of TS 6.5.C.3. This event indicates that reference to the Technical Specification alone in this case does not insure compliance with the Technical Specification and that additional guidance is needed.

Corrective Steps Taken and Results Achieved

1. OCD 4201 was revised to clarify the prerequisite on TS 3.3.A to insure adequate shutdown margin is available prior to performing isolations that result in control rod inoperability. This insures that adequate shutdown margin will exist for any activities performed under this OCD.

W G Guldemond, Region III April 14, 1987 Page 2

2. Operations Manual B.1.3, which is referenced by OCD 4201, was revised to add a precaution prior to the procedure for HCU Isolation for Maintenance to insure that shutdown margin is verified prior to making isolations resulting in an inoperable control rod. This insures that adequate shutdown margin will exist for any activities performed under this procedure. In addition the Operations Manual was revised to define isolations which result in an inoperable control rod drive.

Corrective Steps to be Taken to Avoid Further Violations

In order to provide additional guidance for procedures that reference Technical Specifications a Technical Specification Interpretations Manual will be developed.

Date When Full Compliance will be Achieved

All corrective steps to be taken will be completed by December 31, 1987.

It is believed that the corrective actions taken and planned in response to this violation will prevent future similar occurrences. Please contact us if you have any questions, or if additional information is required.

C E Larson

Vice President Nuclear Generation

CEL/MMV/dab

c: NRR Project Manager, NRC Resident Inspector, NRC G Charnoff