

SAVANNAH RIVER REMEDIATION LLC

We do the right thing

Savannah River Site, Aiken, SC 29808

September 15, 2010

SRR-CWDA-2010-00137

TO:

V. G. DICKERT, 705-1C

FROM:

F. MALCOLM SMITH, 705-1C

JULY 28, 2010 U. S. NRC ONSITE OBSERVATION FOR SALT WASTE DISPOSAL AT THE SAVANNAH RIVER SITE ACTION ITEM RESPONSE

Attached, please find the Disposal Unit 2 Water Tightness Test Chronology from April 3, 2010 through July 29, 2010 and associated notes. Significant events related to water tightness testing of Disposal Unit 2 are contained in the Primavera schedule tool, while salient comments for selected activities are contained in the accompanying table. Please note that Disposal Unit 2 (cells 2A and 2B) are currently undergoing coating repairs and will be retested for water tightness. As such the chronology represents activities related to water tightness test activities conducted to date and does not represent the entire scope of water tightness testing.

If you have any questions please contact me at 557-9349.

FMS:fms

Att

V. A. Franklin, 705-1C c: L. D. Olson, 766-H L. K. Sonnenberg, 704-S C. J. Winkler, 766-H S. A. Thomas, 705-1C T. C. Robinson, Jr., 705-1C M. A. Schmitz, 766-H R. A. Runnels, 707-14E S. W. Wilkerson, 704-S P. W. Norris, 704-Z D. B. Little, 766-H D. S. Burke, 766-H K. S. Cassara, 766-H E. R. Selden, 704-Z B. T. Young, 766-H B. E. Long, 704-Z P. M. Allen, 766-H K.R. Liner, 704-S D. S. Burke, 766-H M. K. Lancaster, 766-H K. H. Rosenberger, 705-1C W. C. Miles, 766-H Closure and Waste Disposal Authority File



Saltstone Facility Schedule WATER TIGHTNESS TEST CHRONOLOGY SS SDU2 TEST REPAIR CHRONOLOGY SDU # 2 LINE Activity ID Start PO PO 2010 Activity Name Finish Sequ... Srt 1 -Major Apr May Jun Jul **SDU #2 Water Tightness** Saltstone Disposal Cell 2B ZV2HT2B-115 .CLEAR WATER FILLING 04-Apr-10 13-Apr-10 000 .CLEAR WATER FILLING U 0d Q17 07:00 A 17:00 A ZV2HT2B-130 08-Apr-10 Q17 .DAMP SPOTS WERE FOUND U 0d 000 ◆ .DAMP SPOTS WERE FOUND 07:00 A ZV2HT2B-140 SHOTCRETE REMOVAL WAS INITIATED 14-Apr-10 U 0d 000 Q17 07:00 A ZV2HT2B-180 .SRR CHALLENGES VENDOR 26-Apr-10 U 0d 000 Q17 ◆ .SRR CHALLENGES VENDOR 07:00 A ZV2HT2B-190 .DYE WAS ADDED 1st 30-Apr-10 000 Q17 U 0d ◆ .DYE WAS ADDED 1st 07:00 A ZV2HT2B-460 .WATER TIGHTNESS TEST 1st (HA) 30-Apr-10 24-May-10 U 0d 000 Q17 17:00 Å 07:00 A ZV2HT2B-210 .DYE WAS VERIFIED AS MIXED 1st 06-May-10 U 0d 001 Q17 07:00 Å 10-May-10 ZV2HT2B-250 .DYE WAS FIRST OBSERVED 1st U 0d 001 Q17 07:00 Á ZV2HT2B-270 .DYE WAS LAST OBSERVED 1st Q17 24-May-10 U 0d 001 17:00 Å ZV2HT2B-155 EPOXY INJECTIONS 14-May-10 15-May-10 U 0d 002 Q17 .EPOXY INJECTIONS 07:00 Å 17:00 A ZV2HT2B-170 .WATER STOP WAS REPAIRED 15-May-10 U 0d 002 Q17 17:00 A ZV2HT2B-120 .WATER TIGHTNESS TEST INITIATED 21-May-10 U 0d 002 Q17 07:00 A ZV2HT2B-380 .TANK DRAINING 1st 24-May-10 05-Jun-10 U 0d 003 Q17 07:00 A 17:00 A ZV2HT2B-450 .COATING INSPECTION 1st 07-Jun-10 14-Jun-10 U 0d 003 Q17

Aug Sep ◆ .SHOTCRETE REMOVAL WAS INITIATED .WATER TIGHTNESS TEST 1st (HA) ◆ .DYE WAS VERIFIED AS MIXED 1st ◆ .DYE WAS FIRST OBSERVED 1st ◆ DYE WAS LAST OBSERVED 1st ◆ .WATER STOP WAS REPAIRED ◆ .WATER TIGHTNESS TEST INITIATED .TANK DRAINING 1st .COATING INSPECTION 1st 07:00 A 17:00 A 07-Jun-10 28-Jun-10 ZV2HT2B-375 .INITAIL COATING REPAIR 1st U 0d 004 Q17 .INITAIL COATING REPAIR 1st 07:00 A 17:00 A ZV2HT2B-440 .WATER FILLING 2nd 01-Jul-10 10-Jul-10 U 0d 004 Q17 .WATER FILLING 2nd 07:00 A 17:00 A ZV2HT2B-200 DYE WAS ADDED 2nd 04-Jul-10 004 ◆ .DYE WAS ADDED 2nd U 0d Q17 07:00 A 04-Jul-10 16-Jul-10 U 0d .WATER TIGHTNESS TEST ZV2HT2B-470 .WATER TIGHTNESS TEST 2nd (HA) 004 Q17 07:00 A 17:00 A ZV2HT2B-220 .DYE WAS VERIFIED AS MIXED 2nd 10-Jul-10 U 0d 005 Q17 ◆ .DYE WAS VERIFIED AS MIXE 07:00 A ZV2HT2B-420 .WATER TIGHTNESS TEST INITIATED 11-Jul-10 005 Q17 ◆ .WATER TIGHTNESS TEST II U 0d 07:00 A Page 1 of 2

LINE	Activity ID	Activity Name	Start	Finish	Org	РО	RD	SEQT: E	EPS:	GRP1:	E	2010					
: Lin_						JE.		Sequ	Srt 1 -	Major Task	1.	Apr	May	Jun	Jul	Aug	Sep
21	ZV2HT2B-260	.DYE WAS FIRST OBSERVED 2nd	12-Jul-10 07:00 A			U	0d	005		Q17	5				♦ .DYI	E WAS FIRST	OBSERVE
22	ZV2HT2B-280	.DYE WAS LAST OBSERVED 2nd		16-Jul-10 17:00 A		U	0d	005		Q17	5				◆ -!D	YE WAS LAST	OBSERVE
23	ZV2HT2B-305	.TANK DRAINING 2nd	19-Jul-10 07:00 A	28-Jul-10 17:00 A		U	0d	800		Q17	٤					TANK DRA	AINING 2nd
24	ZV2HT2B-345	.COATING INSPECTION 2nd	28-Jul-10 07:00 A	29-Jul-10 17:00 A		U	0d	009		Q17	5					.COATING	INSPECTI
	Saltstone D	isposal Cell 2A															
25	ZV2HT2A-105	.CLEAR WATER FILLING	24-May-10 07:00 A	03-Jun-10 17:00 A		U	0d	000		Q17	٤			.CLEAR W	VATER FILL	ING	
26	ZV2HT2A-130	.DAMP SPOTS WERE FOUND	08-Jun-10 07:00 A			U	0d	001		Q17	٤			◆ .DAMP	SPOTS WE	RE FOUND	
27	ZV2HT2A-140	.SHOTCRETE REMOVAL WAS INITIATED	08-Jun-10 07:00 A			U	0d	001		Q17	٤			◆ .SHOTO	CRETE REM	IOVAL WAS IN	ITIATED
28	ZV2HT2A-155	.EPOXY INJECTIONS	15-Jun-10 07:00 A	29-Jul-10 17:00 A		U	0d	002		Q17	٤					.EPOXY IN	IJECTIONS
29	ZV2HT2A-180	.SRR CHALLENGES VENDOR	21-Jun-10 07:00 A			U	0d	002		Q17	٤			♦ .S	RR CHALLE	ENGES VENDO	OR
30	ZV2HT2A-190	.DYE WAS ADDED	26-Jun-10 07:00 A			U	0d	003		Q17	٤			•	.DYE WAS	ADDED	
31	ZV2HT2A-165	.WATER TIGHTNESS TEST	26-Jun-10 07:00 A	08-Jul-10 17:00 A		U	0d	003		Q17	٤			- ■	.WATI	ER TIGHTNES	S TEST
32	ZV2HT2A-120	.DYE WAS VERIFIED AS MIXED	29-Jun-10 07:00 A			U	0d	003		Q17	5			•	DYE WAS	S VERIFIED AS	MIXED
33	ZV2HT2A-200	.WATER TIGHTNESS TEST INITIATED	04-Jul-10 07:00 A			U	0d	003		Q17	5				◆ .WATER	RTIGHTNESS	TEST INIT
34	ZV2HT2A-210	.DYE WAS FIRST OBSERVED	04-Jul-10 07:00 A			U	0d	003		Q17	٤				◆ .DYE W	AS FIRST OBS	SERVED
35	ZV2HT2A-220	.DYE WAS LAST OBSERVED		08-Jul-10 17:00 A		U	0d	003		Q17	5				DYE.	WAS LAST OF	SERVED
36	ZV2HT2A-290	.TANK DRAINING	08-Jul-10 07:00 A	17-Jul-10 17:00 A		U	0d	004		Q17	٤				Т.	ANK DRAININ	G
37	ZV2HT2A-310	.COATING INSPECTION	19-Jul-10 07:00 A	21-Jul-10 17:00 A		U	0d	005		Q17	٤					.COATING INS	SPECTION
38	ZV2HT2A-300	.INITAIL COATING REPAIR	19-Jul-10 07:00 A	29-Jul-10 17:00 A		U	0d	006		Q17	5					.INITAIL C	OATING R

WATER TIGHTNESS TEST & REPAIR TIMELINE – SDU 2 (Cells A & B)

ACTIVITY ID(s)	ACTIVITY	SDU 2A COMMENTS	SDU 2B COMMENTS
01, 25	Clear Water Filling	Clear water testing was directed by SRR as per contract with vendor. Water Tightness Test Procedure WB00001K-041-B-MDM.	Clear water testing was initiated in accordance with standard industry practice and specification requirements. Water Tightness Test Procedure WB00001K-041-B-MDM.
03, 27	Shotcrete Removal	Shotcrete was removed at various locations to accommodate inspections and find the source of the dampness.	Shotcrete was removed at various locations to accommodate inspections and find the source of the dampness.
10, 28	Epoxy Injections	Additional injections performed after tank was emptied; various dates.	Additional injections performed after tank was emptied; various dates.
11	Water Stop Was Repaired	This was only performed on 2B.	This was only performed on 2B.
04, 30	SRR Challenges Vendor	Vendor formally challenged to provide positive means to discriminate interior and construction / environmental water.	Vendor formally challenged to provide positive means to discriminate interior and construction / environmental water.

ACTIVITY ID(s)	ACTIVITY	SDU 2A COMMENTS	SDU 2B COMMENTS		
07, 19, 32	Dye Was Verified as Mixed	Samples collected from various locations and various depths. Color consistency between samples confirmed thorough mixing. IAW dye test procedure WB00001K-046-C-MDM.	Samples collected from various locations and various depths. Color consistency between samples confirmed thorough mixing. IAW dye test procedure WB00001K-046-C-MDM.		
12, 20, 33	Water Tightness Test Initiated	IAW dye test procedure WB00001K-046-C-MDM. The test entry conditions could not be met. In order to declare a failure the test entry was forced so that failure could be declared.	IAW dye test procedure WB00001K-046-C-MDM. The test entry conditions could not be met. In order to declare a failure the test entry was forced so that failure could be declared.		
09. 22, 35	Dye Was Last Observed	N/A	2 nd Test– Dye was observed only on the floor to upper mud mat interface.		
14, 24, 37	Coating Inspection	Soundings and visual inspection on the floor used to detect anomalies in the coating. Improperly saturated chopped strand mat was the failure mode.	Soundings and visual inspection on the floor used to detect anomalies in the coating.		
16	2 nd Water Filling	Cell 2A did not undergo a second fill / test cycle.	N/A		