



Florida Power & Light Company, 6501 S. Ocean Drive, Jensen Beach, FL 34957

January 3, 2012

L-2011-562  
10 CFR 50.73

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, D.C. 20555

Re: St. Lucie Unit 1  
Docket No. 50-335  
Reportable Event: 2011-003  
Date of Event: November 3, 2011  
Long-Term Post-LOCA Hot Leg Injection Single Failure Vulnerability

The attached Licensee Event Report 2011-003 is being submitted pursuant to the requirements of 10 CFR 50.73 to provide notification of the subject event.

Respectfully,

A handwritten signature in black ink, appearing to read 'Richard L. Anderson', written in a cursive style.

Richard L. Anderson  
Site Vice President  
St. Lucie Plant

RLA/KWF

Attachment

IE 22  
NRR

**1. FACILITY NAME** St. Lucie Unit 1 **2. DOCKET NUMBER** 05000335 **3. PAGE** 1 OF 6

**4. TITLE**  
Long-Term Post-LOCA Hot Leg Injection Single Failure Vulnerability

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
11	03	2011	2011	003	00	01	03	2012	na	
									na	

**9. OPERATING MODE** 1 **11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR§:** (Check all that apply)

<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)
<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)
<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input checked="" type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)
<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)
<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)
<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)
<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)	Specify in Abstract below or in NRC Form 366A

**12. LICENSEE CONTACT FOR THIS LER**

NAME: Ken Frehafer - Licensing Engineer TELEPHONE NUMBER (Include Area Code): 772-467-7748

**13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT**

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX
X	na	na	na	NO					

**14. SUPPLEMENTAL REPORT EXPECTED**  YES (If yes, complete 15. EXPECTED SUBMISSION DATE)  NO

**15. EXPECTED SUBMISSION DATE** MONTH: 03 DAY: 30 YEAR: 2012

**ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)**

On November 3, 2011, with St. Lucie Unit 1 in Mode 1 at 85% power, the Onsite Review Group determined that past operation with unproceduralized manual actions to mitigate postulated single failures in the hot leg injection flow path constituted a reportable condition.

St. Lucie failed to recognize that the historical condition was reportable due to weaknesses in corrective action program (CAP) implementation and legacy issues with operability/functionality determinations. Programmatic CAP improvements have been implemented to ensure condition reports are appropriately screened and dispositioned, and the operability/functionality determination program requirements have been updated.

The legacy design issue is being handled in the interim via proceduralized manual actions that are being tracked as an open functional but degraded condition via the station RIS 2005-20 list until an appropriate long-term solution is implemented.

This LER will be supplemented to include the potential effects of postulated HLI flow on the integrity of the regenerative heat exchanger.

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 2 of 6
		2011	- 003	- 00	

**NARRATIVE**

**Description of the Event**

On November 3, 2011, with St. Lucie Unit 1 in Mode 1 at 85% power, the St. Lucie Onsite Review Group determined that the unproceduralized manual actions to mitigate postulated single failures in the St. Lucie Unit 1 hot leg injection (HLI) flow path constituted a reportable condition.

Long-term core cooling and boron precipitation became an issue during the initial licensing of St. Lucie Unit 1. Because the St. Lucie Unit 1 design did not provide dedicated hot leg injection paths, St. Lucie Unit 1 was licensed to develop HLI procedures that utilized the existing low pressure safety injection (LPSI) and/or high pressure safety injection (HPSI) flow paths for hot leg injection. The HLI procedures developed for St. Lucie Unit 1 are described in Chapter 6, Appendix 6C of the Unit 1 Updated Final Safety Analysis Report (UFSAR).

The preferred HLI flow path is to direct the discharge of one LPSI pump through the 2-inch shutdown cooling (SDC) warm-up line to the opposite pump's suction line, and "backwards" through the suction line into the hot leg. The cold leg injection is via the normal HPSI pump operation. This flow path requires the opening of two motor operated valves (MOVs) in series to be successful; each valve is powered from a different electric bus. This single failure vulnerability was mitigated by developing procedures which identified alternative success paths to ensure that HLI could be achieved. If the preferred flow path is not available, the alternative flow path for HLI is from the HPSI pumps, via the connection to the charging pump discharge piping, through the pressurizer auxiliary spray piping to the pressurizer, and down the surge line to the hot leg.

The St. Lucie Unit 1 Safety Evaluation Report, Supplement 2, documents the NRC review of the HLI procedures. Through a review of the piping and instrument drawings (P&IDs), the NRC concluded that "the two methods proposed for hot leg injection do not meet the single failure criterion individually. However, the two methods complement one another, and the overall ECCS is, therefore, single failure proof."

In 1999, St. Lucie documented in a condition report (CR) that the HLI methods were not single failure proof. Loss of an electric bus would prevent both the primary and alternative HLI flow paths from being successful. However, the alternative HLI flow path could be restored by the use of temporary jumpers to restore power to the MOVs affected by the loss of an electric train. Even though no procedures were revised and jumpers were not fabricated, the alternative HLI flow path was considered fully operable because: 1) jumper fabrication was considered to be within the skill of the craft and, 2) the long-term nature of HLI initiation allowed sufficient time for the emergency response organization to determine where jumpers were needed. Actions were developed to proceduralize the use of the temporary jumpers to mitigate the identified single failure scenarios. In 2008 another CR documented that the previously identified jumpers and procedure changes were not implemented. The 2008 CR credited the 1999 CR with respect to operability and developed new tracking actions for the required procedure changes and jumper fabrication.

Subsequently, St. Lucie applied for increasing reactor power via an extended power uprate (EPU) license amendment. The EPU analysis for HLI required increasing the flow rate. The failure modes and effects analysis (FMEA) performed as part of the 2011 design modification effort identified that: 1) the procedure changes and jumper fabrication identified in the 1999 and 2008 CRs had not been implemented, 2) the previously identified jumper scope was not adequate to mitigate postulated single

## LICENSEE EVENT REPORT (LER)

TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 3 of 6
		2011	- 003	- 00	

**NARRATIVE**

failures in the HLI flow path, and 3) the alternate HLI flow through the regenerative heat exchanger would exceed the heat exchanger shell side design flow rate. The required jumpers were fabricated and required procedure changes implemented. The functional but degraded condition is being tracked as an open RIS 2005-20 issue.

St. Lucie determined that crediting unproceduralized manual actions for maintaining the HLI flow paths as fully operable was non-conservative with respect to RIS 2005-20, revision 1. Furthermore, the discovery of additional jumper scope and the potential effects of postulated HLI flow on the integrity of the regenerative heat exchanger during the EPU alternate HLI flow path design modification called into question the 1999 CR assertion that the emergency response organization would be successful initiating HLI within the required time frame, given a loss of power. Based on the above, this condition is reportable.

**Cause of the Event**

The original single failure vulnerability is a legacy design issue.

The failure to implement effective contingency measures once the single failure vulnerability was identified was due to two issues. The first issue was the inadequate operability assessment in the 1999 CR. This CR concluded that the HLI function remained fully operable without the need to proceduralize the required jumpers. Additionally, the engineering rigor applied to the FMEA was inadequate. A 1970's vintage Combustion Engineering letter was used to develop the required jumper scope; this over-reliance on vendor input led to the inadequate FMEA that did not identify the full scope.

The lack of rigor in operability assessments (now referred to as prompt operability/functionality determinations) is considered a legacy human performance issue. An extent of condition review was performed by reviewing the condition reports for the past five years. No issues were found that invalidated the conclusions of the prompt operability/functionality determinations. Additionally, the NextEra Energy (NEE) Fleet procedure platform revised the fleet operability procedure in 2008. The newer process is more formal than the freeform operability assessment performed in 1999, and engineering department personnel have had recent training on the subject.

The second issue that led to the failure to implement effective contingency measures (and represents the second opportunity for discovery) was the inadequate screening of the 2008 CR that documented the untimely corrective actions for the 1999 CR. The 2008 CR was screened as an administrative issue with no plant impact because of the referenced 1999 CR disposition. The CR initial screening team failed to recognize the significance of crediting non-proceduralized manual actions for continued operability. Had the NEE fleet prompt operability determination process been utilized in 2008, this condition would have been classified as functional but degraded and the manual actions needed as compensatory measures would have been proceduralized during the prompt operability/functionality determination process.

Subsequent to the 2008 CR, the St. Lucie corrective action program (CAP) was significantly revised as a result of the NRC 95002 inspection following 2008/2009 component cooling water (CCW) air intrusion events. The CR initial screening team and management review committee methods were revised to ensure that CR screening categorization and classification are based on nuclear safety and risk. An extent of condition review was performed on similar CRs screened as administrative in nature

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 4 of 6
		2011	- 003	- 00	

**NARRATIVE**

over the last five years, and none were found that had unresolved safety issues. These corrective actions became effective after the 2008 HLI CR.

**Analysis of the Event**

This condition is reportable pursuant to 10 CFR 50.73(a)(2)(ii)(B) as any event or condition that resulted in the nuclear power plant being in an unanalyzed condition that significantly degraded plant safety. NUREG-1022 states that the discovery of a system that does not meet the single failure criterion is reportable under this section. The NRC SER clearly stated that no single failure would prevent HLI, but the current design requires the use of jumpers to mitigate single failure scenarios.

Additionally, this condition is reportable pursuant to 10 CFR 50.73(a)(2)(v) as any condition that could have prevented the fulfillment of the safety function of structures or systems that are needed to mitigate the consequences of an accident. NUREG-1022 states that it is not required to postulate an additional random single failure in the system. However, only one single failure would be necessary to prevent hot leg injection, a required long-term cooling safety function.

This condition is not applicable to St. Lucie Unit 2 as it has a dedicated HLI flow path as part of its original design.

**Analysis of Safety Significance**

The mechanism for potential boron precipitation is as follows. For a hot leg break, the injection flow passes from the cold legs, through the core, into the hot legs, and out the break. So, for a hot leg break, core heat removal is via forced flow of the injection water. In contrast, for a cold leg break, after the reflooding is completed, the hydraulic balance will cause most of the injection flow to spill out of the break - the only flow into the core will be that required to make-up for the boil-off in the core that removes the core decay heat. The boron problem arises only during a cold leg break; as borated injection flow enters the core, and only pure water (as steam) leaves the core, the boron concentration in the core region will continue to increase. Once the boron concentration exceeds the solubility limit the boron will precipitate and challenge long-term core cooling capability. The solution to the potential problem is to achieve subcooled flow through the core: when boron in equals boron out, the concentration will not be increasing.

St. Lucie uses simultaneous hot and cold leg injection as the method to achieve forced flow through the core for long-term post-LOCA cooling. With simultaneous hot and cold leg injection, the recirculated sump fluid is injected into the hot legs as well as the cold legs. Regardless of break location, approximately half of the flow will pass through the core on its way to the break (the flow to the side with the break simply spills directly out of the break into containment, contributing nothing).

In order to preclude boron precipitation, the operators are procedurally required to initiate HLI within four to six hours post-LOCA. The original St. Lucie Unit 1 Operating License HLI analysis required initiation of long-term post-LOCA cooling within 20 hours of the event. FPL committed to initiating HLI within ten hours to preserve the analysis. In 1993, the boron concentration in the boric acid makeup tanks was reduced, and this unofficially increased the initiation of long-term post-LOCA cooling up to 32 hours after the event. In 1999, the HLI analysis of record was revised to incorporate the NRC accepted CENPD-254-P-A, "Post-LOCA Long Term Cooling Evaluation Model," and the time limit for HLI initiation was reduced from 32 to ten

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 5 of 6
		2011	- 003	- 00	

**NARRATIVE**

hours. In addition to the maximum time limit to preclude boron precipitation, decay heat and steam formation in the reactor head render HLI flow through the hot leg ineffective for the first four hours post-LOCA; this concern is addressed by the procedural initiation of HLI after the first four hours.

In 2003, the St. Lucie reload analysis added a return to criticality aspect to the HLI analysis. This cycle specific calculation required that HLI be initiated within seven to ten hours to preclude a return to criticality. Once the conservatisms are removed from the return to criticality calculation, the boron precipitation time limit of 10 hours becomes bounding. Based on this, after waiting for the first four hours post-LOCA for HLI flow through the hot leg to become effective, the operators had an approximate six hour window to initiate HLI.

If there was a loss of an electrical bus, even without procedures, the emergency response organization (ERO) problem solving teams in the technical support center (TSC) and emergency response facility (ERF) would be looking ahead and would come to the conclusion that jumpers would be needed to initiate HLI. Additionally, the ERO may need to diagnose and mitigate regenerative heat exchanger tube failures if the alternate HLI flow path was used. Because such actions would be knowledge-based instead of rule-based, there is a small probability that HLI would not be initiated in time to preclude boron precipitation, even with the consideration of the relatively long time period needed to establish HLI flow.

A probabilistic safety assessment is being performed to determine the risk associated with the ERO directed actions and jumper fabrication needed to mitigate the failure scenarios. The LER supplement will include the results of this assessment.

**Corrective Actions**

The corrective actions listed have been entered into the site CAP. Any changes to the actions below will be processed in accordance with the CAP.

1. The required jumpers were fabricated and required procedure changes implemented. The functional but degraded condition is being tracked as an open RIS 2005-20 issue.
2. The appropriate long-term solution to the HLI failure vulnerabilities will be implemented no later than the end of the SL1-25 refueling outage.
3. The improvements to the St. Lucie CAP are as described in LER 50-335/2010-001-01, "Air Intrusion From 1A Containment Instrument Air Compressor Into Unit 1 Component Cooling Water (CCW) System."

**LICENSEE EVENT REPORT (LER)**  
TEXT CONTINUATION

FACILITY NAME (1)	DOCKET NUMBER (2)	LER NUMBER (6)			PAGE (3)
St. Lucie Unit 1	05000335	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	Page 6 of 6
		2011	- 003	- 00	

**NARRATIVE**

**Similar Events**

LER 50-335/2010-001-01, "Air Intrusion From 1A Containment Instrument Air Compressor Into Unit 1 Component Cooling Water (CCW) System." This event was the onus for the St. Lucie CAP improvements driven by the NRC 95002 inspection on CCW air intrusion events. The causes for the CCW air intrusion event that are applicable to and bound the current LER on HLI single failure issue include the organization and programmatic weaknesses that existed in the areas of prompt identification, understanding of event significance, and timely corrective actions. As such, the corrective actions for the CCW air intrusion event bound the HLI single failure event.

**Failed Components**

None