



Three Mile Island, Unit 1 Summary of Tube-to-Tube Wear Identified During T1R19 (Fall 2011)

January 26, 2012


NRC Headquarters

Introductions and Opening Remarks

Bill Carsky, TMI-1 Site Engineering Director

- Greg Ciraula, TMI-1 Engineering Programs Manager
- Mark Torborg, TMI-1 Steam Generator (SG) Program Engineer
- Steve Queen, Director Corporate Engineering Programs
- Jay Smith, Corporate SG Program Manager
- Wendi Croft, Senior Licensing Engineer

- ✓ Provide information on tube-to-tube (T-T) wear
 - Inspection results
 - How the indications were identified
 - Reporting Criteria
 - Primary and secondary analysis
 - How the indications were sized
 - Basis for sizing techniques
 - Future planned actions



- ✓ TMI-1 installed AREVA, Enhanced Once Through Steam Generators (EOTSGs) during T1R18
 - Operated January 2010 – October 2011
- ✓ General design features of EOTSGs
 - 15,597 tubes per EOTSG
 - Full depth hydraulic expansions in tubesheets
 - 15 stainless steel tube support plates (TSP)
 - Trefoil broached holes, 1.18" thick
 - Numbered 01S (bottom) – 15S (top)
 - 15S TSP has 1470 drill holes in peripheral tubes
 - Spacing between TSPs varies from 35" - 46.4"
 - Aspirating ports are in 10th span
 - Nominal gap between tubes is 0.25"
- ✓ First inservice inspection performed in October 2011
 - 24-month fuel cycles
 - 1.72 effective full power years (EFPY) on EOTSGs
 - Maintained hot conditions throughout operating cycle


T1R19 Inspection Overview

5

- ✓ 100% full length bobbin coil inspections in each EOTSG
- ✓ X-Probe inspections of peripheral tubes (two tubes deep) in each EOTSG (Evaluated 1st span for loose parts)
- ✓ Tube damage mechanisms found in each EOTSG
 - Tube-to-tube support plate wear (T-TSP) (expected)
 - Tube-to-tube wear (T-T) (not expected)
- ✓ No evidence of tie rod bowing
- ✓ No tie rod to tube contact or proximity

EOTSG A, T-T Wear Map

6



TMI Unit 1 Repl
1R19 - 10/11

Tube-to-Tube
Contact

AREVA - FOMS map module Version 11.0

S/G A
PRIMARY FACE
INLET

TOTAL TUBES:	15597
TUBES SELECTED:	74
OUT OF SERVICE (#):	0


GROUP	TUBES
Tube-to-Tube Contact	74

SCALE: 0.068887 X
Thu Nov 10 08:28:21 2011

TMI Unit 1 Repl. S/G A INLET AREVA
This document and any information contained herein is the property of
AREVA NP Inc. AREVA NP and is to be considered proprietary and
confidential and may not be reproduced or copied in whole or in part.
This document shall not be furnished to others without the express
written consent of AREVA NP and is not to be used in any way which is
or may be detrimental to AREVA NP. This document and any copies
that may have been made must be returned to AREVA NP upon
request.

EOTSG B, T-T Wear Map

7



TMI Unit 1 Repl
1R19 - 10/11

Tube-to-Tube Contact

AREVA - FOMIS map module Version 11.0

S/G B
PRIMARY FACE
INLET
TOTAL TUBES: 15597
TUBES SELECTED: 183
OUT OF SERVICE (#): NA

GROUP	TUBES
Tube-to-Tube Contact	183

SCALE: 0.068887 X
Thu Nov 10 08:43:19 2011

AREVA
This document and any information contained herein is the property of
AREVA NP inc. (AREVA NP) and is to be considered proprietary and
confidential and may not be reproduced or copied in whole or in part.
This document shall not be furnished to others without the express
written consent of AREVA NP and is not to be used in any way which is
or may be detrimental to AREVA NP. This document and any copies
that may have been made must be returned to AREVA NP upon
request.

T1R19 T-T Wear Identification

8


- ✓ Reported as absolute drift indications (ADIs) during bobbin coil inspection with most indications located:
 - In mid-span
 - In the 9th span
 - In a radial pattern 30" – 45"
 - In adjacent tubes (two or three)
- ✓ Performed X-Probe and +Point on ADI signals
 - Verified indications in adjacent tubes face each other
 - Symmetrically tapered to maximum depth in center
 - In adjacent tubes the indications are at same elevation and are same length/depth
 - Length and depth have a correlation that is consistent with wear
 - Good correlation of phase angles and voltages between channels
- ✓ Analysts, Exelon Engineering, and AREVA Engineering consensus is that these indications are T-T wear
 - Notified Steam Generator Management Program (SGMP) per the requirements of Nuclear Energy Institute (NEI) 97-06
 - Notified NRC

✓ Indications reported as ADIs

- Industry standard is to use I-Codes to identify (possible) flaw signals where no qualified sizing technique exists and supplemental testing is required.
- Exelon guidelines require analysts to report all indications of suspected tube wall degradation.
- Primary Analysis (manual)
 - ≥ 0.5 volts & $\leq 90^\circ$ channel 6 **or** %TW >0 on channels 4 & 6
- Secondary Analysis (auto)
 - ≥ 0.5 volts & $30^\circ - 95^\circ$ on channel 6
 - %TW >0 on channels 4 & 6 and ≥ 0.16 volts on channel 6
 - ≥ 0.25 volts & $60^\circ - 120^\circ$ on channel 6


Example TMI-1 T-T Wear Bobbin Data

10




Example TMI-1 T-T Wear Bobbin Data

11



Example TMI-1 MBM Screened as ADI

12



Summary of ADI Indications (T-T Wear)


13

- ✓ ADI Indications ≥ 0.5 volt
 - “A” - 9 Tubes
 - Primary = 9, Secondary = 7, Both = 7
 - “B” - 19 Tubes
 - Primary = 19, Secondary = 18, Both = 18
- ✓ All ADIs including review for paired tubes
 - “A” - 74 Tubes with ADIs (0.08 – 1.62 volts)
 - Primary = 20, Secondary = 34, Both = 13
 - o Either Primary or Secondary = 41
 - o 74 of 74 confirmed by +Point or X-Probe
 - “B” - 202* Tubes with ADIs (0.07 - 1.25 volts)
 - Primary = 145, Secondary = 95, Both = 71
 - o Either Primary or Secondary = 169
 - o *183 of 202 confirmed by X-Probe

- ✓ Per Exelon & SGMP PWR Steam Generator Examinations Guidelines, I-Code indications are “Category III: Supplemental Test Required”
 - Prior to T1R19, +Point and X-Probe identified as probes to be used for supplemental examinations
 - X-Probe qualified for sizing T–TSP wear (EPRI ETSS 11956.3)
 - +Point qualified for sizing T-TSP wear (EPRI ETSS 96910.1)
 - +Point qualified for sizing various shapes of wear (EPRI ETSS 27901 – 27907)
 - o EPRI ETSS 27905.3 “Flat Wear” was determined to be the correct technique for T-T wear in EOTSGs

Example TMI-1 T-T Wear +Point Data

15



NOTE: Graphic shows partial indication


16



Example Depth Profiles in Paired Tubes

17

T-T Wear Depth Profiles
EOTSG A , Tubes R26-T36 AND R26-T37



18





- ✓ X-Probe T-T wear sizing technique developed in cooperation with EPRI
 - Used two of the same samples used to develop ETSS 27905.3 (+Point Flat Wear)
 - Developed “Power” trend line/regression curve using methodology used for other EPRI X-Probe techniques
 - ETSS 11956.1 – 11956.4, Broached TSP Wear
 - “Power” trend line/regression scatter plot based on multiple examinations of 16 wear scars
 - Wear scars ranged from 8% - 60% TW
 - Analysis of standards performed by multiple analysts from three different vendor organizations
 - Accuracy validated through comparison of +Point and X-Probe results for EOTSG A

20




Graphic of Flat Wear Standard +Point

21




X-Probe Calibration Curve

22




X-Probe Calibration Curve Validation

23



Comparison of +Point and X-Probe

24



T1R19 T-T Wear Summary



25

- ✓ A total of 257 tubes were identified with T-T wear
 - EOTSG A: 89 indications in 74 tubes
 - EOTSG B: 206 indications in 183 tubes
- ✓ Wear depths range from 1% to 21% through wall (TW)
- ✓ Wear axial lengths range from 2" to 8"
- ✓ No proximity or tube contact detected
 - Tubes are in tension at cold conditions and in compression at hot conditions
- ✓ Sizing performed by +Point Technique 27905.3 and a site qualified X-Probe Technique
 - Good correlation between Bobbin, +Point, and X-Probe techniques
- ✓ All tubes met condition monitoring limits and in-situ pressure testing was not required

T-T Wear Depth Distribution

26

EOTSG A



EOTSG B

T1R19 T-T Wear Summary

27

	EOTSG A	EOTSG B
Total number of In-Service Tubes	15597	15597
Number of T-T Wear Indications	89	206
Number of Tubes T-T Wear	74	183
Average Depth of T-T Wear	5.8%	7.4%
Maximum Depth of T-T Wear	21%	19%
Number of T-T Wear Indications >40% TW	0	0
Average Growth Rate T-T Wear	3.4%/EFPY	4.3%/EFPY
95 th Percentile Growth Rate T-T Wear	9.3%/EFPY	7.6%/EFPY
Maximum Growth Rate T-T Wear	12.2%/EFPY	11.1%/EFPY
Number of Tubes Plugged for T-T Wear	4	3


✓ Condition Monitoring Satisfied

- Utilized maximum depth and bounding length of 39" for 3 X normal operating pressure differential conditions ($3\Delta P$)
- Substantial margin against accident leakage and structural limits
- Large break loss of coolant accident (LBLOCA) loading conditions evaluated and satisfied
 - Assumed 180 degree circumferential extent of wear

Condition Monitoring Assessment for T-T Wear

29

CM Results for Tube-to-Tube Wear for Both Array Coil and +Point Sizing



- ✓ Mixed arithmetic/Monte Carlo method utilized
 - Cycle length 1.927 EFPY
 - Addressed indications sized with +Point and X-Probe separately
 - End of cycle (EOC) length conservatively assumed 39"
 - Used maximum growth over previous cycle
 - Conservative relative to ANO experience
- ✓ Significant margin to leakage and burst at EOC
 - Margin ~17% for worst case flaw at EOC
- ✓ LBLOCA evaluation also demonstrates significant margin

- ✓ Update Site Specific Performance Demonstration (SSPD) training to include T-T wear
- ✓ Convert TMI-1, X-Probe site qualification to EPRI “Appendix H, Qualified Technique”
- ✓ Provide raw data to EPRI
- ✓ Perform 100% eddy current examinations during T1R20 (Fall 2013)
- ✓ Support AREVA root cause analysis
- ✓ Implement appropriate actions based on the results of the root cause

- ✓ T-T wear was identified during the first inservice inspection of the TMI-1 EOTSGs
- ✓ All T-T wear indications meet Condition Monitoring and Operational Assessment performance criteria
- ✓ T-T wear does not impact inspection interval length for Cycle 19