



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**
WASHINGTON, D.C. 20555-0001

May 7, 2012

Mr. Barry S. Allen
Site Vice President
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
Mail Stop A-DB-3080
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT NO. 1 - UPCOMING
STEAM GENERATOR TUBE INSERVICE INSPECTIONS FOR SPRING 2012
REFUELING OUTAGE (TAC NO. ME8477)

Dear Mr Allen.:

Inservice inspections of steam generator (SG) tubes play a vital role in assuring tube integrity. A telephone conference will be arranged with members of your staff to discuss the ongoing results of the SG tube inspections to be conducted during the upcoming Davis-Besse Nuclear Power Station, Unit 1, 2012, spring refueling outage. This call will occur after the majority of the tubes have been inspected, but before the SG inspection activities have been completed (when approximately 70% of the inspection results have been analyzed). Enclosed is a list of discussion points to facilitate this call.

The U.S. Nuclear Regulatory Commission (NRC) staff will document a summary of the conference call, including any material that you provide to the NRC staff in support of the call.

Should you have any questions you can contact me at 301-415-3867.

Sincerely,

A handwritten signature in black ink, appearing to read "Michael Mahoney", is written over a horizontal line.

Michael Mahoney, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-346

Enclosure:
Steam Generator Tube Inspection Discussion Points

cc w/encl: Distribution via Listserv

STEAM GENERATOR TUBE INSPECTION DISCUSSION POINTS

The following discussion points have been prepared to facilitate the conference call arranged with the licensee to discuss the results of the steam generator (SG) tube inspections to be conducted during the upcoming Davis-Besse Nuclear Power Station, Unit No. 1 (DBNPS), spring 2012, refueling outage. This conference call is scheduled to occur towards the end of the planned SG tube inspections (when approximately 70% of the inspection results have been analyzed), but before DBNPS completes the inspections and repairs.

The U.S. Nuclear Regulatory Commission staff plans to document a summary of the conference call, as well as any material that is provided in support of the call.

1. Discuss any trends in the amount of primary-to-secondary leakage observed during the recently completed cycle.
2. Discuss whether any secondary side pressure tests were performed during the outage and the associated results.
3. Discuss any exceptions taken to the industry guidelines.
4. For each steam generator, provide a description of the inspections performed, including the areas examined and the probes used (e.g., dents/dings, sleeves, expansion-transition), the scope of the inspection (e.g., 100% of dents/dings greater than 5 volts and a 20% sample between 2 and 5 volts), and the expansion criteria.
5. For each area examined (e.g., tube supports, dent/dings, sleeves, etc), provide a summary of the number of indications identified to-date for each degradation mode (e.g., number of circumferential primary water stress corrosion cracking indications at the expansion transition). For the most significant indications in each area, provide an estimate of the severity of the indication (e.g., provide the voltage, depth, and length of the indication). In particular, address whether tube integrity (structural and accident induced leakage integrity) was maintained during the previous operating cycle. In addition, discuss whether any location exhibited a degradation mode that had not previously been observed at this location at this unit (e.g., observed circumferential primary water stress corrosion cracking at the expansion transition for the first time at this unit).
6. Describe repair/plugging plans.
7. Describe in-situ pressure test and tube pull plans and results (as applicable and if available).
8. Discuss the following regarding loose parts:
 - What inspections are performed to detect loose parts.
 - A description of any loose parts detected and their location within the SG (including the source or nature of the loose part, if known).

Enclosure

- If the loose parts were removed from the SG.
 - Indications of tube damage associated with the loose parts.
9. Discuss the scope and results of any secondary side inspection and maintenance activities (e.g., in-bundle visual inspections, feedring inspections, sludge lancing, assessing deposit loading, etc).
 10. Discuss any unexpected or unusual results.
 11. Provide the schedule for SG-related activities during the remainder of the current outage.

May 7, 2012

Mr. Barry S. Allen
Site Vice President
FirstEnergy Nuclear Operating Company
Davis-Besse Nuclear Power Station
Mail Stop A-DB-3080
5501 North State Route 2
Oak Harbor, OH 43449-9760

SUBJECT: DAVIS-BESSE NUCLEAR POWER STATION, UNIT NO. 1 - UPCOMING
STEAM GENERATOR TUBE INSERVICE INSPECTIONS FOR SPRING 2012
REFUELING OUTAGE (TAC NO. ME8477)

Dear Mr Allen.:

Inservice inspections of steam generator (SG) tubes play a vital role in assuring tube integrity. A telephone conference will be arranged with members of your staff to discuss the ongoing results of the SG tube inspections to be conducted during the upcoming DavisBesse Nuclear Power Station, Unit 1, 2012, spring refueling outage. This call will occur after the majority of the tubes have been inspected, but before the SG inspection activities have been completed (when approximately 70% of the inspection results have been analyzed). Enclosed isa list of discussion points to facilitate this call.

The U.S. Nuclear Regulatory Commission (NRC) staff will document a summary of the conference call, including any material that you provide to the NRC staff in support of the call.

Should you have any questions you can contact me at 301-415-3867.

Sincerely,
/RA/
Michael Mahoney, Project Manager
Plant Licensing Branch III-2
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-346

Enclosure:

Steam Generator Tube Inspection Discussion Points

cc w/encl: Distribution via Listserv

DISTRIBUTION:

PUBLIC

LPL3-2 R/F

RidsNrrDorILpl3-2 Resource

KKarwoski, NRR

RidsNrrPMMMahoney

RidsNrrLASRohrer Resource

RidsRgn3MailCenter Resource

AJohnson, NRR

ADAMS Accession No. ML12121A538

OFFICE	LPL3-2/PM	LPL3-2/LA	LPL3-2/BC	LPL3-2/PM
NAME	MMahoney	SRohrer	JZimmerman	MMahoney
DATE	05/ 02 /12	05/ 01 /12	05/ 03 /12	05/ 07 /12

OFFICIAL RECORD COPY