



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001

July 27, 2012

Mr. David A. Heacock
President and Chief Nuclear Officer
Dominion Nuclear Connecticut, Inc.
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: MILLSTONE POWER STATION, UNIT 3 – REQUEST FOR ADDITIONAL
INFORMATION REGARDING END OF CYCLE 14 STEAM GENERATOR TUBE
INSERVICE INSPECTION REPORT (TAC NO. ME8842)

Dear Mr. Heacock:

By letter dated April 6, 2012 (Agencywide Documents Access and Management System (ADAMS) Accession No. ML12109A044), Dominion Nuclear Connecticut, Inc. (the licensee), submitted information summarizing the results of the 2011 steam generator tube inspections at Millstone Power Station, Unit 3. These inspections were performed during the fourteenth refueling outage.

The U.S. Nuclear Regulatory Commission staff has reviewed the information provided by the licensee and has determined that the enclosed request for additional information (RAI) is needed in order to complete the review. A response to this RAI is requested to be provided within 60 days.

If you have any questions regarding this matter, please contact me at 301-415-4125.

Sincerely,

A handwritten signature in black ink that reads "James Kim".

James Kim, Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-423

Enclosure:
As stated

cc w/encl: Distribution via Listserv

OFFICE OF NUCLEAR REACTOR REGULATION
REQUEST FOR ADDITIONAL INFORMATION
STEAM GENERATOR TUBE INSERVICE INSPECTION
MILLSTONE POWER STATION, UNIT 3
DOCKET NUMBER 50-423

By letter dated April 6, 2012 (Agencywide Documents Access and Management System (ADAMS) Accession No. ML12109A044), Dominion Nuclear Connecticut, Inc. (the licensee), submitted information summarizing the results of the end of cycle 14 steam generator tube inspections at Millstone Power Station, Unit 3. These inspections were performed during the fourteenth refueling outage. In order to complete its review of the documents listed above, the staff needs the following additional information:

1. Page 3 of Enclosure 1 to your April 6 letter indicates that secondary side activities were performed in all SGs, and secondary side examinations were performed in SG D. Please discuss the findings of these activities and examinations.
2. Table 2 indicates that visual examinations of the plugs were performed during 3R12. Please provide the results of these examinations.
3. Table 7 indicates that a tube with foreign object wear was stabilized and plugged, since a secondary side inspection could not be performed in the area of the degraded tube. One page 3, you state that the augmented sample inspections with the rotating coil probe included bounding examinations for possible loose part indications and new volumetric flaw (fabrication or foreign object wear) detections. Presumably, these augmented sample inspections included the area around the tube that was stabilized and plugged. Please discuss the following:
 - a. The scope of the augmented sample inspections performed in the area of the tube that was stabilized and plugged.
 - b. The technical basis used for your operational assessment, assuming that the loose part is still in the SG.

Enclosure

July 27, 2012

Mr. David A. Heacock
President and Chief Nuclear Officer
Dominion Nuclear Connecticut, Inc.
Innsbrook Technical Center
5000 Dominion Boulevard
Glen Allen, VA 23060-6711

SUBJECT: MILLSTONE POWER STATION, UNIT 3 – REQUEST FOR ADDITIONAL
INFORMATION REGARDING END OF CYCLE 14 STEAM GENERATOR TUBE
INSERVICE INSPECTION REPORT (TAC NO. ME8842)

Dear Mr. Heacock:

By letter dated April 6, 2012 (Agencywide Documents Access and Management System (ADAMS) Accession No. ML12109A044), Dominion Nuclear Connecticut, Inc. (the licensee), submitted information summarizing the results of the 2011 steam generator tube inspections at Millstone Power Station, Unit 3. These inspections were performed during the fourteenth refueling outage.

The U.S. Nuclear Regulatory Commission staff has reviewed the information provided by the licensee and has determined that the enclosed request for additional information (RAI) is needed in order to complete the review. A response to this RAI is requested to be provided within 60 days.

If you have any questions regarding this matter, please contact me at 301-415-4125.

Sincerely,

/ra/

James Kim, Project Manager
Plant Licensing Branch I-1
Division of Operating Reactor Licensing
Office of Nuclear Reactor Regulation

Docket No. 50-423

Enclosure:
As stated

cc w/encl: Distribution via Listserv

Distribution:

RidsAcrsAcnw_MailCTR Resource
RidsNrrDeEsgb Resource
RidsOgcRp Resource
AJohnson, NRR

RidsNrrDorIDpr Resource
RidsNrrLKGGoldstein Resource
RidsRgn1MailCenter Resource
PUBLIC

RidsNrrDorLp1-1 Resource
RidsNrrPMMillstone Resource
Branch Reading

ADAMS Accession No.: ML12208A266

*via memo dated July 17, 2012

OFFICE	LPL1-1/PM	LPL1-1/LA	DE/ESGB/BC	LPL1-1/BC
NAME	JKim	KGoldstein	GKulesa*	GWilson
DATE	7/26/12	7/26/12	7/17/12	7/27/12

Official Record Copy