

Part 21 (PAR)

Event # 48157

Rep Org: FLOWSERVE	Notification Date / Time: 08/03/2012 14:34 (EDT)
Supplier: FLOWSERVE	Event Date / Time: 08/03/2012 (EDT)
	Last Modification: 08/03/2012
Region: 1	Docket #:
City: RALEIGH	Agreement State: Yes
County:	License #:
State: NC	
NRC Notified by: ROBERT BARRY	Notifications: PAUL KROHN R1DO
HQ Ops Officer: CHARLES TEAL	MIKE ERNSTES R2DO
Emergency Class: NON EMERGENCY	MICHAEL KUNOWSKI R3DO
10 CFR Section:	PART 21 GROUP EMAIL
21.21(d)(3)(i) DEFECTS AND NONCOMPLIANCE	

PART 21 - DEFECTIVE VALVE SEAL CAP

The following was provided via fax:

"Background:

"On July 17, 2012, Duke Power - McGuire NPP notified Flowserve Corporation that they had attempted to install a Seal Cap supplied by Flowserve on a Kerotest 1-1500 Y-Type Globe Valve. They found that the Seal Cap could not be installed on the valve due to interference with the Valve Stem.

"Discussion:

"The Seal Cap is used to contain leakage past the Valve Diaphragm. The Seal Cap fits over the Valve Stem after Handle removal and is screwed onto the Yoke until it contacts the top of the Body. It is then seal welded to the Body to create a leak tight cap. At this point the Seal Cap is considered pressure retaining.

"Inspection of the Seal Cap revealed an inside flat bottom in lieu of the conical bottom shown on the drawing. The conical drill point allows clearance for the valve stem when the Seal Cap is installed on the valve. Review of a layout shows the Seal Cap with a Flat bottom cannot be completely installed whether the valve is open or closed.

"Conclusion:

"The Seal Cap with a flat bottom cannot be properly installed on the Kerotest Series R9900 size 1/2 to 2 Valves for which it was designed. The Valve Stem will prevent complete installation and the ability to seal weld the Seal Cap to the Body. The Seal Caps supplied would not be available at the Nuclear Power Plant site for an urgent repair if

TE19
MRR

Part 21 (PAR)

Event # 48157

required. The following Nuclear Power Plant Utilities were provide these Seal Caps without the conical shaped area.

TVA - Purchase Order# 00020077-00050 and 00020077-00018

First Energy - Purchase Order# 45108999, and 45254808

Alabama Power - Purchase Order# QP040387, QP040872 and QP060575

Duke Power - Purchase Order # NM18494 001, NM25245, 00108212 and 00124677.

"Based on the above, the Nuclear Utilities need to be notified concerning this deviation so that an evaluation may be performed to determine if this constitutes a defect that could create a substantial safety hazard."

US NRC
August 3, 2012
Page 2 of 2

Conclusion


The Seal Cap with a flat bottom cannot be properly installed on the Kerotest Series R9900 size 1/2 to 2 Valves for which it was designed. The Valve Stem will prevent complete installation and the ability to seal weld the Seal Cap to the Body. The Seal Caps supplied would not be available at the Nuclear Power Plant site for an urgent repair if required.

The following Nuclear Power Plant Utilities were provide these Seal Caps without the conical shaped area.

TVA – Purchase Order# 00020077-00050 and 00020077-00018
First Energy – Purchase Order# 45108999, and 45254808
Alabama Power – Purchase Order# QP040387, QP040872 and QP060575
Duke Power – Purchase Order # NM18494 001, NM25245, 00108212 and 00124677.

Based on the above, the Nuclear Utilities need to be notified concerning this deviation so that an evaluation may be performed to determine if this constitutes a defect that could create a substantial safety hazard.

Respectfully submitted,



Robert D. Barry
Manager, Quality Assurance
Flowserve Corporation
Flow Control Division
1900 S. Saunders St.
Raleigh, N.C. 27603

US NRC
August 3, 2012
Page 2 of 2

Conclusion


The Seal Cap with a flat bottom cannot be properly installed on the Kerotest Series R9900 size 1/2 to 2 Valves for which it was designed. The Valve Stem will prevent complete installation and the ability to seal weld the Seal Cap to the Body. The Seal Caps supplied would not be available at the Nuclear Power Plant site for an urgent repair if required.

The following Nuclear Power Plant Utilities were provide these Seal Caps without the conical shaped area.

TVA – Purchase Order# 00020077-00050 and 00020077-00018
First Energy – Purchase Order# 45108999, and 45254808
Alabama Power – Purchase Order# QP040387, QP040872 and QP060575
Duke Power – Purchase Order # NM18494 001, NM25245, 00108212 and 00124677.

Based on the above, the Nuclear Utilities need to be notified concerning this deviation so that an evaluation may be performed to determine if this constitutes a defect that could create a substantial safety hazard.

Respectfully submitted,



Robert D. Barry
Manager, Quality Assurance
Flowsolve Corporation
Flow Control Division
1900 S. Saunders St.
Raleigh, N.C. 27603