Shield Building Crack Investigation and Root Cause Presentation





Davis-Besse Nuclear Power Station

August 9, 2012

Agenda

Introduction

- Barry Allen, Site Vice President - Davis-Besse

Shield Building Condition Evaluation

– **Ken Byrd**, Director – Site Engineering

Shield Building Root Cause Investigation

- Jon Hook, Design Engineering Manager

Shield Building Corrective Actions

- Ken Byrd, Director – Site Engineering

Closing Comments

- Barry Allen, Site Vice President - Davis-Besse



Shield Building Condition Evaluation

Ken Byrd, Director - Site Engineering





Background

- Mid-cycle outage to replace Reactor Pressure Vessel Head
- Access opening required in concrete Shield Building
- Opening dimensions
 26.5' wide X 35.5' high
- Hydro-demolition method employed
- Previous opening in 2002 used similar method
- Size and orientation different than in 2002





Shield Building

FENOC



Shield Building

Purpose of Shield Building

- Biological shielding
- Environmental protection for Containment Vessel
- Controlled release of Annulus atmosphere under accident conditions





Shield Building Flutes/Shoulders



FENOC

Shield Building Crack Investigation and Root Cause ମିଟିର୍ଟ୍ଟିମିକ୍ଷିକିର୍ବ Update Public Meeting August 9, 2012

Shield Building Flute Shoulders

Architectural Feature

- The flute shoulders are a part of the Shield Building; concrete for shoulders and building shell was placed concurrently
- Evaluation of structural capacity of Shield Building does not credit flute shoulders
- Evaluated as a dead load in structural analysis





Discovery

- Cracking found on October 10, 2011, during hydro-demolition
- NRC resident notified
- Condition Report written
- Restraint on restart established
- Team of experts to investigate issue mobilized



Investigation

Impulse Response (IR) testing methodology used to investigate extent of crack





Investigation, continued

- Core bores taken to validate IR testing results, to determine crack depth and to determine crack width
- Investigation results were documented in the corrective action process, and the NRC was promptly notified of findings





Summary of Shield Building Condition

- Cracking is generic to flute shoulder regions and can be assumed to be present at any elevation in the flutes shoulders; cracking was observed to be more prevalent on the south side of the building
- Cracks are located near the outer reinforcing mat; no cracking observed in interior reinforcing mat





Summary of Shield Building Condition, *continued*

- Cracking exists at the top 20 feet of the Shield Building wall outside the flute shoulder region
- Two small regions adjacent to the Main Steam Line penetration have similar cracks
 - The extent of these regions is localized and unique to these particular penetrations
- Cracks are very tight





Structural Evaluation

Original Shield Building design

- Building designed and constructed with significant reinforcement
- Significant margin under design basis loads
- Design Basis
 - Earthquake 6–6.5 on Richter magnitude scale
 - Tornado winds of 300 miles per hour
 - Tornado depressurization and missiles

Impact of laminar cracks on original design

- Potentially reduce the bond strength between concrete and reinforcing steel
- Cracks of little impact unless reinforcing bars are spliced in the cracked region
- Shield Building remains adequate for safety function



Bounding Building Analysis

- Bond strength of reinforcement lap splices with adjacent cracks could not be quantified and were conservatively treated as non-existent in analysis
- Calculations performed to provide a bounding evaluation of the effect of cracking
 - Vertical and horizontal reinforcement assumed ineffective for strength in flute shoulders, two steam line penetration areas and in regions at top of shield building.
- Any bond between reinforcement and concrete in crack regions provides additional margin



Summary of Calculation Results

- Shield Building meets strength requirements
- Any bond between the concrete and reinforcement in cracked regions would be an additional margin of safety
- Shield Building is capable of performing all safety functions with margin



Shield Building Root Cause Investigation

Jon Hook, Manager - Design Engineering





Root Cause Overview

- Established independent team of experts
- Established a comprehensive Failure Modes Analysis
- Investigated the design, materials, construction methods, and present day operational conditions
- Performed concrete tests
- Performed analyses
- Identified root cause



Root Cause Overview, continued

Performance Improvement International (PII)

- The PII team are experts in root cause investigation
- Team consist of Professional Engineers, PhDs, and university professors
- Performed more than 500 root causes
- Industry experts as well as assistance from FENOC Engineering
- Followed our established and proven root cause process



Shield Building Root Cause Fault Tree



Public Meeting August 9, 2012

Shield Building Concrete

- Concrete was subjected to a series of tests
- 36 concrete cores from the Shield Building tested
- Concrete properties were determined
- Test results confirmed the concrete is sound and can be ruled out





Shield Building Concrete, continued

- Typical concrete sample showing the laminar crack sheared the coarse aggregate
- Therefore, laminar crack occurred after the concrete achieved it strength



FENOC

Shield Building Concrete, continued

- No evidence of micro cracks
- No signs of cyclic load mechanism
- No cyclic freeze-thaw mechanism
- No indication of fatigue or age related events



Magnification at 100 Times



Shield Building Concrete Tests, continued

16 samples were tested for carbonation

- Average depth of carbonation is 8.57 mm (0.337 inches)
- Maximum average
 11.7 mm (0.46 inches)
- Typical for concrete
 40 years old





Shield Building Concrete - Conclusion

- Crack passed through the course aggregate
 - Strong bond between the cement paste and the coarse aggregate; therefore, initial placement concerns can be ruled out
 - Large tensile force is required to initiate the crack
- No micro cracks identified that would indicate freeze-thaw or cyclic events
- Chemical properties, carbonation, corrosion, etc, were all acceptable
- Based on the above, concrete can be ruled out as an initiating or contributing cause



Shield Building Configuration

- Cracking is predominantly located in the shoulder areas, the top 20 feet of the Shield Building, and near the Main Steam Line penetration block-outs; cracking concentrated on southern exposures
- Shoulder areas are regions of discontinuity
- Limited radial reinforcing steel in the shoulder areas
- High rebar density (6" spacing) located at the top of the Shield Building and around the Main Steam Line penetration construction block-outs
- Conclusion
 - There is a correlation between the crack locations and the physical layout of the reinforcing steel that needed to be investigated



Shield Building Analytical Analyses

- Numerous computer analyses were performed for normal design conditions
 - Self weight, wind loads
 - Thermal analyses (summer hot and winter cold conditions)
 - Fujita Category 2 tornado
- Stresses were significantly below the normal tensile capacity of the concrete



FENOC

Shield Building Analytical Analyses, *continued*

Analysis showed:

- Design stresses can not initiate the laminar crack
- Significant stresses beyond what is normally analyzed would be required to crack the concrete

Investigate industry experience for similar conditions



Industry Experience with Laminar Cracks

- Ontario Ministry of the Environment study on 50 above ground water tanks in Ontario
- Water migrated into the concrete from the inside
 - Inner layer of the wall freezes and expands
 - Outer layer of wall contracts
 - Creates high radial stress
 - Results in laminar cracking



 Conclusion: Laminar cracking as a result of water freezing is a real potential



Shield Building Investigation into Water Intrusion/Freezing

- The effects of moisture intrusion and sub freezing temperatures was investigated as a possible cause
- The review of severe environmental conditions that the plant was exposed to was performed
- The most significant event recorded at the site and also in Ohio history was the storm of January 25-27, 1978



Moisture Intrusion and Low Temperatures

- January 25-27, 1978, was the worst in terms of:
 - Moisture
 - Winds
 - Temperature
 - Duration
 - Pressure





Moisture Intrusion and Low Temperatures, *continued*

- Scenario:
 - Temperature near zero
 - Sustained strong winds
 - Moisture penetrated the Shield Building
 - Moisture trapped in the outer layer of concrete crystallized
 - Concrete expansion exceeded the tensile capacity of the concrete and propagated the crack





Moisture Intrusion and Low Temperatures, *continued*

- A complex computer model of the Shield Building was developed
- Concrete properties from the concrete core tests were used
- Laboratory tests showed moisture infiltration up to four inches
- Maximum radial stress in the shoulder area were approximately the tensile capacity of the concrete
- High stresses were located in areas of observed cracking





Sensitivity Analysis – High Density of Rebar

- A complex computer model evaluated the affects of rebar spacing to determine the potential for developing cracks
- Evaluation showed laminar cracks could:
 - Form in regions of closely spaced rebar and
 - Less likely in areas were the rebar is spaced at 12 inches
- This analysis establishes that rebar spacing is a probable contributing factor



Summary of Analyses

- Normal design conditions result in low stresses which could not cause cracking
- Moisture and freezing could cause high stresses in the shoulder areas that results in cracking
- Analysis shows closely spaced reinforcing steel can be a contributor to laminar cracking
- Observed cracking coincides with the locations of high stress in the shoulder areas and in the areas of high density of rebar; cracking concentrated on southern exposures



Shield Building Root Cause

Root Cause:

- Lack of water sealant on the concrete exterior

Contributing Causes:

- Shoulder reinforcing details (discontinuity and no radial rebar)
- High density of rebar spacing
- High moisture, severe wind, and low temperature conditions



Shield Building Additional Actions

Ken Byrd, Director - Site Engineering





Shield Building – Preventative Action

Root Cause

- Lack of concrete sealant

Preventative Action to Prevent Recurrence

- The exposed exterior surfaces of the Shield Building will be sealed
- Contractor has started and is expected to be completed by the end of September of this year





Shield Building – Additional Actions

- The Root Cause has established several additional Corrective Actions
 - Complete Impulse Response (IR) examinations on the Shield Building wall
 - Perform IR mapping on another structure (Auxiliary Building) to confirm assumptions of our analyses
 - Develop and implement a test program to establish capacity in an area of laminar cracks
 - Develop a Long-Term Monitoring program



Additional Actions - IR Mapping

 Complete IR examinations on the Shield Building wall and an independent structure

- All accessible areas of the Shield Building wall were mapped
- Over 60,000 individual readings were obtained to fully characterize the condition of the building





Additional Actions - IR Mapping, continued

- The IR validated our original assessment that the laminar cracks are generally confined to:
 - The shoulder areas
 - Top of the Shield Building
 - Near one corner of the Main Steam Line penetration
- Impulse Response reading on an independent structure validated that laminar cracks are not present



Additional Actions - IR Mapping, continued



Shield Building Crack Investigation and Root Cause Presentation Public Meeting August 9, 2012

42

Additional Actions – Testing

- Tests were developed and conducted at two nationally recognized universities
- Professors are industry experts and are American Concrete Institute (ACI) Committee members





Additional Actions – Testing, *continued*

- Two different methods were used to create laminar cracks in the samples to be tested
- Results were independently verified





Additional Actions – Testing, continued

Testing results

- Full capability of reinforcement is maintained in regions with longer splice lengths (upper portion of Shield Building)
- Results showed near to full capability of reinforcement in regions with shorter splice lengths

Testing conclusions

- The tests provide high confidence of the capability of the rebar located in regions of laminar cracking
- Testing confirms the assumptions made in structural calculation prior to restart were very conservative



Additional Actions – Long Term Monitoring

- Establish a Long-Term Monitoring Program
 - FENOC has established a long-term monitoring plan that includes:
 - Monitoring existing core bores for crack propagation
 - Inspection of the integrity of the Shield Building coatings
 - Inspection of the integrity of other safety related building coatings





Summary

The corrective actions established will:

- Prevent moisture from entering the Shield Building and freezing
- Provide comprehensive characterization of the laminar crack
- Establish the capacity of the rebar in the area of laminar crack
- Provide long term monitoring of the shield building



Closing Comments

Barry Allen, Site Vice President



