



August 30, 2012

NG-12-0346
10 CFR 50.73

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D.C. 20555-0001

Duane Arnold Energy Center
Docket 50-331
License No. DPR-49

Licensee Event Report #2012-004-00

Please find attached the subject report submitted in accordance with 10 CFR 50.73. This letter makes no new commitments or changes to any existing commitments.

A handwritten signature in black ink, appearing to read "Richard L. Anderson".

Richard L. Anderson
Vice President, Duane Arnold Energy Center
NextEra Energy Duane Arnold, LLC

*JE22
MRR*

LICENSEE EVENT REPORT (LER)

(See reverse for required number of digits/characters for each block)

1. FACILITY NAME Duane Arnold Energy Center	2. DOCKET NUMBER 05000331	3. PAGE 1 OF 3
---	-------------------------------------	--------------------------

4. TITLE
High Pressure Coolant Injection Declared Inoperable

5. EVENT DATE			6. LER NUMBER			7. REPORT DATE			8. OTHER FACILITIES INVOLVED	
MONTH	DAY	YEAR	YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DAY	YEAR	FACILITY NAME	DOCKET NUMBER
07	02	12	2012	004	0	08	30	12	N/A	05000
									N/A	05000

9. OPERATING MODE 1	11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)										
	<input type="checkbox"/> 20.2201(b)	<input type="checkbox"/> 20.2203(a)(3)(i)	<input type="checkbox"/> 50.73(a)(2)(i)(C)	<input type="checkbox"/> 50.73(a)(2)(vii)							
10. POWER LEVEL 100%	<input type="checkbox"/> 20.2201(d)	<input type="checkbox"/> 20.2203(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(viii)(A)							
	<input type="checkbox"/> 20.2203(a)(1)	<input type="checkbox"/> 20.2203(a)(4)	<input type="checkbox"/> 50.73(a)(2)(ii)(B)	<input type="checkbox"/> 50.73(a)(2)(viii)(B)							
	<input type="checkbox"/> 20.2203(a)(2)(i)	<input type="checkbox"/> 50.36(c)(1)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(iii)	<input type="checkbox"/> 50.73(a)(2)(ix)(A)							
	<input type="checkbox"/> 20.2203(a)(2)(ii)	<input type="checkbox"/> 50.36(c)(1)(ii)(A)	<input type="checkbox"/> 50.73(a)(2)(iv)(A)	<input type="checkbox"/> 50.73(a)(2)(x)							
	<input type="checkbox"/> 20.2203(a)(2)(iii)	<input type="checkbox"/> 50.36(c)(2)	<input type="checkbox"/> 50.73(a)(2)(v)(A)	<input type="checkbox"/> 73.71(a)(4)							
	<input type="checkbox"/> 20.2203(a)(2)(iv)	<input type="checkbox"/> 50.46(a)(3)(ii)	<input type="checkbox"/> 50.73(a)(2)(v)(B)	<input type="checkbox"/> 73.71(a)(5)							
<input type="checkbox"/> 20.2203(a)(2)(v)	<input type="checkbox"/> 50.73(a)(2)(i)(A)	<input type="checkbox"/> 50.73(a)(2)(v)(C)	<input type="checkbox"/> OTHER								
<input type="checkbox"/> 20.2203(a)(2)(vi)	<input type="checkbox"/> 50.73(a)(2)(i)(B)	<input checked="" type="checkbox"/> 50.73(a)(2)(v)(D)	<input type="checkbox"/> VOLUNTARY LER								

12. LICENSEE CONTACT FOR THIS LER

NAME Robert J. Murrell, Engineering Analyst	TELEPHONE NUMBER (Include Area Code) (319) 851-7900
--	--

13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT

CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX	CAUSE	SYSTEM	COMPONENT	MANUFACTURER	REPORTABLE TO EPIX

14. SUPPLEMENTAL REPORT EXPECTED <input type="checkbox"/> YES (If yes, complete 15. EXPECTED SUBMISSION DATE) <input checked="" type="checkbox"/> NO	15. EXPECTED SUBMISSION DATE MONTH: _____ DAY: _____ YEAR: _____
--	--

ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)

On July 2, 2012, at 15:05, while operating at 100% power, a spurious isolation of the High Pressure Coolant Injection (HPCI) Outboard Steam Supply Valve and Outboard Torus Suction Valve occurred. The isolation resulted from a trip of the HPCI Steam Leak Detection (SLD) system. Immediate investigations into the event determined that there was no steam leak and the probable cause was from a bad connection in the SLD system. Subsequent investigation identified a broken solid conductor thermocouple extension wire. The wire was damaged earlier in the day as part of maintenance activities investigating erroneous readings on unrelated circuits. The damaged wire was replaced and HPCI was declared operable on July 3, 2012, at 0002. The root cause of this event was an inadequate installation position of a recorder in the control room panel. The recorder was installed in such a manner that the removal of its terminal cover placed excessive stress on the thermocouple wire resulting in its failure.

This condition was reported under 10 CFR 50.72(b)(3)(v)(D), any event or condition that at the time of discovery could have prevented the fulfillment of the safety function of the structures or systems that are needed to mitigate the consequences of an accident. Reference EN#48064.

The safety significance of this event was minimized by the fact that all other Emergency Core Cooling Systems (ECCS) remained fully operable during the time that HPCI was inoperable.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME Duane Arnold Energy Center	2. DOCKET 05000 - 331	6. LER NUMBER			3. PAGE 2 OF 3
		YEAR 2012	SEQUENTIAL NUMBER 004	REV NO. 0	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

I. Description of Event:

On July 2, 2012, at 15:05, while operating at 100% power, a spurious isolation of the High Pressure Coolant Injection (HPCI) (System Code BG) Outboard Steam Supply Valve and Outboard Torus Suction Valve occurred. The isolation resulted from a trip of the HPCI Steam Leak Detection (SLD) system. Immediate investigations into the event determined that there was no steam leak and the probable cause was from a bad connection in the SLD system. Subsequent investigation identified a broken solid conductor thermocouple extension wire. The wire was damaged earlier in the day as part of maintenance activities investigating erroneous readings unrelated circuits. The damaged wire was replaced and HPCI was declared operable on July 3, 2012, at 0002.

There were no structures, systems or components inoperable at the start of this event that contributed to the event.

II. Assessment of Safety Consequences:

During the period HPCI was inoperable, all other Emergency Core Cooling Systems were operable, and therefore fully capable of mitigating the consequences of an accident had it occurred.

This event did result in a safety system functional failure.

III. Cause of Event:

A root cause evaluation was completed for this event. The root cause of this event was an inadequate installation position of a recorder in the control room panel. The recorder was installed in February 2007 in such a manner that the removal of its terminal cover placed excessive stress on the thermocouple wire resulting in its failure.

IV. Corrective Actions:

On July 03, 2012, all maintenance activities associated with replacing the failed thermocouple wire were completed, and HPCI was declared operable.

The following actions are planned to address the root cause of this event:

Installation of signs inside the cabinet containing the SLD thermocouple wires warning of the potential fragility of the wires in the vicinity of the terminal covers for the associated recorders.

**LICENSEE EVENT REPORT (LER)
CONTINUATION SHEET**

1. FACILITY NAME Duane Arnold Energy Center	2. DOCKET 05000 - 331	6. LER NUMBER			3. PAGE 3 OF 3
		YEAR 2012	SEQUENTIAL NUMBER 004	REV NO. 0	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

Completion of an inspection of other thermocouple wires associated with recorders installed by the Engineering Change Package that installed the recorder identified as the root cause of this event.

Revision of the model Work Order associated with work inside the cabinet containing the SLD thermocouple wires to require maintenance technicians be briefed on the susceptibility of the SLD wires to break.

V. Additional Information:

Previous Similar Occurrences:

A review of License Event Reports from the past 5 years did not identify any previous similar occurrences where HPCI was declared inoperable due to an invalid SLD isolation.

EIIS System and Component Codes:

BJ - High Pressure Coolant Injection System (BWR)

Reporting Requirements:

This event is being reported as an Event or Condition that Could Have Prevented Fulfillment of a Safety Function, 10CFR50.73(a)(2)(v)(D). Additionally, this event was reported under 50.72(b)(3)(v)(D), any event or condition that at the time of discovery could have prevented the fulfillment of the safety function of the structures or systems that are needed to mitigate the consequences of an accident. Reference EN#48064.