



**UNITED STATES
NUCLEAR REGULATORY COMMISSION**

REGION III
2443 WARRENVILLE ROAD, SUITE 210
LISLE, IL 60532-4352

September 25, 2012

Mr. Joel P. Sorensen
Acting Site Vice President
Prairie Island Nuclear Generating Plant
Northern States Power Company, Minnesota
1717 Wakonade Drive East
Welch, MN 55089

**SUBJECT: PRAIRIE ISLAND NUCLEAR GENERATING PLANT, UNITS 1 AND 2;
NRC BIENNIAL PROBLEM IDENTIFICATION AND RESOLUTION
INSPECTION REPORT 05000282/2012007; 05000306/2012007**

Dear Mr. Sorensen:

On August 22, 2012, the U.S. Nuclear Regulatory Commission (NRC) completed a biennial team inspection of Problem Identification and Resolution at your Prairie Island Nuclear Generating Plant, Units 1 and 2. The enclosed inspection report documents the inspection findings which were discussed on August 22, 2012, with you and members of your staff.

This inspection was an examination of activities conducted under your license as they relate to the identification and resolution of problems, compliance with the Commission's rules and regulations, and with the conditions of your operating license. Within these areas, the inspection involved selected examination of procedures and representative records, observations of activities, and interviews with personnel.

Overall, the corrective action program was considered functional, but there were significant challenges that reduced its overall efficacy. Most issues were properly evaluated, but there were examples of inconsistency and a lack of rigor, resulting in some issues being minimally reviewed and having more significant concerns that were not identified. Workers continued to identify issues, but were losing confidence in the program due to the large backlog of open items, recurrent plant events and continued management turnover. Although your staff was taking action to address these weaknesses, it was questionable whether these initiatives would be self-sustaining in the long term.

Based on the results of this inspection, no findings were identified. However, there were three Unresolved Items identified. The specifics of these items and the information needed to disposition them are discussed in the report.

J. Sorensen

-2-

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response (if any), will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Kenneth Riemer, Chief
Branch 2
Division of Reactor Projects

Docket Nos. 50-282, 50-306, and 72-010
License Nos. DPR-42, DPR-60, and SNM-2506

Enclosure: Inspection Report 05000282/2012007; 05000306/2012007
w/Attachment: Supplemental Information

cc w/encl: Distribution via ListServ

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Docket Nos: 50-282; 50-306; 72-010
License Nos: DPR-42; DPR-60; SNM-2506

Report No: 05000282/2012007; 05000306/2012007

Licensee: Northern States Power Company, Minnesota

Facility: Prairie Island Nuclear Generating Plant, Units 1 and 2

Location: Welch, MN

Dates: July 23 through August 22, 2012

Inspectors: N. Shah, Project Engineer, Team Leader
K. Stodter, Senior Resident Inspector, Prairie Island
D. McNeil, Senior Operating License Examiner
E. Sanchez-Santiago, Engineering Inspector

Approved by: K. Riemer, Chief
Branch 2
Division of Reactor Projects

Enclosure

TABLE OF CONTENTS

| | |
|---|---|
| REPORT DETIALS | 2 |
| 4. OTHER ACTIVITIES | 2 |
| 4OA2 Biennial Problem Identification and Resolution (71152B) | 2 |
| SUPPLEMENTAL INFORMATION..... | 1 |
| KEY POINTS OF CONTACT | 1 |
| LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED | 1 |
| LIST OF DOCUMENTS REVIEWED | 2 |

SUMMARY OF FINDINGS

Inspection Report 05000282;05000306/2012-007; 07/23/2012 – 8/10/2012; Prairie Island Nuclear Generating Plant, Units 1 and 2; Routine Biennial Problem Identification and Resolution Inspection.

This report covers a 3 week period of announced baseline inspection by three regional inspectors and one senior resident inspector. The significance of most findings is indicated by their color (Green, White, Yellow, Red) using Inspection Manual Chapter 0609, "Significance Determination Process" (SDP). Findings for which the SDP does not apply may be Green or be assigned a severity level after NRC management review. The NRC's program for overseeing the safe operation of commercial nuclear power reactors is described in NURE-1649, "Reactor Oversight Process," Revision 4, dated December 2006.

Problem Identification and Resolution

Although the Prairie Island corrective action program (CAP) was functional, there were a significant number of challenges that reduced its overall efficacy. Workers continued to identify issues at an appropriate threshold, but there was a significant number of issues that remained uncorrected. This growing backlog of legacy issues resulted in recurring events that significantly challenged current plant performance. Most items entered into the CAP were screened and prioritized in a timely manner using established criteria, but there were some examples of inconsistency and a lack of rigor in the screening process. Most issues were properly evaluated, but there were numerous examples where issues were minimally reviewed and more significant concerns were not identified. There were also examples where the inspectors questioned whether the safety significance of the issues was properly characterized. Audits and self-assessments were performed at an appropriate frequency, but were generally less intrusive than those conducted by Nuclear Oversight, lessening their overall effectiveness. Collectively, these issues resulted in declining confidence among workers that problems would be corrected.

Of particular concern, was the high rate of management turnover. This negatively impacted the licensee's ability to maintain continuous improvement; to reinforce management expectations for CAP implementation; and to allow the line organization to effectively manage the workload and ensure that corrective actions were timely implemented.

In 2007 and 2009, the inspectors were critical of the corrective action program implementation based on observed deficiencies similar to those discussed above. The licensee subsequently initiated several improvement initiatives that had resulted in some improvement, as documented in the 2010 biennial problem identification and resolution inspection. However, as noted above, these improvements were not sustained and overall performance had declined. Although the licensee had identified these weaknesses and was taking additional action, the current improvement program was not yet fully implemented and effective.

A. NRC-Identified and Self-Revealed Findings

No findings were identified.

B. Licensee-Identified Violations

No violations were identified.

REPORT DETAILS

4. OTHER ACTIVITIES

4OA2 Biennial Problem Identification and Resolution (71152B)

The activities documented in Sections a. through d. constituted one biennial sample of problem identification and resolution as defined in Inspection Procedure (IP) 71152.

.1. Assessment of the Corrective Action Program Effectiveness

a. Inspection Scope

The inspectors reviewed the licensee's Corrective Action Program (CAP) implementing procedures, interviewed personnel and attended CAP program meetings to assess the implementation of the CAP by site personnel.

The inspectors reviewed risk and safety significant issues in the licensee's CAP program since the last NRC Problem Identification and Resolution (PI&R) inspection in 2010. The selection of issues ensured an adequate review of issues across NRC cornerstones. The inspectors used NRC generic communications, department self assessments, licensee audits, operating experience reports, and NRC documented findings as sources to select issues. Additionally, the inspectors reviewed Action Items (ARs), generated as a result of facility personnel's performance in daily plant activities. In addition, the inspectors reviewed ARs and a selection of completed investigations from the licensee's various investigation methods, which included root causes, apparent causes, equipment apparent causes, and common cause investigations.

The review included all ARs (closed or open) documenting operator performance and fatigue related issues since June 2007; including any special audits, evaluations, action plans, etc. performed to address any associated significant issues or trends.

During the reviews, the inspectors evaluated the licensee staff's actions to comply with the facility's corrective action program and 10 CFR Part 50, Appendix B, requirements. Specifically, the inspectors evaluated if licensee personnel were identifying plant issues at the proper threshold, entering the plant issues into the CAP in a timely manner, and assigning the appropriate prioritization for resolution of the issues. The inspectors also evaluated whether the licensee staff assigned the appropriate investigation method to ensure the proper determination of root, apparent, and contributing causes. The inspectors also evaluated the timeliness and effectiveness of corrective actions for selected issue reports, completed investigations, and NRC findings, including Non-Cited Violations.

Assessment

(1) Effectiveness of Problem Identification

Based on the information reviewed, the inspectors concluded that the threshold for initiating ARs was appropriate and was consistent with the plant procedural requirements. Issues were entered into the CAP at a low threshold and AR generation

numbers were representative of a good problem identification ethic. Other safety conscious work environment (SCWE) indications such as surveys and interviews indicated willingness to identify issues and capture them in the CAP.

The inspectors identified an Unresolved Item (URI) regarding the failure to evaluate the minimum number of air receivers needed to ensure the operability of the emergency diesel generators. This URI is discussed below.

The inspectors identified several examples where ARs were not properly entered into the PASSPORT electronic database, which was used to track CAP related issues. The licensee documented this observation as AR 1347676.

Findings

.1 Unresolved item Regarding the Number of Air Receivers Required to be Greater than 480 psig to Support Emergency Diesel Generator Operability

Introduction: The inspectors identified an unresolved item due to differences between procedural guidance and the Updated Safety Analysis Report (USAR) regarding the number of emergency diesel generator (EDG) air receivers that needed to be pressurized to greater than 480 pounds per square inch gauge (psig) to support EDG operability.

Description: On October 15, 2010, the licensee initiated AR 1254304 to document that the D6 EDG 2A starting air compressor relief valve (2EG-39-7) was leaking. This condition caused the pressure in the 2A starting air receiver to drop below 480 psig. Upon identifying this condition, the operators checked the operating status of the remaining three air receivers and determined that the 1A receiver was also less than 480 psig due to maintenance on the 1A starting air compressor. The operations crew immediately declared the D6 EDG inoperable since Alarm Response Procedures C50001, "D5 Engine 1 Remote Alarm Responses" and C60001, "D6 Engine 1 Remote Alarm Responses," contained a note which stated that the pressure in three out of four air receivers must be greater than 480 psig to maintain EDG operability.

As part of this inspection, the inspectors reviewed the licensee's evaluation and resolution of AR 1254304. The inspectors found that the 1A and 2A starting air compressors were repaired by the maintenance staff. Repairing the compressors allowed the pressure in the associated air receivers to be restored to normal operating levels. The inspectors also found that the licensee had assigned engineering personnel to evaluate whether the inability to maintain pressure in the 1A and 2A air receivers above 480 psig needed to be considered a maintenance rule functional failure. The inspectors reviewed the licensee's completed maintenance rule evaluation and found that the condition of the 1A and 2A air receivers was not considered a functional failure due to information contained in the USAR which specified that only two of the four air receivers were needed for EDG operability. The inspectors were concerned by this conclusion since it was supported by information that conflicted with the alarm response procedures in effect in July 2010 and Procedure 2C20.7, "D5/D6 Diesel Generators."

On August 3, 2012, the inspectors discussed the conflicting information with the licensee. The inspectors specifically discussed that the conflicting information could have resulted in one of the following conditions:

- Operations personnel declaring the D6 EDG inoperable due to overly conservative procedural guidance regarding air receiver pressure; or
- An incorrect maintenance rule evaluation may have been completed due to incorrect USAR information.

The licensee initiated AR 1347636 to document the inspectors concern. The licensee was evaluating the actual number of air receivers required to be pressurized to greater than 480 psig to support EDG operability at the conclusion of the inspection. As a result, this issue will be considered unresolved pending the inspectors review of the licensee's evaluation and a determination regarding whether the licensee had appropriately evaluated the conditions described in AR 1254304 (**URI 05000306/2012007-01: Number of Air Receivers Required to be Greater than 480 psig to Support EDG Operability**).

(2) Effectiveness of Prioritization and Evaluation of Issues

Assessment

The overall performance in prioritization and evaluation of issues was acceptable, but this area still presented the most challenges to the CAP. AR screening was generally good and ownership was demonstrated by the line organization and the CAP team. However, there continued to be problems with meeting CAP standards during the AR screening meetings. Although station management had increased observations of the screening meetings in order to provide feedback, the inspectors concluded that performance hadn't yet improved to the point where it could be sustained without continued management attention.

The licensee was applying a safety related (condition adverse to quality (CAQ)) versus non-safety related (not a condition adverse to quality (NCAQ)) screening criteria to assist with prioritization. Inspectors noted that this approach did not address the risk to plant operations and was not always accurately applied. Although all issues were addressed, the understanding of what constituted a "Significant Condition Adverse to Quality (SCAQ)" was limited; potentially resulting in some issues receiving an inappropriate level of oversight. Several licensee staff commented that this classification was only warranted for issues involving offsite radiological releases or having a significant effect on public safety. This meant that other issues that significantly affected plant performance would require a less rigorous evaluation. For example, the licensee had identified a potential substantive cross-cutting issue in the area of Problem Identification and Resolution, as CAQ instead of an SCAQ. A substantive cross-cutting issue was issued by the NRC after evidence of a significant decline in performance as indicated by an adverse trend (i.e., three or more) of similar NRC findings in a 12 month period. By not classifying this as an SCAQ, the licensee was potentially taking inappropriate action to address a significant breakdown in performance. This issue was documented as AR 1346177.

The inspectors noted that the station continued to focus on the symptoms rather than the causes when evaluating issues. Several examples were noted where questioning by inspectors had resulted in significant changes to the evaluations and, in some cases, NRC findings. One example was how the licensee addressed a question raised by the NRC resident inspector concerning the boot seals in the residual heat removal pits. Specifically, the inspector noted that the boot seal was degraded and questioned the purpose of the seal. Initially, the licensee closed the issue by concluding that the seal was unnecessary for flood mitigation and then repaired the seal. However, further questioning by the NRC PI&R team, identified that the boot seal was a flood mitigation barrier and that compensatory measures may have been necessary during the period the seal was degraded. This issue was documented as AR 1347687

Root causes and Quality Assurance (QA) reports were generally acceptable, but there were some examples where these evaluations were neither sufficiently self-critical nor had a clearly defined problem statement. The licensee also had a common practice of "rolling-up" ARs into a single evaluation, which made it difficult to discern how the individual issues were addressed. The licensee had enhanced CAP oversight functions through the Plant Assessment Review Board which reviewed and graded CAP evaluations for all higher significance items, including root and apparent cause evaluations, and provided feedback to the staff. This enhanced oversight was a recent initiative; therefore it was too soon to determine if these improvements would be sustained long term.

The inspectors identified several issues with a root cause evaluation performed by the licensee after 34 senior management changes occurred between 2006 and 2011. This evaluation was documented as AR 1311305. The evaluation concluded that the turnover had not resulted in any actual consequence to the affected departments and that the causes were related to pay and benefits, high work load and quality of life issues. However, the inspectors noted that the overall conclusion was inconsistent with the results of other root and apparent causes, all of which identified "management churn" as a primary reason for continued poor CAP performance. Additionally, the evaluation did not address why the turnover only occurred at the Prairie Island station and not at other licensee facilities. The observations were included in the corrective actions assigned to AR 1311305.

Findings

.1 Unresolved Item for the Failure to Perform Maintenance Rule Evaluations After Discovering Degraded Radiation Monitors

Introduction: The inspectors identified an unresolved item regarding the failure to perform maintenance rule evaluations after discovering degraded conditions on four separate radiation monitors. Due to the missing evaluations, the inspectors were unable to determine whether the radiation monitor system had been appropriately evaluated under the maintenance rule as required by 10 CFR 50.65.

Description: On July 15, 2010, the licensee initiated AR 1241216 to document that radiation monitor 1RM-48 was reading downscale. During the screening of this AR, the licensee assigned an individual to complete an apparent cause evaluation to determine the cause of the downscale condition. The licensee also

assigned a maintenance rule evaluation to determine whether the condition of the radiation monitor constituted a maintenance rule functional failure as defined by 10 CFR 50.65.

Two days later, the licensee initiated AR 1241453 to document that several radiation monitors (including 1RM-48) were adversely impacted during the installation of a new R-11 radiation monitor. During the screening of this corrective action document, the licensee determined that an apparent cause evaluation was not needed since the poor design of the radiation monitor cabinetry, combined with the installation of new wires amongst older wires, had caused the adverse impacts. In addition, the screening team approved the cancellation of the apparent cause and maintenance rule evaluations assigned as part of AR 1241216 based upon the information contained in AR 1241453. The inspectors reviewed the assignment cancellation information and agreed that the apparent cause evaluation was not needed. However, the maintenance rule evaluation was needed to determine whether additional maintenance rule related actions were required.

The inspectors questioned licensee personnel to determine whether a maintenance rule evaluation was completed for the equipment issue discussed in AR 1241216. The licensee informed the inspectors that the maintenance rule evaluation had not been completed. In addition, maintenance rule evaluations for the three other radiation monitors (2RM-48, 2R-71, and R-41) discussed in AR 1241453 were not performed. The licensee documented the failure to perform the maintenance rule evaluations as AR 1347349. The maintenance rule evaluations were ongoing at the conclusion of the inspection. As a result, this issue will be considered unresolved pending the inspectors review of the maintenance rule evaluations and a determination of whether the failures should have resulted in the radiation monitoring system being classified as an a(1) maintenance rule system (**URI 05000282/2012007-03; 05000306/2012007-03: Failure to Perform Maintenance Rule Evaluations After Discovering Degraded Radiation Monitors**).

(3) Effectiveness of Corrective Actions

Assessment

The licensee resolved the majority of issues, but there remained a significant backlog of open issues that challenged the station's ability to manage current performance while addressing legacy issues. The station currently had a backlog of 78 open issues involving systems, structures and components considered operable, but degraded; 211 ARs that had been open for 2+ years; and 130 open high priority work items. These issues had resulted in workers having to live with long term deficiencies, resulting in a significant decline in worker morale. For example, during interviews with the inspectors, several plant operators felt that station management was unresponsive to their concerns about the large number of open operator burdens. In one case, the inspectors identified that a long standing concern regarding the functionality of the steam exclusion dampers and the associated operability of the safety-related equipment protected by those dampers had been open since 1998. This issue was considered a URI as discussed below.

The work load associated with the large backlog adversely affected the timely implementation of corrective actions and contributed to the common practice of addressing symptoms rather than evaluating causes.

Prairie Island continued to experience plant transients and equipment deficiencies due to the failure to adequately resolve previously identified problems. The resources needed to address these recurring issues have hindered the stations efforts to improve the CAP. For example, in March 2012, the licensee lost reactor vessel level indication while lowering water in the reactor vessel. This was a significant event as the failure to maintain adequate water level in the reactor vessel could result in core damage due to insufficient cooling. The event resulted in part, from a failure to take corrective actions following a similar event in 2010. The 2012 event was investigated by the NRC and was documented in NRC Inspection Report 2012011.

There were several examples where Effectiveness Reviews were either inappropriate or were scheduled too early to be useful. This potentially allowed for recurrence of past events due to the mistaken belief that the underlying issues were corrected. The inspectors identified examples where these Reviews were scheduled prior to the completion of corrective actions and/or where similar problems recurred simply because a premature review erroneously concluded that the issues were resolved. This observation was documented as AR 1347397.

Findings

.1 Unresolved Item Regarding the Design Basis of the Steam Exclusion Dampers.

Introduction: An unresolved item was identified by the inspectors due to a lack of steam exclusion (SE) damper leakage design basis information, questions regarding the adequacy of SE damper testing, the functionality of the SE system, and the operability of safety related equipment protected by the dampers following a high energy line break (HELB) event.

Description: In 1998 the licensee identified concerns regarding the ability of the SE system dampers to meet the leakage rate described in the USAR and the deterioration of non-metallic gears due to environmental conditions. These issues were documented as Nonconformance Reports 19981361 and 19981104. The licensee initially planned to disposition the conditions as “use as is” conditions until a revised HELB analysis was completed and the SE dampers were replaced.

On October 7, 2009, the licensee initiated AR 1201589 to document that the activities needed to disposition the conditions described above as “use as is” conditions had not been completed. The licensee reviewed operability recommendations, engineering change records, and 10 CFR 50.59 screenings and evaluations and were unable to find any documents which evaluated the condition of the SE dampers as acceptable. The licensee screened AR 1201589 as a “B” level corrective action document. No apparent or root cause evaluation was assigned. The screening team concluded that the equipment conditions described in the 1998 Nonconformance Reports should be classified as operable but nonconforming conditions since they had not been corrected.

As part of this inspection, the inspectors reviewed the licensee's resolution of AR 1201589. The inspectors identified the following:

- The licensee had not used the operability/functionality process described in Procedure FP-OP-OL-01, "Operability/Functionality Program," when classifying the SE damper conditions as operable but nonconforming in 2009;
- The failure to use the process described in Procedure FP-OP-OL-01 resulted in someone other than the shift manager approving the operable but nonconforming decision;
- A formal operability recommendation did not exist; and
- The status of the SE system dampers should have been classified as functional but nonconforming rather than operable but nonconforming.

Corrective action document 1201589 also clarified that the SE damper leakage rate described in the USAR was a manufacturing specification rather than design basis information. The inspectors reviewed the most recent SE system health report and found that it also contained information which indicated that design basis information regarding the amount of SE damper leakage that could exist following a HELB did not exist. A large contributor to the lack of this design basis information was due to the fact that the 1998 HELB analysis remained incomplete as of August 10, 2012.

Based upon this information, the inspectors were concerned that the licensee's monthly SE damper testing may not be adequately verifying the functionality of the SE system. The inspectors were also concerned that assumptions used in currently open operability recommendations regarding the heat up of the battery rooms, the auxiliary feedwater pump rooms, the D1 and D2 emergency diesel generator rooms and several other areas may not be adequate to ensure that the equipment in these rooms would remain capable of performing their specified safety functions following a HELB event. The licensee documented the inspectors concerns in ARs 1345879, 1347752, and 1349909. At the conclusion of the inspection, the shift manager had designated the SE dampers as functional but nonconforming due to the lack of design basis leakage criteria and recent SE damper test results which demonstrated that the dampers had appropriately closed when needed. However, the licensee was continuing to review the adequacy of the SE damper test and the assumptions in the currently open operability recommendations. As a result, this issue will be considered unresolved pending an inspection of the licensee's review results **(URI 05000282/2012007-03; 05000306/2012007-03: Lack of Design Basis Information for Steam Exclusion Damper Leakage).**

.2. Assessment of the Use of Operating Experience

Inspection Scope

The inspectors reviewed the licensee's implementation of the facility's Operating Experience (OE) program. Specifically, the inspectors reviewed implementing operating experience program procedures, attended CA program meetings to observe the use of OE information, reviewed completed evaluations of OE issues and events, and reviewed selected assessments of the OE program. The inspectors' review was to determine whether the licensee was effectively integrating OE experience into the performance of

daily activities, whether evaluations of issues were proper and conducted by qualified personnel, whether the licensee's program was sufficient to prevent future occurrences of previous industry events, and whether the licensee effectively used the information in developing departmental assessments and facility audits. The inspectors also assessed if corrective actions, as a result of OE experience, were identified and effectively implemented.

Assessment

In general, OE was effectively screened and corrective actions were assigned as appropriate. Root and apparent cause evaluations included discussions of OE, but there were some examples where the OE review was limited in focus. In addition, the inspectors found some examples where the OE evaluations were not of high quality despite having gone through supervisory review. Similar issues were also identified in the licensee self-assessments of the OE program and were being addressed in the CAP. Although some corrective actions had been implemented, it was too early to determine their long term effectiveness.

Findings

No findings were identified.

.3. Assessment of Self-Assessments and Audits

a. Inspection Scope

The inspectors assessed the licensee staff's ability to identify and enter issues into the CAP, prioritize and evaluate issues, and implement effective corrective actions through efforts from departmental self-assessments and NOS audits.

Assessment

The inspectors concluded that departmental self-assessments were adequate and did identify issues at an appropriate threshold level. The assessments were completed by personnel knowledgeable in the subject area. By contrast, NOS assessments were typically more intrusive, critical and of better quality than the department self-assessments. In general, NOS was observed to be a more effective driver for CAP improvement than the department self-assessments. For example, the department self-assessment concluded that the CAP performance was improving and that corrective actions were effective at driving change. The NOS audit also noted that the CAP was improving, but identified significant challenges to CAP performance; NOS also questioned whether the observed improvements were self-sustaining. Overall, the NOS observations were more in line with the NRC inspection conclusions than the department self-assessments.

Findings

No findings were identified.

.4 Assessment of Safety Conscious Work Environment

a. Inspection Scope

The inspectors assessed the licensee's safety conscious work environment by reviewing the facility's employee concerns program (ECP) implementing procedures, postings for maintaining employee awareness of the ECP program, discussions with the ECP coordinator, interviews with personnel from various departments, and reviews of ECP issue reports. The inspectors also reviewed the implementing procedures for the Differing Professional Opinions (DPO) program and the results of DPOs generated over the previous 2 years.

The inspectors reviewed the licensee's safety culture policy statements and the results of safety culture assessments performed within the last 2 years. The inspectors also interviewed employees from various departments to assess their willingness to raise nuclear safety issues. The individuals were selected to provide a cross-section across the various departments at the site. In addition to assessing the willingness to raise nuclear safety issues, the interviews also addressed the changes in the CAP and plant environment over the past 2 years. Other items discussed included:

- knowledge and understanding of the program;
- effectiveness and efficiency of the program;
- willingness to use the program;
- management's support of the program;
- feedback on issues raised; and
- ease of input to the system.

Assessment

The licensee maintains an accessible, functioning ECP that is generally well regarded by plant employees. Issues identified through the program were generally appropriately resolved and there were no significant trends noted. The DPO process was also well regarded, although not as commonly used as the ECP.

Employees were generally free to raise issues without fear of retaliation. During interviews, workers stated that they felt it was important to raise issues and felt free to do so. The process was not seen as cumbersome and was generally supported by management.

However, workers were losing confidence in the ability of the CAP to resolve issues. The continued high backlog, recurrence of past events and high workload have left many workers feeling that long standing issues would not always be resolved in a timely manner. This was supported by statements made during interviews with the inspectors and the results of licensee safety culture assessments.

Additionally, continued "management churn" has degraded worker confidence in the CAP, hampered station efforts to maintain sustained CAP improvement and adversely affected the ability of the line organization to ensure that management expectations were met. This conclusion was based on the aggregate review of root and apparent cause evaluations and the consensus of workers during interviews with the inspectors.

Overall the inspectors concluded that while the safety culture was currently adequate, absent sustained long term improvement, workers may eventually lose confidence in the CAP and stop raising issues.

Findings

No findings were identified.

4OA6 Management Meetings

Exit Meetings Summary

On August 22, 2012, the inspectors presented the inspection results to J. Molden and other members of the licensee staff. The licensee acknowledged the issues presented. The inspectors confirmed that none of the potential report input discussed was considered proprietary.

ATTACHMENT: SUPPLEMENTAL INFORMATION

SUPPLEMENTAL INFORMATION

KEY POINTS OF CONTACT

Licensee

T. Allen, Site Engineering Manager
P. Anderson, Corporate Director, Regulatory Affairs
B. Boyer, Radiation Protection Manager
H. Butterworth, Director, Corporate Functional Area Management
K. Davison, Director of Site Operations
P. Huffman, Site Engineering Director
A. Khanifar, Corporate Vice-President, Engineering
J. Lash, Nuclear Oversight Manager
P. Lindburg, Design Engineering Manager
J. Molden, Site Vice President—Prairie Island
T. O'Conner, Corporate Vice President of Engineering and Nuclear Regulatory Compliance and Licensing
K. Petersen, Business Support Manager
D. Potter, Programs Engineering Manager
J. Ruttar, Operations Manager

Nuclear Regulatory Commission

G. Shear, Acting Director, Division of Reactor Projects, Region III
K. Riemer, Chief, Reactor Branch 2, Division of Reactor Projects, Region III
B. Kemker, Senior Resident Inspector, Clinton
S. Thomas, Senior Resident Inspector, Monticello

LIST OF ITEMS OPENED, CLOSED, AND DISCUSSED

Opened

| | | |
|---|-----|---|
| 05000306/2012007-01 | URI | Number of Air Receivers Required to be Greater than 480 psig to Support EDG Operability |
| 05000282/2012007-02; 05000306/2012007-02 | URI | Failure to Perform Maintenance Rule Evaluations After Discovering Degraded Radiation Monitors |
| 05000306/2012007-03; 05000306/2012007-03 | URI | Lack of Design Basis Information for Steam Exclusion Damper Leakage |

Closed and Discussed

None.

LIST OF DOCUMENTS REVIEWED

The following is a list of documents reviewed during the inspection. Inclusion on this list does not imply that the NRC inspectors reviewed the documents in their entirety, but rather, that selected sections of portions of the documents were evaluated as part of the overall inspection effort. Inclusion of a document on this list does not imply NRC acceptance of the document or any part of it, unless this is stated in the body of the inspection report.

APPARENT CAUSE EVALUATIONS

| <u>Number</u> | <u>Description or Title</u> | <u>Date or Revision</u> |
|---------------|--|-------------------------|
| 1341153-01 | Apparent Cause Evaluation: NOS Assessment of ISI Program Identified 15 Non-Conformances | 08/08/12 |
| 1324465 | Apparent Cause Evaluation: 122 SPF HX Tornado Missile Protection Project Stopped | 08/07/12 |
| 1345542 | Equipment Cause Evaluation: RPS Logic BKR 1-52 BYB Failed to Remain Closed During Surveillance | 08/06/12 |
| 1189176 | Grout Use for Safety Related Applications D75 Noncompliance | 0 |
| 1242770 | Apparent Disconnect or Sheared Shaft on 121 Cooling Water Pump | 07/25/10 |
| 1259323 | Breaker 113G Has No Light Indication | 11/19/10 |
| 1286842 | Incorrect Bolting Apparently Installed in 12 Residual Heat Removal Pump Coupling | 05/20/11 |
| 1308464 | PM Deferral – Error Made in Completing Section 6 | 10/15/11 |
| 1322830 | During 1R27 Motor Valve 32145 was Reassembled with the Wrong Worm Gear | 01/30/12 |
| 1337891 | Vital Loads were not On While Breaker 25-5 Troubleshooting Occurred | 05/16/12 |
| 1266075 | Potential LER Issue on DEC 121 MDCLP Autostart | 1/12/11 |
| 1297740 | CAP 1296358 Does Not Address Inappropriate Closure of CAPs | 8/12/11 |
| 1303267 | Safeguards Battery Room Temperatures | 9/21/11 |
| 1300997 | EC 17949 Provides Justification for Higher battery Room Temperatures | 8/26/11 |
| 1261328 | Programmatic Breakdown of Life Cycle Management Obsolescence | 12/3/10 |
| 1325119 | LER Required, U1 FO Inventory Inadequate During Last 3 Years | 2/15/12 |
| 1314190 | Lack of Timely Response to non-Conservative Technical Specification | 11/21/11 |
| 12883586 | Worker Accidentally Breached System Without Isolation | 5/3/11 |
| 1286842 | Incorrect Bolting Apparently Installed in 12 RHR Pump Coupling | 5/20/11 |
| 1292649 | 12 RYBT Breaker Would Not Rack In Properly | 6/30/11 |
| 1323227 | Three Findings in H.1.(b) Cross-Cutting Aspect | 2/1/12 |
| 1266815 | Extent of Condition on Room Heat Up Issues | 1/18/11 |

| | | |
|---------|---|-----------|
| 1299381 | Loss of Two Paths from the Grid | 8/15/11 |
| 1253478 | Two NRC Identified NCV's Associated w/FP-OP-OL-01 Compliance | 3/14/2011 |
| 1283740 | Safety Related Breaker Installed Without QC Inspection | 6/7/2011 |
| 1283928 | CV-31337, 11 RCP SL WTR MU ISOL CV Leaking By | 6/1/11 |
| 1203409 | CC Pump Acceptance Criteria Not Applied with Instrument Uncertainty | 11/21/09 |
| 1233577 | U2 RHR Suction Check Valves Fail SP 2369 Closed Function | 8/5/10 |
| 1238951 | Inadequate Extent of Condition for CC/HELB RCE | 6/25/10 |
| 1247140 | Equivalency Evaluation Not Addressed for Valve 2DG-54 | 11/17/10 |
| 1162695 | Gas Void Found at Location 1RH-3 From the HL | 12/16/08 |

CORRECTIVE ACTION DOCUMENTS CREATED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|---|-------------|
| 1345879 | 2012 PI&R Disconnect Between Ops Status and OBN Assignment | 7/24/12 |
| 1345961 | 2012 PI&R: Reportability Evaluation Contains Incorrect OPR Revision | 7/25/12 |
| 1345996 | Improper Tie-Off of CR-5-1 to Unistrut | 7/25/12 |
| 1346034 | PI&R 2012: CAPR 01085806-16 Has Incorrect Reference | 7/25/12 |
| 1346177 | 2012 PI&R: NRC Asked for Clarification on SCAQ/CAQ Attribute | 7/26/12 |
| 1347359 | Inadequate Closure of AR 1273486 | 8/7/12 |
| 1347349 | MREs Not Issued for 4 RD Failures | 8/7/12 |
| 1347370 | PI&R 2012—NRC Found No CE On Missed OE Item | 8/7/12 |
| 1347397 | RCE Effectiveness Review Lacks Documentation | 8/7/12 |
| 1347489 | 2012 PI&R: RCE 1255628—No CAPR for RC3 | 8/8/12 |
| 1347448 | PI&R Work Orders for BKR Rolls Cancelled | 8/8/12 |
| 1347481 | 2012 PI&R Question on OEE 1246674 | 8/8/12 |
| 1347474 | 2012 PI&R Question on OEE 1243419 | 8/8/12 |
| 1347636 | 2012 PI&R Questions Noted with D5/D6 Air Start Requirements | 8/9/12 |
| 1347676 | 2012 PI&R: Passport CAP Documentation Issues | 8/9/12 |
| 1347683 | 2012 PI&R: NRC Observations Regarding problem Evaluation | 8/9/12 |
| 1347702 | 2012 PI&R: NRC Observations in Area of Operating Experience | 8/9/12 |
| 1347752 | PI&R: NRC Question #143 for SE System | 8/9/12 |
| 1347714 | 2012 PI&R: NRC Comment on old CAP/actions (>2 years) | 8/9/12 |
| 1347641 | Increasing Backlog of Work Activities Assigned to FIN | 8/9/12 |
| 1347687 | Boot Seals in RHR Pits May Be Missing Inspection | 8/9/12 |
| 1346727 | Questions Involving AR Screening Quorum | 8/1/12 |
| 1347366 | PI&R: Inappropriate Closure of CAP Assignment | 8/7/12 |

CORRECTIVE ACTION DOCUMENTS CREATED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|---|-------------|
| 1347498 | 2012 PI&R: CAP 1162695 Identified as a SCAQ With No CAPR | 8/8/12 |
| 1347638 | RMRFF Identified: CAP Not Initiated as Required by QF-0450 | 8/9/12 |
| 1347749 | Galvanic Corrosion Not Considered in EC 17270 | 8/13/12 |
| 1203409 | CC Pump Acceptance Criteria Not Applied with Instrument Uncertainty | 11/21/09 |

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|--|-------------|
| 01106214 | No Formalized Process for Reactivity Plan/Refs Not Provided | 08/09/07 |
| 01164047 | Stopped Work on WO359173, No Reactivity Plan | 12/31/08 |
| 01177080 | WO 00380731 Has Vague Rx Plan, Work Not Completed | 04/06/09 |
| 01182902 | U1 Reactor Startup on 5/21/09 Suspended | 05/21/09 |
| 1217545 | Reactivity Transient During SP 1003 | 02/09/10 |
| 1332102 | Adverse Trends Noted in Operator Fundamentals | 04/03/12 |
| 1285097 | Unit 2 Was Placed in an Unplanned Orange PRA | 05/11/11 |
| 1278221 | Station Personnel Are Not Complying with Written Standards. | 03/30/11 |
| 1271750 | Unplanned Entry into T.S. LCO 3.6.10 Condition A | 02/19/11 |
| 1336495 | SRO Removed T&D Employee from CO 47975 | 05/04/12 |
| 1223720 | Unit 1 & 2 Rapid Load Reduction Rx Plan Worksheet Not Done | 03/22/10 |
| 1120914 | Both Units entered LCO 3.0.3, Sfgds Chilled Water | |
| 1158394 | Change in Reactor Power during SP 2318.3 | 11/06/08 |
| 1177080 | WO 00380731 has vague RX plan, was not completed | 04/06/09 |
| 1214986 | INPO ARI Operational Configuration Control | 01/23/10 |
| 1331737 | Danger Tag Found Incorrectly Installed on Breaker 26-2 | 03/31/12 |
| 1335105 | NOS Observed Danger Tag Hanging on the Remote Hand Wheel Only on 2BL 8-1. | 07/22/11 |
| 1333673 | Degraded Performance Resulted in 16 NRC Findings Over the Past 4 Quarters w/ Cross-Cutting Aspects | 05/08/12 |
| 133591 | Protective Tag Not Found on Breaker 13-2 for as Expected | 04/13/12 |
| 1029449 | Nonsafety Related Parts Used in Safety Related Application | 05/11/06 |
| 1116992 | 121 Control Room Chiller Tripped Several Hours into Run | 11/03/07 |
| 1132098 | 11 Auxiliary Feedwater Pump Stopped due to Turbine Outboard Bearing High Temperature | 03/23/08 |
| 1152509 | DC Panel 23 to Generator and Transformer Lockouts | 09/28/08 |
| 1156626 | Lack of Progress in Resolving Panel 22 Breaker Issues | 10/23/08 |
| 1173309 | ABB Part 21 Notification Deviation – Tension Spring | 03/17/09 |
| 1182488 | 12 Circulating Water Pump Lock Out and Reactor Trip | 05/18/09 |
| 1201589 | Turbine Building Steam Exclusion Dampers Need Evaluation for Use As Is Issue | 10/07/09 |
| 1210283 | ENG-ME-338 was Identified as Requiring Revision | 12/10/09 |
| 1217332 | Chronic Packing Leak on Motor Valve 32170 | 02/08/10 |

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|---|-------------|
| 1218940 | CDBI Prep 2010 – Site Conducted Testing Used in Calculations | 02/18/10 |
| 1219135 | CDBI Preps 2010 – Underground Cables Calculation Needed | 02/19/10 |
| 1219281 | Battery Inter-Cell Cables not Included in Analysis | 02/22/10 |
| 1222649 | Foreign Material Found Inside D1 Lube Oil Sump | 03/15/10 |
| 1230668 | Unit 1 Safeguards Bus Source Breakers | 05/03/10 |
| 1231841 | D6 Breaker Tripped | 05/09/10 |
| 1237859 | Screenhouse Cooling Water Piping Potential Missile Path | 06/18/10 |
| 1247908 | Unable to Perform Work on 111 Switchgear Unit Cooler | 08/31/10 |
| 1255628 | Organizational Failure to Evaluate Changes to Integrated Safety Injection Test | 10/25/10 |
| 1261328 | Programmatic Breakdown of Life Cycle Management and Obsolescence Program | 12/03/10 |
| 1264623 | OE2198 Incorrect Lugs Installed in Rosemont Transmitters | 12/30/10 |
| 1271750 | Unplanned Entry into Technical Specification Limiting Condition for Operation 3.6.10, Condition A | 02/19/11 |
| 1273100 | KTK-R-1 Control Fuse Found in Breaker Bucket | 03/01/11 |
| 1273708 | 122 Control Room Chiller Inlet Flow Switch Failed | 03/04/11 |
| 1283838 | Preventive Maintenance Performed on Wrong Piece of Equipment | 05/04/11 |
| 1285097 | Unit 2 was Placed in a Unplanned Orange Path | 05/11/11 |
| 1288922 | GL 08-01: Void Found at Susceptible Location 1CS-05 | 06/02/11 |
| 1288924 | GL 08-01: Void Found at Susceptible Location 1CS-23 | 06/02/11 |
| 1288925 | GL 08-01: Void Found at Susceptible Location 1CS-25 | 06/02/11 |
| 1289490 | GL 08-01: Void at 1RH-03 | 06/07/11 |
| 1298412 | High Energy Line Break Interaction #3881 Overstresses 1 ½-ZH | 08/08/11 |
| 1301352 | Evaluate Mercoïd Pressure Control Manual | 08/29/11 |
| 1301589 | Turbine Building Steam Exclusion Dampers Appear to Need Use as Is Evaluation | 10/07/09 |
| 1308154 | CDBR: Residual Heat Removal Pit Sump Pump Function for Mitigating Pit Flooding | 10/13/11 |
| 1308408 | 121 Control Room Chiller Chilled Water Pump Vibration Reading in Alert Range | 10/14/11 |
| 1317372 | Unable to Perform SP1158a as Written due to Equipment Deficiency | 12/14/11 |
| 1322404 | Breaker 212E-44 Found Unable to Function | 01/26/12 |
| 1324668 | 123 Air Compressor Tripped with Low Oil Pressure Alarm | 02/11/12 |
| 1331961 | Found Loose Insulation Inside 121 Control Room Air Handler | 04/03/12 |
| 1338553 | Failed 21 Residual Heat Removal Pump Shaft Material Inconsistent with OEM Specification | 05/21/12 |
| 1311305 | 2011 INPO AFI OR. 4-1 | 11/2/11 |
| 1297895 | Adverse Trend in NRC Findings with PI&R Cross-Cuts | 8/4/11 |

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|---|-------------|
| 1260332 | Developing Cross-Cutting Theme in P.1.c | 11/26/10 |
| 1308296 | Three Cross Cut Aspect Hits (h.4.b-Procedure Adherence) | 10/14/11 |
| 1273263 | DPO, CAP Process Ineffective in Timely Resolution of MR a(1) | 3/2/11 |
| 1269172 | DPO, RCS Leak Detection | 2/3/11 |
| 1009304 | SB Flow Control Valves are Non-Safety Related | 1/4/06 |
| 1304446 | OE Review of Westinghouse NSAL 11-2 | 9/20/11 |
| 1302331 | SOER Implementation at Prairie Island | 9/2/11 |
| 1246674 | Evaluate OE 31073 Water Intrusion into Auxiliary Electric Rooms | 8/24/10 |
| 1243419 | Review of NRC IN 2010-13 | 7/29/10 |
| 1241473 | Westinghouse NSAL 10-2 Non-Conservative Jet Impingement Zone | 7/14/10 |
| 1249228 | NRC IN 2010-18 Generic Issue 199 | 9/10/10 |
| 1324193 | PARB Identified Adverse Trend in OEE Quality | 2/8/12 |
| 1251327 | Evaluate NERI Power Cable Issue Update and Recommendations | 9/24/10 |
| 1298597 | OE-NRC Part 21 2011-32-00 Rosemount Model 710 Trip Units | 8/9/11 |
| 1278461 | Evaluate Monticello 2010 Fire FSA | 4/1/11 |
| 1209753 | Evaluate Westinghouse Part 21 2009-23-00 | 12/8/09 |
| 1295684 | Trend in CAP Actions >365 Since January 2011 | 7/21/11 |
| 1342049 | PI&R FSA: Issues With the Volume and Timeliness of OBN's | 6/18/12 |
| 1340739 | PI SCWE Index Has Declined Significantly | 6/6/12 |
| 1211532 | Safety Culture Issue Related to the CA Program | 12/22/09 |
| 1177567 | Adverse Trend in Station Safety Culture | 4/9/09 |
| 1239912 | 11 RHR Sump B Suction Pipe Penetration | 7/1/10 |
| 1273486 | Backdraft Damper Arms Misaligned and Duct Work Cracking | 3/3/11 |
| 1272888 | NRC Identified Scaffold Storage Question in Auxiliary Building | 2/28/11 |
| 1240130 | Tools and Other Objects in Unit 2 Containment Spray Pump Room | 7/2/10 |
| 1297740 | CAP 1296358 Does Not Address Inappropriate Closure of CAPs | 8/3/11 |
| 1257118 | 50.59 Screening Not Sufficient | 11/4/10 |
| 1262227 | Past Operability Not Performed | 12/9/10 |
| 1292940 | Loss of Two Paths from the Grid | 7/1/11 |
| 1003334 | NFPA Code Compliance Review—CAP Inappropriately Closed | 11/10/05 |
| 1173309 | ABB Part 21 Notification of Deviation—Tension Spring | 3/17/09 |
| 1290118 | Two NRC Identified NCV's Associated w/FP-OP-OL-01 Compliance | 6/10/11 |

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

| Number | Description or Title | Date |
|---------------|---|-------------|
| 1245144 | MV-32314 Yolk Broke Upon Actuation | 8/11/11 |
| 1241722 | GL 08-01 Gas Void Found at Location ISI-23 | 7/16/11 |
| 1255307 | HELB Interaction in Aux Building Overstresses CC Piping | 10/22/10 |
| 1271027 | MRB-008 Inadequate Available NPSH | 2/15/11 |
| 1258037 | BE-411 BE-411 Snubbers Operability | 11/10/10 |
| 1128438 | Damage, Erosion , FME Found in 15A FWH | 2/23/08 |
| 1033009 | Discrepancies in FW support 1-FWH-35, Restraints 2 & 10 | 5/30/06 |
| 1196214 | NRC Questioned Rate of Fouling on 12 DDCLP and Past Response | 9/2/09 |
| 1313024 | Aux Feedwater Pump Room Heat Up Issue | 11/14/11 |
| 1246406 | Unit 1 & Unit 2 AFWP Design Flow Margin Reduced | 8/20/10 |
| 1262227 | Past operability Not Performed | 12/9/10 |
| 1129489 | 135-031 11 CC Heat Exchanger Has a small CI Water Leak | 3/2/08 |
| 1156737 | 21 CC HX Divider Plate Configuration Allowed Bypass Flow | 10/23/08 |
| 1285151 | ISI Indication on Support RCVCH-896 | 5/11/11 |
| 1329765 | As Found Condition of Leakage Check Valve 2RH-3-2 | 3/17/12 |
| 1187115 | 09 NRC Heavy Loads Inspection NEI 08-05 | 6/29/09 |
| 1124573 | NRC GL 2008-01 Gas Accumulation in ECCS and CS System | 1/22/10 |
| 1094176 | CDBI07 Non-Conservative Input in Calculations ENG-EE-147 | 5/25/07 |
| 1227545 | MS Piping Stress Exceeds Allowable – Snubbers Inactive | 4/16/10 |
| 1242456 | RHR Operability for ECCS While Aligned for Shutdown Cooling | 7/22/10 |
| 1145695 | CC Piping Adjacent to HELB Location in Turbine Building | 7/29/08 |
| 1245037 | Evaluate OE29631 Misapplication of ASME Class 1 Pressure | 8/10/10 |
| 1247608 | Evaluate OE31393 Misalignment of Charging Spring Motor | 8/30/10 |
| 1251545 | NRC IN 2012-20 Turbine Driven Auxiliary Feedwater Pump | 9/27/10 |
| 1061790 | FW Support Baseplate Anchor Bolt Stresses Higher Than Operability | 11/25/06 |
| 1090396 | Inadequate EDG Surveillance Test Procedures | 5/1/07 |
| 1249636 | Interaction Between FW and CC piping in the Aux Building | 9/14/10 |
| 1265193 | Potential NCV Cross-Cut Issue: Inadequate OE Eval | 1/5/11 |
| 1286638 | Missed Surveillances for 2SI-16-4, 2SI-16-6 due EC 13483 | 5/19/11 |
| 1321313 | On Rounds, Found SF-26-4 122 SFP Pump Discharge Valve Open | 1/18/12 |
| 1145695 | CC Piping Adjacent to HELB Location in Turbine Building | 7/29/08 |
| 1217275 | Flooding Affects on DDCLP FOST Xfer Pumps | 2/8/10 |
| 1300034 | Isolated Sump A Discharge Caused Unplanned LCO 3.0.3 Entry | 8/19/11 |
| 1242456 | RHR Operability for ECCS while Aligned for Shutdown Cooling | 7/22/10 |
| 1308222 | OE From Palisades Services Water Pump Coupling Failure | 10/13/11 |

CORRECTIVE ACTION DOCUMENTS REVIEWED DURING THE INSPECTION

| <u>Number</u> | <u>Description or Title</u> | <u>Date</u> |
|---------------|--|-------------|
| 1146005 | Mispositioned Block Valve on 11 TDAFWP | 7/31/08 |
| 1313953 | Did Not Obtain the Min Flow of 2555gpm Through CC-5-1 | 11/19/11 |
| 1344632 | Received Unexpected Annunciator, 47033-0309 Rad Monitor | 7/12/12 |
| 1175363 | 12 DD CLG Water Pump Missing Required NDE reports | 3/27/09 |
| 1209214 | Unit 1 MS Elbow not Modeled in Stress Analysis as Built | 12/3/09 |
| 1174370 | No Tornado Protection of CC Piping for 122 SFR-HX | 3/23/09 |
| 1233935 | Potential Common Mode Failure of Unit 2 Fuel Oil Transfer Pumps | 5/21/10 |
| 1178236 | No HELB Flooding Calculation for Turbine Building | 4/15/09 |
| 1236642 | Battery Room Door Bottom gaps not i.a.w HELB Flooding Evaluation | 6/9/10 |

EFFECTIVENESS REVIEWS

| <u>Number</u> | <u>Description or Title</u> | <u>Date</u> |
|---------------|---|-------------|
| 1265185 | As Found Test of Pressurizer Safety Valve Failed High | 1/5/11 |
| 1221390 | Confirmed Unanalyzed Condition Due to Postulated HELB | 3/5/10 |

PROCEDURES

| <u>Number</u> | <u>Description or Title</u> | <u>Revision</u> |
|---------------|--|-----------------|
| SWI NE-23 | Preparation and Implementation of Reactivity Plans | 11 |
| FP-OP-OL-01 | Operability/Functionality Determination | 1 |
| FP-PA-ARP-01 | CAP Action Request Process | 33 |
| FP-PA-SA-01 | Focused Self-Assessment Planning, Conduct and Reporting | 13 |
| FP-PA-SA-04 | Benchmarking Process | 6 |
| FP-WM-WOI-01 | Work Identification, Screening, Validation and Cancellation | 14 |
| PE 0007 | 5HK250/350 Breaker Testing Maintenance and Repair – Minor | 8 |
| FP-PA-OE-01 | Operating Experience Program | 16 |
| CP 0021 | Employee Concerns Program | 4 |
| FP-EC-ECP-01 | Employee Concerns Program | 6 |
| FP-PA-ARP-01 | CAP Action Request Process | 33 |
| FP-PA-RCE-01 | Root Cause Evaluation Manual | 0 |
| FP-PA-PAR-01 | Performance Assessment Review Board and Performance Assessment Oversight | 5 |
| FP-PA-ARP-03 | Non-Cap Action Request Process | 5 |
| FP-PA-ACE-01 | Apparent Cause Evaluation Manual | 0 |
| FP-OP-ODM-01 | Operational Decision Making | 4 |

ROOT CAUSE EVALUATIONS

| <u>Number</u> | <u>Description or Title</u> | <u>Date or Revision</u> |
|---------------|-----------------------------|-------------------------|
| | | |

ROOT CAUSE EVALUATIONS

| <u>Number</u> | <u>Description or Title</u> | <u>Date or Revision</u> |
|-----------------|--|-------------------------|
| 01326556, Rev 1 | Root Cause Evaluation: Eight Instances of Feedwater Heater Hi-Hi Level Alarms | 07/20/12 |
| 1333673 | Root Cause Evaluation: Potential SCCI in Human Performance Cross Cutting Area | 08/07/12 |
| 01332102 | Root Cause Evaluation: Adverse Trends Noted in Operator Fundamentals | 05/22/12 |
| 1085806 | Unit 1 Breaker 16-7 Inoperable | 0 |
| 1132717 | Organizational Issues Regarding Valve SI 9-5 | 0 |
| 1171797 | Adverse Assessment Finding: Maintenance and Test Equipment Programmatic Breakdown | 0 |
| 1255628 | Organizational Failure to Evaluate Changes to Integrated Safety Injection Test | 2 |
| 1306901 | Procedure/Equipment Issue Delaying Cooldown to Mode 5 | 0 |
| 1311302 | Managers and Supervisors do not Consistently Model and Reinforce Performance Standards | 0 |
| 1271699 | LER 1-09-06, Supplement 2 is Required to be Submitted | 0 |
| 1311686 | Adherence to Lifting and Rigging Requirements | 0 |
| 1316877 | Appendix R Concern with DC Power to Bus 27 | 0 |
| 1297439 | Conduct a RCE for NRC Battery Charger Installation Finding | 2 |
| 1284787 | Unit 2 Reactor Trip from Generator Lockout | 5/9/11 |
| 1266154 | QA Type 0 (non-Q)parts used for QA Type 1 (SR) Repair | 3 |

SELF-ASSESSMENT REPORTS AND AUDITS

| <u>Number</u> | <u>Description or Title</u> | <u>Date</u> |
|---------------|--|-------------|
| 2010-04-033 | NOS Audit of Maintenance Organization | 12/08/10 |
| 2011-02-037 | NOS Audit of Post Maintenance and Modification Testing | 05/27/11 |
| 2011-01-001 | NOS Audit of Measurement and Test Equipment Program | 01/04/11 |
| 2011-02-014 | NOS Audit of Maintenance, Planning and Scheduling Organization | 06/13/11 |
| 2011-03-025 | NOS Audit of Maintenance Organization | 09/12/11 |
| 2012-01-004 | NOS Audit of Measuring and Test Equipment | 01/03/12 |
| 1310775 | Focused Self-Assessment of CAP | 1/6/12 |
| | Site Department Roll-Up Report | 4Q2011 |
| 12596904 | Performance Assessment Excellence | 3/18/11 |
| 1262070 | Conduct SnapShot Evaluation of Employee Concerns Program | 12/8/10 |
| 1288937 | Adverse Trend Regarding Procedure Use and Adherence | 6/2/11 |
| | Nuclear Oversight Fourth Quarter 2011 Assessment Report for Prairie Island | 2/10/12 |
| 1292477 | 2011 50.59/ Modification Snapshot Self Assessment | 8/30/11 |

MISCELLANEOUS DOCUMENTS

| <u>Number</u> | <u>Description or Title</u> | <u>Date or Revision</u> |
|----------------------|--|--------------------------------|
| | 2010 USA Nuclear Safety Culture Assessment Response | |
| | Fourth Quarter 2011 Safety Culture Principles Assessment | |
| | Prairie Island MSRC Organizational Excellence Subcommittee Meeting Minutes | 4/30/12 |
| | CC/HELB Extent of Condition Walkdown Report | 10/27/10 |
| | Engineering Excellence Plan | 6/6/12 |
| | Engineering Department DRUM Report | 7/31/12 |
| | PRA Self Assessment | 0 |

J. Sorensen

-2-

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter, its enclosure, and your response (if any), will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records System (PARS) component of NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

Sincerely,

/RA/

Kenneth Riemer, Chief
Branch 2
Division of Reactor Projects

Docket Nos. 50-282, 50-306, and 72-010
License Nos. DPR-42, DPR-60, and SNM-2506

Enclosure: Inspection Report 05000282/2012007; 05000306/2012007
w/Attachment: Supplemental Information

cc w/encl: Distribution via ListServ

DISTRIBUTION:
See next page

DOCUMENT NAME: PRA\PRA 2012 007 PI&R.docx

Publicly Available Non-Publicly Available Sensitive Non-Sensitive

To receive a copy of this document, indicate in the concurrence box "C" = Copy without attach/encl "E" = Copy with attach/encl "N" = No copy

| | | | | | | | |
|--------|--------------|--|----------|--|--|--|--|
| OFFICE | RIII | | RIII | | | | |
| NAME | NShah:ntp/rj | | KRiemer | | | | |
| DATE | 09/25/12 | | 09/25/12 | | | | |

OFFICIAL RECORD COPY

Letter to J. Sorensen from K. Riemer dated September 25, 2012

SUBJECT: PRAIRIE ISLAND NUCLEAR GENERATING PLANT, UNITS 1 AND 2;
NRC BIENNIAL PROBLEM IDENTIFICATION AND RESOLUTION
INSPECTION REPORT 05000282/2012007; 05000306/2012007

DISTRIBUTION:

Silas Kennedy
RidsNrrPMPrairieIsland Resource
RidsNrrDorLpl3-1 Resource
RidsNrrDirslrib Resource
Chuck Casto
Cynthia Pederson
Steven Orth
Jared Heck
Allan Barker
Christine Lipa
Carole Ariano
Linda Linn
DRPIII
DRSIII
Patricia Buckley
Tammy Tomczak
ROPAssessment.Resource@nrc.gov