

Official Transcript of Proceedings  
NUCLEAR REGULATORY COMMISSION

Title: Advisory Committee on Reactor Safeguards  
Plant License Renewal Subcommittee

Docket Number: (n/a)

Location: Rockville, Maryland

Date: Wednesday, September 19, 2012

Work Order No.: NRC-1898

Pages 1-211

**NEAL R. GROSS AND CO., INC.**  
**Court Reporters and Transcribers**  
**1323 Rhode Island Avenue, N.W.**  
**Washington, D.C. 20005**  
**(202) 234-4433**

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25

UNITED STATES OF AMERICA

NUCLEAR REGULATORY COMMISSION

+ + + + +

ADVISORY COMMITTEE ON REACTOR SAFEGUARDS

(ACRS)

+ + + + +

PLANT LICENSE RENEWAL SUBCOMMITTEE

+ + + + +

WEDNESDAY

SEPTEMBER 19, 2012

+ + + + +

ROCKVILLE, MARYLAND

+ + + + +

The Subcommittee met at the Nuclear  
Regulatory Commission, Two White Flint North, Room  
T2B1, 11545 Rockville Pike, at 8:30 a.m., John D.  
Sieber, Chairman, presiding.

COMMITTEE MEMBERS:

JOHN D. SIEBER, Chairman

J. SAM ARMIJO

HAROLD B. RAY

WILLIAM J. SHACK

GORDON R. SKILLMAN

JOHN W. STETKAR

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1  
2  
3  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15  
16  
17  
18  
19  
20  
21  
22  
23  
24  
25

CONSULTANT TO THE SUBCOMMITTEE:

JOHN J. BARTON

NRC STAFF PRESENT:

KENT HOWARD, Designated Federal Official

BART FU

MELANIE GALLOWAY

BRIAN HARRIS

ALLEN HISER

BILL HOLSTON

BENNY JOSE

JOHN LUBINSKI

JEFF POEHLER

ANN MARIE STONE

ALSO PRESENT:

BARRY ALLEN

RICHARD BAIR

DENNIS BLAKELY

JOE BRUNKHORST

KEN BYRD

DAVID CHEW

CHONG CHIU

1 CLIFF CUSTER  
2 ALVIN DAWSON  
3 STEVE DORT  
4 TRENT HENLINE  
5 LARRY HINKLE  
6 JAKE HOFELICH  
7 JON HOOK  
8 ERIC JOHNSON  
9 DON KOSLOFF  
10 ALLEN McALLISTER  
11 MARK RINCKEL  
12 FRANK ZURVALEC  
13

1	T-A-B-L-E O-F C-O-N-T-E-N-T-S	
2	Opening Remarks, Jack Sieber.....	5
3	Staff Introduction, John Lubinski.....	7
4	FirstEnergy Nuclear Operating Company (FENOC) -	
5	Davis-Besse Nuclear Power Station (Davis-Besse)	
6	Introduction	
7	Ken Byrd.....	10
8	Presentation	
9	Cliff Custer.....	12
10	Ken Byrd.....	16
11	NRC Staff Presentation SER Overview	
12	Introduction	
13	John Lubinski.....	158
14	Presentation	
15	Brian Harris.....	159
16	Benny Jose.....	161
17	Ann Marie Stone.....	166
18	Brian Harris.....	175
19	Bill Holston.....	189
20	Bryce Lehman.....	191
21	Adjournment.....	211
22		
23		
24		
25		

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

P-R-O-C-E-E-D-I-N-G-S

8:28 a.m.

CHAIRMAN SIEBER: Good morning. The meeting will now come to order. This is a meeting of the Davis-Besse Nuclear Power Station Plant License Renewal Subcommittee.

My name is Jack Sieber and I'm Chairman of the Davis-Besse Plant License Renewal Subcommittee. ACRS members in attendance are Bill Shack, John Stetkar, Sam Armijo, Harold Ray and Gordon Skillman. Also with us today is John Barton, who is a consultant to the ACRS.

Kent Howard of the ACRS staff is the Designated Federal Official for this meeting.

The Subcommittee today will review the license renewal application for Davis-Besse Nuclear Power Station and the associated staff Safety Evaluation Report with open items. I note that the current draft of the SER contains four open items which must be satisfactorily resolved prior to the hearing of this application by the full ACRS Committee which is currently scheduled for next March. These open items relate to containment, concrete cracking issues, use of operating experience to update the tests and examinations that the licensee will perform during the renewal period, and reactor vessel integrity issues.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 Today's agenda contains time also to discuss these  
2 issues.

3 We will hear presentations from FirstEnergy  
4 Nuclear Operating Company representatives, the NRC  
5 staff, and other interested persons regarding this  
6 matter.

7 We have not received written comments and  
8 requests for time to make oral statements from members  
9 of the public regarding today's meeting.

10 The entire meeting will be open to public  
11 attendance.

12 The Subcommittee will gather information,  
13 analyze relevant issues and facts, and formulate  
14 proposed positions and actions as appropriate for  
15 deliberation by the full Committee.

16 The rules for participation in today's  
17 meeting have been announced as part of the notice of  
18 this meeting previously published in the Federal  
19 Register.

20 A transcript of this meeting is being kept  
21 and will be made available as stated in the Federal  
22 Register notice, therefore, I request that participants  
23 in this meeting use the microphones located throughout  
24 the meeting room when addressing the Subcommittee. The  
25 participants are requested to please identify

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 themselves and speak with sufficient clarity and volume  
2 so that they may be readily heard.

3 We will now proceed with the meeting, and  
4 I call upon John Lubinski of the NRC staff to begin the  
5 presentation. John?

6 MR. LUBINSKI: Thank you, Jack. As  
7 stated, I'm John Lubinski. I'm the director of the  
8 Division of License Renewal. I started in this position  
9 last Monday. I have been with NRC for 22 years and most  
10 recently was the deputy division director of our  
11 Division of Inspection and Regional Support at NRR.

12 As stated, this is our ACRS Subcommittee  
13 meeting on Davis-Besse license renewal application.  
14 When the application was received, we initially  
15 established a 22-month schedule. That was to  
16 accommodate the concurrent review of the license renewal  
17 application with plant outages and the ability to  
18 support on-site audits.

19 Since that time we have modified the  
20 scheduled twice. The first item was in December of 2011  
21 where the schedule was moved out two months. And this  
22 was due to delay in responses to RAIs, as well as a large  
23 number of follow-up items and RAIs. The second time  
24 was in March of this year where the schedule was delayed  
25 by another four months. And this was to resolve at that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 time 11 open items.

2 Since that time we have reached resolution  
3 on 7 of those 11 items, but there are 4 open items still  
4 in the application and the SER that was provided on July  
5 30th of 2012. As stated, those four items are: The  
6 shield building cracking, which we did allow extra time  
7 in today's meeting for discussion; operating  
8 experience, which is an item that the ACRS Subcommittee  
9 and full Committee has seen previously in Limerick and  
10 Columbia applications; and then the vessel integrity  
11 issues related to pressure-temperature limits, as well  
12 as the upper shelf energy. These four open items will  
13 be the focus of the staff's discussion this afternoon.

14  
15 This morning I'd like to introduce members  
16 of our management team in DLR that are here today. To  
17 my right is Melanie Galloway, the deputy director of  
18 the Division of License Renewal. We also have several  
19 branch chiefs in the division; Dennis Morey, Bo Pham,  
20 Mike Marshall, and Raj Auluck. We also have the branch  
21 chief from our Region III office, Ann Marie Stone.

22 When the staff does its presentation this  
23 afternoon, I will introduce the specific members that  
24 will be providing comments. We also have a large number  
25 of our staff here in the audience today that can step

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 to the microphone and answer comments.

2 At this time what I'd like to do is turn  
3 the presentation over to FENOC, and specifically Barry  
4 Allen to introduce his folks.

5 MR. ALLEN: Thank you very much. Good  
6 morning, Mr. Chairman and Committee Members. We're  
7 very happy to be here this morning and we're looking  
8 forward to just good discussion, healthy dialogue on  
9 our license renewal application. We will provide you  
10 a little bit of background information on Davis-Besse  
11 for those of you who may not have been there before.

12 We'll provide an overview of our application and our  
13 process that we've gone through. And as far as the four  
14 Safety Evaluation Report open items, we have plenty of  
15 information. Plan on having a good dialogue on that,  
16 healthy discussion and a fairly long discussion on the  
17 shield building laminar cracking to ensure that this  
18 Committee has a good full understanding of that issue  
19 as we do.

20 As I said, I'm Barry Allen and I'll let my  
21 team up here with me introduce themselves.

22 MR. BYRD: I'm Ken Byrd, the director of  
23 engineering at Davis-Besse.

24 MR. CUSTER: My name is Cliff Custer. I'm  
25 the project manager for FENOC license renewal.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. DORT: My name is Steven Dort. I'm a  
2 license renewal project lead.

3 MR. ALLEN: We're looking forward to a very  
4 healthy dialogue today and we're looking forward to  
5 entertaining your questions and satisfying your needs.  
6 And with that, I'll turn the presentation over to Mr.  
7 Byrd.

8 MR. BYRD: All right. I'm going to start  
9 out with a brief introduction of Davis-Besse. If you  
10 can go to the next slide, please. So the Davis-Besse  
11 site, we are located on the southwestern shore of Lake  
12 Erie. We're in Ottawa County, Ohio. It's a 954-acre  
13 site, and of that site 221 acres are for the plant  
14 structures and equipment and the rest of the site is  
15 a wildlife refuge.

16 So next slide, please. So a very quick  
17 background on our plant. Davis-Besse is a pressurized  
18 water reactor. We're a Babcock & Wilcox raised-loop  
19 design, 2817 megawatts thermal. And we did do a  
20 measurement uncertainly recapture power up rate in July  
21 of 2008, and that was a 1.6 percent upgrade.  
22 Our license is currently -- would expire on April 22nd,  
23 2017. And as of today the plant's at 100 percent power  
24 and we've been on the line for 98 days. That's following  
25 our 17th refueling outage.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 Next slide, please. So we have had -- at  
2 Davis-Besse we've had two outages in the last 12 months.

3 We did have a mid-cycle outage which we conducted last  
4 October, and that was in order to replace the reactor  
5 vessel head. Then we had a refueling outage this  
6 spring. And in those two outages we made a number of  
7 upgrades and did a number of inspections, and I'm going  
8 to very briefly review some of the things we did to  
9 improve the plant over those two outages.

10 Obviously, we replaced the reactor vessel  
11 head, and that was the reason we shut down back in October  
12 for the mid-cycle outage. We replaced selected power  
13 cables during both of these outages. We replaced  
14 selected service water piping as part of our ongoing  
15 program to replaced service water piping. We replaced  
16 both emergency diesel generator exhaust pipes. We did  
17 some upgrades to prepare for our steam generator  
18 replacement, which will be coming up in 2014 in our 18th  
19 refueling outage. We upgraded the polar crane and we  
20 installed a Palfinger crane. And we also did our  
21 in-service inspection for the reactor vessel removal  
22 core support with no unacceptable limitations. And we  
23 performed an integrated leak rate test of the  
24 containment.

25 So at this point, I'm going to turn it over

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 to Cliff Custer to provide an overview of the license  
2 renewal.

3 MR. CUSTER: Thank you, Ken. The  
4 application was developed with the FENOC core team  
5 that's been involved in working on license renewals  
6 since 2006. Davis-Besse program owners and subject  
7 matter experts were involved in the development of the  
8 application and the audit and inspection interviews,  
9 NRC staff calls, RAI responses, and commitment  
10 development. In addition AREVA supported us in  
11 development of the application. During the time of the  
12 development of the application we participated in NEI  
13 working groups and industry peer reviews.

14 Next slide. The application was submitted  
15 in August of 2010. It was developed using GALL Rev 1  
16 standards, which were the standards at the time. There  
17 are 43 aging management programs. Twelve are new, four  
18 plant-specific. Thirty-one are existing, four are  
19 plant-specific. The 49 license renewal commitments and  
20 those commitments are included in the USAR Supplement,  
21 which is Appendix A of the LRA.

22 MEMBER SHACK: And when your license  
23 renewal application came in, you had 25 commitments.

24 MR. CUSTER: That's correct, and it jumped  
25 to 49, which is a large increment.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MEMBER SHACK: Is that -- what's the -- why  
2 do you attribute that large number of changes in  
3 commitments? I mean, was something incomplete about  
4 the original application?

5 MR. CUSTER: The application, as I said,  
6 was originally submitted to GALL Rev 1. GALL Rev 2  
7 changes a lot of the additional specifics. A lot of  
8 our RAI responses in fact were formulated based on GALL  
9 Rev 2. A lot of those commitments came from that.

10 CHAIRMAN SIEBER: Would you conclude that  
11 you now comply with all Rev 2, or are there exceptions?

12 MR. CUSTER: I would say that there are some  
13 exceptions. There are -- we have eight programs with  
14 exceptions. And I think the regulator this afternoon  
15 will talk about he selectively reviewed application to  
16 GALL Rev 2 during the audits and inspections.

17 CHAIRMAN SIEBER: Yes, will you present  
18 want the character of those exceptions are today to us?

19 MR. CUSTER: I had not intended to. We  
20 could respond to some of those questions as they come  
21 through.

22 CHAIRMAN SIEBER: Okay.

23 MR. CUSTER: Yes.

24 CHAIRMAN SIEBER: Okay. So we'll see when  
25 the time comes.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. CUSTER: Okay.

2 CHAIRMAN SIEBER: Thank you.

3 MR. CUSTER: Our commitments will be  
4 managed by the FENOC commitment tracking program.

5 Next slide. On this slide are listed the  
6 audits and the inspections that were conducted. Our  
7 RAIs and responses addressed the differences primarily  
8 between GALL Rev 1 and GALL Rev 2, as I said. Our Safety  
9 Evaluation Report with open items was issued on July  
10 31st of this year.

11 Next slide. Our SER open items. As we  
12 said, we have four SER open items. Reactor vessel  
13 neutron embrittlement is one. Pressure-temperature  
14 limits is another. The use of operating experience and  
15 management of the shield building is the final one.

16 Next slide. With respect to neutron  
17 embrittlement, the reactor vessel upper-shelf energy  
18 evaluation, originally we chose a mean value of 70  
19 foot-pounds in projection to the 52 effective full power  
20 years upper-shelf energy. Based on questions from the  
21 staff, we later chose to use equivalent margins analysis  
22 to qualify our upper-shelf energy selections.

23 Next slide. The equivalent margin  
24 analysis is as listed. And we provided the response  
25 to the nozzle belt forging on June 14th. The

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 upper-shelf forging was addressed in the LRA. The  
2 nozzle belt forging to the upper shelf circumferential  
3 weld and lower shelf forging to the Dutchman forging  
4 were just submitted September 14th. Those items are  
5 under review by the staff.

6 With respect to pressurizer-temperature  
7 limits, the staff had questions on the methodology used  
8 to establish pressurizer-temperature limits. Appendix  
9 G requires pressurizer-temperature limits to include  
10 all ferritic materials of the boundary, include  
11 discontinuities and nozzles, and evaluate non-beltline  
12 components which may have  $RT_{NDT}$  values that define a more  
13 restrictive lowest operating temperature.

14 Next slide. In our response we reviewed  
15 and provided our limits in accordance with 10 C.F.R.  
16 Appendix G, Reg Guide 1.99 Rev 2, using the methods in  
17 the approved topical report BAW-10046A.

18 And the bottom line is really on the next  
19 slide, Steve, that the reactor vessel closure head  
20 outlet nozzles and beltline region are the controlling  
21 regulations that regulate the P-T limits. Our response  
22 has been submitted and is under review by the staff.

23 With respect to operating experience, the  
24 Interim Staff Guidance LR-ISG-2011-05 was issued in  
25 March to address age-related degradation and aging

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 management programs, inform and enhance programs. We  
2 reviewed the ISG, and our response brings us in  
3 compliance. Our changes will be flag aging-related OE,  
4 consideration of material, environment and aging  
5 mechanisms. We will revise our OE and corrective action  
6 programs to provide feedback to aging management program  
7 owners, identify training needs. Those responses have  
8 been submitted and we will be in alignment with the ISG.

9 At this point in time our commitment is by the end of  
10 the year.

11 Next slide.

12 MR. BYRD: Okay. I'll be providing the  
13 discussion on the open item B.2.34 for the shield  
14 building. So what I'm going to do for this open item,  
15 first I'll briefly walk through the function and design  
16 of the shield building, talk about how we discovered  
17 laminar cracking, review the investigation of the  
18 cracking, describe how we went about doing the root  
19 cause, corrective actions and then discuss the aging  
20 management program that we've put in place.

21 MEMBER STETKAR: Ken, can I interrupt you  
22 just for a second? I want to ask Jack something.

23 In terms of organizing the meeting, do you  
24 want to go through all of the shield building first?

25 I have questions on other issues that they're not going

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 to present in their formal slides here. You want to  
2 get those out of the way first, or you want to go through  
3 the shield building and then catch up on those after  
4 the shield building?

5 CHAIRMAN SIEBER: I would prefer to discuss  
6 the shield building now.

7 MEMBER STETKAR: Okay.

8 CHAIRMAN SIEBER: Because I think it's  
9 going to take the longest --

10 MEMBER STETKAR: Yes, that's --

11 CHAIRMAN SIEBER: -- amount of time.

12 And --

13 MEMBER STETKAR: We have all -- I'm sure  
14 John has some also, so --

15 CHAIRMAN SIEBER: -- there are still  
16 significant questions. Okay. Just keep your  
17 questions noted.

18 MEMBER STETKAR: Don't worry. I have --

19 CHAIRMAN SIEBER: Oh, that whole book?

20 MEMBER STETKAR: I have notes.

21 CHAIRMAN SIEBER: Okay.

22 MR. BYRD: Okay. Go to the next slide,  
23 please. Okay. What this slide is intended to show is  
24 the shield building, the annulus and the containment  
25 vessel. And the important thing I wanted to -- point

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 I wanted to make here is our shield building at  
2 Davis-Besse is a freestanding concrete structure. We  
3 have a separate containment vessel that's shown in this  
4 slide. The containment vessel is an inch-and-a-half  
5 thick steel, and the function of the containment vessel  
6 is to be able to withstand the pressure for the largest  
7 postulated break we would have in the reactor coolant  
8 system. We have a four-and-a-half-foot annulus between  
9 the containment vessel and the shield building.

10 Go to the next slide, please.

11 MEMBER SHACK: While you're here, could you  
12 just show me the geometry of the sand pocket?

13 MR. BYRD: Yes, the sand pocket would be  
14 located in this area between the shield building and  
15 the containment vessel. So it's down in this location  
16 here.

17 MEMBER SHACK: And how big is it?

18 MR. BYRD: Well, the annulus itself is  
19 approximately four-and-a-half feet across.

20 MEMBER SHACK: And the sand pocket goes  
21 down how far?

22 MEMBER STETKAR: Ken, you have to speak  
23 into the microphone.

24 MEMBER SHACK: You have to be a little bit  
25 closer to the microphone.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BYRD: I'm sorry. The annulus is  
2 four-and-a-half feet, and so the sand pocket would  
3 encompass that. As far as the depth of the sand pocket,  
4 maybe Mr. Hook could help me with that. Jon Hook, our  
5 design engineer and manager.

6 MR. HOOK: Right, I'm Jon Hook, design  
7 engineer and manager. So the sand pocket region is  
8 approximately -- tapered. At the top it is  
9 approximately 15 inches wide and at the bottom it's about  
10 nine inches wide. It's about four feet deep.

11 The sand pocket, I just want to clarify, we call  
12 it the sand pocket because at one time there was sand  
13 in it, but the sand has been removed. But we still call  
14 it the sand pocket area.

15 CHAIRMAN SIEBER: Have you found  
16 accumulations of water in the annular space between the  
17 building and the containment vessel?

18 MR. BYRD: We have. John, you want to  
19 continue with answering that question, please?

20 MR. HOOK: Can you repeat that question for  
21 me, please?

22 CHAIRMAN SIEBER: Have you found  
23 accumulations of water between the shield building  
24 structure and the containment vessel?

25 MR. HOOK: Yes, there is some minor seepage

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 coming up in that area. We've been monitoring that.  
2 We look at it every refueling outage.

3 CHAIRMAN SIEBER: And is it enough water  
4 so that the containment vessel is wetted most of the  
5 time?

6 MR. HOOK: That access is -- that area is  
7 only accessed to us during the refueling outage. So  
8 we do take that opportunity at that time to go in and  
9 inspect that area. And it is wetted, but the slope is  
10 such that the water is -- flows away from the shield  
11 building. So normally there's not water progressing  
12 up against the metal.

13 DR. BARTON: Yes, but at one time there was,  
14 right? Don't you have some corrosion down there?

15 MR. HOOK: Right, there is some minor  
16 discoloration and corrosion down there.

17 DR. BARTON: What is minor? Have you done  
18 UTs or anything like that?

19 MR. HOOK: We did extensive investigation  
20 in 2002. We did UT readings back then and all the UT  
21 readings were greater than the minimum thickness  
22 required. And we've done -- like I said, we've done  
23 inspections every refueling outage and there's no  
24 significant change from 2002.

25 CHAIRMAN SIEBER: Well, since there's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 access to the containment, the steel containment vessel  
2 at the bottom, is there concrete or any kind of  
3 obstruction in that area that would prevent you from  
4 getting thickness measurements throughout the bottom  
5 of the containment vessel?

6 MR. HOOK: Right, so when you look on the  
7 drawing there, the bottom portion of the containment  
8 vessel is encased in concrete on the top and on the bottom  
9 of it.

10 CHAIRMAN SIEBER: And so how do you get  
11 thickness measurements and defected --

12 MR. HOOK: Right, so --

13 CHAIRMAN SIEBER: -- limitations through  
14 the concrete.

15 MR. HOOK: In 2002 we did UT readings down  
16 at the sand pocket area.

17 CHAIRMAN SIEBER: Okay.

18 MR. HOOK: Those were the exposed shield  
19 -- the exposed areas. We didn't do any excavation in  
20 that area.

21 CHAIRMAN SIEBER: Okay. So you went down  
22 from the four-foot space between the shield building  
23 and the containment vessel, and around that curve made  
24 measurements basically perpendicular to the lower  
25 surface of the containment vessel?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. HOOK: The areas that are inaccessible  
2 due to concrete up against it we did not get UT readings.

3 But from the outside at the bottom of the sand pit we  
4 could take UT readings. We had access to that area in  
5 the sand pocket region.

6 MEMBER ARMIJO: It's my understanding  
7 you're going to do some boring in the future --

8 MR. BYRD: That's correct.

9 MEMBER ARMIJO: -- to look for corrosion  
10 of the containment vessel due to borated water seepage.

11 MR. BYRD: We have a commitment; that's  
12 correct, to do a core bore, and that would be from the  
13 inside down to the containment vessel. And so it'll  
14 be from in here up to the --

15 MEMBER SHACK: It's at that little step,  
16 the thinnest part there?

17 MR. BYRD: It would be -- I'm not sure  
18 exactly. This is obviously --

19 MEMBER SHACK: Can't see where you're  
20 pointing.

21 MR. BYRD: It would be in this region.  
22 We'd be coming from down underneath the reactor going  
23 down to the --

24 MEMBER STETKAR: Maybe you could use the  
25 mouse? Yes, so everybody can see.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BYRD: So we'd be taking a core bore  
2 from the region below the reactor vessel and going down  
3 to access the containment vessel. So the core bore would  
4 be going down through the concrete. And that's -- we  
5 have that, and we're committed to performing that prior  
6 to the 18th refueling outage in 2014.

7 MEMBER STETKAR: But that won't be at the  
8 low point of the containment vessel.

9 MR. BYRD: That would be --

10 MEMBER STETKAR: That's about 30 inches  
11 above the --

12 MR. BYRD: No, I'm not sure if it is. Maybe  
13 -- it says 30 inches.

14 MEMBER STETKAR: Well, it is 30 inches.

15 MR. BYRD: I think we have -- Dick Bair can  
16 answer that.

17 MR. BAIR: My name's Richard Bair. Work  
18 in design engineering. Our plan is in the 18th  
19 refueling outages to install the core bore through the  
20 concrete in the under-vessel area to access the inside  
21 base of the containment vessel for inspection for  
22 potential boric acid effects. It will not be through  
23 the -- necessarily through the lowest portion. The  
24 least amount of concrete between the vessel that we can  
25 go through is our containment sump that has a stainless

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 steel liner. We don't wish to perforate that, nor put  
2 in this core drill. So we're going to be somewhat off  
3 from that area going through approximately two feet of  
4 concrete to access the inside face of the vessel for  
5 inspection.

6 CHAIRMAN SIEBER: Now you have a history  
7 of leaks that the reactor vessel had at the attachments  
8 through the control rod drive mechanisms. Do you have  
9 evidence on the concrete basemat of the containment that  
10 borated water was able to leak down to that level in  
11 the containment?

12 MR. BYRD: I'm not -- do we have a -- Mr.  
13 Hook?

14 MR. HOOK: So we do do inspections in that  
15 area and the leakage through the refueling canal, when  
16 we have the refueling canal filled, it's relatively  
17 minor. We do inspections and we have found no  
18 deterioration at all in the concrete area.

19 CHAIRMAN SIEBER: Did you find evidence of  
20 boric acid deposits there?

21 MR. HOOK: We have evidence of boric acid  
22 deposits on the concrete. There's a few cracks where  
23 it has come up.

24 MR. CHEW: My name is David Chew. I'm the  
25 refueling canal system engineer and also a boric acid

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inspector.

2           What we've done is in past outages, or in  
3 -- and in current outages now we do documented boric  
4 acid inspections. When we go into containment when we  
5 first start a refueling outage we do an as-found  
6 inspection, take pictures, document that it in an  
7 inspection report. We take -- when the canal is filled  
8 after a few days, we go back in, do another as-found  
9 inspection, do pictures and an inspection report.

10           Then when it is drained, we go in and decon  
11 the area, clean it up and then do an as-left inspection,  
12 take those pictures, document that. And then the next  
13 outage when we come back, we do our initial as-found.

14           The pictures are compared, the documents are compared  
15 to see if there's any changes. And in the past several  
16 outages we haven't seen any changes, any further  
17 degradation.

18           CHAIRMAN SIEBER: When was the -- when did  
19 you last perform the integrated containment leak rate  
20 test?

21           MR. BYRD: We performed an integrated  
22 containment leak rate test during our last refueling  
23 outage.

24           CHAIRMAN SIEBER: And what was your initial  
25 result? Did you have to repair anything?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. BYRD: Actually 2011 it was.

2 MR. ALLEN: It was 2011. It was the  
3 mid-cycle outage. I'm sorry, the mid-cycle outage was  
4 -- the mid-replacement outage.

5 CHAIRMAN SIEBER: Were you required to  
6 repair anything to meet the requirements of that test?

7 MR. BYRD: Mr. Henline, Trent Henline, our  
8 program supervisor can provide some more information  
9 on that.

10 MR. HENLINE: My name's Trent Henline,  
11 engineering program supervisor. And we provided our  
12 integrated leak rate test during the 17th mid-cycle in  
13 November of 2011. And we passed that test on the initial  
14 attempt with an approximately 80 percent margin. We  
15 did not have to repair anything.

16 CHAIRMAN SIEBER: Okay. Thank you.

17 MEMBER STETKAR: Jack, I want to ask a  
18 couple of questions, as long as you brought it up, on  
19 the containment shell.

20 The water that you found in the annulus is  
21 groundwater, is that correct?

22 MR. BYRD: That's correct.

23 MEMBER STETKAR: And you've got a fairly  
24 aggressive groundwater chemistry at the site, as I  
25 understand it.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. BYRD: That's correct.

2 MEMBER STETKAR: I understand you've  
3 inspected the parts of the shell that you can access  
4 right at the interface there. What confidence do you  
5 have that groundwater has not migrated to the bottom  
6 part of that area and initiated corrosion from the  
7 exterior part of the shell in an area -- what's the  
8 surface area at the bottom of the containment shell that  
9 you won't be able to access during that single core bore  
10 from the interior? In other words, there's a big dish  
11 there that water could be collected for some period of  
12 time that you have no evidence of the status of the shell  
13 in that area.

14 MR. BYRD: You're asking about water that  
15 would be migrating from the sand pocket region --

16 MEMBER STETKAR: That's correct.

17 MR. BYRD: -- through the concrete?

18 MEMBER STETKAR: Well, or through -- it's  
19 not air-tight. Through the gap between the concrete  
20 and the shell.

21 MR. BYRD: Okay. I understand. I'll have  
22 -- Jon Hook can address that issue.

23 MR. HOOK: Right. I'm Jon Hook, design  
24 engineer and manager. I think your question is related  
25 to corrosion on the underside of the containment vessel.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER STETKAR: That's exactly right.

2 MR. HOOK: Right. So there is groundwater  
3 infiltration. The foundation that we have underneath  
4 there is a waterproof membrane, but obviously there's  
5 either a tear or a rip in that. We've got water migrating  
6 in that area. Again, we monitor that area. In the sand  
7 pocket we take samples of the water every refueling  
8 outage, and based on the samples of the water that we  
9 have, we have very low iron content in there. The  
10 concrete is a very high pH area and it's very passive  
11 -- passivates any corrosion in that area. So based upon  
12 that, we -- there is very little if any corrosion in  
13 the inaccessible areas of the containment vessel.

14 MEMBER STETKAR: Well, you have drains in  
15 that area.

16 MR. HOOK: We have two drains in the sand  
17 pocket area, that is correct.

18 MEMBER STETKAR: How do you keep water out  
19 from the bottom? I'm not very well versed in --

20 MR. HOOK: Right, so there is --

21 MEMBER STETKAR: I'm an engineer. The  
22 bottom point of the --

23 MR. HOOK: There is a potential that we'll  
24 have water between the concrete foundation and the  
25 underside of the containment vessel.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MEMBER STETKAR: Right.

2 MR. HOOK: Right. And then water would be  
3 there and it migrates up through the interface between  
4 the containment vessel to the sand pocket area.

5 MEMBER STETKAR: Yes.

6 MR. HOOK: But again, that's exposed to the  
7 concrete that's there. Concrete is very passive to  
8 corrosion. There's very little if any oxygen in that  
9 area, so based upon the passive nature of the concrete,  
10 low oxygen content and monitoring the water in the sand  
11 pocket area, we have high confidence there is no  
12 corrosion going on in the vessel.

13 MEMBER STETKAR: That's presuming the  
14 water comes in from the low point and fills the entire  
15 volume. Is that right? I mean, if the water's coming  
16 in and flowing down, sampling the water in the sand  
17 pocket gives you absolutely no indication of possible  
18 corrosion products collected at the bottom.

19 MR. HOOK: Right, the water is coming up  
20 between the containment vessel on the underside and  
21 migrating up --

22 MEMBER STETKAR: Ah.

23 MR. HOOK: -- sand pocket area.

24 MEMBER STETKAR: Okay. And you know that?

25 MR. HOOK: We know that. That is for sure.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Again, we go in there every refueling outage, or every  
2 time we have an outage and then -- to verify that. The  
3 sand pocket --

4 MEMBER SHACK: Seems that you've left all  
5 the chlorides down somewhere in the -- all the -- the  
6 chlorides come in somewhere. There's a conservation  
7 of chloride going on somewhere here.

8 MR. HOOK: That is correct. We have high  
9 chlorides in that area.

10 MEMBER SHACK: Well, that's not a good  
11 thing.

12 MEMBER STETKAR: And from what you're  
13 saying, that must be continuously wetted then.

14 MR. HOOK: There are some regions  
15 -- there's five small areas that have some seepage in  
16 that area. So the far majority of that area is dry.

17 MEMBER STETKAR: Now that's where you see  
18 -- I'll use the term --

19 MR. HOOK: Migrating to the top.

20 MEMBER STETKAR: -- migrating to the  
21 -- thank you -- migrating to the -- I was going to use  
22 the term bubbling up, but migrating to the top. But  
23 what confidence do you have that the vast majority of  
24 the lower portion of that shell is not continuously  
25 wetted? Just because you see it in five locations

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 doesn't necessarily mean that that's -- you know, that  
2 there are little rivulets coming up or something.

3 MR. HOOK: So there is a potential that a  
4 large area could be in contact with the water. But  
5 again, that large area is in contact with the concrete  
6 with a high pH. Very, very low oxygen content in that  
7 area. So based upon those items, corrosion's not taking  
8 place.

9 MEMBER SHACK: Those are good things, but  
10 then the high chloride's --

11 MEMBER STETKAR: Doesn't make you feel  
12 good.

13 MEMBER SHACK: -- not a good point.

14 MR. HOOK: Right, so there is chlorides in  
15 the groundwater. So --

16 MEMBER SHACK: It is apparently collecting  
17 since you're not seeing it in the stuff that's coming  
18 up. You told me that was low chloride. Un-aggressive,  
19 right?

20 MR. HOOK: There is chlorides in the water  
21 that we have sampled. And as the water comes up, there  
22 could be some evaporation and then concentration of the  
23 water that's in there. So the part that we see and we  
24 tested could be a concentrated area.

25 DR. BARTON: Where are these drains, these

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 -- you said five drains or something? Where are they  
2 located?

3 MR. HOOK: No, there's two drains.

4 DR. BARTON: Pardon?

5 MR. HOOK: There's two drains --

6 DR. BARTON: Where are they located and how  
7 big are they?

8 MR. HOOK: I think they're four-inch drains  
9 and they are located approximately on each side of the  
10 fuel transfer tube area.

11 DR. BARTON: In what amount?

12 MR. HOOK: And the sand pocket area is  
13 sloped to the floor drains.

14 DR. BARTON: Now can you get access through  
15 the drain lines with a boroscope or something and get  
16 down there and see what you got on the bottom?

17 MR. HOOK: The floor drains are accessible.  
18 They're on the bottom of the sand pocket.

19 MEMBER STETKAR: But they're just normal.  
20 I mean, it's a big annulus so there are just floor drains  
21 in there to collect leakage from pipes that come through  
22 and -- they're just floor drains.

23 DR. BARTON: Well, I'm just looking at  
24 access to the bottom of the --

25 MEMBER STETKAR: Yes, but they'll just go

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 out. It hits the interface and that's it, yes. All  
2 right.

3 CHAIRMAN SIEBER: It has to go to a sump.

4 MEMBER STETKAR: Yes, they'll go out --

5 CHAIRMAN SIEBER: It's all underground.

6 MEMBER STETKAR: Yes, they'll go to a floor  
7 drain.

8 MEMBER ARMIJO: Well, you know, it would  
9 be helpful if we could get -- and I know this isn't the  
10 main shield building issue, but it's going -- we're going  
11 to come to that. That's one of the RAIs. We can  
12 probably hear more about that in future meetings. But  
13 the source of the infiltration of the water, if it's  
14 coming in through the bottom of the concrete -- you know,  
15 water normally doesn't flow up hill, so I don't know  
16 how it gets up to the sand pocket region unless it's  
17 leaking in near the sand pocket region.

18 MR. HOOK: The sand pocket area is  
19 approximately -- well, there's approximately 25 foot  
20 of head on the groundwater. So that's why the sand  
21 pocket --

22 MEMBER STETKAR: The normal groundwater  
23 level is 570, and this is 5 --

24 MR. HOOK: Five-forty-five.

25 MEMBER STETKAR: -- 545.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER ARMIJO: So that's leads to, not a  
2 conclusion, but a suspicion that there's plenty of  
3 water, I mean, in between the steel and the concrete.

4 MEMBER STETKAR: Right. Yes.

5 MEMBER SHACK: It's a question of how  
6 benign that environment is --

7 MEMBER ARMIJO: Yes, right.

8 MEMBER SHACK: -- with the concrete.

9 MEMBER ARMIJO: Right. Right, right,  
10 right. So that's the -- we got to get at that at some  
11 point in more detail to understand the chemistry.

12 MR. HOOK: Well, so one of the things that  
13 -- when -- Dick Bear talked about that. During the next  
14 refueling outage we're going to take a core bore at the  
15 bottom. And to get to the bottom of the containment  
16 vessel, we'll do new UT readings and at the bottom.  
17 Then we'll absolutely be able to determine the thickness  
18 as well.

19 MEMBER ARMIJO: So when you bore it, do your  
20 core bore, then you'll get -- do a UT and you'll get  
21 thickness at the location of where --

22 MR. HOOK: That is correct.

23 MEMBER ARMIJO: A low location? Not --

24 MEMBER SHACK: A low location. Thirty  
25 inches off the --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER ARMIJO: Not the absolute bottom.

2 MEMBER SHACK: Right. Right. But it will  
3 be low.

4 MEMBER STETKAR: It'll be low enough to see  
5 this effect from the groundwater.

6 MEMBER SHACK: I would think.

7 MEMBER STETKAR: You would think.

8 MEMBER ARMIJO: Well, this is something in  
9 a future presentation more detailed on how that's put  
10 to bed.

11 MEMBER RAY: How is the containment vessel  
12 supported? Is it just supported at the bottom by its  
13 embedment in the concrete, or is there any other support  
14 provided to the containment vessel above the sand  
15 pocket?

16 MR. HOOK: Yes, again, I'm Jon Hook, design  
17 engineer and manager. The containment vessel and the  
18 shield building are two separate complete structures.  
19 There's no interaction except for at the base. They  
20 share the same common foundation. And the containment  
21 vessel has concrete on the bottom, a significant mass  
22 of 15 feet of concrete at the bottom. It is a  
23 cantilevered structure.

24 MEMBER RAY: Okay. So it's freestanding  
25 above the foundation?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. HOOK: That is correct.

2 MR. BYRD: Okay. Any further questions on  
3 this before I move on?

4 (No response.)

5 MR. BYRD: Okay. I'll move on now to talk  
6 a little bit about the shield building.

7 So the shield building itself is a -- it's  
8 a 30-inch concrete structure. And the purposes of the  
9 shield building, there's really three primary purposes:  
10 One is biological shielding. Secondly, it provides  
11 environmental protection for the containment vessel.  
12 I mean by that protection from various different kind  
13 of missiles. And then it allows for a controlled  
14 release of the annulus under accident conditions. And  
15 we do have a ventilation system which can take a suction  
16 on the annular area and provide us with a negative  
17 pressure in that area.

18 Next slide.

19 DR. BARTON: I understand there's no  
20 waterproof membrane on the exterior of the shield  
21 building below grade.

22 MR. BYRD: That is not correct. There  
23 actually is a waterproof membrane on the shield building  
24 below grade. There is not a waterproof membrane on it  
25 above grade. It was constructed with a waterproof --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 DR. BARTON: I must have read that wrong.  
2 All right.

3 CHAIRMAN SIEBER: But you doubt the  
4 integrity of the waterproof membrane below grade, right?  
5 Did I hear you say that before?

6 MR. BYRD: I didn't say that. I mean, I  
7 don't know that we've done -- I think, Joe Brunkhorst,  
8 maybe you could provide a little bit more information  
9 on that.

10 MR. BRUNKHORST: Joe Brunkhorst,  
11 structures monitoring program owner. As far as the  
12 waterproof membrane below grade, there is obvious  
13 evidence that there may be a nick or flaw or in the  
14 membrane, but it covers substantial surface area for  
15 below-grade shield building.

16 DR. BARTON: Well, if you're getting water  
17 into the concrete below grade, how do you know the  
18 condition of that concrete? You got to address the  
19 water down there.

20 MR. BRUNKHORST: That's correct. We  
21 haven't seen any signs of any sort of degradation,  
22 spalling from what has been accessible. I mean  
23 opportunistic inspections of the area has not shown any  
24 signs of any sort of aggressive groundwater attack on  
25 the concrete.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 CHAIRMAN SIEBER: Have you had  
2 opportunistic inspection opportunities --

3 MR. BRUNKHORST: I can --

4 CHAIRMAN SIEBER: -- down below the -- on  
5 the curvature of the base of the shield building?

6 MR. BRUNKHORST: I do not believe so. We  
7 have not had any specific on the shield building itself,  
8 no.

9 CHAIRMAN SIEBER: Okay. Thank you.

10 MR. BYRD: Okay. Moving on, please, to the  
11 next slide. So the purpose of this slide is to provide  
12 you with a little bit of information on some of the terms  
13 we're going to be using here to describe the shield  
14 building cracking issue.

15 First of all, the shield building wall, as  
16 I've mentioned before, it is 30 inches thick. There's  
17 two mats of primary reinforcement bar on the shield  
18 building, an inner and outer mat. And those are No.  
19 11 rebar horizontally, which is one-and-three-eighths  
20 inches, and No. 10 vertically.

21 We also have these -- eight of these flutes,  
22 which are labeled on this picture around the perimeter  
23 of the shield building. And around each flute we have  
24 two of what we have -- we call a flute shoulder. Now  
25 these three shoulders, the dimensions, it's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 approximately -- on the inside that's about 18 inches.

2 And the flute shoulder has its own reinforcement, as  
3 you can see in the diagram. That's No. 8 rebar, one-inch  
4 diameter. And that rebar is -- it attaches to the main  
5 rebar in two locations on each end of the flute shoulder.

6  
7 And the dimension between the two points  
8 of the rebar is -- it's about -- between 11 and 12 inches.

9 We took quite a bit of -- 11 and 12 feet, rather. We  
10 took quite a bit of radar, ground-penetrating radar  
11 measurements of that during our evaluation of the  
12 condition.

13 CHAIRMAN SIEBER: What's the purpose of the  
14 flute?

15 MR. BYRD: The flute is only intended  
16 -- it's an architectural feature. It's only for  
17 aesthetics.

18 CHAIRMAN SIEBER: It's only for --

19 DR. BARTON: To make the building look  
20 pretty.

21 MR. BYRD: That's correct.

22 DR. BARTON: That's what it is.

23 CHAIRMAN SIEBER: Yes, that caused me to  
24 scratch my head.

25 DR. BARTON: We don't have those kind of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 buildings.

2 MR. BYRD: And actually the next slide --

3 MEMBER ARMIJO: Before you do that, I just  
4 want to make sure, the only thing that hooks that  
5 shoulder to the rest -- to the structural part of the  
6 shield building are these rebar that comes through the  
7 wall, those --

8 MR. BYRD: Those -- on each end of the -- on  
9 each end those hooks. That is correct.

10 MEMBER ARMIJO: And down the length of the  
11 flute there's hooks?

12 MR. BYRD: This rebar is spaced every 12  
13 inches horizontally, so you have a hook every 12 inches.

14 But that's one of the factors I'll be discussing,  
15 because that was one of the contributing issues we had  
16 lack radial reinforcement on these flute shoulders.

17 MEMBER ARMIJO: Okay.

18 MR. BYRD: If you go to the next slide, it  
19 provides a little bit better information on the function  
20 of these flute shoulders.

21 So this is a picture of a flute shoulder  
22 taken up close. This is actually from the roof of our  
23 auxiliary building. And the interesting thing to note  
24 here is that the flute shoulder ends at the roof of the  
25 building. Actually only 3 of our flute shoulders out

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 of 16 actually go down to ground level. All the rest  
2 of them are truncated like this one at various different  
3 roof levels. So this makes it pretty apparent that this  
4 was intended as an -- for aesthetic purposes. In our  
5 evaluation of the capability of the shield building,  
6 we don't take any credit for the flute shoulders. We  
7 do evaluate them as a dead load in our analysis.

8 The other interesting thing I just want to  
9 point out on this picture, you can see a lot of blue  
10 dots on the concrete there. That is the -- and I'll  
11 be talking about this a little bit more. That's the  
12 grid we laid out for the impulse response testing we  
13 did on the shield building. We actually laid out over  
14 60,000 of those points. That's on a one-foot square.

15 The other thing of interest there, you can  
16 see in the middle of the flute on the upper left-hand  
17 side of this picture there's a red circle there, a little  
18 red dot. That's actually a plug. We did a core bore  
19 in that area and that's one of the plugs we use protect  
20 the core bores.

21 So next slide, please.

22 MEMBER ARMIJO: Just to make sure I  
23 understand. Now, the shoulders don't actually -- do  
24 not -- there's no shoulders, let's say in the protected  
25 areas? Let's say the -- with the auxiliary building

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the shoulders don't go down to there?

2 MR. BYRD: They don't go down. What you're  
3 --

4 MEMBER ARMIJO: Or the turbine building.  
5 They just stop?

6 MR. BYRD: They stop at the -- what you're  
7 -- what we're standing -- on this particular picture  
8 here, you're -- we're standing on top of the main steam  
9 line rooms at Davis-Besse. And if you go down  
10 underneath, there is no shoulder down there. This  
11 actually several feet above the roof line. And it does  
12 that everywhere where there's a building adjacent to  
13 the shield building. So there's actually only three  
14 flute shoulders which go down to ground level.

15 MEMBER ARMIJO: Okay. Thanks.

16 MR. BYRD: Okay. Next slide, please. So  
17 very briefly, we discovered this issue on October 10th.  
18 We were performing hydro-demolition. That was part  
19 of creating a construction opening for our head  
20 replacement. Upon discovery of the condition, we did  
21 notify the Nuclear Regulatory Commission resident,  
22 wrote a condition report and we placed a restraint on  
23 the restart. And then we put together a team of experts  
24 to investigate the issue. And for that we mobilized  
25 various different consultants. We also brought in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 experts from FirstEnergy.

2 MEMBER SHACK: Hydro-demolition, is that  
3 just a water jet cut?

4 MR. BYRD: That's the -- yes,  
5 hydro-demolition is the method we use. That's where  
6 we us 20,000 pounds per square inch water pressure to  
7 cut through the concrete.

8 Next slide, please. So one of the methods  
9 we use to investigate this condition was the methodology  
10 called impulse response, which is a non-destructive  
11 methodology that can be used in concrete. And the way  
12 this works is you have an instrumented hammer. And in  
13 this picture you can see the individual who is performing  
14 this testing. He has that hammer in his right hand.

15 And they have a geophone then which they use to monitor  
16 the response, which in this case he has in his left hand.

17 So what he'll do is he'll strike the wall at one of  
18 those blue dots which were gridded out. And then these  
19 -- the hammer and the geophone are both linked to a  
20 portable field computer which collects the data. And  
21 that information then is -- that data is processed to  
22 obtain a parameter that's called mobility, and that  
23 mobility can then be related to the structure thickness.

24

25 So in our total campaign -- again, we did

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 actually a couple different campaigns. We did some  
2 impulse response testing in 2011 until the weather got  
3 -- you know, towards the end of the year. Then this  
4 summer we completed the rest of the building. We did  
5 about 60,000 individual points in the building with this  
6 methodology.

7 CHAIRMAN SIEBER: When you perform this  
8 test what frequency range are you intending to receive  
9 in the microphone-type device in the workman's left  
10 hand?

11 MR. BYRD: I couldn't answer that question.  
12 I don't believe I have anyone here that could answer  
13 that. That would be something I'd have to refer -- we  
14 used Construction Technology Laboratories. That's the  
15 organization in Chicago who performed this testing.  
16 So I'm not familiar with the specific frequency that  
17 was being --

18 CHAIRMAN SIEBER: And so what you're  
19 looking for is the reflections from the cracked surface,  
20 if any?

21 MR. BYRD: That's correct.

22 CHAIRMAN SIEBER: And how do you determine  
23 how deep the crack is?

24 MR. BYRD: The way you determine; I'm going  
25 to show that on the next page, you have to do a core

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 bore, because impulse response testing cannot give you  
2 the depth of the crack. What can tell you is you have  
3 an area of high mobility, and then we would investigate  
4 those areas further using core bores.

5 CHAIRMAN SIEBER: Okay. So all this does  
6 is tell you where the cracks are? It doesn't  
7 characterize them in any way?

8 MR. BYRD: That is correct. Well  
9 actually, if you do a lot of this -- we could tell by  
10 looking at this -- and I -- it's not quantitative, but  
11 you could look at the results and say I know you have  
12 some cracking in this region. I mean, after we'd done  
13 this over the entire building, we gained a lot of  
14 experience. And obviously the Construction Technology  
15 people are very experience at this, but in order to  
16 validate this information, we used core bores.

17 MEMBER ARMIJO: What is the definition of  
18 "mobility?" What are you actually measuring?

19 MR. BYRD: It's the -- it's really a -- it's  
20 a measure of the structure. It's related to -- the  
21 structure thickness is what you're getting. So you can  
22 detect if you have a crack or a laminar -- delamination  
23 in that area.

24 MEMBER ARMIJO: So if you had some mobility  
25 parameter that you're measuring and you've taken all

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 these data points, can you get a map of where this  
2 discontinuity --

3 MR. BYRD: Yes, and I'll be showing you a  
4 slide later which shows you the mobility mapping we did  
5 for the entire shield building.

6 MEMBER ARMIJO: Okay.

7 CHAIRMAN SIEBER: Now, from this portion  
8 of the test you cannot tell anything about the geometry  
9 of the crack?

10 MR. BYRD: That is correct.

11 CHAIRMAN SIEBER: For example, direction,  
12 depth, width. Those just do not appear in the test  
13 result?

14 MR. BYRD: That is correct. And I'll be  
15 talking a little bit more about that in my next slide,  
16 how we gained that information.

17 CHAIRMAN SIEBER: Well, I'll let you go  
18 a little further before I ask the next question.

19 MR. BYRD: All right. Very good. Thank  
20 you, sir.

21 Then go to my next slide where I talk a  
22 little bit about the other methodology we used. We used  
23 core bores extensively to investigate the condition.  
24 And this picture shows a typical core bore. Our core  
25 bores, you know, we varied them from two to four inches

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 in width, depending on what we were attempting to do.

2 They could be from 8 to 28 inches deep.

3 And there was really four reasons we used  
4 to do core bores. And first of all; and we discussed  
5 this, we used these to validate the impulse response  
6 data. And I might point out we did find that the impulse  
7 response data was very accurate. What we would  
8 frequently do, or we tried to as much as possible, is  
9 use pairs of core bores. So when we'd get to an area  
10 where the mobility told us that cracking was extended,  
11 we would put core bores as close together as a foot and  
12 we could get cracked and not cracked. So we could  
13 validate that the impulse response data was valid. And  
14 it was very accurately able to do that.

15 The second purpose of these was to establish  
16 the crack depth. Again, impulse response couldn't tell  
17 us how deep the crack was, but we could actually go down  
18 with the boroscope and we could look and see where the  
19 crack existed and measure the crack depth.

20 We could measure the crack width using the  
21 -- and we did that with the crack comparator, and I'll  
22 show you that on the next slide how we did that.

23 And finally, we took some of our core bores  
24 for material sampling for part of our root cause process,  
25 and I'll describe how we did that later on when I talk

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 about the root cause.

2 CHAIRMAN SIEBER: Now this design is unique  
3 to the architect engineer for this facility?

4 MR. BYRD: The design of the shield  
5 building?

6 CHAIRMAN SIEBER: Yes.

7 MR. BYRD: It was unique for this -- there  
8 are other -- when I say "this design," there are several  
9 other plants that have freestanding shield buildings,  
10 but I'm not sure if any of them were precisely the same  
11 as Davis-Besse.

12 CHAIRMAN SIEBER: That have flutes?

13 MR. BYRD: There are other designs with  
14 flutes, but again not -- they're all a little different.  
15 There are some other plants that do have flutes that  
16 I'm aware of.

17 CHAIRMAN SIEBER: Has any other licensee  
18 with a containment building design like this found  
19 similar effects?

20 MR. BYRD: No, they have not, and  
21 -- although we have talked to some of them and some of  
22 them were actually up at Davis-Besse while we were doing  
23 the investigation. But when I get to the root cause,  
24 when I'm going to -- when I explain to you what caused  
25 this, there's a number of -- a series of what I would

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 consider rather unique conditions that needed to occur  
2 in some of the other plants, for example, that may be  
3 in the South where we don't get the cold weather and  
4 some other things that may have had an impact on that.

5 So at this point none of the other ones have observed  
6 this condition.

7 CHAIRMAN SIEBER: Yes, well cracking in a  
8 containment building is not a unique phenomenon.

9 MR. BYRD: Understand that. We'll  
10 -- again, when I get into the root cause, I can talk  
11 about what we --

12 CHAIRMAN SIEBER: Okay.

13 MR. BYRD: -- obtained from operating  
14 experience.

15 DR. BARTON: But their rebar design may  
16 have been different also.

17 MR. BYRD: That's possible, too.

18 DR. BARTON: Different designer.

19 MR. BYRD: Right.

20 CHAIRMAN SIEBER: Well, it can have -- it  
21 can be a design issue, it could be a concrete mix issue.

22 MR. BYRD: Right.

23 CHAIRMAN SIEBER: Or chemical reaction, or  
24 weather conditions, or -- there's a variety of things  
25 that can cause these.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BYRD: Right, and we'll talk a little  
2 bit more about that. I'll get to the root cause portion.

3 MEMBER ARMIJO: When you pulled out the  
4 core when you were doing this core boring in a region  
5 where you had these cracks, did they come out where they  
6 actually came out in two pieces?

7 MR. BYRD: Yes, they would.

8 MEMBER ARMIJO: Okay.

9 MR. BYRD: When they were cracked, they  
10 would come out in two pieces. But really the way to  
11 measure the crack was actually going to the core bore  
12 and look in the bore itself.

13 MEMBER ARMIJO: After they were done?

14 MR. BYRD: After they were taken out,  
15 right. Sometimes you'd get them cracked where there  
16 wasn't a crack just trying to get out -- if you had a  
17 long core bore you're trying to pull out, it may crack.

18  
19 MEMBER SHACK: Now I see Kewaunee and  
20 Prairie Island have similar constructions. At least  
21 they're still cylinders with concrete shield buildings  
22 that have your kind of weather.

23 MR. BYRD: Yes, I'm not sure either of them  
24 have flutes either though. I know there are flutes at  
25 some plants, and I'm not -- those two don't come to my

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 mind as one that are fluted.

2           Okay. Going to the next slide, I can  
3 summarize now where we saw the cracking. So the drawing  
4 you see on this slide depicts the primary region where  
5 we saw cracking. So what we determined was that  
6 cracking is -- can be found in the flute shoulders.  
7 And I say it's generic. We found it -- it could be found  
8 at various different elevations in the flute shoulders.

9           It was observed to be more prevalent and actually much  
10 -- significantly more prevalent -- and I'll show the  
11 map of the completed impulse response testing later on  
12 the south side of the building.

13           We did identify that the cracks were located  
14 in, as shown on this picture, near the outer reinforcing  
15 mat. There were no cracks observed on the inner mat.

16           And to investigate the inner mat, first of all we had  
17 the construction opening. When we cut it, we had a  
18 25-foot by 35-foot opening. We did inspect the  
19 perimeter. We did have a cracking on the outside. In  
20 fact, the picture here shows where the boundary of the  
21 construction up here was. So we actually cut right  
22 through the flute shoulder. We had no cracking observed  
23 on the inner mat. It was all on the out outer mat.

24           We also further validated that. We did  
25 eight deep core bores. So we did eight core bores and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 then all the way through to the inner rebar mat. And  
2 in none of those core bores did we find any cracking  
3 in the inner rebar.

4 CHAIRMAN SIEBER: Did any of the cracking  
5 appear on the surface where it --

6 MR. BYRD: No, it did not. This cracking  
7 was contained inside as shown on this picture in that  
8 inner mat of rebar. When I say "in the inner," it was  
9 in the vicinity of the inner rebar mat. It did not have  
10 any of the cracking that appeared on the surface. There  
11 was no way through a visual inspection we had this line  
12 in the cracking.

13 CHAIRMAN SIEBER: Okay. So you saw no  
14 spalling, no cracks on either side of the containment?

15 MR. BYRD: We saw no spalling or cracking  
16 that was associated with this laminar cracking. I mean,  
17 there was none.

18 Okay. Moving onto the next slide, so we  
19 also identified that we had some cracks in the top 20  
20 feet of the shield building outside of the flute shoulder  
21 region. The way it appeared is it appeared  
22 -- and this is in -- and I'll -- this will be more obvious  
23 when I show you the map of the total cracking, the cracks  
24 had spilled out of the shoulders in the top 20 feet.  
25 And then we found two small regions; and these were

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 adjacent to the main steamline penetration block-outs  
2 where we also found similar cracking. Now the main  
3 steamline penetration block-outs are actually the areas  
4 that are right adjacent; and again, the drawing will  
5 show that more clearly -- are adjacent to the regions  
6 where -- and in the shoulders.

7 And finally, we identified the cracks are  
8 very tight. And the method we used to measure crack  
9 width -- again, that was something we had to with the  
10 core bores. And we use the -- a core bore and we use  
11 crack width comparitor. And the picture you see here  
12 shows us with a -- measuring the width of the crack.

13 And we photographed these using the boroscope. This  
14 particular crack we measured at 0.005 inches. So again,  
15 it's a very tight crack. All of the cracks except one  
16 were less than 0.01 inches. We did have one crack that  
17 was 0.013 inches. That was the only case we had that  
18 was greater than 0.01.

19 Okay. Next slide, please. So that really  
20 very briefly summarizes the condition that we  
21 identified. So I'll talk a little bit about -- next  
22 about the evaluation we did to determine that this -- the  
23 shield building was structurally adequate to restart  
24 the plant.

25 So first of all, the original steel building

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 design is -- it's pretty conservative. It was  
2 constructed with significant reinforcement and there  
3 was a significant of margin. We had -- the maximum  
4 vertical stress on the rebar was only 32 percent of  
5 maximum in the vertical and about 50 percent  
6 horizontally. So there was considerable amount of  
7 margin.

8 So the concern we had though with these  
9 laminar cracks is a concern about the potential effect  
10 of the bond strength between the rebar and the concrete.

11 Obviously that was because we had identified that the  
12 cracking was in the rebar mat. And in particular there  
13 was a concern where we had laps on the rebar, whether  
14 or not we'd have sufficient capability for those  
15 splices.

16 MEMBER SHACK: Do you know how long those  
17 laps are?

18 MR. BYRD: Yes, we do. The laps are in the  
19 lower portion of the building. The laps are 79 inches.  
20 That's the specification. And in the upper part of  
21 the building, they're 120 inches.

22 MEMBER SHACK: Now is that consistent with  
23 current code requirements? Three eighteen --

24 MR. BYRD: That would be --

25 MEMBER SHACK: -- for lap for that size bar?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BYRD: That would be larger than the  
2 current code. I think Jon Hook could tell me what the  
3 current code is. I think that's significantly larger.

4 MR. HOOK: Right, the -- it's either  
5 consistent with or more conservative than the existing  
6 code. And on the original AE, Bechtel was conservative  
7 when they came up with a 120-inch splice up on top.

8 MEMBER SHACK: Thank you, John.

9 MEMBER STETKAR: Before you switch, I don't  
10 do conversions from Richter to acceleration all that  
11 well, as can nobody. Six to 6.5 Richter, are you saying  
12 it's about --

13 MR. BYRD: I can give you the acceleration.  
14 That's 0.08 g. That's maximum probable. Maximum  
15 possible is 0.15.

16 MEMBER STETKAR: 0.15?

17 MR. BYRD: 0.15. That's correct.

18 MEMBER STETKAR: Thank you.

19 MR. BYRD: Okay. Going to the next slide,  
20 please. So we understood that with these cracks in the  
21 rebar that would be a concern with the bond between the  
22 rebar and the margin. We also recognize with the very  
23 tight cracks, there probably was a considerable amount  
24 of bond strength, but we didn't have a method to quantify  
25 it. We didn't have any specific testing that could tell

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 us what bond strength was left. So therefore we -- in  
2 our analysis we performed prior to restarting we  
3 conservatively treated all of the rebar in the shoulder  
4 areas, in affected areas of the top 20 feet, and in these  
5 main steamline penetration areas as non-existent in the  
6 analysis. So we performed calculations to prove they  
7 provide bounding evaluation.

8 And if you go onto the next page, the result  
9 of that was that the -- even with these very conservative  
10 assumptions of the lack of -- or not effectiveness of  
11 the rebar in these regions, we didn't meet our  
12 requirements with traditional margins of safety. So  
13 that was the process we used to demonstrate that the  
14 shield building was capable of performing its safety  
15 functions.

16 If we can go to the next slide, please --

17 CHAIRMAN SIEBER: Now, its only safety  
18 function is to provide shielding as opposed to  
19 containing the pressure of the accident?

20 MR. BYRD: That is correct. It is not  
21 designed to contain the pressure of the accident. It  
22 does provided, as I mentioned before in the functions,  
23 we do have the annulus base which we can take a suction  
24 on with our ventilation, so it does provide a function  
25 of being able to provide that controlled release of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 annulus.

2 CHAIRMAN SIEBER: And so as part of the  
3 original design you have the ability to have a controlled  
4 release of gaseous material in the annular space between  
5 the containment pressure vessel and the containment  
6 shield building?

7 MR. BYRD: Correct.

8 CHAIRMAN SIEBER: Okay.

9 MEMBER STETKAR: The safety analysis  
10 accounts for that, the availability of that interstitial  
11 ventilation filtering system, or not?

12 MR. BYRD: I would have to ask Dennis  
13 Blakely to respond to that question. He's our analysis  
14 supervisor.

15 MR. BLAKELY: Dennis Blakely, engineering  
16 analysis supervisor. The LOCA analysis does credit the  
17 ability to take suction on the annular space through  
18 our emergency ventilation system. It filters the  
19 release prior to going to the environment.

20 MEMBER STETKAR: Thank you. Some do.  
21 Some don't. That's why I asked. Thank you.

22 CHAIRMAN SIEBER: Well, the purpose of my  
23 question is to establish clearly just what the function  
24 of the building is, the structure is. And that  
25 -- because it's different than other types of large dry

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 containers.

2 MR. BYRD: Okay. Next I'm going to talk  
3 about the root cause. And while we were in the process  
4 of doing the investigation that I just described, we  
5 had established an independent root cause team which  
6 was evaluating the root cause. And so what I'm going  
7 to talk about here, I'll talk a little bit about the  
8 team, the establishment of the team, talk about how we  
9 put together our failure- modes analysis, discuss a  
10 little bit of the testing we did, some of the concrete  
11 testing analysis, and then explain what our root cause  
12 was.

13 So the next slide, please. So early in the  
14 process we did get Performance Improvement  
15 International involved. And I'm sure that you're  
16 -- most of you are familiar with Performance Improvement  
17 International. They are very experienced. They've  
18 performed over 500 root causes. But what was  
19 particularly beneficial for us is they had done the root  
20 cause on Crystal River, and as a result of doing that  
21 root cause on the containment, they had developed  
22 expertise in analytical methods for concrete, and they  
23 also had a lot of expertise in concrete testing. So  
24 that was very beneficial to us in getting our root cause  
25 moving in a fairly expeditious manner.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1           We also supplemented the Performance  
2 Improvement International with other industry experts  
3 and we used our on FENOC engineering as well. And we  
4 did follow our own FENOC root cause process.

5           CHAIRMAN SIEBER:   Crystal River is a  
6 post-tension concrete vessel --

7           MR. BYRD:   That's correct.

8           CHAIRMAN SIEBER:   -- which is  
9 substantially different in structural design from the  
10 Davis-Besse containment building. And so the root  
11 cause at Crystal River is not applicable here.

12          MR. BYRD:   The root cause was completely  
13 different --

14          CHAIRMAN SIEBER:   Right.

15          MR. BYRD:   -- I would agree, at Crystal  
16 River. What was helpful to us however was having --

17          CHAIRMAN SIEBER:   The analytical  
18 techniques.

19          MR. BYRD:   -- the analytical techniques,  
20 the experience in testing concrete, some of that other  
21 -- that was what helped with us.

22          CHAIRMAN SIEBER:   Now as part of your root  
23 cause analysis did you look into any aspect of the  
24 composition of the concrete that was used as it came  
25 from the batch plant and, for example, reactions within

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 the concrete such as was found at Seabrook?

2 MR. BYRD: Yes, we looked at that  
3 extensively. In fact, Mr. Hook is going to be able to  
4 explain that you.

5 MR. HOOK: Right, I think you're referring  
6 to alkali-silica reaction.

7 CHAIRMAN SIEBER: That's right.

8 MR. HOOK: Right, so as part of our root  
9 cause; and Ken will get to that in a little bit though,  
10 we took over -- we took 90 core bores. Thirty-six of  
11 those core bores we sent out to independent  
12 laboratories. We used several laboratories to do that.

13 And that's one of the things they specifically looked  
14 for, is chemical reaction. They did petrograph  
15 examination and all of those tests came back as being  
16 negative, meaning we had no indications of alkali-silica  
17 reaction.

18 And so we also -- all the aggregate for the  
19 shield building came from the same quarry as we used  
20 for all the other concrete on the site. So we have no  
21 indications of chemical reactions. So we have high  
22 confidence that ASR is not an issue at Davis-Besse.

23 CHAIRMAN SIEBER: Okay. Now when  
24 Davis-Besse was constructed, I presume you had your own  
25 concrete batch plant?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 MR. HOOK: Right, we had a batch plant on  
2 site. That's right.

3 CHAIRMAN SIEBER: Yes, you don't look old  
4 enough to remember that, but I do.

5 MR. HOOK: I have seen pictures. But,  
6 right. In fact, we had our own batch plant on site,  
7 a central batch plant. And so all the concrete on site  
8 was batched from that batch plant.

9 CHAIRMAN SIEBER: And you poured samples  
10 daily --

11 MR. HOOK: Absolutely.

12 CHAIRMAN SIEBER: -- from the batch plant  
13 and typically from each truckload as it was delivered  
14 from the batch plant to the building construction site,  
15 is that correct?

16 MR. HOOK: That's right. And as part of  
17 our root cause investigation, we do look at the batch  
18 records. We looked at QC reports. The sequencing of  
19 the pours. The shield building was poured as slip form.

20 So we looked at all those construction records. We  
21 looked at the 28-day concrete strengths that we did,  
22 and the 90-day strengths. And they -- our design is  
23 based on a 4,000-psi concrete, and the average 28-day  
24 strength was about 5,800. So we had high concrete  
25 strength.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 CHAIRMAN SIEBER: Yes, typically you can  
2 meet the strength requirements. On the other hand,  
3 typically the data that you get from the blocks that  
4 you pour for testing do not contain chemistry data.  
5 Do you have any chemistry data that corresponds to the  
6 blocks that were tested for your concrete mixture as  
7 it was put in place with the removable --

8 MR. HOOK: Right, so part of the mix design  
9 process -- so we did evaluate the chemical and the  
10 -- well, the coarse aggregate and the fine aggregate  
11 met the ASTM requirements at the time.

12 CHAIRMAN SIEBER: Okay. And the water  
13 content and the water purity was off the -- you have  
14 records of those?

15 MR. HOOK: Right. It's all potable water,  
16 correct.

17 CHAIRMAN SIEBER: And you verified that  
18 those met the ACI standards at the time?

19 MR. HOOK: They met the ACI and the American  
20 Society for Testing Materials standards. That is  
21 correct. And as spelled out in our specifications for  
22 that, correct.

23 CHAIRMAN SIEBER: Okay. Thank you.

24 MR. BYRD: Okay. Let's go to the next  
25 slide, please. So this slide shows the fault tree of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 failure modes that we used to investigate the condition.

2 So we had 45 failure modes and we grouped these into  
3 three different categories. Those were design issues,  
4 construction and fabrication issues, and then  
5 operational phase issues. So each of these issues was  
6 worked through methodically and we either eliminated  
7 them or determined we needed to have additional  
8 evaluation. So what you can see from this slide, the  
9 ones that are circled in blue, those are the one that  
10 were eliminated. And the one which are reddish or  
11 orange, those were the issues that we performed  
12 additional investigation on.

13 The next slide, please. So in order to do  
14 the root cause we did extensive testing of the concrete.

15 We sent 36 core bores for testing at six different  
16 locations. They subjected it to a number of different  
17 tests. Tested for concrete properties, tensile  
18 strength, compressive strength. They looked at thermal  
19 properties of the concrete. And we also looked at some  
20 of the issues which we were -- if there were chemical  
21 attack. We looked for issues of micro-cracking. So  
22 quite a bit of work was done. The tests came back  
23 indicating, however, that the concrete quality was good,  
24 conformed to our mix design, and the compressive and  
25 tensile strength exceeded the minimum design

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 requirements.

2 So I'm not going to go talk about each of  
3 these concrete tests we did, but there was there tests  
4 I want to talk about that were maybe somewhat revealing  
5 with regards to the root cause that we ended up coming  
6 to.

7 So the first one; if go to the next slide,  
8 was the manner in which the concrete fractured and  
9 through the aggregate. And the picture you see here  
10 is a piece of the concrete that we picked up in the area  
11 of where we were doing the hydro-demolition. And as  
12 you can see the surface of the crack is smooth. It  
13 actually sheared through the coarse aggregate. And  
14 that told us several things. We also saw this in the  
15 core bore samples we took, which --

16 MEMBER ARMIJO: This is -- the crack's face  
17 is in a vertical --

18 MR. BYRD: That's correct. The vertical  
19 is the crack face. And you can see it goes through the  
20 aggregate. It's very, very smooth. It told us several  
21 things. It told us first of all that there was a -- a  
22 considerable force was required to -- for that crack.

23 Our aggregate is not -- it is strong. We don't have  
24 a problem with the aggregate. It told us we had good  
25 bond between the aggregate and the paste. What that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 told us, that this crack occurred in mature concrete.

2 This obviously wasn't something that occurred early  
3 in the process before the concrete had time to gain its  
4 strength.

5 Next slide, please. Another test that was  
6 revealing is the inspection for micro-cracking. And  
7 the slide here is a cross-section of the concrete sample  
8 that was used to do an inspection for micro-cracking.

9 So we found no evidence of micro-cracking in the areas  
10 near the laminar cracks. There was no sign of a cyclic  
11 loading mechanism or a freeze-thaw mechanism. And what  
12 this suggested to us, there was no indication of a  
13 fatigue or an age-related event.

14 Now to be clear, there was in some of the  
15 reports micro-cracking identified. That  
16 micro-cracking was near the surface. So surface  
17 cracking was identified. But in the vicinity of these  
18 laminar cracks, which was really the area of interest,  
19 we did not identify micro-cracking.

20 MEMBER ARMIJO: I just want to make sure.

21 Were these cracks just -- was it a one-planar crack,  
22 or were there a number of just parallel cracks along  
23 this?

24 MR. BYRD: It would be -- there was probably  
25 -- I wouldn't say it was a -- it was generally on a plane

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 in the rebar, but I wouldn't say there was just one crack.

2 It was -- in some places --

3 MEMBER ARMIJO: So it's a zone where there  
4 might be --

5 MR. BYRD: Yes, it might. And it might  
6 meander around a bit. And then we would -- what we  
7 concluded, the cracking was generally in a plane around  
8 the inner -- outer rebar mat. But not to say that we  
9 wouldn't have --

10 MEMBER ARMIJO: Yes, something --

11 MR. BYRD: Yes, like you're describing it.

12 CHAIRMAN SIEBER: But it was really  
13 circumferentially as opposed to radially?

14 MR. BYRD: I'm sorry, sir?

15 CHAIRMAN SIEBER: It was oriented -- the  
16 cracks were oriented circumferentially rather than  
17 radially.

18 MR. BYRD: That's correct. That is  
19 correct.

20 Okay. The next slide, please. The final  
21 test I want to talk about is carbonation. And actually  
22 we had a lot of evidence without actually testing the  
23 concrete that carbonation was not the issue. And it  
24 becomes -- first of all, it was the particular location  
25 where we found the cracks. The cracks were -- as I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 mentioned before, they were primarily in the outer  
2 -- well, pretty much all in the outer rebar mat and mostly  
3 in the shoulder region. The shoulder region is an area  
4 where we actually have quite a bit of concrete cover.

5 On the thick side, you have almost 20 inches of concrete  
6 cover. So that would suggest that carbonation was not  
7 an issue.

8 Additionally, we had no evidence of degradation of the  
9 rebar. We did inspect rebar that we removed in the area  
10 where we had the construction opening. And we had no  
11 indication, as I mentioned before, of surface spalling  
12 in these areas that were cracked. All that suggested  
13 that carbonation was not an issue.

14 However, I wanted to discuss this testing  
15 because carbonation was discussed a lot and it was -- and  
16 it's an aging mechanism. So what you can see here on  
17 this picture, there's a dye. And the areas that are  
18 pink are the non-carbonated areas. But the surface of  
19 this concrete sample which was exposed to the atmosphere  
20 you can see is the carbonated area. We found that in  
21 general, average it was about a third of an inch we'd  
22 get carbonation. Maximum, about a half of an inch.  
23 And we have the three-inch cover over the outer rebar  
24 mat, so that was sufficient for a -- of course this is  
25 in -- in 40 years we had this much carbonation, so this

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 should not be an issue for the duration of the plant  
2 through its extended life.

3 MEMBER ARMIJO: I may be the only guy in  
4 the room that doesn't know what carbonation is, but could  
5 you tell me what that is?

6 MR. BYRD: Sure. Carbonation is a process  
7 where carbon dioxide in the air reacts with calcium  
8 hydroxide, the lime in the concrete, and that forms  
9 calcium carbonate. And it's not really a problem in  
10 concrete. Actually it makes the concrete, if anything,  
11 a little stronger. But the issue is is concrete  
12 normally has a pH which tends to inhibit corrosion in  
13 the areas where you have rebar. And carbonation will  
14 actually affect the pH of the concrete. So if you were  
15 to -- normally, if you were -- carbonation damage, what  
16 would happen is you'd get carbonation that would go deep  
17 enough so it gets to the point where you have your rebar  
18 mat. At that point you're affecting the pH. Then you'd  
19 get corrosion of your rebar. Then you'd see the rebar  
20 would start expanding. You'd see spalling and cracking  
21 in the concrete. I mean, that's typically what you  
22 would you see for carbonation damage.

23 MEMBER ARMIJO: All right.

24 MR. BYRD: So as I mentioned before, we  
25 didn't see any spalling, any damage to the rebar.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Additionally, we've got maximum half an inch with  
2 three-inch cover, so it's really not a concern.

3 MEMBER ARMIJO: Okay. Great.

4 MR. BYRD: Okay. Next slide, please. So  
5 to summarize what we saw with our concrete, so the crack  
6 passed through coarse aggregate and that told us we had  
7 a strong bond between the paste and the aggregate and  
8 the crack occurred in mature concrete. It also told  
9 us we had to have a pretty large force to initiate that  
10 crack.

11 CHAIRMAN SIEBER: So you had evidence that  
12 the aggregate itself had cracked and split?

13 MR. BYRD: Oh, absolutely. The aggregate  
14 -- the crack went right through the aggregate. That  
15 shear picture you saw, you know, if you see it close,  
16 you would see the aggregate was actually sheared  
17 straight through. And as I said before, our aggregate  
18 is local limestone. It's reasonably hard and it's -- so  
19 it was a considerable force.

20 So we also identified no micro-cracks in  
21 the vicinity's laminar crackings that would indicate  
22 freeze-thaw or cyclic event.

23 Chemical properties, as I mentioned, we did  
24 carbonation. And as Mr. Hook mentioned, we also looked  
25 for alkali-aggregate reaction. We looked for sulfate

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 attack and any kind of acid damage. We didn't see any  
2 indication of chemical attack. So based on that we were  
3 able to rule out concrete as an initiating or a  
4 contributing cause. We also gained some additional  
5 information. We pretty much told us this appeared to  
6 be an event that had occurred which had caused this  
7 crack, rather than some kind of a cyclic or a  
8 fatigue-type of a mechanism.

9 CHAIRMAN SIEBER: Okay. And Lake Erie is  
10 a freshwater lake, right?

11 MR. BYRD: Lake Erie is a freshwater lake.  
12 That is correct.

13 CHAIRMAN SIEBER: And can we conclude that  
14 atmospheric conditions do not contain any unusual  
15 chemistry that you might find near a seashore? For  
16 example, industrial plants sometimes emit things that  
17 can deposit on concrete and changes its physical and  
18 chemical characteristics. You have no industrial  
19 plants close to Davis-Besse?

20 MR. BYRD: Where we are -- as I mentioned,  
21 we're in a wildlife refuge, so there's really no  
22 -- there's no industrial plants. They would -- you  
23 would have to be 30 miles away to Toledo, or it's probably  
24 50 miles or 60 miles to Cleveland. So we're not in an  
25 area that's --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 CHAIRMAN SIEBER: My recollection is that  
2 the closest coal-fired power plant is about 30 miles  
3 away, 35 miles away.

4 MR. BYRD: About that, that's correct.

5 CHAIRMAN SIEBER: Okay. And I don't  
6 recall any others along Lake Erie until you get to the  
7 area where Perry is.

8 MR. BYRD: That's correct.

9 CHAIRMAN SIEBER: Okay. Thank you.

10 MR. BYRD: Okay. Next slide, please. So  
11 the next thing we looked at was shield building  
12 configuration. And actually looking at the  
13 configuration of the cracks did provide some pretty  
14 valuable insight. And I mentioned before, cracking is  
15 predominantly located in the shoulder areas in the top  
16 20 feet and in the main steamline penetration  
17 block-outs, and it was concentrated on the southern  
18 exposures. So as we looked at the crack locations and  
19 looked at the details which I previously described to  
20 you of the shield building, several things became fairly  
21 apparent. One is that the shoulder areas are regions  
22 of discontinuity. In other words, we have these  
23 shoulders built on. And there was -- and was pointed  
24 out, there's limited radial reinforcing steel in those  
25 areas. So based on that we decided that was an area

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 that we'd want to investigate further.

2 Another thing we noticed is the top 20 feet  
3 of our shield building has more horizontal  
4 reinforcement. The horizontal reinforcement, which is  
5 this No. 11 rebar, is every since 6-inch spacing until  
6 you get to the top 20 feet and then it goes to -- I'm  
7 sorry, it's 12-inch spacing, thank you, until we get  
8 to the top 20 feet in which it goes to 6-inch spacing.

9 And actually we noticed in some of our  
10 impulse response testing the really good correlation  
11 we got. Up above into the higher-density rebar we start  
12 seeing laminar cracking outside of the shoulders. So  
13 we decided that obviously the density of the rebar was  
14 something that would be -- warrant further  
15 investigation.

16 And we also were aware that around the main  
17 steamline penetration block-outs there's another area  
18 where we have dense rebar around the block-outs.  
19 Because the cracking we saw around the block-outs,  
20 within the block-out itself there was no cracking at  
21 all. In fact, we could actually use an impulse  
22 response. We could trace the block-out itself. But  
23 we find the cracking was actually occurring around the  
24 edge of the block-out. We could actually see the  
25 corners of the block-out in the impulse response

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 testing, which was quite remarkable. So that told us  
2 there was again -- appeared to be a correlation between  
3 rebar density and the cracking we were observing. And  
4 then finally there was clearly this south versus north  
5 orientation. That was something else we needed to do  
6 some further investigation of.

7 MEMBER ARMIJO: And you'll get into that  
8 when you get to your root cause --

9 MR. BYRD: Yes, I will.

10 MEMBER ARMIJO: -- to show why south?

11 MR. BYRD: I will.

12 MEMBER ARMIJO: Why top 20?

13 MR. BYRD: Absolutely.

14 CHAIRMAN SIEBER: Rebar density in a  
15 containment design like Davis-Besse is far less than  
16 those where the containment building is actually a  
17 pressure barrier. Is that not correct?

18 MR. BYRD: That would be correct.

19 Okay. So we -- going onto the next slide,  
20 please. So we did a number of detailed analysis to  
21 better understand -- and again, I mentioned the shoulder  
22 areas appeared to be a discontinuity and something to  
23 further investigate. So we did a number of very  
24 detailed analysis to understand how these shoulder areas  
25 responded to various loading conditions. And the first

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 area that we really looked at seriously was thermal  
2 conditions. Looked at -- and to do this we evaluated  
3 32 different thermal conditions. In other words,  
4 winter, summer, various different combinations of  
5 inside and outside temperatures. Did screening on 32  
6 of those. And then we did a more detailed evaluation  
7 on the most -- the top six events. And then for those  
8 events we combined the thermal stresses with stresses  
9 caused by dead weight and wind.

10 And the results of all of this though was  
11 that the radial stresses -- well, first of all, the  
12 radial stress was maximized in summer conditions, hot  
13 summer conditions. But when we combined the thermal  
14 stress with the dead weight and wind loads, we didn't  
15 come up with stresses that were nearly sufficient to  
16 create the kind of cracking we saw. The maximum was  
17 about 300 pound per square inch. That's about half of  
18 the -- what would be required to create the cracking.

19 So the other thing we looked at was unusual  
20 events that have occurred. And we did have a tornado.

21 It was a category 2 tornado which had been in the  
22 vicinity of the plant; I don't believe it actually struck  
23 the shield building, and that was in 1998. We did  
24 evaluate wind loads. Wind loads based on this model  
25 were not even -- very insignificant for those kind of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 wind conditions. So we'd eliminated thermal  
2 conditions, which actually when we first looked at this  
3 was very suggestive on the south side, and eliminated  
4 the tornado, determined those weren't sufficient for  
5 cracking.

6 Next slide, please. So what we had is we  
7 understood that we had an event, as I said before, from  
8 the concrete. This was a event-driven event. So at  
9 this point we did research into additional industry  
10 experience to determine if there was other similar  
11 conditions.

12 So if we'd go to the next slide, I'll talk  
13 a little bit about the operating experience we  
14 identified. Okay. As I mentioned before, for  
15 operating experience we had Performance Improvement who  
16 had performed the root cause on the Crystal River laminar  
17 cracking. However, it was also pointed out here  
18 previously, the Crystal River really didn't apply to  
19 Davis-Besse. They have a post-tension containment.  
20 We have a freestanding containment. The conditions,  
21 they had some concrete quality issues. And as I  
22 mentioned before, we didn't appear to have any concrete  
23 quality issues. So really there was not any correlation  
24 we could get between Crystal River and Davis-Besse.

25 However we did find some operating

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 experience from the Ontario Ministry of the Environment.

2 They'd done a study of above-ground water tanks up in  
3 Ontario and the conditions that they'd found was that  
4 the water tanks -- in the winter you would have the -- the  
5 water would penetrate the concrete on the inside of the  
6 tank. And then when you got very cold weather, the  
7 moisture in the concrete on the inside was expanding.

8 The cold weather was also causing the exterior to  
9 contract and that was creating high radial stresses in  
10 these tanks and actually was causing laminar cracking  
11 in the tanks. So that suggested to us another possible  
12 failure, which could be moisture penetration and  
13 freezing.

14 Now obviously Davis-Besse is not a water  
15 tank, and so we were looking at it really from the other  
16 way around, having water penetrating from the outside  
17 and then having very cold temperatures. So we  
18 considered some potential for water penetration, and  
19 it appeared the most probable cause would be high wind  
20 and rain that could cause water penetration.

21 So going to the next slide, please. So we  
22 investigated potential conditions where we could have  
23 had water penetration in the shield building followed  
24 by extreme cold. And the most significant  
25 environmental condition was in the winter of 1978, which

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 also was the worst environmental condition in recorded  
2 Ohio history in terms of moisture, temperature, wind  
3 and duration.

4           If you'd go to the next slide. So on  
5 January 25th through 27th of 1978, it rained several  
6 days and we had -- actually the temperatures were in  
7 the 40s during that period. There were high sustained  
8 winds. There were gusts of over 100 miles an hour in  
9 the vicinity of the plant. We had very low  
10 temperatures. Temperatures then dropped down to  
11 approximately 0 degrees Fahrenheit. We had sustained  
12 low-temperature conditions for several days. So those  
13 really are the conditions that occurred in '78.

14           So if you go to the next slide. So the  
15 scenario for the event that we proposed was if we had  
16 heavy rains preceding a blizzard and that caused  
17 moisture to penetrate the exterior surface of the  
18 concrete, and we had a drop in temperature to well below  
19 freezing and that would freeze -- and strong winds, that  
20 would freeze the outer concrete, the moisture in the  
21 outer concrete. And then with no radial reinforcing  
22 in the shoulder areas, the radial stresses that we were  
23 developing in the building were exceeding the capability  
24 of the concrete, tensile capability of the concrete.

25

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 All right. So next slide, please. So in  
2 order to demonstrate that this was in fact a credible  
3 theory, we did develop a computer model of the shield  
4 building to evaluate the condition. Used thermal  
5 properties from the concrete which we used from some  
6 of these core tests that we'd performed. There were  
7 laboratory tests performed which demonstrated that  
8 moisture infiltration could be up to four inches for  
9 the particular wind duration and strength that we had  
10 during this storm. What the model did show is that our  
11 maximum radial stress is approximately 550 pounds per  
12 square inch. And as you can see from this picture, the  
13 radial stress was concentrated precisely in the area  
14 where we saw -- primarily we saw the cracking. So again,  
15 this was consistent with what we saw in the root cause.

16 We also -- I just want to make a point here.

17 We did look at other events other than the storm of  
18 1978. We did look at some of the other significant  
19 storms we've had and we didn't find any other storm.

20 We actually evaluated -- I think the second worst was  
21 in 1977. We didn't find another storm that had the right  
22 combination of rain, cold and duration to create this  
23 event. So that's why we believe this occurred in 1978  
24 and not at another period of time.

25 Okay. So that explained -- at least this

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 created for us in our minds a plausible explanation for  
2 the cracking we saw in the flute shoulders. We still  
3 also had the other issue with the cracking in the  
4 high-density rebar areas. So here we did a computer  
5 model to do a sensitivity analysis of cracking in  
6 high-density rebar. And this evaluation demonstrated  
7 that the laminar cracks are more likely to occur in  
8 regions where we have closely-spaced rebar. We did an  
9 analysis with 12-inch versus 6-inch rebar. And so that  
10 established that the rebar spacing was a probable  
11 contributing factor. And what we believe occurred was  
12 that the cracking would have been initiated in the  
13 shoulders and then propagated into some of these areas  
14 where it's more -- where it's more likely in the  
15 high-density rebar areas. And we think that occurred  
16 both in the shoulders and in the main steamline  
17 penetration block-out areas.

18 Okay. To summarize what we got from the  
19 analysis. So to summarize, the normal temperature  
20 -- when I say "normal," the extreme temperature  
21 conditions weren't sufficient to create radial stresses  
22 that could cause cracking. We did not find sufficient  
23 -- any -- high-wind was not sufficient. We did find  
24 though that this moisture freezing could cause stresses  
25 in the shoulder areas that could result in the cracking.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 So that appeared to be a plausible event that occurred.

2 We also found that the closely-spaced reinforcing steel  
3 was a -- could be a contributor to the laminar cracking.

4  
5 And then finally, the observed cracking.

6 And this is very important what we actually saw, and  
7 I'll show it in a few slides from now, the picture of  
8 our impulse response testing. What we found in the  
9 cracking very much coincides with the areas of high  
10 stress. The cracking was in the flute shoulders, in  
11 the areas of high-density rebar, and it was also  
12 concentrated on the southern exposure, which would have  
13 been the direction we would have had the storm coming  
14 from and the moisture penetration. So again, it had  
15 good correlation with this theory with the actual facts  
16 we'd obtained from investigating the shield building.

17 MEMBER ARMIJO: That southern exposure  
18 argument sure doesn't really tell me much, because  
19 that's a big storm. The whole plant's affected.  
20 Moisture's -- I'm sure it didn't rain just on one side  
21 of the building.

22 MR. BYRD: No, it rained, but the southern  
23 exposure -- the issue is the direction of the wind,  
24 because the wind was an important -- would have been  
25 an important in providing the force for the moisture

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 penetration in the shield building. And as you can see  
2 from the picture, it isn't that there's not cracking  
3 on the northern side. It's just there is more extensive  
4 cracking on the southern side of the building.

5 So finally, to go to our root cause, really  
6 there was many things, or several things acting together  
7 that caused cracking to occur. So we had the  
8 discontinuity on the shoulders with the lack of radial  
9 reinforcing rebar. We had the areas of high-density  
10 rebar. Then we had the particular storm with high  
11 moisture, severe winds and very low temperatures.  
12 However, for us to establish -- for our process and root  
13 cause it had to be something that we could eliminate  
14 to prevent recurrence. So we identified the root cause  
15 for our -- to be a lack of water sealant on the exterior  
16 of the building.

17 If you'd go to the next slide, please.

18 DR. BARTON: I've got a question on it.

19 MR. BYRD: Yes?

20 DR. BARTON: So you're going to seal the  
21 building?

22 MR. BYRD: We are in the process of doing  
23 that now. That's correct.

24 DR. BARTON: The question I've got is how  
25 do you know that there's no water trapped inside this

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 concrete before you're sealing it?

2 MR. BYRD: Well, there probably is some.

3 We have taken samples very recently. Mr. Hook, can  
4 you talk about the samples we took of the concrete?

5 MR. HOOK: Right, so there is some moisture  
6 in the concrete always. It's not like bone, bone dry.

7 But part of the root cause investigation and the  
8 sensitivity analysis that we needed to have, we need  
9 to have high moisture content in the concrete for this  
10 -- for the freezing and expansion to occur. That was  
11 in the area of 90-plus percent of concrete. So concrete  
12 breathes and normally the concrete that's out there is  
13 in the range of 40 to 60 percent. So those moisture  
14 levels are well below the threshold that's needed to  
15 cause any expansion. So when we paint the building,  
16 whatever moisture is there, it has no effect at all.

17 And also keep in mind though the inside of the wall  
18 is not painted. So that's also an opportunity for the  
19 concrete to breathe on the inside in the annulus area.

20 DR. BARTON: So you've looked at -- even  
21 though you've got some moisture in there, you've looked  
22 at weather conditions, severe weather conditions, and  
23 you're convinced that that won't cause cracking to  
24 expand?

25 MR. BYRD: That's correct. And then we're

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 following the manufacturer's instructions on how to  
2 paint the concrete. And so you need to have certain  
3 humidity and temperature requirements. And obviously  
4 you can't paint the concrete when it's wet. So we are  
5 following all of those requirements as well.

6 DR. BARTON: Thank you.

7 CHAIRMAN SIEBER: As part of your overall  
8 investigation, I notice the slide which shows the map  
9 and the path of the storm of January 1978 is pretty  
10 extensive. It covers the entire state of Michigan from  
11 Central Illinois to Gary, Indiana and about half of the  
12 State of Indiana and reaches to Toledo and appears to  
13 be on the edge of the excessive area appears to be where  
14 the Davis-Besse appears. Did anyone look at other news  
15 stories or event reporting from that storm to determine  
16 whether other structures were damaged by any kind of  
17 a phenomenon that you believe occurred here at the  
18 Davis-Besse plant?

19 MR. BYRD: Well, if your question is did  
20 we have -- did we find any other evidence of laminar  
21 cracking caused by moisture penetration, the answer  
22 would be no. The only -- and we looked pretty  
23 extensively through operating experience and what we  
24 found was this Ontario Ministry -- the information we  
25 found on the water tanks was actually online. So we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 did not find evidence specifically of cracking that was  
2 attributed to this storm.

3 CHAIRMAN SIEBER: Well, most industries  
4 don't have a reporting structure similar to that --

5 MR. BYRD: And we understand that and  
6 that's why we looked extensively. We didn't find the  
7 Ontario Ministry of Hydro through the normal reporting  
8 structures. Obviously it would be difficult, and as  
9 I mentioned in our root cause, there were some unique  
10 characteristics of Davis-Besse; the flute design and  
11 so forth, that along with this storm contributed to the  
12 laminar cracking. So -- and but there was certainly  
13 a lot of news. The storm of 1978 was a very significant  
14 event in the Midwest. So obviously at the time there  
15 was a lot of news coverage, but I don't believe there  
16 was any trouble with laminar cracking.

17 CHAIRMAN SIEBER: All right. Thank you.

18 MEMBER ARMIJO: How does your root cause  
19 explain the absence of cracking at the surface? Visible  
20 cracking. In other words, all the cracking is inside  
21 in this -- between the shoulder and the -- you know,  
22 the outer steel. But the cracks don't penetrate to  
23 let's say the notch.

24 MR. BYRD: No, and the reason --

25 MEMBER ARMIJO: And they -- you know, so

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 what's the explanation for that?

2 MR. BYRD: If we could go back to the slide  
3 that shows the rebar design of the shoulder. I'm not  
4 sure which number it is.

5 CHAIRMAN SIEBER: Way back.

6 MR. BYRD: It's pretty far back. I can  
7 explain that.

8 MEMBER ARMIJO: Twenty-one?

9 MR. BYRD: That's correct.

10 MEMBER ARMIJO: Where the hooks are?

11 MR. BYRD: Yes, the explanation is, as I  
12 mentioned, the crack occurred and it was stopped before  
13 it got to those -- that inner -- or the radial reinforcing  
14 rebar on the inside. And actually on some of these  
15 shoulders we drilled on the shoulder four core bores  
16 on the same -- at the same horizontal plane. And if  
17 you could point with your mouse, we did one core bore  
18 on the shoulder on the outside of the rebar there.

19 MEMBER ARMIJO: Yes.

20 MR. BYRD: And one on the insider. It  
21 shows we did one right here. We managed to get a core  
22 bore in there. And we do the core bore on the other  
23 side. Well, I'm sorry, we did one core bore up adjacent  
24 to the rebar here and we found we did not have cracking  
25 up beside the rebar. Then we went over. We found

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 cracking. So the crack was actually stopped by the  
2 rebar. Then on the other side we drilled the same thing.

3 We drilled a core boring here and we found no cracking  
4 right adjacent to the radial reinforcement. So we were  
5 able to demonstrate with our core bores that actually  
6 that radial reinforcement was in areas out -- like it's  
7 up on the 20 feet. The cracking would be restricted  
8 between that area. Then on the top 20 feet we found  
9 that we did have some cracking that would go outside  
10 through this area. But it didn't go beyond these hooks  
11 on the inside.

12 MEMBER ARMIJO: But you would have expected  
13 that the water penetration would be greater in near the  
14 surface?

15 MR. BYRD: That's correct.

16 MEMBER ARMIJO: And in that corner notch  
17 where you have a stress concentration, plenty of access  
18 to water. Yet it didn't crack there.

19 MR. BYRD: It didn't crack there except on  
20 the -- in the -- some areas in the top 20 feet we found  
21 cracking. But again, that cracking was along the -- in  
22 this rebar mat and again there's still a cover of  
23 concrete on that as well. So it was actually in the  
24 -- it was always covered with concrete on the cracking.

25 And that's actually -- you know, we did not -- in the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 carbonation samples we took we didn't find extensive  
2 carbonation in the crack regions either. So that would  
3 indicate that these cracks had been -- not been exposed  
4 to the air.

5 MR. ALLEN: What's unique about the design  
6 here is that if the shoulders were not present, even  
7 with the moisture, the wind, we would have had no  
8 cracking.

9 MEMBER ARMIJO: Oh, I agree with you there.

10  
11 MR. ALLEN: But discontinuity Ken talked  
12 about, rather than a right circular cylinder which can  
13 expand and contract uniformly, it's sitting there  
14 essentially shrugging with those shoulders as it's  
15 moving. And you have to have that stress concentration  
16 plus the moisture and freezing for it to be an issue.  
17 And then it propagates.

18 MEMBER ARMIJO: You know, the argument  
19 -- I'm just -- I'm skeptical about the moisture and  
20 freezing part of your root cause. The thermal analysis  
21 surprised me, that that didn't provide sufficient  
22 stress. Just -- it's a -- looks like a design flaw.  
23 Not the shield building integrity, but the flute  
24 attachments. You know, I think -- and if it isn't  
25 related to moisture, then painting isn't going to do

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 any good.

2 MR. ALLEN: Well, first of all, maybe Dr.  
3 Chiu could discuss that a little bit more from  
4 performance improvement and what we did for evaluating  
5 thermal versus moisture.

6 DR. CHIU: What was the question? Can you  
7 repeat that question?

8 MEMBER ARMIJO: Yes, you know, why isn't  
9 this -- why do you need the moisture from one event,  
10 one storm caused all this damage as opposed to it just  
11 being a design flaw and the thermal stresses over time  
12 just simply created cracks without the need for any kind  
13 of moisture?

14 DR. CHIU: I think the reason for that is  
15 because the -- as you look at a corner, we have water  
16 penetrated on both directions, goes through the  
17 crystallization of concrete, would generate a lot more  
18 expansion than thermal. It's almost a factor of three.

19 So with the water crystallization-induced expansion,  
20 it's lot more severe than thermal. You can imagine if  
21 the thermal is -- in Arizona we have so much hot weather,  
22 120 degree Fahrenheit, the fluting didn't report an  
23 crack. And we just finish another analysis at another  
24 power plant in the south that has flute. But you just  
25 look at thermal, it not going to have any laminar crack.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1       So you really need both, very high thermal expansion  
2       -- I mean, crystallization-induced expansion.

3               MEMBER ARMIJO:   Okay.   Well, near the  
4       surface I would expect more water, more crystallization  
5       so that cracks should penetrate to the surface at those  
6       notches and elsewhere, but in every case, at least the  
7       way it's been described, the cracking is varied inside.

8       It doesn't penetrate to the surface.   So I'm just  
9       -- can't understand.

10              MEMBER SHACK:   It needs constraint.   It's  
11       free to expand at the outer surface.

12              MEMBER ARMIJO:   Right.

13              MEMBER SHACK:   You know, so he has to build  
14       up constraint before he can build up some force.   So  
15       I can understand that you wouldn't see cracking at the  
16       surface.   I'd have to be somewhere underneath where I  
17       have enough restraint so I can build up a radial stress.

18       You know, in plane it's going to be compressive as it  
19       expands.   And at the outer surface it's going to be free  
20       to expand.   Somewhere in the middle, things are going  
21       to go wrong.

22              But I was -- My question is do you actually  
23       -- did you do measurements of the expansion of  
24       water-saturated concrete as it freezes, or is this some  
25       model, or you just put in enough expansion to get

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 whatever you needed?

2 DR. CHIU: We did a test. We did a test.

3 As you know, that only this type of concrete -- certain  
4 type of concrete, when the water diffuse into concrete,  
5 it can cause the crystallization-induced --

6 MEMBER SHACK: Yes, when you say "cause  
7 crystallization," are we talking about water freezing  
8 and expanding, or we're talking about a change in the  
9 concrete property?

10 DR. CHIU: Water.

11 MEMBER SHACK: Water?

12 DR. CHIU: Water.

13 MEMBER SHACK: Okay. So the --

14 DR. CHIU: And the critical point is void  
15 fraction. For typical concrete, like household, your  
16 house. The void fraction is very, very high, probably  
17 four percent, five percent. When water diffuse into  
18 the concrete, it's sort of goes away. You don't have  
19 that expansion. But when the nuclear grade, we have  
20 very, very tight void. We control the quality very  
21 well. The void fraction is like three percent, two  
22 percent. Then we have water diffuse into concrete.  
23 You would expect.

24 So what we did is we did a test at the  
25 University of Colorado by Dr. Xi and reproduced this

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 -- I call it crystallization-induced expansion. And  
2 we really reproduced that. As you drop the temperature,  
3 the thermal expansion coefficient, you will -- the  
4 concrete will shrink. By the certain temperature and  
5 certain void fraction of that concrete the -- absolutely  
6 the thermal coefficient will turn around. When that  
7 turn around, that is the problem.

8 MEMBER ARMIJO: Well, I think we'd like  
9 -- I'd like to see that test result and the analysis.

10 Because, you know, what you're saying may be fine, but  
11 it just seems that the denser concrete, smaller void  
12 fractions, the penetration rate of the water would be  
13 slowed down just doesn't seem to hang together. But  
14 maybe if I read the report, I'll understand it better.

15 MEMBER SHACK: Well, did you actually try  
16 tests with different void fractions of concrete?

17 DR. CHIU: No, we only test this concrete.

18 MEMBER SHACK: This concrete?

19 DR. CHIU: But in the Canadian paper they  
20 do alluded to that was their test with high-void fraction  
21 concrete. They don't have that denominator.

22 MEMBER ARMIJO: Okay.

23 DR. CHIU: Only in certain concrete.

24 MEMBER ARMIJO: Maybe ask, Dr. Chiu, is it  
25 your conclusion that all of this cracking happened

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 during that storm?

2 MR. BYRD: That was the conclusion of our  
3 root cause. That is correct.

4 MEMBER ARMIJO: Okay.

5 MR. BYRD: This was an event we believe that  
6 occurred during the storm.

7 MEMBER ARMIJO: And it wasn't detectable  
8 because it didn't -- never penetrated to the outside?

9 MR. BYRD: It was -- it never penetrated  
10 to the outside and it --

11 MEMBER ARMIJO: That's the thing that  
12 bothers me the most.

13 MR. BYRD: And it did not -- in our previous  
14 construction opening we had cut in 2002 or 2003, we did  
15 not cut that -- because we actually cut that construction  
16 open entirely within the confines of our -- the original  
17 construction opening, and that is not an area where we  
18 had any evidence of this kind of cracking.

19 And to further comment on your -- because  
20 what your insight was, when I first this I was completely  
21 convinced this was thermal.

22 MEMBER ARMIJO: I'm still convinced, but  
23 it's --

24 MR. BYRD: Well, because it was on the south  
25 side and I saw it there and that was what I thought.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 You know, I'll have to admit it took awhile for me to  
2 come around to this, but the very strong -- actually,  
3 I mentioned before on the -- this is no evidence of any  
4 kind of a cyclic or a fatigue-type of an event. So this  
5 occurred as one event. And that's based on actually  
6 the concrete. So not only do we have the analysis that's  
7 aligned with what we observed with the concrete -- so  
8 I just want to point that out that it appeared to be  
9 an event with enough force to have created this, and  
10 which would have been a pretty significant amount of  
11 force.

12 MEMBER ARMIJO: Okay. Well, I still would  
13 like to get a copy of that report, if it's available.

14 CHAIRMAN SIEBER: Yes, there is a root  
15 cause report.

16 MEMBER ARMIJO: Yes. Yes, particularly  
17 that test that Dr. Chiu --

18 MEMBER STETKAR: You're looking for the  
19 University of Colorado test?

20 MEMBER ARMIJO: Yes.

21 CHAIRMAN SIEBER: Yes, that's different.  
22 That's not in the report.

23 MR. BYRD: Okay. If I could move on,  
24 unless there's another question. I believe we're on  
25 slide No. 50.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           Okay. So we had identified the root cause  
2 to be a lack of concrete sealer. And for that particular  
3 root cause there was really one practical corrective  
4 action that we could take to prevent recurrence, and  
5 that was to coat the exterior of the building. And as  
6 I mentioned before, that coating is in progress right  
7 now. In fact, the photograph we have here shows some  
8 of the recent coating activities. We're at this point  
9 approximately 75 percent complete with our project to  
10 coat the entire shield building.

11           CHAIRMAN SIEBER: Yes, what's the coating  
12 material?

13           MR. BYRD: So the walls are going to be a  
14 latex acrylic primer and a styrene acrylic top coat.  
15 And the dome is a polyurethane.

16           CHAIRMAN SIEBER: Okay. So you're  
17 painting it?

18           MR. BYRD: That's correct.

19           CHAIRMAN SIEBER: Okay.

20           MR. BYRD: Next slide, please. So we also  
21 identified several additional corrective actions as a  
22 result of our root cause. And those corrective actions  
23 included completing the impulse response examinations  
24 of the shield building wall. They included performing  
25 impulse response mapping of another structure which was

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 in this case the auxiliary building to confirm the  
2 assumptions of the analysis. We did also developed and  
3 implemented a test program to establish the capability  
4 of the bond between the rebar and the concrete in the  
5 area of the laminar cracks, and we developed a long-term  
6 monitoring program. So I'll briefly describe each of  
7 these corrective actions and what we're doing in these  
8 areas.

9 MEMBER SHACK: Just a quick question on the  
10 analysis again. You said you gave up on all the regions  
11 of cracking on the lap strength.

12 MR. BYRD: That's correct.

13 MEMBER SHACK: Now, I mean, you did a full  
14 -- I mean, we keep seeing pictures of membrane-kind of  
15 regions here. Do you -- but you did a full stress  
16 analysis including the bending regions. I mean, that's  
17 why I have dense rebar at the top is I've got flexural  
18 strength up there.

19 MR. BYRD: That's correct.

20 MEMBER SHACK: And you do that -- even with  
21 the zero lap strength, you can still meet all your design  
22 requirements?

23 MR. BYRD: That is correct. That is  
24 correct. The pictures I've been showing here were done  
25 as part of the root cause, and that was done

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 independently of the analysis done for the -- to  
2 determine flexural integrity.

3 Okay. So I'll go to the next slide, which  
4 will be No. 52. So we did complete the impulse response  
5 testing on the shield building this summer. So we did  
6 all accessible areas of the shield building wall, and  
7 that was over 60,000 individual points. So you can see  
8 the work going in progress with a couple of scaffolds  
9 up on the building. And actually in this picture you  
10 can see our most recent construction opening directly  
11 under that one scaffold.

12 So what the -- going onto the next slide,  
13 please. What this impulse response testing did, it  
14 validated the original assumption that laminar cracking  
15 was generally confined to the shoulder areas, top of  
16 the building and regions of the main streamline, and it  
17 was more concentrated on the southern part of the  
18 building.

19 We also validated this by doing impulse  
20 response testing on an independent site structure and  
21 we selected a portion of the auxiliary building. And  
22 the portion we did had some of the susceptible  
23 characteristics. It was -- actually we did an area  
24 above a large opening. It was above the train bay door  
25 on the auxiliary building on the southwest side of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 building. However, the auxiliary building has -- it  
2 has a coating -- it has had a coating put on it for the  
3 life of the building. And we did not detect laminar  
4 cracking on the auxiliary building.

5 So the next slide, finally we get to this  
6 impulse response mapping -- testing map that I've been  
7 talking about. And there are a couple areas I want to  
8 point out. First of all, the magenta areas on this are  
9 areas of the building which are areas of higher mobility,  
10 and that would suggest that we have laminar cracking  
11 in those regions. And you can see that the laminar  
12 cracking is generally confined to the shoulders. YOU  
13 can see how it's going down on the shoulders. You also  
14 see it spilling out into the top 20 feet. And if you  
15 look on the lower left-hand side, you can see the azimuth  
16 down there. You see zero azimuth. That's north. And  
17 so you notice on the north side we have relatively  
18 limited cracking on the north side of the building as  
19 opposed to what we see on the south side of the building.

20 So again, the -- what we had identified here is  
21 consistent with what we saw during the -- consistent  
22 with what we developed in the root cause.

23 Okay. The next slide, please. So as I'd  
24 previously described in our analysis we did, we  
25 considered the reinforcement to be non-existent in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 regions of laminar cracking. And although we're aware  
2 that there was probably a considerable amount of  
3 concrete to bond strength in those areas, so we did  
4 develop testing at two universities, and these were  
5 developed by professors who are experts and members of  
6 the American Concrete Institute. The picture you see  
7 here is a test that's ongoing at -- that was ongoing  
8 at one of the universities. That's about a 40-foot beam  
9 there. That beam has two -- actually it has four pieces  
10 of No. 11 rebar imbedded in it and they're spliced in  
11 the center of the beam. And you can see there's  
12 hydraulic rams on either side of that beam and they're  
13 putting the -- applying force to that beam until it  
14 fails.

15 The next slide, please. So the two  
16 universities used two different methods to create the  
17 laminar cracks. At one university they used a -- they  
18 cast the beam in two halves. So we had a cold joint,  
19 or actually a weak joint down the middle on the plane  
20 of the splices on the rebar. The other university, they  
21 applied the force until they got a crack and then they  
22 relieved the force and then they reapplied force to crack  
23 it. The picture you see here is the second method, and  
24 you can see that the crack that was created is 0.02  
25 inches, which is greater than any crack we saw in the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 shield building.

2           Next slide.     So the results of the  
3 cracking, both universities demonstrated that in the  
4 area of the longer lap splices, the 120-inch lap slices  
5 on the top portions of the building, we got full  
6 capability from the rebar. In the areas where we had  
7 the shorter lap splices, the 79-inch, the results  
8 differed slightly depending on the method. At one  
9 university we got full capability. The other was very  
10 close to full.

11           So in conclusion, what we could determine  
12 was -- first of all, we did testing at two different  
13 sites using two different methodologies that were  
14 independently developed so we had very confidence in  
15 the results of what we'd obtained. Tests demonstrated  
16 that there was considerable bond strength remaining  
17 between the concrete and the rebar in these regions of  
18 cracking. And the testing was also conservative and  
19 the -- as I mentioned before when we created this beam  
20 we had two lap splices right in the area where we were  
21 applying the stress. The way the building was actually  
22 designed these were staggered, so you have a lap splice  
23 and you have a -- then you have rebar that's continuous.  
24       So the results we have are conservative actually to  
25 the actual design of the building.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 All right. Finally, I'll go to my last  
2 slide here for the shield building, we established a  
3 long-term monitoring program. Now as I mentioned  
4 before, we had concluded that the laminar cracking is  
5 based on an event rather than an aging mechanism and,  
6 you know, that conclusion is supported by the concrete  
7 testing we performed. It's also supported by the  
8 analysis. However, you know, we've also monitored the  
9 shield building. We've monitored the shield building  
10 cracks now three times. We've monitored existing core  
11 bores three times since we started up back in December  
12 and we've noticed no change in either un-cracked or  
13 cracked core bores that we've investigated.

14 So though we don't expect this cracking to  
15 propagate, we do -- we are putting in place a long-term  
16 monitoring program and that building will -- and that  
17 program rather will inspect existing core bores for  
18 crack propagation. So we'll be inspecting core bores  
19 that are cracked to determine if the cracks changes and  
20 we'll also being inspecting core bores that are  
21 un-cracked and generally we're inspecting ones that are  
22 adjacent to each other so we could see if there was any  
23 change. We're also inspecting the integrity of the  
24 shield building coatings and inspecting the integrity  
25 of the coatings of other safety-related buildings.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1           And our picture here shows a couple of our  
2 engineers who are monitoring an existing core bore for  
3 any change that we would see in the cracking or the  
4 monitoring of the boroscope.

5           So that would complete my discussion on the  
6 shield building. Unless there's any further questions,  
7 I will turn it back over to Mr. Custer here.

8           MR. CUSTER: Yes, and as Ken had said, the  
9 essence of the program is as he described; monitoring  
10 more cracking in the core bores and looking at the  
11 protective coating. That aging management program has  
12 been submitted to the staff for review.

13           So in summary, the application's been  
14 reviewed, in many cases reviewed to NUREG-1801 Rev 2.

15           There are 43 aging management programs that have been  
16 identified, 49 commitments, site owners and subject  
17 matter experts have been involved in the development  
18 of the application, inspections and audits and  
19 responses, all of the SER open items are currently under  
20 review by the NRC staff, and the proposed programs  
21 address the aging management of Davis-Besse for the  
22 period of extended operations.

23           DR. BARTON: Let me ask you a question.  
24 You're within the five-year window of license extension.

25           MR. CUSTER: That's correct.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 DR. BARTON: There's a lot of the aging  
2 management programs that say within five years, within  
3 six years we're going to implement this program. How  
4 many of those have you implemented?

5 MR. CUSTER: Well, actually we just got our  
6 final SER in July. Okay? So certainly this program  
7 on the shield building --

8 DR. BARTON: I'm not clear that one.

9 MR. CUSTER: Okay.

10 DR. BARTON: All the other ones that fall  
11 within this five or six-year window.

12 MR. CUSTER: None of the new programs have  
13 been implemented as --

14 DR. BARTON: None of them? So you got a  
15 whole bunch of programs within that window that you got  
16 to do?

17 MR. CUSTER: That's correct. That's  
18 correct.

19 DR. BARTON: Well, good luck.

20 CHAIRMAN SIEBER: That's rather typical of  
21 license renewal activities and licensees use the time  
22 between the granting of the reviewed license and the  
23 start of the extended period. That's their time to  
24 prepare these programs and get them started, that they  
25 must be established by the time of the extended period

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 of operation.

2 I'd like to take this time to ask the members  
3 if they have additional questions. John, you indicated  
4 that you had some?

5 MEMBER STETKAR: Yes, I do. I have a  
6 number though, Jack, and it may be better for us to take  
7 a break and come back and address those other issues.

8 CHAIRMAN SIEBER: Okay.

9 MEMBER STETKAR: Because if I start asking  
10 questions, we'll --

11 CHAIRMAN SIEBER: We won't get a break.

12 MEMBER STETKAR: You know me well enough  
13 by now.

14 CHAIRMAN SIEBER: We'll be broken.

15 MEMBER STETKAR: And I think John has some  
16 also.

17 CHAIRMAN SIEBER: Okay. And actually I  
18 think that's a pretty good idea. According to my watch,  
19 why don't we -- according to the clock on the wall, we'll  
20 come back at quarter to 11:00. So we're in recess now.

21 (Whereupon, the above-entitled matter went  
22 off the record at 10:24 a.m. and resumed at 10:44 a.m.)

23 CHAIRMAN SIEBER: Okay. At this time  
24 we'll resume our session with the applicant for  
25 Davis-Besse. And we were at the point where we were

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 inviting questions from ACRS members. John?

2 MEMBER STETKAR: Yes, I'm just going to  
3 walk through there. There's no real rhyme or reason,  
4 because I just wrote these down as I went through the  
5 reports.

6 In the scoping analysis you have some  
7 safety-related equipment out in the turbine building,  
8 and what I focused on in particular were the start-up  
9 feedwater pump control valves, I guess. And arguments  
10 were -- this is regarding effects of non-safety  
11 equipment located in the vicinity of safety-related  
12 equipment.

13 CHAIRMAN SIEBER: 2 over 1.

14 MEMBER STETKAR: 2 over -- seismic 2 over  
15 1 or, you know, leaks or what -- any kind of impacts  
16 that you could think about. The argument was made that  
17 those valves failed in the open position and therefore  
18 no damage from non-safety equipment could prevent them  
19 from performing that function. I have no idea how your  
20 start-up feedwater system is designed. I didn't have  
21 enough time to do that level of research. If those  
22 valves are failed open and you can't close them, how  
23 do you prevent overfilling your steam generators and  
24 isolating a lot of other things like auxiliary feedwater  
25 or whatever you call it?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. BYRD: Well, first of all, I think the  
2 valves you're referring to -- you've mentioned these  
3 start-up feedwater. That is -- you're probably meaning  
4 the motor-driven feed pump, I believe.

5 MEMBER STETKAR: I don't know. It's only  
6 -- in what I read, it was characterized as the start-up  
7 --

8 MR. BYRD: We had a start-up feed pump that  
9 -- and we had a motor-driven feed pump which would have  
10 a level control valve. That start-up feed pump though  
11 is not a pump that's going to be starting. That's a  
12 manually-started valve pump, so the --

13 MEMBER STETKAR: Let me help. Before you  
14 -- because I'll tell you entirely the sum contents of  
15 what I know. And this was a quote that I read actually  
16 in the SER, so it's a paraphrase from I guess a response  
17 to an RAI. For your reference, it's RAI 2.1-1. And  
18 it says the safety-related components of the start-up  
19 feedwater pump and auxiliary system that are located  
20 in the turbine building are the position controllers  
21 for control valves DBFV-6459 and DBFV-6460 shown on  
22 license renewal drawing LRMO-06D. These control valves  
23 fail open and the valve position controller is energized  
24 to close the valves so the associated control valve opens  
25 on a loss of signal from the controller. That's all

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 I know.

2 From that context it sounds like those  
3 valves are safety-related valves that are designed to  
4 fail -- control valves that are designed to fail open.

5 I don't know exactly if they are directly associated  
6 with the start-up feedwater pump. It's just the context  
7 of that quote led me to believe that they are. And I  
8 know some plants actually have qualified their start-up  
9 feedwater pump as a safety-related source of water  
10 supply. As I said, I have no idea how your plant is  
11 designed.

12 And the question I had is if those valves  
13 indeed do fail open, what protection do you have against  
14 overflow of the steam generator? And if the steam  
15 generator does overflow, does that also isolate  
16 safety-related water -- other safety-related water  
17 supplies, or the only safety-related water supplies?

18 In other words, is the closure function of those valves  
19 also required?

20 CHAIRMAN SIEBER: Yes, I might point out  
21 that in some plants the start-up feed up is also an  
22 alternate auxiliary feed pump.

23 MEMBER STETKAR: Yes, that's -- I've seen  
24 that. That's -- yes.

25 CHAIRMAN SIEBER: And you need to tell us

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 in the case of Davis-Besse whether the start-up feed  
2 pump is used in that capacity or not.

3 MR. BYRD: So we have a -- we do have a  
4 start-up feed pump which is not used in that capacity.

5 We also have a motor-driven feed pump which is used  
6 as an alternate auxiliary feedwater pump, however, it  
7 is a -- it is only manually initiated. So in other words,  
8 it's the -- our steam feed rupture control system would  
9 only manually initiate our two steam-driven auxiliary  
10 feedwater pumps. Now the two auxiliary -- the two  
11 steam-driven auxiliary feedwater pumps are actually  
12 located in the auxiliary building. They're located in  
13 -- they have their own room, which is actually accessed  
14 through the turbine building, but it is a part of the  
15 auxiliary building. So the particular valves which  
16 would be controlling from the auxiliary feedwater pumps  
17 would be contained with the auxiliary building.

18 MEMBER STETKAR: Well, I guess my question  
19 is then is there a concern with these two particular  
20 valves that I've cited, because as I said, the only thing  
21 that I've read leads me to believe that for some reason  
22 they're safety-related valves. And not having a flow  
23 diagram of your systems, I couldn't go find out what  
24 those valves --

25 MR. BYRD: Yes, discussing the overfilling

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 issue, if I could have Dennis Blakely, our analysis  
2 supervisor -- I think he could provide a little bit more  
3 of that, how we analyzed the overflow.

4 MEMBER STETKAR: By the way, if you don't  
5 have a quick answer, we're here all day. You know, you  
6 can do some homework over lunch.

7 MR. BYRD: That's right. Just trying to  
8 understand the question.

9 MR. BLAKELY: I'm Dennis Blakely, the  
10 engineering analysis supervisor. The auxiliary  
11 feedwater pumps, as Ken said, are located in a separate  
12 -- or separate rooms of the auxiliary building and they  
13 have level control valves associated with them and they  
14 are protected -- they are within those auxiliary feed  
15 pump rooms.

16 The valves you're referring to are  
17 associated with the motor-driven feed pump, which is  
18 a manually started pump. And the boundary for the  
19 system would include check valves that would prevent  
20 overfeed.

21 Now, the operators also have the capability  
22 to shut off the motor-driven feed pump if those valves  
23 would fail open, if they had started it. Okay?

24 MEMBER STETKAR: If they had -- but --

25 MR. BLAKELY: But they -- that pump is not

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 relied upon within the safety analysis for the  
2 mitigation of accidents. So those valves are also not  
3 relied upon.

4 CHAIRMAN SIEBER: Is that pump used during  
5 normal operation?

6 MR. BLAKELY: It's used for -- in normal  
7 operations for plant start-up and shutdown. But in that  
8 case it's a line to the main feedwater system rather  
9 than to the auxiliary feedwater system, so it's going  
10 in the main feedwater headers of the steam generators  
11 rather than the auxiliary feedwater header.

12 CHAIRMAN SIEBER: And when you get to a  
13 certain power level that pump just shuts down?

14 MR. BLAKELY: Once the main feed pumps are  
15 started up and supporting plant operations, the  
16 motor-driven feed pump is shut down and realigned to  
17 the auxiliary feedwater pump so that it's available for  
18 the operator should they need it.

19 CHAIRMAN SIEBER: And that occurs at what,  
20 20 percent power? Is that about --

21 MR. BLAKELY: Approximately. Yes, sir.

22 CHAIRMAN SIEBER: Okay.

23 MEMBER STETKAR: Okay. Thank you. That  
24 solves my question about that.

25 I have several notes here, and if you'd just

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 bear with me because in the interest of time I'll try  
2 to do some screening.

3           The bolting integrity program. There's  
4 some discussion in the SER and responses to RAIs about  
5 your examination program for high-strength bolting.  
6 And the response that I read said the applicant further  
7 stated in response to RAI B.2.4-1, that volumetric or  
8 surface examinations are not currently conducted to  
9 detect stress corrosion cracking on bolts; these are  
10 high-strength bolts, since no instances of failed  
11 bolting of bolted connections due to stress corrosion  
12 cracking had occurred at Davis-Besse. Applicant stated  
13 that visual examinations of structural components will  
14 detect corrosion or corrosive environment that leads  
15 to stress corrosion cracking.

16           I'm not a materials person; I may need help  
17 from our materials people here, but it seems to me just  
18 because you haven't had any fails -- failures doesn't  
19 provide me a lot of confidence that you shouldn't check  
20 for conditions that might cause cracking. And I know  
21 that your reactor vessel head closure studs are high  
22 strength material. What other bolts in the plant are  
23 those high-strength materials?

24           MR. BYRD: I'll ask my core team. Do we  
25 have a response to that that we can provide right now?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. KOSLOFF: Don Kosloff with the core  
2 team. I'm the civil structural lead.

3 I've looked at several drawings and we have  
4 quite a few structural bolts that are high- strength.

5 MEMBER STETKAR: That are high-strength?

6 MR. KOSLOFF: It would be difficult to give  
7 a list --

8 MEMBER STETKAR: Okay.

9 MR. KOSLOFF: -- of how many there are, but  
10 there are quite a number of them.

11 MEMBER STETKAR: Let me ask our other two  
12 -- Dr. Armijo and Dr. Shack, because I am now well past  
13 anything that I know anything about. Are surface visual  
14 inspections adequate?

15 MEMBER ARMIJO: Have to be pretty severe.

16 MEMBER STETKAR: I mean, the Yale report  
17 recommends volumetric examination.

18 MEMBER ARMIJO: Yes. Yes.

19 MEMBER STETKAR: That's --

20 MEMBER ARMIJO: Sometimes people do  
21 penetrating exams.

22 MEMBER STETKAR: Yes.

23 MEMBER ARMIJO: But, no, if you really  
24 thought you had a cracking thing potential --

25 MEMBER SHACK: You'd want to get it before

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 it failed.

2 MEMBER ARMIJO: That's right. Right,  
3 they're not --

4 MEMBER STETKAR: Oh, but they're just  
5 volumetric. They're proposing simple, right, you know,  
6 visual --

7 MR. BYRD: I think we have our bolting  
8 engineer here. I turn -- I'm sorry, Jake Hofelich?

9 MR. HOFELICH: Jake Hofelich, ISI program  
10 owner. Some of the bolting is examined ultrasonically.  
11 The bolting within the section 11 ISI program, the  
12 reactor head closure studs in particular, each stud is  
13 examined each 10-year --

14 MEMBER STETKAR: Yes, I read that.

15 MR. HOFELICH: And also the other systems,  
16 class 1, 2 and 3 systems are pressure tested and we look  
17 for any evidence of degradation or any leaks that would  
18 be a result of any cracking in the bolting.

19 MEMBER STETKAR: Yes, but that's after the  
20 failure has occurred.

21 MR. HOFELICH: Correct.

22 MEMBER ARMIJO: What's your history with  
23 those bolts?

24 MR. HOFELICH: We have not had any cracking  
25 indications in the record at closure sites.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MEMBER ARMIJO: I saw the magic words "moly  
2 disulfide" somewhere. I keep wondering. I thought  
3 that disappeared when I was a young man, younger than  
4 you.

5 MR. HOFELICH: The lubricant that we  
6 previously used contained molybdenum disulfide. And  
7 one of the commitments in our license renewal  
8 application is to preclude the use of that reactor head  
9 closure studs.

10 MEMBER ARMIJO: Better late than never.

11 MEMBER STETKAR: I'll have to think about  
12 that one. Buried piping. I understand that your diesel  
13 fuel oil piping is cathodically protected, right? And  
14 you're upgrading that system, is that correct?

15 MR. BYRD: That's correct.

16 MEMBER STETKAR: And you're going -- are  
17 you going to protect -- provide cathodic protection for  
18 the service water piping?

19 MR. BYRD: To discuss our buried piping,  
20 we have our program owner Frank Zurvalec here.

21 MR. ZURVALEC: My name is Frank Zurvalec.  
22 I'm the buried pipe program owner at Davis-Besse. And  
23 our cathodic protection system is approximately 30 -- or  
24 70 percent complete, the restoration. We spent  
25 approximately \$2 million. We still have one phase left

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 to go. Currently the diesel fire pump piping, buried  
2 piping is cathodically protected. That was installed  
3 either this year or last year.

4 DR. BARTON: How effective is the cathodic  
5 protection system that you do have installed? I know  
6 you're still working on it, that you've got some  
7 installed. How effective is it?

8 MR. ZURVALEC: We monitor it for the base  
9 guidelines monthly voltage current readings and also  
10 yearly ground potential readings.

11 DR. BARTON: Ninety, ninety-five percent  
12 effective, or --

13 MR. ZURVALEC: I don't have that number.  
14 The cathodic protection engineer is back at our site,  
15 but I would argue at least 99 percent.

16 MEMBER STETKAR: I'm not sure you answered  
17 my question. I was asking you about the service water  
18 piping.

19 MR. ZURVALEC: Service water? I thought  
20 diesel fire pump.

21 MEMBER STETKAR: No, I --

22 MR. ZURVALEC: Our service water piping  
23 that's been scoped is cathodically protected at this  
24 time.

25 MEMBER STETKAR: At this time? But it has

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 not in the past, is that correct?

2 MR. ZURVALEC: The service water cathodic  
3 protection was reestablished again either this year or  
4 last year reestablished.

5 MEMBER STETKAR: Oh, it did have cathodic  
6 protection in -- at --

7 MR. ZURVALEC: At one time it did. It had  
8 fallen into a state of disrepair.

9 MEMBER STETKAR: Okay.

10 MR. ZURVALEC: But our plans are to  
11 cathodically protect all of the buried lines within the  
12 protected area. All of the pipes, all of the buried  
13 lines within the scope of the license renewal are  
14 currently cathodically protected.

15 CHAIRMAN SIEBER: How long in the history  
16 of Davis-Besse did the plant go without serviceable  
17 cathodic protection?

18 MR. ZURVALEC: I would argue the vast  
19 majority of time. I do not have those details, but  
20 originally after construction and start-up the cathodic  
21 protection system fell into disarray and was not  
22 maintained properly. Through industry discussions and  
23 the shared operating experience at the license renewal,  
24 I think the industry has embraced the idea that cathodic  
25 protection is an integral part of the health of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 buried piping system and must be reestablished and  
2 maintained.

3 CHAIRMAN SIEBER: So you probably got 25-30  
4 years of issues with the buried piping where you did  
5 not have protection established?

6 MR. ZURVALEC: That's a good estimate, but  
7 again with our buried pipe program we are doing  
8 inspections of the line that we have, opportunistic  
9 inspections. I do not see a degraded condition. As  
10 long as the coating is intact, we did not have to rely  
11 upon the cathodic protection system. It's only when  
12 that coating has been degraded or damaged that will cause  
13 a problem, and that's what that cathodic protection  
14 system is for.

15 CHAIRMAN SIEBER: Okay. That's  
16 degradation from the exterior of the pipe?

17 MR. ZURVALEC: That's correct.

18 CHAIRMAN SIEBER: Have you done  
19 examinations of -- other than opportunistic where you  
20 actually physically go down and make measurements on  
21 the pipe in the -- including wall thickness and --

22 MR. ZURVALEC: Yes, sir.

23 CHAIRMAN SIEBER: -- the interior surface?

24 MR. ZURVALEC: Direct examinations.

25 We've performed direct examinations of our -- some of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 our service water piping, various pipings. And the  
2 coating that I've seen has all been intact. It's not  
3 delaminated. It's not cracking. We have removed some  
4 coating to perform ultrasonic examinations. Then we  
5 establish that coating again. But there has been -- the  
6 pipe that I've inspected is in new condition.

7 MEMBER STETKAR: It's also service water?

8 I mean, there's a lot of focus on --

9 MR. ZURVALEC: It includes portions of the  
10 service water system.

11 MEMBER STETKAR: Okay. Okay.

12 MR. BYRD: Just to make sure you  
13 understand, the main service water discharge and supply  
14 headers are actually in a tunnel, so they're not buried.

15  
16 MEMBER STETKAR: So it's an underground?

17 MR. BYRD: It's underground, but it's in  
18 a tunnel. Okay?

19 MEMBER STETKAR: Okay. Thank you. Let me  
20 make a note here.

21 Kind of following up, the -- I couldn't  
22 follow the story -- there's a story about materials in  
23 your firewater system that are copper alloy with zinc.

24 And originally, as I understand it, inspections of that  
25 material for possible stress corrosion cracking were

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 in one of the programs. I don't have my whole list here.

2 It was in one program, but the staff had questions about  
3 it. You said, well, we'll take it out of the program.

4 And then it kind of popped up in another one and it  
5 was taken out of there. I can't find now any --

6 DR. BARTON: It's in an aging --

7 MEMBER STETKAR: Now we're --

8 DR. BARTON: It's in aging management  
9 program now, fire --

10 MEMBER STETKAR: Where? Well, but not -- I  
11 don't think for these alloys.

12 DR. BARTON: Oh, no, it's --

13 MEMBER STETKAR: That's -- what I want  
14 -- the whole key, I think, is, as I finally walk my way  
15 through all of this, in an initial response it says the  
16 applicant also stated that they could not verify the  
17 absence of ammonia in it's raw water source to be below  
18 a threshold concentration in which cracking would not  
19 be a concern. There are several negatives there, but  
20 basically it says you couldn't -- you thought there might  
21 be enough ammonia to cause cracking. And then as I  
22 understand it, all of the following discussions wherever  
23 it pops up and questions were asked, you finally said  
24 that operating experience did not identify ammonia or  
25 ammonium salt in the raw water or cracking of comparable

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 alloys in the associated system. Do you know that you  
2 don't have raw water chemistry that would facilitate  
3 cracking in that material?

4 MR. BYRD: We have Alvin Dawson here, our  
5 chemistry manager who can --

6 MEMBER STETKAR: Beyond a shadow of a  
7 doubt?

8 MR. DAWSON: Alvin Dawson, chemistry  
9 manager. In answer to your question, yes, we know.  
10 We drew samples on our raw water system both going in  
11 and going out after that question was raised. All those  
12 samples were sent out for analysis and we have no ammonia  
13 --

14 MEMBER STETKAR: Okay.

15 MR. DAWSON: -- in our raw water system.

16 MEMBER STETKAR: Thank you. Ground water.  
17 Asked a little about groundwater earlier with regard  
18 to the containment shell and I wanted to follow up on  
19 a couple of other things.

20 You've committed to sample the groundwater  
21 system during a period of extended operation at least  
22 once every five years. Do you have in place and have  
23 you had during the operating history of Davis-Besse a  
24 groundwater sampling program? In other words, you've  
25 committed to something. Sample every five years means

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 you get three or four during the period of extended  
2 operation to look for trends in the groundwater  
3 chemistry. Do you have any idea about past trends in  
4 the groundwater chemistry?

5 MR. BYRD: Yes, we do and Alvin Dawson here  
6 would be able to explain that.

7 MR. DAWSON: Again, Alvin Dawson,  
8 chemistry manager. We have had a groundwater system  
9 -- a groundwater sampling system in place at Davis-Besse  
10 for a number of years. In 2007, when NEI 07-07 came  
11 out, we instituted a more rigid groundwater sampling  
12 program. Right now we sample groundwater every six  
13 months for tritium and hard gamma emitters and different  
14 species that we're interested in. We sample every six  
15 months and if --

16 MEMBER STETKAR: Do you sample for  
17 chloride, sulfates and pH? I'm not interested in  
18 sampling for radionuclides. I'm interested in sampling  
19 for water chemistry, aggressive water chemistry.

20 MR. DAWSON: Oh, you're referring to the  
21 five-year commitment for water chemistry?

22 MEMBER STETKAR: That's -- yes.

23 MR. DAWSON: We do -- on that five-year  
24 basis we sample for -- we do sample for pH on a regular  
25 basis, but for chlorides and sulfates we do sample every

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 five years.

2 MEMBER STETKAR: Has that been done in the  
3 past during the last 35 years of operation, or is that  
4 just something you're going to start in 2017?

5 MR. BYRD: Alvin, I think Donald has  
6 something to add to that. Don Kosloff?

7 MR. KOSLOFF: Yes, there's a bit of  
8 confusion in the SER.

9 MEMBER STETKAR: Okay.

10 MR. KOSLOFF: Donald Kosloff, license  
11 renewal core team, structural civil engineer. We  
12 followed GALL Rev 1 in our application, which required  
13 sampling of groundwater if the groundwater is  
14 non-aggressive. It had no requirement for sampling if  
15 the water was determined to be aggressive. We  
16 determined that the groundwater was aggressive and we  
17 did not commit to sample groundwater. We committed to  
18 sample raw water; i.e., lake water because the lake water  
19 is non-aggressive and we want to monitor that to make  
20 sure that it doesn't become aggressive.

21 MEMBER STETKAR: That's -- I didn't want  
22 to bring that up, but I saw the commitment to sample  
23 raw water and I thought that might have been a typo.  
24 Apparently it's not. Apparently that response was  
25 very carefully worded.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1           So you're not actually going to sample  
2 groundwater to determine its chemistry?

3           MR. KOSLOFF: There is no plan at this time  
4 to sample groundwater for sulfates, chlorides or pH.

5           MEMBER STETKAR: Okay. So you're just  
6 going to rely on your basic opportunistic inspections  
7 of below-grade structures whenever they're exposed.  
8 And as I -- and I wanted to ask you about -- I know you're  
9 going to take a couple of core bores --

10          MR. KOSLOFF: Right.

11          MEMBER STETKAR: -- from the turbine  
12 building and the ECCS pump room, I guess. Let me ask  
13 about the core bores. The groundwater level, as I  
14 understand it, nominal is about 570 feet, is that right?

15          MR. KOSLOFF: That's correct. Dick Bair  
16 of our structural engineering group can provide a more  
17 detailed answer on that.

18          MEMBER STETKAR: Okay.

19          MR. BAIR: Richard Bair, design  
20 engineering. As you stated, we are planning on taking  
21 two of the core bores; one in our turbine building, one  
22 in our ECCS pump room, which is in the auxiliary  
23 building. Those cores will be taken deep into the  
24 structure so we can access the portion of the concrete  
25 most likely to potentially be affected by the aggressive

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 groundwater. We will be testing that in concrete and  
2 our commitment -- we have a license renewal commitment  
3 to perform these two initial core bores by the end of  
4 2014. And we have additional commitments to perform  
5 core bores in the future if groundwater infiltration  
6 persists. I plan on entering the information from these  
7 core bores into our corrective action program for  
8 tracking and that will also allow us to initiate any  
9 additional corrective actions that may be necessary for  
10 this condition.

11 MEMBER STETKAR: Thank you. You said the  
12 core bores are going to be deep. Any estimate of  
13 -- because you're boring from the interior going out,  
14 you'd expect the problem if there is any to be  
15 progressing from the exterior in. So will they go  
16 completely through wall, or --

17 MR. BAIR: No, we're not planning on going  
18 completely through wall. We're planning on going to  
19 approximately the lowest -- in the case of the ECCS pump  
20 room, we'll be going through the actual foundation mat  
21 of the auxiliary building. So we'd be going to  
22 approximately the depth of the bottom rebar mat. And  
23 in the turbine building it would be on walls, so we would  
24 be core boring approximately to the location of the outer  
25 rebar mat, which would be -- leave a couple inches of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 concrete in each one of those locations.

2 MEMBER STETKAR: Okay. Bear with me here.

3 I've got one more question. I'm a slow writer.

4 One last simple question: And in the  
5 turbine building, at least again from what I've read  
6 said that the core bore would be at the turbine building  
7 condenser pit at approximately elevation 573, which as  
8 I understand is about 3 feet above groundwater level.

9 Why not below groundwater level in the turbine  
10 building, or is that a typo?

11 MR. BAIR: Offhand I'm not sure how we  
12 selected that specific elevation. We will be taking  
13 one at a sufficiently low elevation to ensure that we're  
14 getting a portion of the structure that potentially had  
15 been affected by the aggressive groundwater.

16 MEMBER STETKAR: Okay. You may want to  
17 check that. I pulled that out --

18 MR. BAIR: Okay.

19 MEMBER STETKAR: It's in the SER. It could  
20 be a typo. I recognize -- we don't get all of the RAIs  
21 and the responses, nor do we want them. We have enough  
22 to read.

23 MR. BAIR: Right.

24 MEMBER STETKAR: And sometimes things get  
25 paraphrased a little bit.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BAIR: As I prepare the engineering  
2 change package for these core drills, I will double check  
3 that. I will be sure it's --

4 MEMBER STETKAR: Yes, it's just --

5 MR. BAIR: -- sufficiently low to capture  
6 the zone affected by the aggressive groundwater.

7 MEMBER STETKAR: Okay. Thank you. Two  
8 more: You've had some slope slippage -- or I'm not a  
9 geotechnical engineer, so I don't know the correct terms  
10 -- in your intake canals. Can you tell us -- and I know  
11 you've done a bunch of analyses that -- you had divers  
12 go down. They say the tow hasn't come out. apparently  
13 a couple of geotechnical analyses came back. As I  
14 understand, it was sort of differing opinions about  
15 the current condition of the intake canal. Can you show  
16 us -- there was one photograph. What's the extent of  
17 that area that slipped --

18 MR. BYRD: Do we have --

19 MEMBER STETKAR: -- in terms of --

20 MR. BYRD: We have --

21 MEMBER STETKAR: Yes, that's the  
22 photograph I was looking --

23 MR. BYRD: -- Joe Brunkhorst here who can  
24 explain this for us.

25 MR. BRUNKHORST: Joe Brunkhorst,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 structures monitoring program owner. Would you like  
2 me to come up front and point --

3 MEMBER STETKAR: It would help. I mean,  
4 if you have a -- but the problem is you have to be near  
5 a microphone or a --

6 MR. BRUNKHORST: I understand.

7 CHAIRMAN SIEBER: Yes, you may want to do  
8 it with a mouse.

9 MR. BRUNKHORST: Okay. So the intake  
10 canal entire length is approximately 2,700 feet, and  
11 the Q-safety-related forebay is about 700 foot long from  
12 the face of the intake structure. So approximately  
13 right where the hand is there's an area -- two areas  
14 that are side by side that equal approximately 150 feet  
15 where this localized settlement is taking place.

16 MEMBER STETKAR: And then we say -- when  
17 you say "localized settlement," is it an actual slip,  
18 or is it a -- what's the configuration?

19 MR. BRUNKHORST: It's more -- it's a shelf.  
20 It's more --

21 MEMBER STETKAR: Okay.

22 MR. BRUNKHORST: It's created more of a  
23 shelf and it's actually settled down more between the  
24 top of the bank and the edge of the water. That's what  
25 the diver confirmed with the tow of the --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER STETKAR: So you actually haven't  
2 seen a slip?

3 MR. BRUNKHORST: There has been some minor  
4 slippage into the canal. We had a slope stability study  
5 recently finalized where they had installed two sloping  
6 inclinometers into two of the cores that were installed  
7 and they over a six-month period saw minimal movement  
8 in a magnitude of approximately a quarter of an inch.  
9 So what that did though confirm is where exactly that  
10 failure plane was in the canal.

11 MEMBER STETKAR: So you have confidence and  
12 you understand where the failure point is?

13 MR. BRUNKHORST: Yes. Yes.

14 DR. BARTON: Do you have some work  
15 scheduled to do in the intake canal in that area?

16 MR. BRUNKHORST: Yes. Yes, we're  
17 currently putting together the engineering change  
18 package to make a repair to that area.

19 MEMBER STETKAR: Do you know what you're  
20 going to do with it?

21 MR. BRUNKHORST: The current repair option  
22 that's being pursued to actually install sheet pile in  
23 the area.

24 MEMBER STETKAR: Okay.

25 DR. BARTON: I don't know, on the intake

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 now while you're -- want me throw it in here? The  
2 description says you have water protection dikes that  
3 are seismic class 2 earthen dikes constructed of  
4 topsoil. My question is, you know, what prevents  
5 washout of the topsoil in the event of severe wave action  
6 in your intake? What am I missing here?

7 MR. BRUNKHORST: The entire length of the  
8 canal is protected by riprap. I mean, as far as  
9 wash-away from normal erosion factors, I mean, it's  
10 protected by armor stone riprap. Yes, on both sides  
11 of the canal, both sides of the dike.

12 DR. BARTON: So that's protecting this  
13 topsoil from getting washed out, the riprap on the side?

14  
15 MR. BRUNKHORST: Right.

16 DR. BARTON: Got you. All right. That  
17 was it, John.

18 MEMBER STETKAR: Good, John? I only have  
19 one more. For your environmentally-adjusted usage  
20 factors in your fatigue monitoring program, I understand  
21 how you -- first of all, I understand that you're  
22 basically using a counter, a count -- a cycle counting  
23 process primarily to -- as the primary means of keeping  
24 track of this. And I read, you know, how you  
25 extrapolated the past operating experience linearly to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 come up with your number -- projected number of cycles  
2 of 60 years, except for the pressurizer surge line, which  
3 has an environmentally-adjusted cumulative usage factor  
4 of 0.996, I believe. And what I've read is -- said,  
5 well, with the nominal number of heat-up/cool-down  
6 cycles of 128, which is projected just using a linear  
7 extrapolation from the historical data you couldn't meet  
8 the project cumulative usage factor of less than 1.0.

9 As it's characterized at least in the SER summary of  
10 the RAI, it says that the applicant stated that  
11 alternatively it used a best estimate 60-year projected  
12 cycle for heat-up/cool-down cycles which is based on  
13 more recent operating experience compared to the entire  
14 operation history of the plant. This resulted in a best  
15 estimate 60-year projected cycles of 114 cycles for the  
16 heat-up/cool-down transients.

17 My background is risk assessment and  
18 uncertainty analysis, so I'll cast it in this context:

19 when I think of a best estimate analysis, I think of  
20 -- some people think of median, some people of means,  
21 but it's something that I've done an analysis, looked  
22 at variability and uncertainty and derived a value that  
23 I feel is my best estimate.

24 Could you explain to me; and probably not  
25 in this venue -- what I'm interested in is what is the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 extent of your more recent operating experience and what  
2 analyses did you use to actually derive this best  
3 estimate which miraculously just gets you below 1.0?

4 MR. CUSTER: I ask my team member Larry  
5 Hinkle to --

6 MEMBER STETKAR: Because that's just  
7 really, really surprising that it would just get you  
8 below 1.0 if it's a best estimate.

9 MR. CUSTER: 0.998?

10 MEMBER STETKAR: 0.996 I think it is, not  
11 0.988. It's 0.996. They gave them --

12 MR. HINKLE: I'm Larry Hinkle with the  
13 license renewal project team. That was based on cycles  
14 accrued since approximately 2008 -- excuse me, accrued  
15 since approximately 2000 up to present day. When we  
16 say "best estimate," it was based on the rate of  
17 occurrence since that time frame. And there's a slight  
18 bit of margin added in there --

19 MEMBER STETKAR: Okay.

20 MR. HINKLE: -- but the most part it was  
21 a -- it was just based on the rate of occurrence.

22 MEMBER STETKAR: We'll do this as a  
23 take-away. What I'd like to see is your historical plot  
24 or tabulation of number of heat-up and cool-down cycles  
25 per year over the entire life of the plant so that I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 can see what the slopes look like. And if you have  
2 documentation of how you did that extrapolation, what  
3 margins, I'd be interested in that. It's just really  
4 surprising to me that it worked out to this miraculously  
5 getting you just below the limit. Oftentimes when you  
6 look at variability and uncertainty, you know, if you  
7 included one more year in the experience, you might not  
8 have had that.

9 MR. HINKLE: Understood.

10 MEMBER STETKAR: So I'd really like to see  
11 what those slopes look like and how you did that.

12 MR. HINKLE: Okay. At the time that this  
13 occurred AREVA was performing the evaluations for us,  
14 and they contacted me personally. I was the TLAA lead.

15 And basically they told me -- well, they told me the  
16 number of cycles it would take to be able to pass this  
17 say under 1.0. However, from there, right, I went in  
18 and I personally looked at the cycles that occurred from  
19 2000 up to present day at that time of the phone call,  
20 which was a couple years ago here now.

21 MEMBER STETKAR: Yes.

22 MR. HINKLE: We looked at those cycles.  
23 And then from there I determined that I could even come  
24 up with a lower number than what they needed. And so  
25 I added some margin back in just to account for some

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 unknowns and things that might occur down the way that  
2 we didn't anticipate.

3 MEMBER STETKAR: The only -- and in some  
4 sense this is a bit of a moot point because I understand  
5 you're just setting a speed limit for yourself and  
6 essentially it's -- on my street the speed limit is 30  
7 and on the next street a block over it's 35, and you're  
8 monitoring your performance so that you're not passing  
9 a speed limit of 30, you know, for this particular  
10 failure mechanism. The thing that I'm hanging up on  
11 is -- the use of the term "best estimate" in the world  
12 these days really means something. It's not just  
13 setting a nominal speed limit. And indeed, if you're  
14 characterizing that as a best estimate, I wonder -- I  
15 want to understand why it is that. If it's just simply  
16 the number of cycles such that the value is less than  
17 1.0, that's not necessarily a best estimate. It's an  
18 arbitrary speed limit.

19 MR. HINKLE: No, this is -- this number of  
20 cycles was based on the rate of occurrence --

21 MEMBER STETKAR: Okay.

22 MR. HINKLE: -- since the year 2000. And  
23 so when I -- and I came up with the term "best estimate."  
24 I thought that was the best term I could come up with.  
25 I wanted to be able to distinguish between that and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 the other 60-year projections we had performed.

2 MEMBER STETKAR: Well, I'd like to see how  
3 you did that.

4 MR. HINKLE: Okay.

5 MR. CUSTER: We can provide that, Mr.  
6 Stetkar.

7 MEMBER STETKAR: Thank you.

8 MEMBER SHACK: Just a quick follow-up on  
9 that. All those CUFs are based on ASME-type code  
10 calculations? You haven't done a -- you haven't redone  
11 the stress analysis to get those numbers lower?

12 MR. RINCKEL: Mark Rinckel with the AREVA  
13 license renewal team. Yes, they're based on ASME code  
14 calcs, or the original stress analysis. So there hasn't  
15 been anything --

16 MEMBER SHACK: Any reanalysis?

17 MR. RINCKEL: No, not for the NUREG-6260  
18 locations.

19 MEMBER SHACK: Now you're going to do more  
20 locations, right?

21 MR. RINCKEL: Yes, we identified  
22 additional ones, so that's a commitment.

23 MEMBER SHACK: Yes, it's the highest one  
24 for each material type?

25 MR. RINCKEL: That is correct.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER SHACK: But that hasn't been done  
2 yet?

3 MR. RINCKEL: That's beyond the NUREG-6260  
4 locations. Yes, that's correct.

5 MEMBER STETKAR: I don't have anymore.

6 CHAIRMAN SIEBER: Okay.

7 MEMBER STETKAR: I don't know if John has  
8 any.

9 DR. BARTON: Yes. I couldn't find in your  
10 small bore piping, class 1 piping inspection what you  
11 committed in regards to inspection of socket welds.  
12 Can you help me out here? Do you have a number? A  
13 percentage?

14 MR. BYRD: I'll let Jake Hofelich, our  
15 small bore piping inspection lead --

16 MR. HOFELICH: I'm Jake Hofelich. I'm the  
17 small bore piping program owner. The inspections are  
18 10 percent of the weld population, or maximum 25 for  
19 each weld type, socket welds and full penetration welds.  
20 Our sock weld population is approximately 437, so we'll  
21 be performing 25 of those. Alternatively, we can  
22 perform 13 destructive examinations if a qualified  
23 ultrasonic technique is --

24 DR. BARTON: Got you. I understand.

25 MEMBER STETKAR: And your other world

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 population is like 180 or so, right?

2 MR. HOFELICH: The full penetration weld  
3 is approximately 180, yes.

4 DR. BARTON: Right. Okay. I've got a  
5 question on tanks in general. Your water storage tank,  
6 diesel oil tanks and your borated water storage tank  
7 could determine whether caulking at the interface at  
8 the tank to the foundation is required on these tanks.

9 And if so, is it installed? Because you had an  
10 experience several years ago where the diesel oil  
11 storage tank had rust and corrosion at the base flange  
12 and corroded bolts at the lower access plate at the tank  
13 base.

14 Now have you fixed that? And do you have  
15 these tanks insulated at the foundation to the lower  
16 tank flange on these things?

17 MR. CUSTER: I think the history on that,  
18 we'll have to get back to you at lunch time. Right now  
19 we don't -- we don't have anybody who can answer that  
20 question with us right now.

21 DR. BARTON: Well, I'm concerned because  
22 I have some experience of tanks that get corroded in  
23 the bottom, start leaking, etcetera. And it looks, from  
24 what I read your, history is maybe that you've got some  
25 of that going on. And I'd like to know the status of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 -- do you require insulation at that interface at not?

2

3 And also, you said that you're going to look  
4 at the initial tank bottom inspection of firewater  
5 storage tank, you know, some 40-45 years after it was  
6 installed. And that tank, according to what I read,  
7 does not have any sealing material. And I question,  
8 you know, doing an initial inspection on a tank that  
9 is not insulated from this foundation after that many  
10 years. So that's a concern I've got. MR.

11 ALLEN: With respect to the firewater tank, I think  
12 Donald can talk to that once we fix this.

13 MR. KOSLOFF: I dropped my microphone ball.

14

15 The firewater storage tank was replaced -- I  
16 believe it was about 20 years ago. I don't -- somebody  
17 in design remember when that was done?

18 MR. HOFELICH: Yes, the firewater storage  
19 tank I believe was replaced in the 1980s.

20 MR. KOSLOFF: That's addressed in the  
21 application in the operating experience discussion.  
22 I believe it's for firewater system.

23 MEMBER STETKAR: But the bottom edge of  
24 that tank is not sealed --

25 MR. KOSLOFF: That is correct.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER STETKAR: -- to the foundation.

2 MR. KOSLOFF: That is correct. The  
3 firewater storage tank is a concrete ring foundation  
4 with a oil/sand base. And that's also discussed in the  
5 --

6 DR. BARTON: Well, I know it's on an  
7 oil/sand base, but I've known tanks on oil/sand bases  
8 that have also had problems, leakage problems.

9 MR. KOSLOFF: Right. And --

10 DR. BARTON: So if it's on that, it does  
11 not preclude any problems with that tank, so --

12 MR. KOSLOFF: And we're going to inspect  
13 that tank periodically.

14 DR. BARTON: How about the other ones? Do  
15 they require insulation around there or not?

16 MR. KOSLOFF: The only tank in the  
17 above-ground tanks program that's insulated in the  
18 borated water storage tank. The other two tanks -- or  
19 the other tank and the borated water storage tank, which  
20 would be the diesel oil storage tank and the borated  
21 water storage tank, require a caulk seal at the base.

22 DR. BARTON: And that is installed as far  
23 as you know?

24 MR. KOSLOFF: As far as I know. Yes, sir.

25 DR. BARTON: Okay. I had a question here

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 on switchyard work. Trying to find out what your  
2 relationship here to -- I know you need the switchyard  
3 for off-site -- loss of off-site power, but I read in  
4 one of the inspection reports the -- there was a question  
5 on the status of some concrete repairs that needed to  
6 be done on switchyard tower foundations which were  
7 identified in station condition reports. A work order  
8 was submitted to the FirstEnergy switchyard people and  
9 it turns out that the work order and condition reports  
10 were closed out by the switchyard department responsible  
11 for the work with no work being done and no reasons given.

12 My question is, you know, what relationship  
13 do you have with FirstEnergy's switchyard people and  
14 do you understand why the work wasn't done, or was it  
15 just okay they closed it out?

16 MR. BYRD: So the relationship we have is  
17 obviously we do not at this point do the maintenance  
18 on the switchyard.

19 DR. BARTON: I understand that.

20 MR. BYRD: We did actually until fairly  
21 recently, but we turned that over to the transmission.  
22 We do provide oversight over that work, however, and  
23 that's done by our electric shop which provides  
24 oversight whenever we have ongoing work in the  
25 switchyard.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 With regards to the transmission tower  
2 concrete, Mr. Hook, if you could provide us with an  
3 update on that?

4 MR. HOOK: Jon Hook, design engineering  
5 manager. So for the transmission foundations, there  
6 are caissons going down to bedrock and there's been some  
7 degradation underneath the base plate. We have done  
8 repairs of that in the past. That's where most of the  
9 material is -- degradation is associated with brick down  
10 to the base plate.

11 We did take a look at that. There's ample  
12 margin in the design for that. And there is some  
13 spalling along the exposed concrete caissons that come  
14 up, and that's all surface. It's not structural.

15 DR. BARTON: So the fact the work wasn't  
16 done, you've agreed with -- you've looked at that and  
17 you've agreed it wasn't required, or what? It just --

18 MR. HOOK: It is required to prevent  
19 further degradation. So that's part of our maintenance  
20 rules for structures during our walk-downs. We go  
21 through that and inspect it and identify it. If it's  
22 appropriate, we either write a notification to get it  
23 fixed or a condition report.

24 DR. BARTON: So in this case how did this  
25 end up?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. HOOK: The current condition right now  
2 is acceptable.

3 DR. BARTON: It's acceptable?

4 MR. HOOK: Right. It's just minor, minor  
5 surface spalling and degradation. Not a structural  
6 concern at this time.

7 MEMBER STETKAR: John, you're asking about  
8 a specific event, right?

9 DR. BARTON: Yes, what I want to know is  
10 they didn't do the work, returned the work order or  
11 whatever with no reason why they didn't do the work.  
12 And that's what bothers me.

13 MEMBER STETKAR: Okay.

14 MR. BYRD: I don't have the details of  
15 why --

16 DR. BARTON: This was in an NRC inspection  
17 report is where I got this.

18 MR. BYRD: Right, and I don't --

19 DR. BARTON: And that was due to looking  
20 at the paper and talking to people while they were doing  
21 the inspection.

22 MR. BYRD: So I don't --

23 DR. BARTON: And that's the problem I've  
24 got.

25 MR. BYRD: Right, I don't have the details

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 of that specific issue. We can follow up with that.

2 DR. BARTON: Okay. I appreciate that.

3 MR. BYRD: And I'm sure there's more  
4 history to that.

5 DR. BARTON: You have inaccessible  
6 medium-voltage cables not subject to 50.59 EQ  
7 requirements. I noticed that you've got water problems  
8 in manholes and cables wetted, etcetera. You had stated  
9 that you were going to improve the water quality removal  
10 capability of the sump pumps. Has that been done?

11 MR. BYRD: I we have Eric Johnson here to  
12 provide some additional information on that.

13 MR. JOHNSON: Eric Johnson, electrical  
14 programs at Davis-Besse.

15 Yes, we did have water problems in a manhole  
16 that supplies -- for our station blackout diesel  
17 generator cables. And we did put a sump pump in that  
18 manhole approximately one year ago. We have two other  
19 manholes associated with cables that go to the  
20 switchyard relay house that has some drainage issues.

21 And we have an engineering change package that will  
22 be scheduled to be implemented next spring that will  
23 provide drainage to an adjacent manhole that has a sump  
24 pump.

25 DR. BARTON: So in the meantime what are

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 you doing to exclude water? More inspections or pumping  
2 it out manually? What are you doing in the interim until  
3 you implement that work order?

4 MR. JOHNSON: We just submitted a change  
5 request to the PM program to inspect that -- those  
6 manholes every 30 days --

7 DR. BARTON: Every 30 days?

8 MR. JOHNSON: -- or as required.

9 DR. BARTON: Now do you also require  
10 inspections in severe weather conditions? You got rain  
11 that comes down, it pours for three or four days and  
12 does that tick off something that says we ought to go  
13 look in the manholes?

14 MR. JOHNSON: That's in our aging  
15 management program. We haven't determined what the  
16 event is yet or how to quantify that.

17 DR. BARTON: So in the meantime you have  
18 a heavy rain, you don't do anything different other than  
19 inspect every 30 days or whatever?

20 MR. JOHNSON: That's correct.

21 DR. BARTON: Okay. I'm not okay about, but  
22 I understand what you said.

23 Question on the makeup purification system.

24 I read where you every seventh refueling cycle replace  
25 your letdown coolers, and I've looked at other plants

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 and I don't recall other plants having to change out  
2 letdown coolers every seven cycles because they can't  
3 repair them. There's got to be a root cause for this  
4 problem and I'd like to know if you've looked at it and  
5 determined what the root cause is, and why did you select  
6 replacing your letdown coolers every 14 years. I don't  
7 understand why you can't fix the problem that causes  
8 letdown coolers to degrade to the point where you have  
9 to buy new ones every 14 years.

10 MR. BYRD: I know our letdown coolers are  
11 somewhat a unique helical-type design, but I don't  
12 really have the answer to your question. We'll have  
13 to follow up with that, unless someone anyone else on  
14 our --

15 MR. ALLEN: Allen, would you like to  
16 comment on that?

17 MR. McALLISTER: Allen McAllister, license  
18 renewal team. Yes, our letdown coolers, they're a  
19 helicoil design. That design of coolers throughout the  
20 world, whether it's in the Navy, whether it's in the  
21 nuclear industry, have a high-cycle fatigue problem.

22 Basically the spiral tries to un-spiral so you're  
23 creating these stresses in there. To take them apart  
24 to do a detailed failure analysis, it's a high dose item.

25 A lot of effort has been put forth in the industry to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 try to do something different. We've made progress as  
2 an industry. Various plants that used to replace their  
3 coolers every three years got them up to five years.

4 The plant that actually had the worst history has now  
5 got theirs up to 20 years.

6 So in the time being we have our PM in place  
7 so that we have spare coolers so that if the thing starts  
8 to leak, we'll pick that up in the chemistry analysis  
9 and replace the coolers. But at this point just based  
10 on the design, based on industry experience, world  
11 experience, Navy experience, there's not a clear success  
12 path other than at some point you're going to have to  
13 replace these.

14 DR. BARTON: Nothing like a different  
15 design cooler will work?

16 MR. McALLISTER: Essentially the place  
17 -- the people that use this design was space  
18 considerations, which is why we used them in the Navy,  
19 why they were copied and put in our plant.

20 DR. BARTON: Did you replace them this  
21 often when you were in the Navy?

22 MR. McALLISTER: Actually it was I believe  
23 every 10 years. I remember when my sub was at the  
24 Portsmouth Naval Shipyard that that's one of the  
25 activities that we did. I think that was a 10-year

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 frequency.

2 DR. BARTON: All right. So it's an  
3 industry problem and you're going along with the  
4 industry and changing them out every so many cycles?

5 MR. McALLISTER: Yes, I mean, we're seeing  
6 what we could learn. You know, I don't want to drop  
7 their name, but you know, one plant has gone from  
8 basically a three-year life expectancy to a 20-year life  
9 expectancy. So we're seeing what we can learn from  
10 them, what they changed, what they did different or the  
11 same to see what we can do to increase the livelihood.

12 DR. BARTON: All right. Thank you. I  
13 just -- it just seemed strange that instead of trying  
14 to get to the root cause of a problem you keep changing  
15 them out. So I understand.

16 In-service inspection program, IWF. I  
17 noticed that you have operating experience that showed  
18 you had rusted areas on I-beam supporting the service  
19 water piping, which appears to be from condensation on  
20 the service water piping dripping onto the I-beams.  
21 Your corrective action evaluation on this deficiency  
22 determined there was no action required. You know, that  
23 tells me you're willing to continue with this condition  
24 for an extended operating period of 20 more years instead  
25 of insulating the service water piping. What am I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 missing?

2 MR. HOFELICH: I'm Jake Hofelich. I'm the  
3 IWF program owner. Those supports were examined in  
4 accordance with ASME section 11 and found to be  
5 acceptable within the acceptance criteria.

6 DR. BARTON: I'm sorry, I didn't hear the  
7 end of that.

8 MR. HOFELICH: They were -- the supports  
9 were examine in accordance with ASME section 11.

10 DR. BARTON: Right.

11 MR. HOFELICH: And as part of the  
12 acceptance criteria the design engineering group took  
13 a look at it and saw it could fulfill its function as  
14 it and it was found to be acceptable.

15 DR. BARTON: So you're going to continue  
16 with the problem?

17 MR. HOFELICH: It's found to be acceptable.

18  
19 MR. BYRD: Jon Hook, can you add anything  
20 to that from the structural side?

21 MR. HOOK: We continue to monitor those  
22 pipe supports, and there's ample margin inside the  
23 calculation and ample thickness such that any  
24 degradation in there is not a concern and --

25 DR. BARTON: So it's rusting very slowly,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 so you're going to live with it? Is that the answer?

2 MR. HOOK: We're inspecting it and managing  
3 it.

4 DR. BARTON: I understand.

5 MR. HOFELICH: It should also be pointed  
6 out that these are periodic inspections, so hangers are  
7 continually looked at and -- hangers in that tunnel,  
8 and usually the same hangers are looked at again at the  
9 next interval. So will continue to monitor those  
10 hangers and the adjacent hangers in the service water  
11 tunnel.

12 DR. BARTON: Open cycle cooling water  
13 system.

14 MR. BYRD: Excuse me, Mr. Barton?

15 DR. BARTON: Yes?

16 MR. BYRD: I believe Mr. Blakely --

17 DR. BARTON: We got something else? All  
18 right.

19 MR. BLAKELY: Dennis Blakely, engineering  
20 analysis supervisor.

21 With respect to correcting the condition  
22 of the condensation, that interplays with the Appendix  
23 R fire protection program because the type of insulation  
24 material that would be used. There's a significant fire  
25 load on the spaces. And that's the reason that we're

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 not addressing the condensation and taking the approach  
2 of managing this.

3 DR. BARTON: So all anti-sweat insulation  
4 gives you an Appendix R problem?

5 MR. BLAKELY: The types that we use in our  
6 plant; yes, sir.

7 DR. BARTON: Isn't there other types that  
8 wouldn't give you an Appendix R problem?

9 MR. BLAKELY: I've not heard of others that  
10 would address the issue.

11 DR. BARTON: Open cycle cooling water. In  
12 operating experience you mentioned in 2008 that you  
13 found a silt layer in the piping between two valves  
14 related to auxiliary feedwater system and you flushed  
15 it and got rid of the silt.

16 My question is how do you know that you don't  
17 have recurrence of this issue, and how would impact the  
18 operation of the auxiliary feedwater system if it did  
19 recur?

20 MR. CUSTER: Can you restate that question?

21 DR. BARTON: You got silt between two  
22 valves in the auxiliary feedwater system.

23 MR. CUSTER: Okay.

24 DR. BARTON: You flushed it out and got rid  
25 of the silt. That's end of story. Now I'm saying, well,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 how do you know that you're not going to get silt  
2 accumulated again? If you do get a bunch of silt between  
3 the two valves, how will that affect the auxiliary  
4 feedwater system if you got to operate these valves and  
5 it goes to a pump or -- I know what these valves do.

6 So, yes, how do you know that you solved the problem  
7 long term?

8 MR. BYRD: I believe we do periodic  
9 flushing, and that's something we'll have to verify and  
10 get back with you on. I don't have any information with  
11 me right now.

12 MEMBER STETKAR: Just for clarification,  
13 when I read that, if you could clarify, it was assuming  
14 that's an alternate suction from your raw water system.

15 MR. BYRD: That's an alternate suction from  
16 the raw water system to auxiliary feedwater. It's a  
17 stagnant line.

18 MEMBER STETKAR: Yes.

19 MR. BYRD: And my recollection is; and I  
20 need to verify this, that we do periodic flushing of  
21 that as a result of this issue. But I need to verify  
22 that.

23 MEMBER STETKAR: Okay.

24 DR. BARTON: Okay. Thanks.

25 Refueling canal leakage. One of your

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 proposed actions was to replace -- you thought these  
2 graphoil washers may be the source of the leakage.

3 And my question is since this condition has  
4 been going on for several years I wondered if you have  
5 replaced these washers. And if you did, has it affected  
6 your leakage rate?

7 MR. BYRD: We have David Chew here as our  
8 program owner.

9 MR. CHEW: My name is David Chew. I'm the  
10 refueling canal system engineer. We haven't done  
11 anything with the washers themselves. When we first  
12 identified the issue, we looked into using an epoxy liner  
13 in 2005 to seal the canal. We applied that at the end  
14 of the outage. When we went into the refueling outage  
15 in 2006, the liner started to de-laminate and it didn't  
16 serve its purpose, so we were going forward. We thought  
17 maybe it was a condition we didn't apply the liner  
18 correctly. So in the next refueling outage we had a  
19 corrective action established to reline the system, or  
20 the refueling canal.

21 Based on -- in that time frame we found some  
22 operating experience that the epoxy we were using in  
23 the industry wouldn't hold up. So since then I've been  
24 working as a system engineer. We've been doing some  
25 research in the industry, looking at operating

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 experience. And I've developed a plan based off of  
2 Prairie Island's. And we're going to cap and seal-weld  
3 all of those nuts. And we're also going to seal-weld  
4 along all the penetrations in the refueling canal coming  
5 up in 2014, our 18th refueling outage.

6 DR. BARTON: Okay. Thank you.

7 MR. CUSTER: I believe Mr. Henline has  
8 something to add to that.

9 CHAIRMAN SIEBER: All right.

10 MR. HENLINE: I've got a response for your  
11 previous question, John, about the silting that was  
12 observed in the service water system. We have a PM that  
13 every outage we open the valve to flush that system and  
14 that commitment's in line with Generic Letter 89-13.

15 DR. BARTON: Thank you.

16 MR. HENLINE: You're welcome.

17 MR. CUSTER: Thank you, Trent.

18 DR. BARTON: One other one. Maintenance  
19 Rule inspection. This goes back a ways. You noted  
20 there were some areas indicating concrete spalling on  
21 the shield building. And we didn't talk about that when  
22 went through the shield building earlier. There was  
23 a maintenance order pending repair of the spalled  
24 concrete. And was that repaired, or do you still have  
25 that problem, or --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. CUSTER: Let Jon Hook answer that  
2 question.

3 MR. HOOK: Jon Hook, design engineering  
4 manager. The areas that you're referring to were the  
5 spalled concrete that's directly above the original  
6 construction opening. During the original  
7 construction they -- part of the pour-back for that area  
8 there are imbedded pipes to allow the concrete to be  
9 injected in that area. And so there's been some surface  
10 spalling in that. We've identified that.

11 Now, part of our corrective actions for the  
12 shield building painting is to repair those areas.

13 DR. BARTON: Okay.

14 MR. HOOK: And that has already been done.

15 DR. BARTON: Thank you. That's all I've  
16 got, Jack.

17 CHAIRMAN SIEBER: Okay. Harold, do you  
18 have any questions? Harold?

19 MEMBER RAY: No, I have none.

20 CHAIRMAN SIEBER: Sam?

21 MEMBER ARMIJO: No.

22 CHAIRMAN SIEBER: Okay. Well, it's pretty  
23 close to 12:00 and our schedule calls for the staff to  
24 go over their SER for their portion of the meeting.  
25 And I propose that we recess for lunch until 1:00.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 1:30? Okay. Until 1:30. Thank you.

2 (Whereupon, the above-entitled matter went  
3 off the record at 11:46 a.m., and resumed at 1:28 p.m.)  
4  
5  
6  
7  
8  
9  
10  
11  
12  
13  
14  
15

16 A-F-T-E-R-N-O-O-N S-E-S-S-I-O-N

17 1:28 p.m.

18 CHAIRMAN SIEBER: We will renew the  
19 Subcommittee meeting on Davis-Besse Nuclear Power  
20 Station license renewal application.

21 Again I would point out that it would appear  
22 that not everyone here has signed in on the rosters that  
23 are in the back of the room. And if you haven't done  
24 so, perhaps at the break you could do so, so we have  
25 an accurate record of who is here.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1           And secondly, before we begin with the staff  
2 presentation, the applicant would like to answer some  
3 questions that they had resolved during the lunch  
4 period. So I call upon the applicant to do that.

5           MR. HINKLE:     Larry Hinkle with the  
6 Davis-Besse license renewal team.

7           As related to the earlier question we had  
8 on best estimate cycles, in response to RAI 4.3-9  
9 submitted under Letter L-11-203 dated 6/17/2011, we've  
10 provided a plot of the heat-up events versus years of  
11 service. And in that plot you can see that the rate  
12 of occurrence in the last 10 years of operation has been  
13 about 1.5 cycles per year.

14          MEMBER STETKAR: And we'll get that from  
15 the staff directly, so thank you.

16          MR. CUSTER:    The response to the second  
17 open question I'd like Trent Henline to speak to, please.

18          MR. HENLINE:   Trent Henline, engineering  
19 program supervisor. I wanted to clarify the storage  
20 tank question concerning sealant. So our diesel oil  
21 storage tanks or tank does have sealant at the interface  
22 and it is raised five inches above grade. Our borated  
23 water storage tank does have a sealant around the  
24 foundation and it's raised approximately a foot above  
25 grade. Our firewater storage tank, as mentioned

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 before, does not have sealant. It's on a sand/oil bed.

2 It's raised approximately six inches above grade and  
3 is internally inspected every five years with the last  
4 inspection being performed in 2009.

5 DR. BARTON: Thank you.

6 CHAIRMAN SIEBER: Is that it, Cliff?

7 MR. CUSTER: That's all we have.

8 CHAIRMAN SIEBER: Okay. Thank you very  
9 much. Next I'd like to call on John Lubinski to  
10 introduce presenters for the staff.

11 MR. LUBINSKI: Thank you, Mr. Sieber.  
12 Appreciate it.

13 This afternoon I'd like to introduce our  
14 four presenters who are up at the front table. We have  
15 Brian Harris, our safety project manager; Bryce Lehman,  
16 a structural engineer, DLR; Allen Hiser, who's our  
17 senior level advisor; and Benny Jose, who's a Region  
18 III inspector. We also have other members of the staff  
19 ready to answer questions including our project manager  
20 Sam Cuadrado.

21 I would also like to invite the  
22 Subcommittee. There were many questions you had of the  
23 licensee this morning. If you would like the staff's  
24 perspectives on those, please ask. May not be people  
25 at the table. People in the audience may be able to

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 address and provide some further information. And  
2 there are a couple of issues that may not show up in  
3 the slides, but we'll be responding to your questions  
4 this morning in a more proactive manner with respect  
5 to some of those.

6 So with that, I'd like to turn it over t  
7 Brian.

8 CHAIRMAN SIEBER: Okay. Thank you.

9 MR. HARRIS: Thank you, John. My name is  
10 Brian Harris. I'm the safety project manager of the  
11 Davis-Besse license renewal application.

12 So I'll begin by providing a brief overview  
13 of the LRA and the staff's review, and I'll discuss  
14 section 2 of the SER. Then I'll turn it over to Mr.  
15 Benny Jose, the Region III inspector who will discuss  
16 his license renewal inspection. Then I'll discuss  
17 sections 3 and 4 of the SER.

18 So this is a slide that was mentioned  
19 earlier that we'll skip because the applicant has  
20 already given you the background information to.

21 So we'll go to the next slide, please. NRC  
22 review teams conducted two audits and one regional  
23 inspection at the Davis-Besse Nuclear Power site during  
24 the periods listed on the slide here. The staff started  
25 the on-site review with the scoping and screening

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 methodology audit towards the end of January, the aging  
2 management program audits in mid-February. Region III  
3 conducts its inspections in April and May, 2011 to review  
4 Davis-Besse scoping and screening of the aging  
5 management programs. An addition week of regional  
6 inspections were held in August of 2011 to review the  
7 differences associated with Revisions 1 and 2 of the  
8 GALL report and the applicant's license renewal  
9 application.

10 So moving onto section 2 of the SER, section  
11 2 discusses structures and components subject to aging  
12 management review, which is shown on this slide.

13 Next slide. During the scoping and  
14 screening methodology audit the staff's review resulted  
15 in additional SSCs being included within the scope of  
16 license renewal in accordance with 10 C.F.R. 54.4(a)(2).

17 The applicant took appropriate actions to evaluate  
18 additional SSCs which were then included into the scope  
19 of license renewal. Based on review of the LRA and  
20 additional information submitted as a result of requests  
21 for additional information, the staff concluded that  
22 the applicant's methodology is consistent with the  
23 requirements of 10 C.F.R. 54.4 and 54.21(a)(1).

24 I'll turn it over to Benny Jose, Region III  
25 inspection team leader who will now discuss the results

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 of his inspection.

2 MR. JOSE: I'm Benny Jose. I was the lead  
3 inspector for the 71002 inspection that we did during  
4 April, May and August time.

5 During the April-May inspections we started  
6 off with scoping and screening. And overall the scoping  
7 and screening were acceptable, however, we did -- our  
8 inspections did result in changes to the -- a few changes  
9 to the license renewal application. I will give you  
10 a few examples here.

11 Some of the out-of-scope systems and  
12 non-safety-related systems were -- in their application  
13 were not clarified to say why they were not -- why they  
14 were truly out of scope. For example, demineralizer  
15 system, control rod drive system, you would think they  
16 would -- you know, there are several demineralizer  
17 systems and also control rod drive system has a pressure  
18 boundary function. So the clarification was to add the  
19 pressure retaining components of those systems will be  
20 in license renewal scope.

21 There was another open item for -- there  
22 was no license renewal -- in the license renewal  
23 application there was no age management program was  
24 assigned to head lift lugs -- head lifting lugs. So  
25 those were type of things that we identified during the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealgross.com](http://www.nealgross.com)

1 scoping and screening inspections.

2 Moving on to the --

3 MEMBER STETKAR: Benny?

4 MR. JOSE: Yes, sir?

5 MEMBER STETKAR: Before you move on, I  
6 noticed reading through your inspection report  
7 comparing to a lot of the inspection reports we've seen  
8 let's say in the last couple of years or so you seem  
9 to have many more questions about scoping and screening.

10 Is that simply because of the original vintage of this  
11 application?

12 MR. JOSE: No, it's the particular style  
13 the applicant used.

14 MEMBER STETKAR: Okay.

15 MR. JOSE: Like I was trying to explain the  
16 out-of-scope systems, that's one place we concentrate  
17 on --

18 MEMBER STETKAR: Sure.

19 MR. JOSE: -- are the truly out-of-scope  
20 systems. And when you see things like control rod drive  
21 system, it's out of scope. And you tend to think that's  
22 got a pressure-retaining function. You know, why is  
23 it out of scope? So they had to add clarification.  
24 So there were several instances of that. That's why  
25 we had more questions on scoping and screening.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 MEMBER STETKAR: Okay. Thank you.

2 MR. JOSE: The aging management portion of  
3 the inspection, in the previous slides, and the licensee  
4 also alluded to this, that originally the application  
5 was submitted in August 2010 to Revision No. 1 of the  
6 GALL. And subsequently in December of 2010 NRC issued  
7 Revision 2 of the GALL. And during the NRR's  
8 inspections, as well as our first round of inspections,  
9 we also came up with several questions to the differences  
10 between Rev 1 and Rev 2.

11 So because of the outstanding number of  
12 RAIs, we decided to go back to re-look at some of the  
13 programs, especially seven or eight programs were  
14 completely revised. So that's the reason we had to go  
15 back in August for another week of inspection.

16 For the aging management programs, at the  
17 time we did the inspection there were 40 aging management  
18 programs the licensee had, and we sampled 28 of them.

19 And how we sample or how we select those programs is  
20 based on what we look at to see if they are a new program  
21 or an existing program, or you know, is it consistent  
22 -- you know, looking through that application we can  
23 figure out whether it's really consistent with GALL or  
24 does it have exceptions identified? And programs  
25 -- some programs are controlled by other regulations

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 like ISI programs. So we tend to not look at those  
2 because we will be going back during our next phase to  
3 look at those. So that's the reason we selected 28 of  
4 the programs that we looked at. Again, examples, like  
5 above-ground steel tanks, air quality monitoring  
6 systems, boron monitoring. Those are some examples of  
7 those. After the inspection they added three more  
8 programs. That's why I keep bringing that up we had  
9 40 programs at the time.

10 Based on our inspection there were several  
11 license renewal application as well as amendments to  
12 the application as well as the -- some program procedure  
13 changes. To give you some flavor of that, for example,  
14 the electrical cables and connections not subjected to  
15 10 C.F.R. 50 -- you know, 49. The cables that are in  
16 localized -- adverse localized alignments. The GALL  
17 required that they looked at all the cables, they  
18 inspected all the cables, but the application said the  
19 applicant said they will do a representative sample.  
20 So we questioned that. So they had to revise the LRA  
21 to include that. External surfaces monitoring, you  
22 know, there were specific acceptance criteria involved  
23 in Rev 2 that you have to inspect components once per  
24 fuel cycle. So licensee went about and made changes.  
25 And in response to our questions, they did not take

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 out specific commitments, but they did have a local  
2 database called an open item number. Several open item  
3 numbers were open based on our inspection.

4 Fuel oil chemistry program also had a  
5 requirement to look for microbiological activity once  
6 ever quarter, that the licensee has taken an action to  
7 do that. These are a few examples, or several more  
8 examples.

9 Next slide, please. Okay. Now coming to  
10 the results. We said before the scoping of SSCs, we  
11 did not find any adverse problems, so we did find them  
12 to be acceptable with the changes that we brought about.

13 And the documentation supporting the application was  
14 audit-able under the rule, and those were all reports,  
15 2010-10 and 2011-12. Those were two reports that we  
16 documented our inspections results.

17 Any additional questions for me?

18 (No response.)

19 MR. JOSE: In addition, some of the  
20 discussion this morning, we could look to some  
21 additional information. I would invite my branch chief  
22 Ann Marie to talk about the intake now. We have some  
23 additional information on that.

24 MS. STONE: Yes, good afternoon. My name  
25 is Ann Marie Stone. I'm the branch chief in Region III.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 I am responsible for license renewal and also  
2 responsible for the ultimate heat sink inspections and  
3 the component design basis inspections.

4 In July 2011, during the ultimate heat sink  
5 inspection, my inspectors walked down -- and I also  
6 walked down the intake canal. We were able to get, you  
7 know, our eyes on the situation.

8 There's actually two issues with the intake  
9 canal. The first is a slope issue. The slope of the  
10 walls are not in accordance with the licensing regs and  
11 so they are operable but non-conforming with the  
12 license. So that is something that the licensee has  
13 to fix. But that's already in the Part 50 as a Part  
14 50 requirement.

15 The other is, as the licensee, or as the  
16 applicant has talked about, is two areas that are  
17 actually sinking. It's not that this material slid into  
18 the intake canal. It appears that it's just sinking  
19 down. And that again is something that they have had  
20 contractors -- as they talked about, contractors take  
21 a look at that. We as a regional office looked at it  
22 from an operability standpoint and we believe that  
23 -- again that it is operable, but in a non-conforming  
24 condition. We also --

25 CHAIRMAN SIEBER: Are there --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MS. STONE: I'm sorry?

2 CHAIRMAN SIEBER: Are there any active  
3 mines in the area? I know that further east they mine  
4 salt along the Lake Erie shores. Are you aware of --

5 MS. STONE: I am not --

6 CHAIRMAN SIEBER: -- anything that's going  
7 on sub-surface?

8 MS. STONE: I am not aware of anything.  
9 I do not have that information.

10 CHAIRMAN SIEBER: Okay.

11 MS. STONE: When my inspectors took a look  
12 at it back in July, we did ask questions with respect  
13 to were there an earthquakes, minor earthquakes,  
14 fracking, you know, anything like that going on. And  
15 there was some, but very, very minor. We're also trying  
16 to figure out what -- you know, change analysis. What  
17 is different now than it -- you know, prior to that,  
18 prior to the identification of that.

19 MEMBER STETKAR: Has the settling -- do you  
20 have any idea whether it's an emergent issue, or is it  
21 -- has it been occurring gradually over the 35-year life  
22 of the facility?

23 MS. STONE: My understanding is that the  
24 license identified it back in 2007. In 2011, as we were  
25 doing our inspection; as I said, we walked it down, our

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 communication, our interview with the system engineer  
2 at that time was that basically it did change from 2007  
3 to 2011. And I was actually out there back in August  
4 of this year, so I saw a slight change between 2011,  
5 2012. My inspectors are following up on that. But at  
6 this point we're not questioning operability on the --

7 MEMBER STETKAR: Right, I understand.

8 DR. BARTON: Well, didn't this site  
9 experience any of that earthquake that went up the East  
10 Coast that North Anna felt went up into Ohio?

11 MEMBER STETKAR: It's too far west, I  
12 think.

13 DR. BARTON: It was in Ohio. I know Ohio  
14 felt some of it. I didn't know whether this site was  
15 affected or not.

16 CHAIRMAN SIEBER: They may have had some  
17 seismic instrument response here, but I'm not aware of  
18 that. But in the 1980s there was a seismic event further  
19 east along Lake Erie that was recordable at least 100  
20 miles away.

21 MS. STONE: And I guess the other thing I'd  
22 like to just add is that I think this was an excellent  
23 example of how the license renewal for us here in  
24 headquarters as well as the license renewal and those  
25 doing Part 50 inspections. And the region worked

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 together to come to a common understanding of what the  
2 issue is and how to proceed from a -- basically on how  
3 to fix the issue.

4 MR. JOSE: I would like to touch upon two  
5 more items that was brought up during the morning  
6 session.

7 The switchyard degradation of foundation.

8 Our teams very specifically noticed that and asked  
9 questions of the licensee. The licensee had taken a  
10 special -- a specific open item No. 383 to either repair,  
11 evaluate the condition and evaluate the process for  
12 addressing degradative conditions in the switchyard.

13 And that's where we left it off.

14 And the second issue has to do with the --

15 CHAIRMAN SIEBER: Yes, I'd like to ask the  
16 licensee a question there. In a lot of plants that I'm  
17 familiar with, in recent years the switchyard -- custody  
18 of the switchyard has been divided, and particularly  
19 when transmission companies differ from the operator,  
20 or the plant operating company. Is that the case at  
21 Davis-Besse? In other words, are there items in the  
22 switchyard that actually do not fall under the custody,  
23 the cognizance of the plant folks?

24 MR. BYRD: So to understand your question,  
25 you're asking who is responsible for the maintenance

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 of the switchyard?

2 CHAIRMAN SIEBER: That's right.

3 MR. BYRD: So the actual work, the  
4 activities, the work activities are performed by the  
5 Western District of transmission and distribution,  
6 however, we do preventative maintenance for activities  
7 in the switchyard. In this specific case though the  
8 issue you're talking about, you know, we did some  
9 research on that. And in this particular activity, this  
10 order that was voided by the transmission and  
11 distribution apparently, you know, this was done back  
12 in 2008. And there was knowledge of that by  
13 engineering. At least the plant engineering has the  
14 responsibility for monitoring the switchyard. They  
15 were aware of that. However, we need to follow and  
16 understand how that was -- some of the other implications  
17 of voiding that order.

18 CHAIRMAN SIEBER: Well, is there a  
19 difference in the standards used by the switchyard -- and  
20 I'll use the word "owner" for back of a better word  
21 engineering and operating standards that differ from  
22 those that one would expect from a nuclear power plant  
23 operating equipment? In other words, is there a  
24 difference in quality level and timeliness,  
25 responsiveness and, you know, procedures and practices?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MR. BYRD: We attempt to control that by  
2 having -- first of all, we do have a -- oversight of  
3 the switchyard by our own electrical maintenance  
4 personnel. So whenever we're having switchyard work  
5 being performed, we do maintain oversight of that work  
6 with our nuclear staff. And in the case of Davis-Besse,  
7 until pretty recently the actual switchyard work was  
8 in fact performed in house. So we do have a quite of  
9 bit of knowledge in house amongst -- with that kind of  
10 activity.

11 CHAIRMAN SIEBER: But that's not the case  
12 today, right?

13 MR. BYRD: As of today that has been  
14 transitioned over to the Western District, that  
15 activity, but we do maintain oversight. Whenever  
16 they're in the yard, we have personnel in the yard  
17 maintaining oversight.

18 CHAIRMAN SIEBER: But it's still under the  
19 control of FirstEnergy Corporation?

20 MR. BYRD: That is correct.

21 CHAIRMAN SIEBER: Okay.

22 MEMBER STETKAR: Do you operate the  
23 breakers in the switchyard from the owner, or does  
24 somebody else operate the actual operation of the  
25 breakers?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. BYRD: The operation of the switchyards  
2 in the -- I'm sorry, breakers in the switchyard would  
3 be from the unit.

4 MEMBER STETKAR: From the unit?

5 MR. BYRD: That's correct.

6 MR. JOSE: The second item I wanted to talk  
7 about was a discussion about manholes and the water.  
8 And we were specifically looking at, you know,  
9 medium-voltage cables, inaccessible cables,  
10 specifically safety-related cables that went through  
11 manholes. We asked them to open up a couple of manholes  
12 and we only identified one of a few cables that were,  
13 you know, going through that particular manhole. And  
14 we did find water. So we wanted to see. So they opened  
15 it up for us. And there was water in there. And based  
16 on that, we asked our question, you know, how are you  
17 going to get rid of the water? There were actually -- it  
18 was configured as four manholes side-by-side. Two of  
19 them had sump pumps installed in them. The initial  
20 reaction or people thought that the other two manholes  
21 were supposed to drain into the two with sump pumps.

22 And the second round, that's why when we  
23 went back in August, we opened that and saw water was  
24 still there. It wasn't draining. So at that point they  
25 initiated a notification to engineering -- design

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 engineering to prepare a modification package to install  
2 sump pumps. And that's also documented in our second  
3 report.

4 CHAIRMAN SIEBER: Okay.

5 MEMBER STETKAR: Benny, I forgot to ask the  
6 applicant, is the water -- do you know; and it's probably  
7 easier to ask the applicant, but because you've looked  
8 at the stuff, is it event-driven or is it groundwater?  
9 Are the bottoms of the manholes below 570 where the  
10 nominal water table is?

11 MR. JOSE: I don't recall the exact  
12 elevation, but it was during rainy season that we there,  
13 you know, May, June, as well as August time frame. There  
14 was rain in between. But the two of the sump pumps had  
15 -- I mean, two of the manholes did have sump pumps and  
16 the other two did not.

17 MEMBER STETKAR: And they're installing  
18 sump pumps or --

19 MR. JOSE: Right.

20 MEMBER STETKAR; -- or at least making sure  
21 the manholes drain to someplace that does have a sump  
22 pump?

23 MR. JOSE: Right. And we also noted that  
24 the sump pumps would be charging right next to the sump  
25 pits. It's true. It pumps right back into that. I

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 mean, that's -- well, it could be sealed, too. But the  
2 modification was supposed to have those things extended  
3 out also.

4 CHAIRMAN SIEBER: And the ones where sump  
5 pumps were dry?

6 MR. JOSE: Yes.

7 CHAIRMAN SIEBER: Okay. So they were  
8 operating the sump pumps?

9 MR. JOSE: Yes.

10 DR. BARTON: I don't remember. Were the  
11 cables actually submerged?

12 MR. JOSE: The cable was, yes. The 141-60  
13 cable, yes.

14 With that, I'll turn over to Brian.

15 MR. HARRIS: All right. Thanks. Thanks,  
16 Benny.

17 So this slide details section 3 of the SER  
18 with the following subsection as shown on the slide here.

19 So I won't cover each subsection, but will touch on  
20 those which either have an open item or an item of  
21 interest.

22 Establish and issue the SER open items of  
23 July 31st of 2012. There are four open items related  
24 to the shield building crack, operating experience,  
25 pressure-temperature limits and upper shelf energy.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 There are no confirmatory items.

2 CHAIRMAN SIEBER: And responses to all four  
3 of these have been submitted to the staff for review?

4 MR. HARRIS: That is correct.

5 CHAIRMAN SIEBER: They're under review  
6 right now?

7 MR. HARRIS: Right. So we'll touch on  
8 that. In the SER the staff had an open item related  
9 to the laminar cracking in the shield building. As the  
10 applicant noted, the cracking was observed in multiple  
11 locations and the applicant concluded that the cracking  
12 was caused by rapid freezing of significant moisture  
13 driven into the concrete during an extreme blizzard of  
14 1978. Although the root cause determined the initial  
15 cracking was event-driven, the staff believes the  
16 degradation could continue to grow. Therefore, it  
17 should be monitoring a period of extended operation.

18 To address this, the applicant submitted a  
19 plant-specific AMP shield building monitoring program  
20 to monitor the cracking. The staff reviewed the  
21 submittal and required additional information in order  
22 to complete its review.

23 Move onto the next slide. So the areas  
24 identified on this slide represent the status of the  
25 issue at the time the SER with open items was prepared.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 So since that time the applicant has submitted an  
2 updated AMP and additional information which addressed  
3 some of these points and which the staff us currently  
4 reviewing.

5 The staff's review of the applicant's  
6 original submittal identified several areas where  
7 additional information is necessary. Specifically,  
8 the staff required additional information regarding the  
9 adequacy of crack monitoring, the proposed coating and  
10 the scope of the program. The staff asked the applicant  
11 to explain why non-destructive examination techniques  
12 were not going to be used to verify the extent of cracking  
13 of 100 percent of the accessible shield building  
14 surface.

15 As the applicant noted in its presentation,  
16 it has since completed impulse response mapping of the  
17 entire accessible surface.

18 The staff also requested more information on how  
19 selected core bores would adequately represent the  
20 cracked areas throughout the building. For the coating  
21 the staff requested more information on the adequacy  
22 of the coating that was going to be selected, how the  
23 coating would be inspected or when or if it would be  
24 reapplied.

25 Finally, since the root cause evaluation

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 indicated the cracking occurred as a result of a blizzard  
2 which affected the entire site, the staff requested  
3 information on why similar cracking did not occur  
4 throughout the site and how other concrete structures  
5 within the scope of license renewal would be monitored  
6 for this type of cracking. And as noted earlier, the  
7 staff is evaluating the updated AMP and RAI responses  
8 and resolution of the open items pending completion of  
9 our review.

10 CHAIRMAN SIEBER: Did you get responses to  
11 each of these RAIs?

12 MR. HARRIS: Yes. Yes, we did.

13 CHAIRMAN SIEBER: Okay.

14 MEMBER ARMIJO: Has the staff concluded it  
15 agrees with the root cause identified by the applicant,  
16 that it was event-driven, or are you not sure?

17 MR. HARRIS: For that one, Bryce Lehman?

18 MR. LEHMAN: Yes, the Region concluded -- I  
19 mean, did an inspection of the root cause report and  
20 they concluded that it was a reasonable explanation of  
21 how the cracking occurred. And I think our focus is  
22 also on -- in license renewal on monitoring the cracking  
23 and making sure that we understand how it's going to  
24 grow or lead to additional degradation.

25 MEMBER SHACK: But you've accepted the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 analysis that the structural integrity is satisfactory  
2 with the extent of cracking that's now present?

3 MR. LEHMAN: Yes, that's correct.

4 CHAIRMAN SIEBER: Okay. Thank you.

5 MR. HARRIS: Okay. Moving onto the next  
6 slide. Open B.1.4-1 is related to the applicant's  
7 consideration of aging-related operating experience  
8 during the term of the new license. Now this issue h  
9 been discussed with the ACRS and previous subcommittees,  
10 most notably the Limerick Generating Station. During  
11 its review the staff issued the final license renewal  
12 ISG-2011-05 entitled, "Ongoing Review of Operating  
13 Experience." This writing emphasizes that operating  
14 experience is a key feedback mechanism used to ensure  
15 the continued effectiveness of the aging management  
16 programs and its activities. A summary of the operating  
17 experience review framework described in the ISG is  
18 presented on the slide here today.

19 In response to the staff's RAIs, the  
20 applicant has described the activities it will us to  
21 review operating experience related to aging. The  
22 staff is completing its review of these activities in  
23 accordance with the framework set forth in the Interim  
24 Staff Guidance. Resolution of this open item is pending  
25 completing of the staff's review.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 Next slide, please. So section 4 of the  
2 SER contains the staff's review of time-limited aging  
3 analysis, or TLAA. TLAAs are certain plant-specific  
4 safety analyses that involved time-limited assumptions  
5 defined by the current operating term and must be listed  
6 by section 54.21(c)(1) and any plant-specific  
7 TLAA-based assumptions per 54.21(c)(2). The staff  
8 reviewed information in the LRA to determine whether  
9 the applicant has provided sufficient information  
10 pursuant to 54.21(c)(1) and (c)(2).

11 So open item 4.2.4-1, this addresses the  
12 methods and bases that will be used to generate the  
13 applicant's P-T limit curves for the period of extended  
14 operation when submitted in accordance with the tech  
15 spec section 5.6.4 requirements for P-T limit curve  
16 provisions. Reactor vessel extended belt line  
17 components, including nozzles will pass a neutron  
18 fluence exposure of 1 times 10 to the 17th neutrons per  
19 centimeter squared during the period of extended  
20 operation. Therefore, the applicant must consider the  
21 effects of neutron embrittlement on P-T limits for these  
22 extended belt line components.

23 RAI 4.2.4-1 requested the applicant to  
24 address how these extended belt line components will  
25 be considered in the P-T limits for the period of

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 extended operation. The applicant has provided a  
2 response to this RAI and the staff is currently reviewing  
3 the response.

4 All right. Moving on to the next open item,  
5 open item 4.2-1 addresses the applicant's upper shelf  
6 energy calculations for the LRA. The rule requires that  
7 the USE value for ferritic components in the belt line  
8 region of the reactor vessel must be at least 50  
9 foot-pounds at the end of the licensing operating term.

10 This applies to the expiration of the period of extended  
11 operation for plants that have been granted license  
12 extensions based on the 60-year fluence projections for  
13 the belt line components. This is why the LRAs include  
14 TLAA's on the USE analysis. If the applicant cannot  
15 demonstrate that the end-of-life USE value for the belt  
16 line component would be greater than or equal to 50  
17 foot-pounds, the rule allows licensees to demonstrate  
18 acceptable resistance to fractures through an  
19 equivalent margin analysis.

20 The applicant used a generic USE value of  
21 70 foot-pounds for the Linde 80 reactor vessel welds  
22 to project the USE for the period of extended operation.

23 The staff did not find this approach acceptable because  
24 the 70 foot-pound values represents an average taken  
25 from generic Charpy impact data for Linde welds, for

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 80 -- Linde 80 welds. The use of an average value is  
2 not a conservative approach as opposed to, for example,  
3 a lower bounding or a mean minus two standard deviation  
4 value.

5 In lieu of justifying that the 70 foot-pound  
6 initial upper shelf energy the applicant's RAI response  
7 includes an equivalent margins analysis for the Linde  
8 80 welds. The staff is currently reviewing these  
9 analyses to determine whether they meet the regulatory  
10 requirements of 10 C.F.R. Part 50 Appendix G for the  
11 period of extended operation.

12 MEMBER SHACK: When you're dealing with  
13 something like this where you don't have data on the  
14 specific weld, would you accept the lowest value if the  
15 mean minus two standard deviations was lower?

16 MR. HARRIS: Dr. Hiser, would you --

17 MEMBER SHACK: I mean, this is -- you know,  
18 it's a question of sample-bound versus population-bound  
19 there.

20 DR. HISER: Yes, I guess a short answer is  
21 it's case-dependent. I mean, we would have to look at  
22 all of the data and the justification. In general, I  
23 think that probably is something that we would find favor  
24 with, using the lowest value.

25 MEMBER SHACK: Oh, using the lowest value?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 Even if the mean minus two is lower?

2 DR. HISER: We'd have to look at all the  
3 data. I mean, again, if it's three data points, then  
4 that might create a difficulty. But in this case they  
5 were able to us copper fluence correlation for fracture  
6 toughness to do the EMA. So the --

7 MEMBER SHACK: Yes.

8 DR. HISER: -- initial upper shelf  
9 energy --

10 MEMBER SHACK: Becomes a moot point, right.  
11 Well, I guess I just don't see why you'd find that  
12 acceptable. I mean, why would I take a sample-bound  
13 rather than population-bound?

14 DR. HISER: As I said, it would be  
15 case-by-case. I think in general we do like --

16 MEMBER SHACK: I'll be asking this question  
17 quite often.

18 MR. HARRIS: The SER also included on  
19 proposed license condition related to inspecting  
20 inaccessible portions of the steel containment vessel.

21 The applicant has operating experience with minor  
22 borated water leakage migrating through concrete  
23 structures inside of containment. Due to the  
24 configuration of the containment there is a slight  
25 possibility that borated water leakage has gathered in

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 inaccessible areas at the bottom of the steel  
2 containment vessel. If the water is in contact with  
3 the vessel, it could cause corrosion which would remain  
4 undetected during the period of extended operation.

5 To address this concern staff has proposed  
6 a license condition requiring the applicant to remove  
7 concrete from a low point of the containment in order  
8 to inspect the inside surface of the containment vessel.

9 If leakage is not successfully stopped or if the initial  
10 inspection identifies water, the inspection will be  
11 repeated during the period of extended operation.  
12 These inspections will provide reasonable assurance  
13 that any degradation to the imbedded portions of the  
14 containment vessel will be identified. The staff  
15 believes this issue is appropriate as a license  
16 condition because it affects containment, and without  
17 these inspections the areas identified would not  
18 normally be inspected. It is possible that the  
19 degradation of the containment vessel could be occurring  
20 without an adequate method of detection.

21 MEMBER STETKAR: Brian, before you switch  
22 slides, I have a couple of questions. The first one  
23 is; and we asked the applicant, this -- as I understand  
24 it, they're going to take their core bore at a location  
25 that's about 30 inches above bottom dead center of the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 reactor -- of the containment shell. How does an  
2 inspection at that location provide confidence that  
3 indeed you have not had a fairly large area of  
4 boric-acid-containing water in contact with that steel  
5 shelf within that 30-inch-deep hemisphere? Or -- it's  
6 not a hemisphere, but --

7 MR. HARRIS: Bryce, do you have --

8 MR. LEHMAN: Yes, I think -- I mean, you're  
9 right they're not taking it from the --

10 MEMBER STETKAR: I mean, you know, I could  
11 look at the side of the -- vertical side of the  
12 containment also and, you know, it wouldn't give me much  
13 confidence about that. So I'm really curious about what  
14 -- if you don't find anything there, what does that tell  
15 you about the status of the shell at the low point?  
16 Because if you do find something, obviously it's a  
17 problem.

18 MR. LEHMAN: Yes. Here's where they're  
19 proposing to take the cores. So even that I think was  
20 about 30-inch delta there.

21 MEMBER STETKAR: That's what it said in the  
22 SER, yes.

23 MR. LEHMAN: And I guess ideally dead  
24 center would be the best, but I think we felt that this  
25 would be a good indication of -- you know if there's

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 an issue with borated water pooling there --

2 MEMBER STETKAR: If there is, that's true.

3 If there's not, how do you have confidence that indeed  
4 five inches below that area there isn't an issue? I  
5 mean, if you do find it there, that's certainly an  
6 indicator.

7 MR. LEHMAN: That's a good question. I  
8 think we can take that and look at it some more detail  
9 and see if it's appropriate, but I think our logic was  
10 that the odds were if it's been pooling there throughout  
11 the --

12 MEMBER STETKAR: We asked the applicant and  
13 they -- you know, why they weren't boring bottom dead  
14 center and they said, well, they don't want to cut a  
15 hole in their sump liner. You know, people understand  
16 how to weld, so that's okay. I'm just curious about  
17 that.

18 MR. LEHMAN: Yes, I think that's a good  
19 question. We can take that and look at it in more detail.

20 MEMBER STETKAR: And since you have this  
21 nice picture here, I'm going to come back to my  
22 groundwater question, the staff has basically accepted  
23 the applicant's program that says, well, we're going  
24 to make sure that the drains in the sand pocket area  
25 are open. We're going to -- if we can collect any water

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 from those drains, we're going to monitor that water  
2 for chemistry, as I understand it. And, you know, we'll  
3 inspect the area that's accessible there at the  
4 interface. How does that give us confidence that we  
5 don't have corrosion from the exterior of the shell  
6 bottom dead center?

7 MR. LEHMAN: Following up on what we just  
8 discussed, I think that's a good point. We'll take it  
9 as feedback and go back and look at it. But they do  
10 have a commitment to take UT measurements at the five  
11 locations where they've seen the groundwater coming into  
12 the sand region.

13 MEMBER STETKAR: But that's way up --

14 MR. LEHMAN: That's right.

15 MEMBER STETKAR: -- and that's way up at  
16 the interface there.

17 MR. LEHMAN: Yes, I thought we had the  
18 closeup of that area.

19 MEMBER STETKAR: We have handouts that show  
20 that actually.

21 MR. LEHMAN: Okay. Okay.

22 MEMBER STETKAR: But again, in some sense  
23 that's relatively high. It's still below groundwater  
24 level, I guess, depending on where you are, but it's  
25 still relatively high in elevation.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. LEHMAN: And that's correct. But I  
2 guess there we'll have he -- that's where you're going  
3 to see the wetting and drying and replenishment of oxygen  
4 in that area.

5 MEMBER STETKAR: You're relying on the  
6 argument that it's a low-oxygen environment and not  
7 conducive to corrosion.

8 MR. LEHMAN: That's part of it, but then  
9 also the other -- the license condition we'll be  
10 -- they'll be doing UTs from the inside which would  
11 identify degradation.

12 MEMBER STETKAR: That's certainly -- yes,  
13 I mean, the 30-inch area is certainly below the  
14 groundwater level, so that should -- that one,  
15 regardless of where they do that bore, ought to give  
16 them some indication.

17 MR. LEHMAN: Yes.

18 MEMBER STETKAR: Okay. I was just curious  
19 because you were so active in following on the boric  
20 acid corrosion, you know, having a license condition  
21 for them to do a core bore from the inside, you seem  
22 to pretty much accept the groundwater issue from the  
23 exterior.

24 MR. LEHMAN: But again, I think that  
25 license condition, it wasn't laid out that way in the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 SER, but that does support --

2 MEMBER STETKAR: Yes, it does.

3 MR. LEHMAN: -- with the UT measurements,  
4 yes.

5 MEMBER STETKAR: Thanks.

6 MR. HARRIS: Any other questions while this  
7 slide is up, or should I go back?

8 (No response.)

9 MR. HARRIS: Yes, I guess before we get to  
10 the conclusions, there were a few items of interest in  
11 this morning's session. And if I can have Bill Holston  
12 from the staff come forward and discuss --

13 MR. HOLSTON: Bill Holston from the DLR  
14 staff. There were two open questions on areas that I  
15 have oversight on, buried piping and underground tanks.  
16 The question was whether their program was consistent  
17 with GALL Rev 3. And I had verified that during the  
18 process of evaluating the LRA --

19 DR. BARTON: We only have 2 on GALL, I  
20 think.

21 MR. HOLSTON: Say again?

22 DR. BARTON: We only have 2 on GALL, I  
23 think.

24 MR. HOLSTON: What did I say?

25 DR. BARTON: You said Rev 3.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. HOLSTON: Sorry. Rev 2.

2 DR. BARTON: No wonder none of this makes  
3 sense, you know? I'm going to spin my head around a  
4 few more times if there's another one out.

5 MR. HOLSTON: So, yes, it is consistent  
6 with Rev 2 of the GALL, and I believe that's the only  
7 outstanding question on the buried piping.

8 On the above-ground tanks program --

9 MEMBER SHACK: No, no, no, no, no.

10 MR. HOLSTON: Okay. Sorry.

11 MEMBER SHACK: Why not make it consistent  
12 with the ISG?

13 MR. HOLSTON: With the ISG we will be  
14 evaluating that, and so --

15 MEMBER SHACK: It's 03. You're making  
16 them consistent with 05.

17 MR. HOLSTON: Correct. Yes, the ISG, we  
18 need to look at -- there are several plants we have to  
19 look at that are currently in process. The ISG just  
20 got issued, you know, right in August. So we'll be doing  
21 that and issuing it -- as necessary, issuing separate  
22 RAIs. This suspects several claims will have RAIs, but  
23 we need to talk that over with DLR management.

24 Any other questions on buried pipe?

25 (No response.)

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MR. HOLSTON: Okay. On above-ground  
2 tanks, the diesel fuel storage tank was a tank that had  
3 -- in 2002 had some degradation that was noted that was  
4 repaired at that time. In 2008, they did a follow-up  
5 examination. They just found minor chips in the  
6 painting that, you know, could have been just some  
7 -- from some mechanical damage, but no further evidence  
8 of corrosion in that area.

9 And then other question of course was the  
10 GALL Rev 2 question, and the above-ground tanks program  
11 was consistent with GALL Rev 2.

12 Any other questions on the above-ground  
13 tanks program?

14 DR. BARTON: Thank you. No.

15 MR. HOWARD: Thank you, Bill.

16 MR. HARRIS: And also I would like to have  
17 Bryce add a few items towards the groundwater issue as  
18 discussed this morning.

19 MR. LEHMAN: Yes, I guess there was also  
20 a question about the sampling of the groundwater for  
21 aggressiveness. I should have addressed that earlier.

22 I went back and looked at the SER when we  
23 were discussing it earlier this morning and it's clear  
24 that it's unclear in the SER that the staff was -- we  
25 knew when we were reviewing it that their enhancement

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 was sampling raw water, but I think the wording does  
2 -- is confusing, so we'll definitely go back and take  
3 a look at straightening that out. But I think the key  
4 with the aging management was that they had admitted  
5 from the very beginning that they had aggressive  
6 groundwater, so there wasn't an issue with continuing  
7 to sample to prove whether or not it was aggressive.

8 They were assuming it was aggressive moving forward.

9 And to address that they were suggesting a one-time  
10 inspection, basically with two core bores from the  
11 locations of known groundwater leakage.

12 MEMBER STETKAR: And also opportunistic,  
13 as I understand it.

14 MR. LEHMAN: Yes. Yes, the opportunistic.  
15 That's correct.

16 MEMBER STETKAR: Okay.

17 MR. LEHMAN: So, does that kind of answer  
18 the question a little bit?

19 MEMBER STETKAR: Yes, it does. I mean, I  
20 was -- I did get confused because it said well water.

21 And I thought, well, maybe their groundwater is mostly  
22 Lake Erie or something like that. But that clears it  
23 up. Thank you.

24 MR. HARRIS: All right. Thank you, Bryce.

25 And lastly, getting back to the upper shelf

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 energy --

2 DR. HISER: I want another crack at that  
3 answer. In the distribution of data, for the lower  
4 bound to be below the lowest data point with any  
5 reasonably sized data set, the deviations have to be  
6 on the high side. So if I have real high values that  
7 are skewing the standard deviation to be very large,  
8 that's probably about the only case where you would end  
9 up with the mean minus two sigma being below all of the  
10 data. And we went through a case with another plant  
11 recently on license renewal where they actually were  
12 mixing upper shelf data with some transition data and  
13 had a very high deviation, standard deviation. I guess  
14 I'd fall back to my first answer that it would be  
15 case-by-case, but I think that would be the kind of thing  
16 that we would want to look at as we evaluate each  
17 individual data set.

18 MEMBER SHACK: Well, I can understand you  
19 might want to understand whether the data looked normal  
20 that you distributed or not, but I've sort of convinced  
21 myself that it would be normally distributed. I still  
22 don't see why I wouldn't take the two sigma answer over  
23 the sample lower bound.

24 DR. HISER: I don't know, Jeff Poehler, do  
25 you have any thoughts on that from the PE perspective?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 Mean minus two sigma versus the lowest value?

2 MR. POEHLER: Jeff Poehler, senior  
3 materials engineer in the Vessel Integrity Branch in  
4 Division of Engineering.

5 I don't really have any input other than  
6 yours. I think -- I mean, going back to -- the question  
7 was -- I'm not -- I think the question was --

8 MEMBER SHACK: My question is when I'm  
9 dealing with a population and I'm dealing with a sample,  
10 how do I choose a population bound? And you gave me  
11 two answers. And I didn't like one of them.

12 MR. POEHLER: Well, I think Dr. Hiser's  
13 answer was a good one. I think -- I mean, normally -- you  
14 know, normally the two sigma is not going to be below  
15 the --

16 MEMBER SHACK: Well --

17 MR. POEHLER: -- middle of the data set,  
18 but --

19 MEMBER SHACK: I mean, I always just think  
20 we ought to be keeping in mind that we're generally  
21 thinking about looking for populations from samples.

22 And as long as you take that into consideration when  
23 you come up with the answer, I'm fine. But I've seen  
24 too many people draw a lower bound between the lowest  
25 data point they happen to have at the moment, and that

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 just sort of doesn't fly.

2 MR. POEHLER: Well, I guess as Dr. Hiser  
3 said, we would have to look at each case individually,  
4 but we would have to make sure that the value we picked  
5 really was conservative.

6 MEMBER SHACK: Well, with an EMA, there's  
7 no --

8 MR. POEHLER: And it -- yes, exactly. At  
9 any rate --

10 MEMBER SHACK: It's moot.

11 MR. POEHLER: At any rate, it's not an issue  
12 for this one, so --

13 MR. HARRIS: Thank you. The staff's  
14 conclusion will be documented in the final SER. On the  
15 basis of its review and pending satisfactory resolution  
16 of the open items, the staff will be able to determine  
17 that the requirements of 10 C.F.R. 54.29(a) have been  
18 met for the renewal of Davis-Besse Nuclear Power Station  
19 operating license.

20 This concludes our presentation.

21 CHAIRMAN SIEBER: Okay. Do you require  
22 any additional information at this point from the  
23 applicant with the SER?

24 MR. HARRIS: We are in the process of  
25 reviewing --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 CHAIRMAN SIEBER: Okay. So you don't --

2 MR. HARRIS: -- responses to --

3 CHAIRMAN SIEBER: You don't know whether  
4 you need more information or not?

5 MR. HARRIS: That is correct.

6 CHAIRMAN SIEBER: Okay.

7 MR. HARRIS: So we are in that process of  
8 reviewing those RAI responses at this time.

9 CHAIRMAN SIEBER: Okay. But right now the  
10 applicant is up to date with responses so far?

11 MR. HARRIS: That is correct.

12 CHAIRMAN SIEBER: Okay. Well, thank you  
13 very much. Appreciate it.

14 MEMBER STETKAR: Actually I have a question  
15 for Allen only because I can't not ask him a question  
16 at one of these things.

17 In the small bore piping --

18 DR. HISER: Yes?

19 MEMBER STETKAR: -- program the  
20 applicant's operating experience listed two failures.

21 And I'm fine. There was one -- there was drain line  
22 weld failure, which is not something that we're  
23 particularly interested in, I think, because they do  
24 monitor it and they've done weld overlays.

25 The other one that caught my attention; and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 I've just lost the page here, was a failure of -- it  
2 says that a metal pipe in the reactor vessel closure  
3 gasket leakage monitoring line. Applicant performed  
4 an evaluation and determined it was stress-corrosion  
5 cracking mainly caused by chloride residue left after  
6 water evaporated in the line. Their solution was they  
7 replaced the line and they now drain and flush the line  
8 after it's used to eliminate chloride residue. And the  
9 determination was, well, they basically fixed the  
10 problem, so therefore it's not relevant going forward.

11  
12 How did they get chlorides in that line?

13 Did you ask at all? I mean, I wouldn't expect chlorides  
14 to be in a vessel head leak-off drain line unless it  
15 came from the vessel.

16 MR. HARRIS: Yes, Bart Fu is --

17 MR. FU: I didn't quite get your question.

18 MEMBER STETKAR: Okay. There is -- I'm  
19 reading from the SER. It says discussing the failure.

20 In the first case the applicant detected a crack in  
21 the pipe metal in the reactor vessel closure gasket  
22 leakage monitoring line --

23 MR. FU: Right.

24 MEMBER STETKAR: -- during an inspection  
25 in 2002. The applicant performed an evaluation and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 determined that it was stress corrosion cracking mainly  
2 caused by chloride residue left after water evaporated  
3 in the line.

4 My question is how did you get chlorides  
5 in that leakage monitoring line unless it came from the  
6 reactor coolant system, which is somewhat troublesome?

7 MR. FU: You're probably right. You know,  
8 they used the line mainly during the outage. But based  
9 on the OE, my understanding is when you left some of  
10 the remaining water in it and then through operation  
11 it could vaporize. And then whatever, you know,  
12 residual that got left there, maybe there's some  
13 concentration. That's what we understand of the OE.

14 And then the concentration could be a chloride or some  
15 induced stress corrosion factor.

16 MS. GALLOWAY: Does the applicant have any  
17 further information on that?

18 MEMBER STETKAR: Thanks.

19 MR. HOFELICH: I'm Jake Hofelich. I'm the  
20 ISI program owner.

21 The issue with the line is when we flooded  
22 up the refueling canal and when we drained it out after  
23 refueling, we didn't drain this line. So the line was  
24 full of the refueling canal water and when it dried up,  
25 it concentrated the chlorides at the bottom of it and

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 caused the cracking.

2 MEMBER STETKAR: Where's the chlorides in  
3 that water coming from? That's supposed to be really  
4 nice clean water.

5 CHAIRMAN SIEBER: Yes, because that has a  
6 steel liner presumably.

7 MR. DAWSON: Alvin Dawson, chemistry  
8 manager at Davis-Besse. I can tell you that we analyze  
9 for chlorides in all conditions and -- all conditions  
10 in the system, both in the reactor cooling system and  
11 in the fueling canal, and at no time do we have chlorides  
12 that exceeded our limits, which are less than our tech  
13 spec limits. So it -- I can't -- that's all I can speak  
14 to, is that we don't -- we wouldn't not have -- we did  
15 not have any chlorides that exceeded our limits, which  
16 are less than the tech spec limits.

17 MEMBER STETKAR: Do you think this was an  
18 accumulation over time just basically because water  
19 evaporating in that line --

20 MR. DAWSON: At first glance it would  
21 appear to be so.

22 MEMBER STETKAR: Okay.

23 MEMBER ARMIJO: Was that actually measured  
24 chloride, or was that just somebody saw some deposits  
25 and said that must have been chloride?

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 MEMBER SHACK: They saw a crack and said  
2 it must be chloride.

3 DR. HISER: This is a concern we've had  
4 going back to Calvert Cliffs, the very first license  
5 renewal application, and this was the position that we  
6 -- I think they may have had the same operating  
7 experience with cracking, and that was where we'd  
8 established the position that flushing the line after  
9 refueling outages would help to eliminate any  
10 contaminants and eliminate the crack concern. So I  
11 think it -- I don't know --

12 MEMBER STETKAR: This predates my time, so  
13 -- and this is my first chance --

14 DR. HISER: But I think the conclusion at  
15 that point was that it was accumulation over a number  
16 of refueling cycles where they would have water in there,  
17 it would flask to steam, leave deposits and just would  
18 slowly accumulate to a level that could cause cracking.

19 MEMBER STETKAR: Thanks.

20 MR. FU: Oh, I just want to elaborate a  
21 little bit. Since that OE, I think during the review  
22 we asked some specific items, like Limerick, from then  
23 on Grand Gulf, you know, make sure they include it in  
24 the aging management program. You know, and the  
25 -- based on the OE what specific procedures do they have,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 like, you know, drain line during the outage, things  
2 like that. And we learned from the OE.

3 MEMBER STETKAR: Thank you.

4 CHAIRMAN SIEBER: Do any of the  
5 Subcommittee Members have questions they would like to  
6 ask? John, you usually do. Do you have any additional  
7 questions?

8 MEMBER STETKAR: No, I'm pretty happy now.  
9 I asked Allen a question.

10 CHAIRMAN SIEBER: Okay. Bill?

11 MEMBER SHACK: No, Jack.

12 MEMBER ARMIJO: Yes, I'm still perplexed  
13 with our root cause on your shield building cracking.

14 I think it doesn't explain a lot of the observations  
15 and I wonder why the staff has agreed that it's  
16 event-driven versus design-driven. But I'm looking  
17 forward to reading the report that the applicant's going  
18 to send me. I think the important thing is that the  
19 conclusion is that that building is structurally sound.

20 That's a more important thing. I agree with that.  
21 But what bothers me is that if you don't really nail  
22 the root cause, you may not fix the problem. And, you  
23 know, I think that what's being done is a good thing  
24 to do, but not necessarily the root cause of the problem.

25 DR. HISER: Yes, I think from the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 perspective of the license renewal review we use things  
2 like that that are part of the current licensing basis.

3 And if the staff has made a determination of what's  
4 acceptable, then we just go forward with that looking  
5 at the condition and likely degradation would occur up  
6 to PEO and then during PEO and ensure adequate aging  
7 after that.

8 MEMBER ARMIJO: Yes, and I think --

9 DR. HISER: We don't question that  
10 decision.

11 MR. LUBINSKI: If I could basically add is  
12 in looking, as we said -- number one, this is an open  
13 item and we appreciate the input today. And I think  
14 what's important, as you said, is we have made a  
15 determination today, or I should say the licensee has  
16 made a determination it's structurally sound, and we  
17 agree with that.

18 In moving forward, if it's structurally  
19 sound today, we need to, as part of our aging management  
20 programs, have the licensee monitor moving forward the  
21 condition. And that's one of the key points that we  
22 did have in our open item and asking questions. And  
23 we are going to be reviewing moving forward so that we  
24 can still make that same determination during the  
25 extended period of operation.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1           From a Part 50 standpoint, as Ann Marie  
2 Stone said, we do coordinate these issues very close,  
3 whether it's a Part 50 issue or Part 54 issue. So this  
4 is not something where we're just waiting until the  
5 extended period for operation. We will be continuing  
6 to look at this during the current 40 years as well.

7           MS. GALLOWAY: And just to clarify a little  
8 bit further, too, we don't just accept blindly the  
9 outcome of root cause analyses. There are other pieces  
10 of information that might come about as part of the Part  
11 50 review. To the extent that we need to have an  
12 understanding to appropriately define and have  
13 reasonable assurance of the aging management programs  
14 in the PEO, we do need to assure ourselves that the  
15 correct starting point is being established in order  
16 to have that determination appropriately defined for  
17 the PEO.

18           I think Bryce did indicate that we had also  
19 looked at the root cause evaluation and we felt  
20 comfortable that it was appropriate and that we could  
21 use that then as a basis to define that aging management  
22 program.

23           MEMBER ARMIJO: Yes, well, you know, the  
24 point I'm trying to make is if after everything you do;  
25 the painting, the ceiling, and in your future monitoring

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealgross.com](http://www.nealgross.com)

1 you see those cracks are still growing, that meant you  
2 didn't get the root cause because the event didn't  
3 happen. The water doesn't get through there anymore.

4 So that means it must have been some other root cause.

5 My opinion is it was simpler than the one that's been  
6 proposed, and it still won't do any harm. But, you know,  
7 there could be situations where if you don't nail the  
8 root cause very well, you put a fix in that doesn't really  
9 fix anything and you find out after a long time.

10 MR. LUBINSKI: We appreciate those  
11 insights and as we move forward looking at this open  
12 item, we will be considering that. And just in a general  
13 statement, as -- if a licensee were to put in a -- you  
14 know, based on root cause what they looked at as  
15 corrective actions and in your example here, if the  
16 cracks were to go, we would be back looking into  
17 determining whether or not the root cause was adequate  
18 at that point. Still could be maybe there's something  
19 else with the fix or contributing causes that we would  
20 need to look at.

21 MEMBER ARMIJO: Okay. Thank you.

22 MEMBER STETKAR: I think the important  
23 thing is, as long as the monitoring program isn't  
24 specifically designed in a way that it precludes looking  
25 for some sort of issue because it's focused too narrowly

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 on that specific root cause, then you could have a  
2 problem. And in this case, that doesn't mean to be --

3 MEMBER ARMIJO: No, it's a general --

4 MR. LUBINSKI: At this point our questions  
5 are all on monitoring crack growth, not just on  
6 monitoring --

7 MEMBER ARMIJO: The effectiveness of the  
8 paint.

9 MR. LUBINSKI: -- the corrective action of  
10 the paint. That's correct.

11 CHAIRMAN SIEBER: Any additional  
12 questions, Sam? Harold, do you have any questions?

13 MEMBER ARMIJO: Well, I do. You know, I  
14 really would like to learn more about that containment,  
15 this water coming up through the bottom around the  
16 containment, getting up into that pocket. I've always  
17 -- that bothers me particularly that there doesn't seem  
18 to be much you can do about it.

19 MEMBER SHACK: Think of it as treated  
20 water, Sam. It's been filtered through concrete.

21 MEMBER ARMIJO: Bill, I -- that's a torture  
22 -- well, you know, I just would like to have the staff  
23 think about it a little bit more. If it's a  
24 high-chloride water coming up through that interface  
25 between the --

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 MEMBER SHACK: Well, that's why they need  
2 that sample with the UT working on both sides of it.

3 MEMBER STETKAR: And it's regardless of  
4 where they take that --

5 MEMBER SHACK: It will at least tell them  
6 what's going on on the exterior.

7 MEMBER ARMIJO: That -- you're right. If  
8 the exterior is being badly corroded, that one  
9 measurement should pick it up because it's coming up.

10 MEMBER STETKAR: Yes.

11 MEMBER ARMIJO: All right.

12 MEMBER STETKAR: It should be reasonably  
13 uniform and --

14 MEMBER ARMIJO: Anyway, next time you  
15 present, if you could get --

16 MR. LUBINSKI: I appreciate that. And as  
17 Bryce said, in general, looking at our conclusion, we  
18 believe today that the information we had that the open  
19 items are the only issues we had out there. We are -- we  
20 heard some very good questions this morning and the staff  
21 is going to go back and reconfirm. We still have that  
22 position with respect to those questions with respect  
23 to that issue. If we still have the same conclusion,  
24 you will be hearing more at the final Committee meeting.

25 CHAIRMAN SIEBER: Okay. At this point,

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 John Barton, do you have any questions or comments?

2 DR. BARTON: No, I don't have -- yes, I got  
3 some comment. I don't have any questions on the staff's  
4 presentation. I thought it was pretty good.

5 In looking at the root cause, you know, I  
6 went through that root cause analysis a couple times  
7 and I think that they did a real good job. And from  
8 the applicant's presentation this morning, if it's not  
9 -- if they didn't identify the root cause, then, you  
10 know, I'd be surprised. It appears to be the right root  
11 cause.

12 Now if Sam's water running uphill changes  
13 that, I'll stand to be corrected, but I think it was  
14 a good root cause analysis and I think the staff and  
15 the applicant made a good presentation of it this  
16 morning. So I'm satisfied with the root cause analysis  
17 of the cracking.

18 Generally, an overview of the application,  
19 the staff pointed out some issues this morning regarding  
20 scope issues and some questions on RAIs on what they  
21 saw. And I thought for, you know, where we were -- some  
22 of that I attributed to maybe GALL 1 and GALL 2, but  
23 wasn't too sure if that was really the issue, and I don't  
24 think it really was.

25 But in many -- in all the applications we

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

[www.nealrgross.com](http://www.nealrgross.com)

1 received over the years, you know, I'm a little  
2 disappointed in this, in the thoroughness of the  
3 application. I am -- in recent memory can't remember  
4 so many RAIs on a section of this application that didn't  
5 change between GALL 1 and GALL 2, which is the TLAAs.

6 There were 53 RAIs just on TLAAs, and I think that is  
7 the result of a poor job on the part of the applicant  
8 in this presentation on TLAAs. And I was disappointed.

9 But this -- I guess that's the -- my main concern with  
10 this application.

11 And I know at this point issuing a license  
12 extension is not for this Subcommittee to recommend one  
13 way or the other, but I think we got some open items  
14 plus we're still looking -- the staff's still looking  
15 at the root cause.

16 MEMBER RAY: John, why did you say the water  
17 was running uphill?

18 DR. BARTON: Oh, I think that was Sam's --

19 MEMBER ARMIJO: No, that was referring to  
20 the containment.

21 MEMBER RAY: Water seeks a level, I mean,  
22 you know?

23 DR. BARTON: Well, it had nothing to do with  
24 the cracking. This is Sam's issues.

25 MEMBER ARMIJO: It's coming up through the

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1 -- to the sand pocket.

2 MEMBER RAY: Yes, but I mean, the grade  
3 level's way up here.

4 MEMBER ARMIJO: It's not running uphill.  
5 It's --

6 MEMBER RAY: It's coming up the gap.

7 MEMBER ARMIJO: I know that.

8 MEMBER RAY: Okay. But it's not going  
9 uphill in the sense that --

10 MEMBER ARMIJO: Well, it wasn't coming in  
11 this way. That's what it is.

12 MEMBER RAY: No. Okay. That's fine.  
13 But it's not -- it's only coming to whatever level the  
14 groundwater level is, right? It's not migrating above  
15 the groundwater level.

16 MEMBER ARMIJO: I just thought that's  
17 initially whatever level the groundwater is.

18 MEMBER RAY: It's trying to reach the water  
19 --

20 MEMBER SHACK: I think it can throw a fair  
21 chunk of --

22 MEMBER ARMIJO: Right, I understand that.

23 MEMBER RAY: Oh, okay. All right. Well,  
24 I just couldn't understand the water going uphill  
25 comment.

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

(202) 234-4433

www.nealrgross.com

1 MEMBER ARMIJO: But that had nothing to do  
2 with the root cause issue.

3 DR. BARTON: No, not at all.

4 MEMBER RAY: I didn't imagine it did.

5 DR. BARTON: No.

6 MEMBER RAY: I just thought maybe --

7 DR. BARTON: Wondering how water runs  
8 uphill. I'm sorry I --

9 MEMBER RAY: I thought it was a --

10 MEMBER ARMIJO: Oh, no, no, no.

11 MEMBER RAY: It seemed pretty obvious to  
12 me that unless the membrane has 100 percent integrity,  
13 which I don't see how it could, you're going to get water  
14 coming up there and there isn't going to be anything  
15 you're going to do to stop it.

16 DR. BARTON: And we know the membrane is  
17 not 100 percent. We know that.

18 That's all I've got, Jack.

19 CHAIRMAN SIEBER: Okay. Thank you very  
20 much. Again, at this point I'd like to thank both the  
21 applicant and the staff for well-done presentations and  
22 a thorough job.

23 I'd also invite at this time any comments  
24 from the audience if you would wish to make any.

25 (No response.)

**NEAL R. GROSS**

COURT REPORTERS AND TRANSCRIBERS

1323 RHODE ISLAND AVE., N.W.

WASHINGTON, D.C. 20005-3701

1                   CHAIRMAN SIEBER:   Seeing none, I think  
2                   -- and again, thank you for all of your hard work and  
3                   your responses today.  And this meeting is adjourned.

4                   (Whereupon, the above-entitled matter went  
5                   off the record at 2:35 p.m.)

6

7

8

9

10

11

12

13

14

15

16

17


18

19



# Davis-Besse Nuclear Power Station License Renewal Application

Advisory Committee on Reactor Safeguards  
License Renewal Subcommittee Meeting  
September 19, 2012



# AGENDA

- **Introductions & Opening Remarks**
- **Background**
- **License Renewal Application Overview**
- **SER Open Item Review**
- **Summary**

# Introductions

- **Barry Allen – Site Vice President**
- **Ken Byrd – Director, Site Engineering**
- **Cliff Custer – Fleet Project Manager**
- **Steve Dort – Project Lead / Coordinator**
- **License Renewal Core Team Members**
- **Aging Management Program Owners and Subject Matter Experts**

# Background – Site



## **Davis-Besse Site**

- Southwestern shore of Lake Erie in Ottawa County, Ohio
- 954 Acre Site
  - 733 acres leased to US Government as wildlife refuge
  - 221 acres for Plant structures & equipment

# Background – Plant

## ■ Design

- Pressurized Water Reactor
- Babcock & Wilcox nuclear steam supply system with raised-loop design
  - 2817 Megawatts thermal / 908 Megawatts electrical rating
  - Measurement uncertainty recapture (MUR) power up-rate of 1.6% implemented July 2008
- Bechtel Engineering construction management
- Facility Operating License expires April 22, 2017


## ■ Currently operating at 100% reactor power

## ■ 98 Days On-Line

# Background – Upgrades/Inspections

## ■ Equipment Improvements/Verifications

- Replaced Reactor Head
- Replaced selected power cables
- Replaced selected Service Water piping
- Replaced Emergency Diesel Generator exhaust piping
- Polar Crane upgrade and insulation replacement
- Palfinger Crane installation
- Completed Reactor Vessel removable core support structure Inservice Inspection – No unacceptable indications
- Performed Integrated Leak Rate Test of Containment



# License Renewal Application – Project

## ■ Application Development

- FENOC core team since 2006
- Davis-Besse Program Owners and Subject Matter Experts
  - Development of application; audit & inspection interviews; NRC Staff conference calls; RAI responses; and, Commitment development

## ■ Industry Interaction

- NEI Working Group involvement
- Industry Peer Review Process

# License Renewal Application – Details

## ■ Application Details

- Application submitted in August 2010
- Developed using NUREG-1801 (GALL) Revision 1
- 43 Aging Management Programs (AMPs)
  - 12 New (4 are plant-specific)
  - 31 Existing (4 are plant-specific)

## ■ License Renewal Commitments

- 49 Commitments
- Included in USAR Supplement (Appendix A of the LRA)
- Managed by FENOC Commitment Tracking Program

# License Renewal Application – Review

- **Audits, Inspections, and Requests for Additional Information (RAIs) based on NUREG-1801 Rev 2**
  - RAIs & responses addressed differences between GALL Rev 1 & Rev 2
  - Audit Schedule (2011)
    - Scoping & Screening January 24-28
    - Aging Management Program Review February 14-25
  - IP 71002 Inspection Schedule (2011)
    - Week 1 Inspection April 25-29
    - Week 2 Inspection May 9-13
    - Week 3 Inspection August 22-26
  - Safety Evaluation Report w-Open Items July 31, 2012

# SER Open Item Review

- **OI 4.2.-1 Reactor Vessel (RV) Neutron Embrittlement**
- **OI 4.2.4-1 Pressure-Temperature (P-T) Limits**
- **OI B.1.4 Operating Experience (OE)**
- **OI B.2.39 Shield Building**

# OI 4.2-1: RV Neutron Embrittlement

## ■ RV Beltline Upper-shelf Energy (USE) Evaluation

- Generic mean value of 70 ft-lb used to project 52 EFPY USE not statistically-conservative (mean value minus two standard deviations or lowest value)
- Selection of lowest value resulted in 52 EFPY USE of < 50 ft-lb
- 10 CFR 50 Appendix G requires end-of license USE to be no less than 50 ft-lb, unless it is demonstrated that lower values of USE will provide margins of safety against fracture, equivalent to those required by Appendix G of Section XI of the ASME Code

## ■ FENOC Response

- In accordance with 10 CFR 50 Appendix G, FENOC elected to qualify welds by equivalent margins analysis (EMA)

# OI 4.2-1: RV Neutron Embrittlement (cont.)

## ■ **EMA status for the RV beltline welds**

- Nozzle Belt Forging to Bottom of RV Inlet/Outlet Nozzle Forging Welds
  - EMA submitted by letter dated June 14, 2012
- Upper Shell Forging to Lower Shell Forging Circumferential Weld (WF-182-1)
  - EMA was addressed in the LRA
- Nozzle Belt Forging to Upper Shell Forging Circumferential Weld and Lower Shell Forging to Dutchman Forging Circumferential Weld
  - EMA submitted by letter dated September 14, 2012

## ■ **Open Item Status**

- Response to RAI 4.2.2-4 under review by NRC

# OI 4.2.4-1: P-T Limits

## ■ RAI 4.2.4-1 Request

- Describe how the P-T limit curves to be developed for use in the period of extended operation, and the methodology used to develop these curves, considered all RV materials (beltline and non-beltline) and the lowest service temperature of all ferritic RCPB materials
  - 10 CFR 50 Appendix G requires P-T Limits to be developed for all ferritic materials of reactor coolant pressure boundary (RCPB)
  - RV nozzles, penetrations & other discontinuities may exhibit significantly higher stresses that potentially result in more restrictive P-T Limits
  - Non-beltline components may have initial  $RT_{NDT}$  values that define a more restrictive lowest operating temperature

## OI 4.2.4-1: P-T Limits (cont.)

### ■ FENOC Response

- Davis-Besse P-T Limits generated in accordance with 10 CFR 50 Appendix G and R.G. 1.99 Rev. 2 using methods described in approved topical report BAW-10046A
- BAW-10046A considered all ferritic materials (beltline & non-beltline material)
  - The RV outlet nozzle, due to consideration of loading conditions, is more limiting relative to stress than any of the Class 1 ferritic branch connections (e.g., hot leg surge nozzle), the large bore RCS piping, or the primary nozzles of the steam generator

## OI 4.2.4-1: P-T Limits (cont.)

- BAW-10046A considered all ferritic materials (beltline & non-beltline material) (cont.)
  - Initial  $RT_{NDT}$  of all RCPB ferritic items were considered when establishing P-T Limits and the lowest service temperature
  - Reactor vessel closure head region, outlet nozzles, and beltline region are controlling locations that regulate P-T Limits

### ■ Open Item Status

- Response to RAI 4.2.4-1 is under review by NRC

## OI B.1.4: Operating Experience (OE)

- **OE review should consider aging management**
  - Interim Staff Guidance LR-ISG-2011-05 issued in March 2012
    - Address age-related degradation and aging management
    - Inform/enhance aging management programs
- **OE Program changes**
  - Revise OE and Corrective Action Programs
    - Flag aging-related OE
    - Consideration of material, environment, aging effects & mechanisms, and aging management program

## OI B.1.4: Operating Experience (OE) (cont.)

- Revise OE and Corrective Action Programs (cont.)
  - Provide feedback to aging management program owners
  - Provide significant OE on aging to the industry
  - Identify training needs

### ■ Aligned with LR-ISG-2011-05


- Responses to RAIs B.1.4-2 and B.1.4-4 are under review by NRC

## OI B.2.34 Shield Building

**Describe how sub-surface laminar cracking in the Shield Building will be managed for aging**


- Function & Design of Shield Building
- Discovery of Laminar Cracking
- Investigation & Extent of Condition
- Root Cause
- Corrective Actions
- Aging Management
- Open Item Status

# Shield Building




# Shield Building (cont.)

- **Purpose of Shield Building**
  - Biological shielding
  - Environmental protection for Containment Vessel
  - Controlled release of Annulus atmosphere under accident conditions




# Shield Building Flutes/Shoulders



# Shield Building Flute Shoulders

## ■ Architectural Feature

- The flute shoulders are a part of the Shield Building; concrete for shoulders and building shell was placed concurrently
- Evaluation of structural capacity of Shield Building does not credit flute shoulders
- Evaluated as a dead load in structural analysis



# Discovery

- **Cracking found on October 10, 2011, during hydro-demolition**
- **NRC resident notified**
- **Condition Report written**
- **Restraint on restart established**
- **Team of experts to investigate issue mobilized**

# Investigation

- **Impulse Response (IR) testing methodology used to investigate extent of crack**




## Investigation (cont.)

- **Core bores taken to validate IR testing results, to determine crack depth and to determine crack width**
- **Investigation results were documented in the corrective action process, and the NRC was promptly notified of findings**




# Summary of Shield Building Condition

- Cracking is generic to flute shoulder regions and can be assumed to be present at any elevation in the flutes shoulders; cracking was observed to be more prevalent on the south side of the building
- Cracks are located near the outer reinforcing mat; no cracking observed in interior reinforcing mat



## Summary of Shield Building Condition (cont.)

- **Cracking exists at the top 20 feet of the Shield Building wall outside the flute shoulder region**
- **Two small regions adjacent to the Main Steam Line penetration have similar cracks**
  - The extent of these regions is localized and unique to these particular penetrations
- **Cracks are very tight**



# Structural Evaluation

## ■ **Original Shield Building design**

- Building designed and constructed with significant reinforcement
- Significant margin under design basis loads
- Design Basis
  - Earthquake 6–6.5 on Richter magnitude scale
  - Tornado winds of 300 miles per hour
  - Tornado depressurization and missiles

## ■ **Impact of laminar cracks on original design**

- Potentially reduce the bond strength between concrete and reinforcing steel
- Cracks of little impact unless reinforcing bars are spliced in the cracked region

# Bounding Building Analysis

- **Bond strength of reinforcement lap splices with adjacent cracks could not be quantified and were conservatively treated as non-existent in analysis**
- **Calculations performed to provide a bounding evaluation of the effect of cracking**
  - Vertical and horizontal reinforcement assumed ineffective for strength in flute shoulders, two steam line penetration areas and in regions at top of shield building.
- **Any bond between reinforcement and concrete in crack regions provides additional margin**

# Summary of Calculation Results

- **Shield Building meets strength requirements**
- **Any bond between the concrete and reinforcement in cracked regions would be an additional margin of safety**
- **Shield Building is capable of performing all safety functions with margin**


# Root Cause Overview

- **Established independent team of experts**
- **Established a comprehensive Failure Modes Analysis**
- **Investigated the design, materials, construction methods, and present day operational conditions**
- **Performed concrete tests**
- **Performed analyses**
- **Identified root cause**

# Root Cause Overview (cont.)

- **Performance Improvement International (PII)**
  - The PII team are experts in root cause investigation
  - Team consist of Professional Engineers, PhDs, and university professors
  - Performed more than 500 root causes
- **Industry experts as well as assistance from FENOC Engineering**
- **Followed our established and proven root cause process**

# Shield Building Root Cause Fault Tree



# Shield Building Concrete

- **Concrete was subjected to a series of tests**
- **36 concrete cores from the Shield Building tested**
- **Concrete properties were determined**
- **Test results confirmed the concrete is sound and can be ruled out**




# Shield Building Concrete (cont.)

- **Typical concrete sample showing the laminar crack sheared the coarse aggregate**
- **Therefore, laminar crack occurred after the concrete achieved its strength**



# Shield Building Concrete (cont.)


- **No evidence of micro cracks**
- **No signs of cyclic load mechanism**
- **No cyclic freeze-thaw mechanism**
- **No indication of fatigue or age related events**



Magnification at 100 Times

# Shield Building Concrete Tests (cont.)

- **16 samples were tested for carbonation**
  - Average depth of carbonation is 8.57 mm (0.337 inches)
  - Maximum average 11.7 mm ( 0.46 inches)
  - Typical for concrete 40 years old



# Shield Building Concrete - Conclusion


- **Crack passed through the course aggregate**
  - Strong bond between the cement paste and the coarse aggregate; therefore, initial placement concerns can be ruled out
  - Large tensile force is required to initiate the crack
- **No micro cracks identified that would indicate freeze-thaw or cyclic events**
- **Chemical properties, carbonation, corrosion, etc, were all acceptable**
- **Based on the above, concrete can be ruled out as an initiating or contributing cause**

# Shield Building Configuration

- **Cracking is predominantly located in the shoulder areas, the top 20 feet of the Shield Building, and near the Main Steam Line penetration block-outs; cracking concentrated on southern exposures**
- **Shoulder areas are regions of discontinuity**
- **Limited radial reinforcing steel in the shoulder areas**
- **High rebar density (6" spacing) located at the top of the Shield Building and around the Main Steam Line penetration construction block-outs**
- **Conclusion**
  - There is a correlation between the crack locations and the physical layout of the reinforcing steel that needed to be investigated

# Shield Building Analytical Analyses

- **Numerous computer analyses were performed for normal design conditions**
  - Self weight, wind loads
  - Thermal analyses (summer hot and winter cold conditions)
  - Fujita Category 2 tornado
- **Stresses were significantly below the normal tensile capacity of the concrete**



Overall View @ EL 683' 6"

Close-Up View @ EL 683' 6"

# Shield Building Analytical Analyses (cont.)


- **Analysis showed:**
  - Design stresses can not initiate the laminar crack
  - Significant stresses beyond what is normally analyzed would be required to crack the concrete
  
- **Investigate industry experience for similar conditions**

# Industry Experience with Laminar Cracks

- **Ontario Ministry of the Environment study on 50 above ground water tanks in Ontario**

- **Water migrated into the concrete from the inside**

- Inner layer of the wall freezes and expands
- Outer layer of wall contracts
- Creates high radial stress
- Results in laminar cracking



- **Conclusion: Laminar cracking as a result of water freezing is a real potential**

# Shield Building Investigation into Water Intrusion/Freezing

- **The effects of moisture intrusion and sub freezing temperatures was investigated as a possible cause**
- **The review of severe environmental conditions that the plant was exposed to was performed**
- **The most significant event recorded at the site and also in Ohio history was the storm of January 25-27, 1978**

# Moisture Intrusion and Low Temperatures

- **January 25-27, 1978, was the worst in terms of:**


- Moisture
- Winds
- Temperature
- Duration
- Pressure



# Moisture Intrusion and Low Temperatures (cont.)

## ■ Scenario:


- Temperature near zero
- Sustained strong winds
- Moisture penetrated the Shield Building
- Moisture trapped in the outer layer of concrete crystallized
- Concrete expansion exceeded the tensile capacity of the concrete and propagated the crack



AP

# Moisture Intrusion and Low Temperatures (cont.)

- A complex computer model of the Shield Building was developed
- Concrete properties from the concrete core tests were used
- Laboratory tests showed moisture infiltration up to four inches
- Maximum radial stress in the shoulder area were approximately the tensile capacity of the concrete
- High stresses were located in areas of observed cracking



# Sensitivity Analysis – High Density of Rebar

- **A complex computer model evaluated the affects of rebar spacing to determine the potential for developing cracks**
- **Evaluation showed laminar cracks could:**
  - Form in regions of closely spaced rebar and
  - Less likely in areas were the rebar is spaced at 12 inches
- **This analysis establishes that rebar spacing is a probable contributing factor**

# Summary of Analyses

- **Normal design conditions result in low stresses which could not cause cracking**
- **Moisture and freezing could cause high stresses in the shoulder areas that results in cracking**
- **Analysis shows closely spaced reinforcing steel can be a contributor to laminar cracking**
- **Observed cracking coincides with the locations of high stress in the shoulder areas and in the areas of high density of rebar; cracking concentrated on southern exposures**

# Shield Building Root Cause

- **Root Cause:**

- Lack of water sealant on the concrete exterior

- **Contributing Causes:**

- Shoulder reinforcing details (discontinuity and no radial rebar)
- High density of rebar spacing
- High moisture, severe wind, and low temperature conditions

# Shield Building – Preventive Action

- **Root Cause**
  - Lack of concrete sealant
- **Preventive Action to Prevent Recurrence**
  - The exposed exterior surfaces of the Shield Building will be sealed
  - Contractor has started and is expected to be completed this year



# Shield Building – Additional Actions

- **The Root Cause has established several additional Corrective Actions**
  - Complete Impulse Response (IR) examinations on the Shield Building wall
  - Perform IR mapping on another structure (Auxiliary Building) to confirm assumptions of our analyses
  - Develop and implement a test program to establish capacity in an area of laminar cracks
  - Develop a Long-Term Monitoring program

# Additional Actions - IR Mapping

- **Complete IR examinations on the Shield Building wall and an independent structure**
  - All accessible areas of the Shield Building wall were mapped
  - Over 60,000 individual readings were obtained to fully characterize the condition of the building




## Additional Actions - IR Mapping (cont.)

- **The IR validated our original assessment that the laminar cracks are generally confined to:**
  - The shoulder areas
  - Top of the Shield Building
  - Near one corner of the Main Steam Line penetration
  - Southern exposure
- **Impulse Response reading on an independent site structure validated that laminar cracks are not present**

# Additional Actions - IR Mapping (cont.)

Shield Building Exterior Elevation IR Test Data  
Data through 24 July 2012



# Additional Actions – Testing

- Tests were developed and conducted at two nationally recognized universities
- Professors are industry experts and are American Concrete Institute (ACI) Committee members



## Additional Actions – Testing (cont.)

- Two different methods were used to create laminar cracks in the samples to be tested
- Results were independently verified



# Additional Actions – Testing (cont.)

## ■ Testing results

- Full capability of reinforcement is maintained in regions with longer splice lengths (upper portion of Shield Building)
- Results showed near to full capability of reinforcement in regions with shorter splice lengths

## ■ Testing conclusions

- The tests provide high confidence of the capability of the rebar located in regions of laminar cracking
- Testing confirms the assumptions made in structural calculation prior to restart were very conservative

# Additional Actions – Long Term Monitoring


## ■ Establish a Long-Term Monitoring Program

- FENOC has established a long-term monitoring plan that includes:
  - Monitoring existing core bores for crack propagation
  - Inspection of the integrity of the Shield Building coatings
  - Inspection of the integrity of other safety related building coatings



# License Renewal Application Summary

- **Application has been reviewed to NUREG-1801, Rev. 2**
- **43 Aging Management Programs identified**
- **49 Commitments**
- **Site Program Owners and Subject Matter Experts involved in:**
  - Development of application; audit & inspection interviews; conference calls with NRC; RAI responses; and, Commitment development
- **SER Open Item responses under review by NRC staff**
- **Proposed programs address aging management at Davis-Besse for the period of extended operation**





**U.S. NRC**

UNITED STATES NUCLEAR REGULATORY COMMISSION

*Protecting People and the Environment*

# **Advisory Committee on Reactor Safeguards License Renewal Subcommittee**

## **Davis-Besse Nuclear Power Station Safety Evaluation Report with Open Items**

September 19, 2012

Brian K. Harris, Project Manager  
Office of Nuclear Reactor Regulation

# Introduction

- Overview
- Section 2: Scoping and Screening Review
- License Renewal Inspections
- Section 3: Aging Management Program (AMP) and Review Results
- Section 4: Time-Limited Aging Analyses (TLAAs)

# Overview

- LRA Submitted by letter dated August 27, 2010
- Pressurized Water Reactor (PWR), Babcock & Wilcox nuclear steam supply system
- Operating license for NPF-3 expires April 22, 2017
- Located approximately 20 miles east of Toledo, OH

## **Overview cont'd**

- **Scoping and Screening Methodology Audit**
  - Jan 24-28, 2011
- **Aging Management Programs Audit**
  - Feb. 14-25, 2011
- **Regional License Renewal Inspections**
  - April 25-29, 2011
  - May 9-13, 2011
  - Aug 22-26, 2011

## **Section 2 - Structures and Components Subject to Aging Management Review**

- Section 2.1 - Scoping and Screening Methodology
- Section 2.2 - Plant-Level Scoping Results
- Section 2.3 - Scoping and Screening Results Mechanical System
- Section 2.4 & 2.5 - Scoping and Screening Results Structural & Electrical

## **Section 2 - Structures and Components Subject to Aging Management Review**

- The staff determined through a review of documents, discussions and plant walkdowns:
  - nonsafety-related pipe attached to safety-related pipe had not been included within the scope of license renewal to ensure structural integrity
  - equipment that was no longer required had been placed in an abandoned state
  - nonsafety-related domestic water valve and other nonsafety-related fluid filled SSCs, which could potentially impact safety-related SSCs through spray or leakage, had not been included within the scope of license renewal.

# 71002 Inspection Summary

- 54.4 Scoping & Screening SSCs
- Reviewed 28 of 40 AMPs during April-May 2011
- Reviewed AMPs changed due to RAIs during August 2011
- Operating Experience Review

# **71002 Inspection Results**

- Inspection results support a conclusion there is reasonable assurance that the effects of aging will be adequately managed
- Scoping of SSCs was acceptable
- Documentation supporting the application was auditable & retrievable
- Reports 05000346/2011010 & 05000346/2011012

## **Section 3 – Aging Management Review**

- Section 3.0 – Aging Management Programs
- Section 3.1 – Reactor Vessel & Internals
- Section 3.2 – Engineered Safety Features
- Section 3.3 – Auxiliary Systems
- Section 3.4 – Steam and Power Conversion System
- Section 3.5 – Containments, Structures and Component Supports
- Section 3.6 – Electrical and Instrumentation and Controls System

# Safety Review Results

- Safety Evaluation Report with Open Items was issued July 2012
- 4 Open Items
  - OI-3.0.3.2.15-1 Shield Building Cracks
  - OI-B.1.4-1 Operating Experience
  - OI-4.2.4-1 Pressure-Temperature Limits
  - OI-4.2-1 Upper Shelf Energy

# **Shield Building Laminar Cracks**

## **Open Item 3.0.3.2.15-1**

- Cracks observed in multiple locations
- Cracking event driven
- Additional information required on how the applicant will age manage the laminar cracks in the concrete shield building

## **OI 3.0.3.2.15-1: Information Required**

- **Cracking**
  - Justify not verifying extent of cracking with NDE techniques
  - Justify adequacy of the core bore inspection sample size, distribution, and inspection frequency
  - Describe acceptance criteria and inspector qualifications
- **Coating**
  - Describe inspection methods and acceptance criteria
- **Scope of Proposed AMP**
  - Explain how degradation will be prevented or identified in other structures

# **Operating Experience for Aging Management Programs (OI B.1.4-1)**

- Clarify how operating experience review will address aging to ensure continued effectiveness of AMPs or develop new AMPs
- Final License Renewal Interim Staff Guidance, LR-ISG-2011-05, “Ongoing Review of Operating Experience,” issued in March 2012
  - Screening and identification of incoming operating experience items for potential aging impacts
  - Inclusion of AMP findings, GALL Report revisions, and guidance as sources of operating experience
  - Consideration of materials, environments, aging effects, aging mechanisms, and AMPs in operating experience evaluations
  - Training on aging for personnel that implement AMPs and process operating experience
  - Incorporate guidelines for reporting plant-specific operating experience on aging to the industry

## **Section 4 – Time-Limited Aging Analysis**

- Section 4.1 – Introduction
- Section 4.2 – Reactor Vessel Neutron Embrittlement of the Reactor Pressure Vessel and Internals
- Section 4.3 – Metal Fatigue
- Section 4.4 – Environmental Qualification of Electrical Equipment
- Section 4.5 – Concrete Containment Prestress
- Section 4.6 – Fatigue of Primary Containment, Piping, and Components
- Section 4.7 – Other Plant-Specific TLAA

# Pressure-Temperature Limits

## Open Item 4.2.4-1

- LRA did not adequately describe how P-T limit curves would be generated for the PEO (§54.(c)(1)(iii))
- Ferritic components of the reactor coolant pressure boundary, including discontinuities such as nozzles, must be considered as potentially limiting components for the generation of P-T curves

# Upper Shelf Energy (USE)

## Open Item 4.2-1

- Applicant must demonstrate a USE value of at least 50 ft-lb for all RV beltline welds at end of life or submit an equivalent margins analysis to demonstrate equivalent margins of safety against fracture.
  - The applicant did not provide an acceptable basis for using generic initial value of 70 ft-lbs in developing its USE for the Linde 80 RV beltline welds.


# **Proposed License Condition**

## **Containment Vessel Inspection**

- Operating experience with borated water leakage migrating through concrete structures inside containment
- Possibility that leakage has come into contact with inaccessible portions of the steel containment vessel causing corrosion
- Staff has proposed a license condition to remove concrete and inspect a normally inaccessible portion of the vessel

# Conclusion

On the basis of its review and pending satisfactory resolution of the open items, the staff will be able to determine that the requirements of 10 CFR 54.29(a) have been met for the license renewal of Davis-Besse Nuclear Power Station



**U.S.NRC**

United States Nuclear Regulatory Commission

---

*Protecting People and the Environment*

# R-III Summary

Site	License Renewal Date	Extended Period
Braidwood 1 & 2		
Byron 1 & 2		
Clinton		
Davis-Besse		
Dresden 2 & 3	Oct-04	Dec-09; Jan-11
Duane Arnold	Dec-10	
D. C. Cook 1 & 2	Aug-05	
Fermi 2		
Kewaunee	Feb-11	
LaSalle 1 & 2		
Monticello	Nov-06	Sept-10
Palisades	Jan-07	Mar-11
Perry		
Point Beach 1 & 2	Dec-05	Oct-10 (U1)
Prairie Island 1 & 2	Jun-11	
Quad Cities 1 & 2	Oct-04	

# Containment Elevation

