



T. PRESTON GILLESPIE, JR.  
Vice President  
Oconee Nuclear Station

Duke Energy  
ON01VP / 7800 Rochester Hwy.  
Seneca, SC 29672

864-873-4478  
864-873-4208 fax  
T.Gillespie@duke-energy.com

October 25, 2012

U. S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555-0001

Subject: Duke Energy Carolinas, LLC (Duke Energy)  
Oconee Nuclear Station, Unit 2  
Docket Numbers 50-270  
2011 Unit 2 End of Cycle (EOC) 25 Request for Additional  
Information (RAI) Response


On February 29, 2012, Duke Energy submitted information summarizing the results of the 2011 Steam Generator (SG) Tube Inservice Inspections performed during the Oconee Nuclear Station (ONS) Unit 2 EOC-25 Refueling Outage (ADAMS Accession No. ML12066A243).

On September 11, 2012, the NRC Staff electronically requested additional information regarding this SG report. The enclosure provided in this submittal contains Duke Energy's response to the RAI.

This submittal document contains no regulatory commitments.

If you have any questions or require additional information, please contact Corey Gray at (864) 873-6325.

Sincerely,

  
T. Preston Gillespie Jr.,  
Site Vice President

Enclosure

A047  
NRR

U. S. Nuclear Regulatory Commission  
October 25, 2012  
Page 2

xc (w/enclosure): Victor McCree  
Region II Administrator  
U. S. Nuclear Regulatory Commission  
Marquis One Tower  
245 Peachtree Center Ave., NE, Suite 1200  
Atlanta, GA 30303-1257

John Boska  
Project Manager  
(by electronic mail only)  
U. S. Nuclear Regulatory Commission  
One White Flint North, M/S O-8G9A  
11555 Rockville Pike  
Rockville, MD 20852-2746

cc: (w/o enclosure)

NRC Senior Resident Inspector  
Oconee Nuclear Station

Susan Jenkins  
Section Manager  
Division of Waste Management  
Bureau of Land and Waste Management  
SC Dept. of Health & Environmental Control  
2600 Bull St.  
Columbia, SC 29201

## Duke Energy Response to Request for Additional Information on Steam Generator Tube Inspection Report, ME8435

1. Please clarify the results of your steam generator tube plug inspections.

Duke Response

All plugs were visually inspected and no abnormal conditions were detected

2. Please clarify which tubes were plugged.

Duke response

The table below contains the tubes that were repaired

Steam Generator	Row	Tube
A	75	1
A	78	1
A	79	1
A	73	2
A	75	3
A	98	125
A	75	131
A	76	131
A	77	131
A	77	132
B	64	5
B	93	6
B	99	6
B	68	10
B	72	10
B	123	97

3. Please provide the effective full power years that the steam generators have operated for the last several outages

Duke Response

Below is listed the EFPY for each refueling outage since replacement

EOC	Date	EFPY
EOC 20	March 2004	Replacement
EOC 21	October 2005	1.31
EOC 22	April 2007	1.37
EOC 23	October 2008	1.38
EOC 24	April 2010	1.36
EOC 25	October 2011	1.37

4. In your condition monitoring assessment, you assess structural integrity against a limit associated with burst at three times the normal operating differential pressure. Please confirm that this limit is more limiting than the limit associated with a large break loss of coolant accident for both single and multiple sided wear indications.

Duke response

Yes, the limit associated with burst at three times the normal operating differential pressure is more limiting than the limit associated with a large break loss of coolant accident for both single and multiple sided wear indications.