United States Nuclear Regulatory Commission Official Hearing Exhibit

Entergy Nuclear Operations, Inc. In the Matter of: (Indian Point Nuclear Generating Units 2 and 3)

ASLBP #: 07-858-03-LR-BD01 Docket #: 05000247 | 05000286 Exhibit #: NYS00030-00-BD01

Admitted: 10/15/2012

Rejected: Other: Identified: 10/15/2012

Withdrawn: Stricken:

NRC: Event Notification Report for November 15, 2010

NYS000030

Submitted: December 12, 2011

http://www.nrc.gov/reading-rm/doc-collections/event-status/event/2010/...

Power Reactor Facility: WATTS BAR Region: 2 State: TN Unit: [1] [] [] RX Type: [1] W-4-LP,[2] W-4-LP

NRC Notified By: SHAWN HAFEN HQ OPS Officer: HOWIE CROUCH

Emergency Class: NON EMERGENCY 10 CFR Section:

50.72(b)(2)(iv)(B) - RPS ACTUATION - CRITICAL 50.72(b)(3)(iv)(A) - VALID SPECIF SYS ACTUATION

UnitSCRAM CodeRX CRITInitial PWR Initial RX Mode Current PWRCurrent RX Mode 100Power Operation 0 Hot Standby

Event Text

MANUAL REACTOR TRIP DUE TO LOSS OF COOLING TO THE 'A' PHASE MAIN BANK TRANSFORMER

"At 0617 [hrs. EST], Watts Bar experienced a failure of the cooling system to the 'A' phase Main Bank Transformer. Due to rising oil temperatures on the 'A' phase Main Bank Transformer, the reactor was manually tripped at 0652 hrs. All systems responded as designed with no issues."

Event Number: 46418

Event Date: 11/14/2010 Event Time: 06:52 [EST]

Person (Organization): ALAN BLAMEY (R2DO)

Notification Date: 11/14/2010

Notification Time: 09:05 [ET]

Last Update Date: 11/14/2010

All rods inserted during the trip. There were no primary or secondary relief valves that lifted during the transient. The grid is stable and the plant is in a normal shutdown electrical line-up. The reactor is at normal pressure and temperature with decay heat being removed via the steam dumps to condenser with auxiliary feedwater providing steam generator make-up. The cause of the loss of cooling to the 'A' phase Main Bank Transformer was the failure of a control power transformer that supplies the Main Bank Transformer cooling system components.

The licensee has notified the NRC Resident Inspector.