



Entergy Operations, Inc.  
1448 S.R. 333  
Russellville, AR 72802  
Tel 479-858-4704

**Stephanie L. Pyle**  
Manager, Licensing  
Arkansas Nuclear One

2CAN021302

February 5, 2013

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555

SUBJECT: Response to Request for Additional Information  
Request for Relief ANO2-ISI-010  
Arkansas Nuclear One, Unit 2  
Docket No. 50-368  
License No. NPF-6

- REFERENCES:
1. Entergy letter to NRC, "Requests for Relief from American Society of Mechanical Engineers (ASME) Section XI Volumetric and Surface Examination Requirements – Third 10-Year Interval," dated March 26, 2012 (2CAN031203) (ML12086A293)
  2. NRC email to Entergy, "RAI on Request for Relief No. ANO2-ISI-010," dated September 6, 2012 (TAC No. ME8272) (ML12250A771)

Dear Sir or Madam:

Entergy Operations, Inc. requested NRC's approval of several Requests for Relief for Arkansas Nuclear One, Unit 2 via Reference 1. These requests are associated with the requirements of the ASME, Boiler and Pressure Vessel Code, Section XI pertaining to volumetric and surface examinations. In several locations, the required coverage cannot be obtained due to interference or geometry.

In Reference 2, the NRC determined that additional information was needed to complete the review of Request for Relief ANO2-ISI-010 provided in Reference 1. Attached are the requests for additional information and corresponding responses.

This submittal contains no regulatory commitments.

If you have any questions or require additional information, please contact me.

Sincerely,

***Original signed by Stephenie L. Pyle***

SLP/rwc

Attachment: Response to Request for Additional Information – Relief Request –  
ANO2-ISI-010

cc: Mr. Elmo E. Collins  
Regional Administrator  
U. S. Nuclear Regulatory Commission, Region IV  
1600 East Lamar Boulevard  
Arlington, TX 76011-4511

NRC Senior Resident Inspector  
Arkansas Nuclear One  
P. O. Box 310  
London, AR 72847

U. S. Nuclear Regulatory Commission  
Attn: Mr. Kaly Kalyanam  
MS O-8B1  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852

**Attachment to**

**2CAN021302**

**Response to Request for Additional Information  
Relief Request - ANO2-ISI-010**

**RESPONSE TO REQUEST FOR ADDITIONAL INFORMATION**  
**RELIEF REQUEST ANO2-ISI-010**

By letter dated March 26, 2012, Entergy Operations, Inc., submitted proposed alternative ANO2-ISI-010 (Reference 1) requesting relief from required volumetric examination coverage of American Society of Mechanical Engineers (ASME), Boiler and Pressure Vessel Code (Code), Section XI, Examination Category B-J welds under the Arkansas Nuclear One, Unit 2 (ANO-2) Risk Informed Inservice Inspection (RI-ISI) Program (Reference 2). In order to complete the review, the staff requests the following additional information:

- 1. How many Examination Category B-J welds exist at ANO-2 and how many were to be examined under the RI-ISI Program?**

The total population of ANO-2 Examination Category B-J welds is 736. A total of 68 ANO-2 Examination Category B-J welds were to be examined under the RI-ISI program during the third 10-year interval.

- 2. How many Examination Category B-J welds for which adequate coverage was obtained were examined with ASME Code, Section XI, Appendix VIII qualified procedures?**

Thirty four (34) Examination Category B-J welds were examined with ASME Code, Section XI, Appendix VIII qualified procedures and completed with the required coverage obtained.

- 3. Describe the procedure used for calculating the scan coverage.**

Scan coverage was calculated by illustrating the cross-sectional profile of the weld with the Code required examination volume being depicted as a rectangle at the lower  $1/3t$  of the component in a scale drawing. The volume of the rectangle was then calculated.

The extent of scanning with the appropriate angle beam transducer(s) was then overlaid on the examination volume in the axial direction scan which interrogates for circumferential flaws. Any limitation to these scans providing 100% coverage on both sides of the weld is documented.

The extent of any scan limitation is measured, and the volume calculated.

The volume of the area scanned is divided by the total volume to determine the estimated percentage of coverage.

Circumferential scans for axial flaws were performed on the adjacent material and the weld crown to the extent possible. These scans were not credited in the coverage calculation.

**4. For each of the 30 subject Examination Category B-J welds for which adequate examination coverage could not be obtained:**

**a. Specify the safety significance classification (High or Medium) of each.**

See Table 1.

**b. Specify whether it was examined using an ASME Code, Section XI, Appendix VIII qualified procedure.**

See Table 1.

**c. Specify the diameter and wall thickness, and the materials of construction**

See Table 1.

**d. Provide accurately proportioned drawings clearly showing the area of missed examination coverage for each weld. Describe the reason for the missed coverage.**

See Table 1 and figures.

**e. Was the weld examined under the RI-ISI program? For those welds that are described by ASME Code, Section XI, Table IWB-2500-1 item numbers (e.g., B9.11, B9.21) identify any potential degradation mechanism the welds may be susceptible to.**

See Table 1.

**f. For those welds that have a potential degradation mechanism, explain why the examination coverage achieved is adequate to detect the potential degradation mechanism. Was an adjacent weld examined?**

See Table 1.

Of the 30 welds reported with limited examinations, 11 had identified degradation mechanisms. Of the 11 with degradation mechanisms, six had adjacent components examined during the third 10-year interval.

Other Examination Category B-J components that were not selected for examination by volumetric processes but are examined during System Pressure Tests and plant walk-downs have not been found to have degradation issues. The examinations that have been performed, demonstrate effective inservice inspection (ISI) rigor.

- g. For those welds that do not have a potential degradation mechanism, explain why other welds with the same safety significance, for which adequate examination coverage could be achieved, are not being examined.**

The component selection process purposely includes welds that have configurations to fittings such as elbows, tees, valves and nozzles. To remove these components in favor of a non-restricted component, e.g., pipe to pipe, would result in an ISI program selection process that would not be conservative or represent the piping system configurations.

- h. For those welds where the scan in the axial direction was performed from one side of the weld only, was a best effort attempt made to scan the material on the opposite side of the weld? If not, explain why this was not done and discuss any benefit that a best effort scan may provide.**

Review of the data sheets indicates that best effort scanning was performed on both sides of the weld joint where accessible and feasible. Generally, it is not feasible to scan from a valve side or branch connection due to material, surface condition, or part geometry.

## REFERENCES

1. **“Requests for Relief from American Society of Mechanical Engineers (ASME) Section XI Volumetric and Surface Examination Requirements – Third 10-Yewar Interval,” Agencywide Documents Access and Management System (ADAMS) Accession No. ML 12086A293**
2. **“Safety Evaluation by the Office of Nuclear Reactor Regulation, Proposal to Use ASME Code Case N-578 as an Alternative to ASME Code Section XI, Table IWX-2500,” ADAMS Accession Nos. 9901050347 and 9901050353**

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.11	02-T-082	Reactor Vessel Closure Head (RVCH) Instrument Nozzle Tube to Flange #82	None Identified	Y 2008 2R19	5.565	0.563	Stainless Steel (SS) to SB-167 Nickel-Chromium-Iron (Ni-Cr-Fe)	Missed coverage was due to Instrument Nozzle Tube to Flange/Weld Configuration. The inside surface was examined. The upper portion of the code volume was missed. 80% exam. See Figure 1	N	N/A	N/A
B9.11	02-T-083	RVCH Instrument Nozzle Tube to Flange #83	None Identified	Y 2008 2R19	5.565	0.563	SS to SB-167 Ni-Cr-Fe	Missed coverage was due to Instrument Nozzle Tube to Flange/Weld Configuration. The inside surface was examined. The upper portion of the code volume was missed. 80% exam. See Figure 2	N	N/A	N/A
B9.11	21-001	Safety Injection Loop 1A Safe End to Nozzle Circumferential (Circ) Weld – Dissimilar Metal (DM) Weld	High	N 2000 2R14	12.0	1.125	SA-351 CF-8M CSS to SA-182 CS	Missed coverage was due to the Safe End to Nozzle Weld Configuration. 100% of the volume was scanned; however, the nozzle side was only scanned in one direction. 82.5% exam. See Figure 3	Y	None Identified	N
R1.11	21-007	Safety Injection Loop 1A Elbow to Valve Circ Weld	Med	Y 2009 2R20	12.0	1.125	SS SA-403 WP 316	Missed coverage was due to Single Side exam due to the Elbow to Valve Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 4	Y	Intergranular Stress Corrosion Cracking (IGSCC) Thermal Stratification, Cycling, and Stripping (TASCS)	N

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.11	22-001	Safety Injection Loop 1B Safe End to Nozzle Circ Weld – DM Weld	High	N 2000 2R14	12.0	1.125	SA-351 CF-8M CSS to SA-182 CS	Missed coverage was due to the Safe End to Nozzle Weld Configuration. 100% of the volume was scanned; however, most of the nozzle side was only scanned in one direction. 70% exam. See Figure 5	Y	None Identified	N
R1.11	22-004	Safety Injection Loop 1B Valve to Pipe Circ Weld	High	Y 2005 2R17	12.0	1.125	SS SA-376 TP 316	Missed coverage was due to single side exam due to the Valve to Pipe Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 6	Y	None Identified	Y
R1.11	22-005	Safety Injection Loop 1B Pipe to Valve Circ Weld	Med	Y 2005 2R17	12.0	1.125	SS SA-376 TP 316	Missed coverage was due to Single Side exam due to the Pipe to Valve Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 7	Y	IGSCC TASCS	Y
B9.11	23-001	Safety Injection Loop 2A Safe End to Nozzle Circ Weld – DM Weld	High	N 2000 2R14	12.0	1.125	SA-351 CF-8M CSS to SA-182 CS	Missed Coverage was due to the Safe End to Nozzle Weld Configuration. 100% of the volume was scanned; however, the nozzle side was only scanned in one direction. 70% exam. See Figure 8	Y	None Identified	N

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.11	23-006	Safety Injection Loop 2A Valve to Pipe Circ Weld	High	Y 2002 2R15	12.0	1.125	SS SA-376 TP 316	Missed coverage was due to Single Side exam due to the Valve to Pipe Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 9	Y	None Identified	Y
B9.11	23-007	Safety Injection Loop 2A Pipe to Valve Circ Weld	Med	Y 2002 2R15	12.0	1.125	SS SA-376 TP 316	Missed coverage was due to Single Side exam due to the Pipe to Valve Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 10	Y	IGSCC TASCS	Y
B9.11	24-001	Safety Injection Loop 2B Safe End to Nozzle Circ Weld – DM Weld	High	N 2000 2R14	12.0	1.125	SA-351 CF- 8M CSS to SA-182 CS	Missed coverage was due to the Safe End to Nozzle Weld Configuration. 100% of the volume was scanned; however, the nozzle side was only scanned in one direction. 66.5% exam. See Figure 11	Y	None Identified	N
R1.11	24-006	Safety Injection Loop 2B Pipe to Valve Circ Weld	Med	Y 2006 2R18	12.0	1.125	SS SA-376 TP 316	Missed coverage was due to Single Side exam due to the Pipe to Valve Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 12	Y	IGSCC TASCS	N

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.11	25-024	Shutdown Cooling Pipe to Weld-o-let Circ Weld	High	Y 2002 2R15	3.0	0.438	SA-312 TP 316 SS to SA-182 F316 SS	Missed coverage was due to Single Side exam due to the Pipe to Weld-o-let Configuration where coverage was limited in the upper code volume. 68.75% exam. See Figure 13	Y	TASCS	Y
B9.21	27-001	Pressurizer Spray Loop 1B Safe End to Nozzle Circ Weld – DM Weld	Med	N 2R14 2002	3.0	0.438	SA-182 TP 316 SS to SA-105 CS	Missed coverage was due to the Nozzle to Safe End Weld and adjacent Pipe Weld Configuration. The area of limited coverage is in the base material on the Safe End side. 83% exam. See Figure 14	Y	None Identified	Y
R1.20	27-002	Pressurizer Spray Piping Loop 1B Elbow to Safe End Circ Weld	Med	Y 2006 2R18	3.0	0.438	SA-403 WP316 SS to SA-182 TP 316	Missed coverage was due to the intrados of the elbow configuration for approximately 33% of scan on one side. Volume was scanned 100% in one direction. 83% exam. See Figure 15	Y	None Identified	Y
R1.20	27-003	Pressurizer Spray Piping Loop 1B Elbow to Pipe Circ Weld	Med	Y 2006 2R18	3.0	0.438	SS SA-312 TP 316	Missed coverage was due to the intrados of the elbow configuration for approximately 33% of scan on one side. Volume was scanned 100% in one direction. 83% exam. See Figure 16	Y	None Identified	Y

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
R1.20	27-065	Pressurizer Spray Piping Loop 1B Valve to Pipe Circ Weld	Med	Y 2005 2R17	3.0	0.438	SS SA-312 TP 316	Missed coverage was due to Single Side exam due to the Valve to Pipe Configuration. Sound was projected into the valve side of the weld. Coverage volume limited to 50% due to procedure qualification restrictions. See Figure 17	Y	None Identified	Y
R1.20	27-066	Pressurizer Spray Piping Loop 1B Pipe to Tee Circ Weld	Med	Y 2005 2R17	3.0	0.438	SS SA-312 TP 316	Missed coverage was due to the tee configuration for approximately 55% of scan on one side. 73% exam. See Figure 18	Y	None Identified	Y
B9.21	40-005	Charging Piping Loop 1A Valve to Pipe Circ Weld	Med	Y 2002 2R15	2.0	0.344	SS SA-312 TP 316	Missed coverage was due to Single Side exam due to the Valve to Pipe Configuration. Volume was limited on the valve side. 59.6% exam. See Figure 19	Y	None Identified	N
B9.21	40-008	Charging Piping Loop 1A Pipe to Elbow Circ Weld	Med	Y 2002 2R15	2.0	0.344	SS SA-312 TP 316 to SA- 403 WP 316	Missed coverage was due to the intrados of the elbow configuration for approximately 20% on one side and weld crown. 74% exam. See Figure 20	Y	None Identified	Y
R1.11	40-025	Charging Piping Loop 1A Elbow to Safe End Circ Weld	High	Y 2009 2R20	2.0	0.344	SS/SS SA-403 TP 316 to SA- 182 TP 316	Missed coverage was due to the intrados of the elbow configuration for approximately 30% on one side. 85% exam. See Figure 21	Y	Thermal Transient (TT)	N

**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.21	41-003	Charging Piping Loop 2A Valve to Pipe Circ Weld	Med	Y 2002 2R15	2.0	0.344	SS SA-312 TP 316	Missed coverage was due to Single Side exam due to the Valve to Pipe Configuration. Volume was limited on the valve side. 60% exam. See Figure 22	Y	None Identified	N
B9.21	41-003C	Charging Piping Loop 2A Tee to Pipe Circ Weld	Med	Y 2002 2R15	2.0	0.344	SS SA-312 TP 316	Missed coverage was due to Single Side exam due to the Tee to Pipe configuration. Volume was limited on the Tee side. 60% exam. See Figure 23	Y	None Identified	N
B9.11	43-022	Pressurizer LTOP Tee to Pipe Circ Weld	High	Y 2003 2R16	6.0	0.562	SS SA-312 TP 316	Missed coverage was due to the Tee to Pipe configuration and branch connection. Volume was limited in base material. 71.2% exam. See Figure 24	Y	TASCS	Y
R1.11	43-023	Pressurizer LTOP Tee to Pipe Circ Weld	High	Y 2005 2R17	6.0	0.562	SS SA-312 TP 316	Missed coverage was due to the Tee to Pipe configuration. Sound was projected into Tee side but scan credit restricted by procedure as single side. 81% exam. See Figure 25	Y	TASCS	Y
B9.11	43-027	Pressurizer LTOP Pipe to Valve Circ Weld	Med	Y 2002 2R15	4.0	0.438	SS SA-312 TP 316	Missed coverage was due to Single Side exam due to the Valve to Pipe Configuration. Volume was limited on the valve side. 67.6% exam. See Figure 26	Y	TASCS TT	N


**Table 1**  
**Limited B-J Examinations**

Component Description			Additional Information								
Item Number	Comp. ID	Item Description	Safety Significance (High or Med)	Examined with ASME Sect. XI App VIII procedure	Dia. (in)	Wall Thick. (in)	Material	Reason for missed coverage	Examined RI-ISI (Y/N)	Degradation Mechanism	Adjacent Weld Examined (Y/N)
B9.11	43-033	Pressurizer LTOP Tee to Pipe Circ Weld	Med	Y 2002 2R15	3.0	0.438	SS SA-312 TP 316	Missed coverage was due to the Tee to Pipe configuration. Volume was limited on Tee side. 72.5% exam. See Figure 27	Y	TASCS TT	N
R1.20	13-008	RCP 2P-32C Discharge Nozzle SE to Pipe Circ Weld -DM Weld	Med	Y 2009 2R20	30.0	3.25	CSS/SS to SA-533- 67A	Missed Coverage was due to Cast Stainless Steel Safe End Side and Weld Crown. Procedure is restricted from crediting Centrifugal Cast Stainless Steel (CCSS) volume credit. Scanned with Phased Array. 60.1% exam. See Figure 28	Y	None Identified	N
R1.20	15-008	RCP 2P-32D Discharge Nozzle SE to Pipe Circ Weld-DM Weld	Med	Y 2009 2R10	30.0	3.25	CSS/SS to SA-533- 67A	Missed Coverage was due to Cast Stainless Steel Safe End Side and Weld Crown. Procedure restricted from crediting CCSS volume credit. Scanned with Phased Array. 62.8% exam. See Figure 29	Y	None Identified	N
R1.11	29-056	Pressurizer Auxiliary Spray Pipe to Tee Circ Weld	High	Y 2008 2R19	2.0	0.344	SS SA-312 TP 316	Missed coverage was due to the Tee to Pipe configuration. Sound was projected into Tee side but coverage volume limited to 50% due to procedure qualification restrictions. See Figure 30	Y	TASCS	Y

**Figure 1**

**Scan Plan and Coverage for ISI Component 02-T-082**


Not to Scale



**Figure 2**


**Scan Plan and Coverage for ISI Component 02-T-083**

Not to Scale




**Figure 3**  
**Scan Plan and Coverage for ISI Component 21-001**

Not to Scale



**Figure 4**  
**Scan Plan and Coverage for ISI Component 21-007**


Not to Scale



**Figure 5**

**Scan Plan and Coverage for ISI Component 22-001**


Not to Scale



**Figure 6**

**Scan Plan and Coverage for ISI Component 22-004**


Not to Scale



**Figure 7**

**Scan Plan and Coverage for ISI Component 22-005**


Not to Scale




**Figure 8**

**Scan Plan and Coverage for ISI Component 23-001**


Not to Scale



**Figure 9**  
**Scan Plan and Coverage for ISI Component 23-006**  
Not to Scale




**Figure 10**  
**Scan Plan and Coverage for ISI Component 23-007**  
Not to Scale




**Figure 11**  
**Scan Plan and Coverage for ISI Component 24-001**

Not to Scale



**Figure 12**  
**Scan Plan and Coverage for ISI Component 24-006**


Not to Scale



**Figure 13**

**Scan Plan and Coverage for ISI Component 25-024**


Not to Scale



**Figure 14**

**Scan Plan and Coverage for ISI Component 27-001**


Not to Scale



**Figure 15**

**Scan Plan and Coverage for ISI Component 27-002**


Not to Scale



**Figure 16**

**Scan Plan and Coverage for ISI Component 27-003**


Not to Scale



**Figure 17**

**Scan Plan and Coverage for ISI Component 27-065**


Not to Scale



**Figure 18**


**Scan Plan and Coverage for ISI Component 27-066**

Not to Scale




**Figure 19**  
**Scan Plan and Coverage for ISI Component 40-005**

Not to Scale




**Figure 20**  
**Scan Plan and Coverage for ISI Component 40-008**

Not to Scale




**Figure 21**  
**Scan Plan and Coverage for ISI Component 40-025**

Not to Scale



**Figure 22**  
**Scan Plan and Coverage for ISI Component 41-003**


Not to Scale



**Figure 23**

**Scan Plan and Coverage for ISI Component 41-003C**


Not to Scale




**Figure 24**

**Scan Plan and Coverage for ISI Component 43-022**


Not to Scale



**Figure 25**  
**Scan Plan and Coverage for ISI Component 43-023**  
Not to Scale




**Figure 26**  
**Scan Plan and Coverage for ISI Component 43-027**  
Not to Scale



**Figure 27**

**Scan Plan and Coverage for ISI Component 43-033**


Not to Scale



**Figure 28**


**Scan Plan and Coverage for ISI Component 13-008**

Not to Scale



**Figure 29**  
**Scan Plan and Coverage for ISI Component 15-008**

Not to Scale



**Figure 30**  
**Scan Plan and Coverage for ISI Component 29-056**

Not to Scale

