



**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:  City of Independence Water Pollution Department Independence, MO 64051  REPORT NUMBER(S) 13-01	2. NRC/REGIONAL OFFICE  Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S)  030-31871	4. LICENSE NUMBER(S)  24-26236-01	5. DATE(S) OF INSPECTION  3/6/2013
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED IP 87124	7. INSPECTION FOCUS AREAS 03.01 through 03.07
---	--

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 3120	2. PRIORITY 5	3. LICENSEE CONTACT Dorris Bender	4. TELEPHONE NUMBER (816) 325-7711
----------------------------	------------------	--------------------------------------	---------------------------------------

Main Office Inspection      Next Inspection Date: 3/6/2018

Field Office Inspection \_\_\_\_\_

Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

The licensee is a city owned and operated wastewater treatment facility. The licensee possesses two specifically licensed fixed level gauges containing licensed material (Texas Nuclear Model 5038). Currently, two individuals are involved with use and oversight of the devices including the RSO. Gauges are leak tested at six-month and three-year frequencies in accordance with manufacturers specifications. Inventories and shutter checks are performed at required frequencies (36 months).

The licensee is authorized to remove and/or relocate gauges, however, according to the RSO, gauges are relocated, removed, etc. by the manufacturer. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer.

**Performance Observations**

The plant facility was toured and the two gauges were observed in conjunction with proper posting and labeling with the licensee's current inventory. Proper lock-out and leak test procedures were also adequately described. Interviews conducted with plant workers revealed that under no circumstances would a vessel be entered without RSO supervision of lock-out/tag-out procedures. The RSO indicated that he gives annual refresher training. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

No violations of NRC requirements were identified.