

W. Grover Hettel Columbia Generating Station P.O. Box 968, PE23 Richland, WA 99352-0968 Ph. 509.377.8311 | F. 509.377.4150 wghettel@energy-northwest.com

March 8, 2013 GO2-13-040

10 CFR 50.73

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555-0001

Subject:

COLUMBIA GENERATING STATION, DOCKET NO. 50-397

LICENSEE EVENT REPORT NO. 2012-006-01

Dear Sir or Madam:

Transmitted herewith is Revision 1 to Licensee Event Report No. 2012-006 for Columbia Generating Station. This report is submitted pursuant to 10 CFR 50.73(a)(2)(v). The attached report discusses being in a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident.

There are no commitments being made to the NRC by this letter. If you have any questions or require additional information, please contact Mr. ZK Dunham at (509) 377-4735.

Respectfully,

WG Hettel

Vice President, Operations

Attachment: Licensee Event Report 2012-006-01

cc: NRC Region IV Administrator NRC NRR Project Manager

NRC Senior Resident Inspector/988C

AJ Rapacz - BPA/1399

WA Horin – Winston & Strawn

IE22 NRR

																	
NRC FORM 366 U.S. NUCLEAR REGULATORY COMMISSION					SION AF	APPROVED BY OMB NO. 3150-0104 EXPIRES 10/31/2013											
(10-2010) LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)							Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov , and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.										
1. FACILIT						2.	2. DOCKET NUMBER					3. P					
	Cc	iumbiز	a Genera	ting Station			05000397						1 OF 3				
4. TITLE																	
Both Divisions of SDC Isolation Valves Made Inoperable																	
5. EV	5. EVENT DATE			6. LER NUMBER		7. R	EPO	ORT DATE			8. OTHE			R FACILITIES II			
MONTH	DAY	YEAF	R YEAR	SEQUENTIAL NUMBER	REV NO.	MONTH	DA	AY	YEAR						(KET NUMBER (05000	
09	19	2012		012 – 006 –		03		8	2013			TY NAME				KET NUMBER 05000	
9. OPERA 1 10. POWER 100			□ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2 □ 20.2	□ 20.2201(d) □ 20. □ 20.2203 (a)(1) □ 20. □ 20.2203(a)(2)(i) □ 50. □ 20.2203(a)(2)(ii) □ 50. □ 20.2203(a)(2)(iii) □ 50. □ 20.2203(a)(2)(iv) □ 50. □ 20.2203(a)(2)(v) □ 50. □ 20.2203(a)(2)(vi) □ 50.			3(a)(3 3(a)(3 3(a)(4 c)(1)(i) c)(1)(ii c)(2) à)(3)(ii à)(2)(i)	(a)(3)(i))) (A) (A) (B) (B)	50.73(a)(2)(vii)				
FACILITY N	JAME				12. LICEN	NSEE CON	TAC	T FO	R THIS L	_E+	R	TEI EPH	ONE NI	MRER /	Include	Area Code)	
Motley Hedges							TELEPHONE NUMBER (Include Area Code) 509-377-8277								Alea Code,		
			13. COMPLE	ETE ONE LINE			DNE	VT F/	AILURE (DES	SCRIBE	D IN THI	S REPO				
		COMPONENT			EPORTABLE TO EPIX			CAUSE		SYSTEM COMPONENT		MANU- FACTURER		REPORTABLE TO EPIX			
14. SUPPLEMENTAL REPORT EXPECTED							15. EXPECTED SUBMISSION			MON	TH	DAY	YEAR				
☐ YES (If yes, complete 15. EXPECTED SUBMISSION DATE) ☐ NO DATE																	
ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines) On September 19, 2012, Energy Northwest (EN) identified that both divisions of Residual Heat Removal (RHR) Shutdown Cooling (SDC) Reactor Vessel isolation valves were inappropriately made inoperable at the same time on multiple occasions in support of maintenance and surveillance testing																	
during the 2011 refueling outage (P. 20). This planned incorrebility of the SDC isolation vege																	

On September 19, 2012, Energy Northwest (EN) identified that both divisions of Residual Heat Removal (RHR) Shutdown Cooling (SDC) Reactor Vessel isolation valves were inappropriately made inoperable at the same time on multiple occasions in support of maintenance and surveillance testing during the 2011 refueling outage (R-20). This planned inoperability of the SDC isolation valves was performed using procedure SOP-RHR-SDC-BYPASS. SOP-RHR-SDC-BYPASS contains the specific steps for preventing the closure of each of the SDC isolation valves and the subsequent restoration steps. SOP-RHR-SDC-BYPASS did not contain guidance to allow both divisions SDC isolation valves to be inoperable at the same time. Since both divisions of SDC isolation valves were made inoperable without procedural guidance, this is being reported as a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident.

NRC FORM 366A (10-2010) **U.S. NUCLEAR REGULATORY COMMISSION**

LICENSEE EVENT REPORT (LER) CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE		
Columbia Generating Station	05000397	YEAR	SEQUENTIAL NUMBER	REV NO.	2 OF 3	
Coldinate denotating Station		2	2012 – 006 – 01	2013		

NARRATIVE

Plant Conditions:

Event Description:

On September 19, 2012, Energy Northwest (EN) identified that both divisions of Residual Heat Removal (RHR) Shutdown Cooling (SDC) [EIIS: BO] Reactor Vessel isolation valves [EIIS: ISV] were inappropriately made inoperable at the same time on multiple occasions in support of maintenance and surveillance testing during the 2011 refueling outage (R-20). This issue was identified and entered into the Columbia Generating Station (Columbia) corrective action program following review of the NRC Operating Experience Smart Sample (OpESS) 2012/02, Revision 1. All required Technical Specification (TS) Conditions for inoperable primary containment isolation valves were entered when the valves were made inoperable, and compliance with TS Actions was maintained. No operations with a potential to drain the reactor vessel were in progress. Columbia was in Mode 5 with the vessel flooded up. During R-20, EN implemented a plant modification to change the Group 1 containment isolation valves [EIIS: ISV] isolation signal of reactor water level from level 2 to level 1. The NRC granted permission for this change to TS in a letter dated August 18, 2009 (TAC NO. MD9598). This planned inoperability of the SDC isolation valves, in support of the maintenance and surveillance activities associated with the modification to change the isolation signal from level 2 to level 1, was performed using procedure SOP-RHR-SDC-BYPASS. SOP-RHR-SDC-BYPASS contains the specific steps for preventing the closure of each of the SDC isolation valves and the subsequent restoration steps. SOP-RHR-SDC-BYPASS did not contain guidance to allow both divisions of SDC isolation valves to be inoperable at the same time. Since both divisions of the SDC isolation valves were made inoperable and the approved procedure did not provide specific guidance for removal of both divisions at the same time, this is being reported as a condition that could have prevented the fulfillment of the safety function of systems that are needed to remove residual heat and to mitigate the consequences of an accident. This condition is reportable under 10 CFR 50.73(a)(2)(v)(B) and 50.73(a)(2)(v)(D).

Extent of Condition:

An extent of condition review was performed. In the last three years, both divisions of RHR SDC isolation valves being inoperable at the same time was during R-20. There were multiple instances in which this occurred in R-20.

A similar issue occurs during transfer of a Reactor Protection System bus. Both divisions of containment isolations valves for RHR SDC and Reactor Water Cleanup [EIIS: CE] are made inoperable.

Immediate Corrective Action:

No immediate corrective action was required.

Cause:

Apparent Cause: The operating crews inappropriately de-energized both divisions of RHR SDC isolation valves in the effort to minimize the potential for the loss of shutdown cooling without adequate procedural guidance.

LICENSEE EVENT REPORT (LER)

CONTINUATION SHEET

I						
1. FACILITY NAME	2. DOCKET		6. LER NUMBER	3. PAGE		
Columbia Generating Station	05000397	YEAR	SEQUENTIAL NUMBER	REV NO.	3 OF 3	
Columbia acherating Station		2	2012 – 006 – 01	3013		

NARRATIVE

Operating Experience & Previous Occurrences:

This had not previously occurred at Columbia.

A similar issue was discussed in Operating Experience Smart Sample (OpESS) 2012/02, Revision 1.

Further Corrective Actions:

Training for Licensed Operators will be conducted on the requirement of TS bases 3.0.2 for intentionally entering TS Actions as identified by the Performance Analysis. Selected plant procedures will be revised to discuss "Operational Convenience".

Assessment of Safety Consequences:

Each occurrence took place when the plant was in Mode 5 with the reactor vessel in a flooded condition. No operations with a potential to drain the vessel were in progress. The inoperability of the RHR SDC isolation valves was not due to equipment failure. If a loss of reactor level was detected, the isolation valves could be quickly restored to an operable condition. All required TS conditions were entered. Compliance with all TS actions was maintained. There was no significant impact on safety consequences.

Energy Industry Identification System (EIIS) Information

EllS codes are bracketed [] where applicable in the narrative.