

Alex L. Javorik
Columbia Generating Station
P.O. Box 968, PE04
Richland, WA 99352-0968
Ph. 509.377.8555 | F. 509.377.2354
aljavorik@energy-northwest.com

April 6, 2013 GO2-13-056

10 CFR 50.55a

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, D.C. 20555-0001

Subject:

COLUMBIA GENERATING STATION, DOCKET NO. 50-397

RELIEF REQUEST 3ISI-13 FOR TEMPORARY NON-CODE REPAIR OF

REACTOR WATER CLEANUP SYSTEM PIPING - COMMITMENT

CHANGE

Reference:

Letter GO2-13-055, AL Javorik (Energy Northwest) to NRC, "Relief Request

ISI3-13 for Temporary Non-Code Repair of Reactor Water Cleanup System

Piping," dated April 5, 2013

Dear Sir or Madam:

In the referenced letter, Energy Northwest provided a relief request to perform a temporary non-code repair of reactor water cleanup system piping. This letter revises commitments made in the referenced letter. Attachment 1 contains a revised list of commitments.

If you have any questions or require additional information regarding this matter, please contact Ms. LL Williams, Licensing Supervisor, at (509) 377-8148.

Respectfully,

A.L. Javorik

Vice President, Engineering

Attachment 1: List of Commitments

cc: NRC RIV Regional Administrator

NRC NRR Project Manager

NRC Senior Resident Inspector/988C

AJ Rapacz - BPA/1399

WA Horin - Winston & Strawn

A 047 NRR

RELIEF REQUEST 3ISI-13 FOR TEMPORARY NON-CODE REPAIR OF REACTOR WATER CLEANUP SYSTEM PIPING — COMMITMENT CHANGE

Attachment 1
Page 1 of 1

List of Commitments

The following table is a revision to regulatory commitments identified in the referenced letter.

	
Commitment	Scheduled Completion
	Date
The post-maintenance testing will include a VT-2	Prior to return of RWCU to
examination.	service
Energy Northwest will perform an augmented inspection via UT or RT to assess the overall degradation of the	
affected system. The inspection of at least 10 susceptible	Prior to startup from
(and accessible) locations for high energy lines will be	Refueling Outage 21
performed. Locations that were re-welded during initial	(June 2013)
fabrication of the RWCU regenerative heat exchanger skid	
will be included in this augmented inspection.	
Energy Northwest will install a camera in the RWCU heat exchanger room to provide leak monitoring until the outage.	April 8, 2013
The non-code repair will be replaced with an ASME Code repair.	Prior to startup from Refueling Outage 21 (June 2013)
Energy Northwest will perform a surface examination of the fillet weld associated with the repair.	Prior to return of RWCU to service
Energy Northwest will obtain additional wall thickness measurements along the circumference of the elbow downstream of the weld.	Prior to return of RWCU to service

Reference:

Letter GO2-13-055, AL Javorik (Energy Northwest) to NRC, "Relief Request ISI3-13 for Temporary Non-Code Repair of Reactor Water Cleanup System Piping," dated April 5, 2013