

Thomas A. Lynch
Vice President - Farley

**Southern Nuclear
Operating Company, Inc.**
Farley Nuclear Plant
Post Office Drawer 470
Ashford, Alabama 36312

Tel 334.814.4511
Fax 334.814.4728



July 26, 2013

Docket Nos.: 50-364

NL-13-1525

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D. C. 20555-0001

Joseph M. Farley Nuclear Plant, Unit 2
Special Report 2013-001-00, Nonfunctional Radiation Monitor R-60B

Ladies and Gentlemen:

In accordance with the requirements of Technical Requirements Manual (TRM) TR 13.3.4, the enclosed Special Report No. 2013-001-00 (Unit 2) is submitted.

This letter contains no NRC commitments. If you have any questions, please contact Bill Arens at (334) 814-4765.

Sincerely,

A handwritten signature in black ink that reads "T. Lynch". The signature is written in a cursive, slightly slanted style.

T. A. Lynch
Vice President – Farley

TAL/WNA

Enclosure: Special Report 2013-001-00

cc: Southern Nuclear Operating Company
Mr. S. E. Kuczynski, Chairman, President & CEO
Mr. D. G. Bost, Executive Vice President & Chief Nuclear Officer
Mr. T. A. Lynch, Vice President – Farley
Mr. B. L. Ivey, Vice President – Regulatory Affairs
Mr. B. J. Adams, Vice President – Fleet Operations
Mr. J. G. Horn, Regulatory Affairs Manager - Farley
RTYPE: CFA04.054

U. S. Nuclear Regulatory Commission
Mr. V. M. McCree, Regional Administrator
Mr. R. E. Martin, NRR Project Manager - Farley
Mr. P. K. Niebaum, Senior Resident - Farley

Joseph M. Farley Nuclear Plant, Unit 2
Special Report 2013-001-00, Nonfunctional Radiation Monitor R-60B

Enclosure

Special Report 2013-001-00

Joseph M. Farley Nuclear Plant, Unit 2
Special Report 2013-001-00, Nonfunctional Radiation Monitor R-60B

Enclosure

Special Report 2013-001-00

This Special Report is being submitted due to the Unit 2 radiation monitor R-60B (Main Steam Relief and Atmospheric Steam Dump Discharge) not being restored to functional status within the time required by Technical Requirements Manual (TRM) TR 13.3.4. The TRM requires that the monitor be restored to functional status within 7 days or submit a Special Report within the following 14 days.

At 1215 on July 9, 2013 radiation monitor R-60B was declared nonfunctional due to a failed indication on the control panel. A TRM Required Action was entered requiring restoration to functional status by July 16, 2013 at 1215 hours and a work order (SNC505391) was generated to repair R-60B.

Troubleshooting isolated the instrument problem to the detector. Due to the detector's location on the main steam valve room roof in close proximity to steam generator safety relief valve exhaust piping, repair of the monitor is a personnel safety risk should any relief valve lift during the repair effort. Therefore, repair of the monitor will be performed only under cold shutdown conditions. R-60B is scheduled to be repaired during the next refueling outage currently scheduled for fall 2014 or at the next outage of sufficient duration when the plant will be in cold shutdown. Compensatory measures have been established and TRM action requirements are being met for radiation monitor R-60B nonfunctionality.