



77C

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V  
1990 N. CALIFORNIA BOULEVARD  
SUITE 202, WALNUT CREEK PLAZA  
WALNUT CREEK, CALIFORNIA 94596

June 27, 1980

Docket Nos. 50-361, 50-362

Southern California Edison Company  
P. O. Box 800  
2244 Walnut Grove Avenue  
Rosemead, California 91770

Attention: Dr. L. T. Papay, Vice President  
Advanced Engineering

Gentlemen:

Enclosed is IE Bulletin No. 80-16 which requires action by you with regard to your power facility(ies) with an operating license or a construction permit. Also enclosed is IE Circular 80-16 for information.

In order to assist the NRC in evaluating the value/impact of each Bulletin on licensees, it would be helpful if you would provide an estimate of the manpower expended in conduct of the review and preparation of the report(s) required by the Bulletin. Please estimate separately the manpower associated with corrective actions necessary following identification of problems through the Bulletin.

Should you have any questions regarding the Bulletin or Circular or the actions required of you, please contact this office.

Sincerely,

R. H. Engelken  
Director

Enclosures:

1. IE Bulletin No. 80-16
2. IE Circular No. 80-16
3. List of Recently Issued  
IE Bulletins and Circulars

cc w/enclosures:  
R. Dietch, SCE

8007230393

AO/I  
2

60

SSINS No.: 6820  
Accession No.:  
8005050066

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

June 27, 1980

IE Bulletin No. 80-16

POTENTIAL MISAPPLICATION OF ROSEMOUNT INC. MODELS 1151 AND 1152 PRESSURE TRANSMITTERS WITH EITHER "A" OR "D" OUTPUT CODES

Description of Circumstances

The NRC has recently been advised through 10 CFR 21 reports that a potential misapplication problem exists on Rosemount Inc. Models 1151 and 1152 pressure transmitters with either "A" or "D" output codes. The pressure transmitters are used in both pressure and differential pressure applications. Applications include pressurizer pressure monitoring (pressure transmitters) and reactor vessel level monitoring (differential pressure transmitters).

The potential misapplication problem occurs when the above specified transmitters are exposed to excessive over or reverse pressures. These pressures can result in ambiguous signal outputs from the transmitter to control and/or indication components. These ambiguous signals could result in erroneous control action, such as an open signal to a solenoid valve rather than a closed signal, or an erroneous indication signal, such as an indication in the normal operating range when a pressure outside the normal range actually exists.

Enclosure 1 contains Rosemount Inc.'s technical description of the potential application problems for Pressure Transmitters Model 1152. This information is applicable to Model 1151 Pressure Transmitters also. This information includes the reasons for the maloperation of the transmitters, a typical pressure versus current output curve and examples of the results of the maloperations. Available information indicates that the problem was reported to each customer who was furnished the subject transmitters by Rosemount Inc.

Actions to be Taken by Licensees of Power Reactor Operating Facilities and Holders of Construction Permits:

1. Determine if your facility has installed or plans to install Rosemount Inc. Model 1151 or 1152 pressure transmitters with output codes "A" or "D" in any safety-related application.
2. If it is determined that your facility has the transmitters described in 1 above in any safety-related application, determine whether they can be exposed to input pressures that could result in anomalous output signals during normal operation, anticipated transients or design bases accidents. If the affected transmitters can be exposed to input pressures that could result in anomalous output signals, perform a worst case analysis to determine whether the anomalous signals could result in violating any

design basis assumption. The safety-related application shall include control, protective or indication functions. If any safety-related application does not conform to the above requirements address the basis for continued plant operation until the problem is resolved and provide an analysis of all potential adverse system effects which could occur as a result of a postulated pressure transmitter maloperation described in Enclosure 1 of this bulletin. In each instance, the analysis should include the effects of postulated transmitter maloperation as it relates to indication, control and protective functions. The analysis shall address both incorrect automatic system operation and incorrect operator actions caused by erroneous indications. Address the conformance to IEEE 279, Section 4.20 in your analysis. Include in your analysis the following table:

- a. Complete model number.
  - b. Transmitter range limits.
  - c. Transmitter range setting.
  - d. Range of process variable measured for (1) normal and (2) accident conditions.
  - e. Values of process variable which could produce anomalous indication based upon your evaluation.
  - f. Service/function.
3. Submit a complete description of all corrective actions required as a result of your analysis and evaluations, together with the schedule for accomplishing the corrective actions.
  4. Provide the response in writing within 30 days for facilities holding an operating license or are NTOL applicants\* and within 60 days for those facilities holding construction permits. Reports shall be submitted to the Director of the appropriate NRC Regional Office with copies forwarded to the U.S. Nuclear Regulatory Commission, Office of Inspection and Enforcement, Division of Reactor Operations Inspection (for facilities holding an operating license) or Division of Reactor Construction Inspection (for facilities holding a construction permit), Washington, D.C. 20555.

\* The plants that are the subject of the near term operating license reviews are: North Anna 2, Salem 2, Sequoyah 1 & 2, McGuire 1 & 2, Diablo 1 & 2, and Zimmer.

Approved by GAO, B180225 (R0072); clearance expires July 31, 1980. Approval was given under a blanket clearance specifically for identified generic problems.

Enclosure:

Extract from Rosemount Inc.

letter to NRC dated June 6, 1980

EXTRACT FROM ROSEMOUNT, INC.  
LETTER TO NRC DATED JUNE 6, 1980

- (i) Name and address of the individual or individuals informing the Commission.

Not Applicable.

- (ii) Identification of the facility, the activity, or the basic component supplied for such facility or such activity within the United States which is affected by the potential application problem.

Rosemount Model 1152 Pressure Transmitters with output codes "A" or "D".

- (iii) Identification of the firm making the report.

Rosemount Inc. 12001 W. 78th St.  
Eden Prairie, MN. 55344

- (iv) Nature of the potential applications problem.

Rosemount's Model 1152 pressure transmitter provides a specified linear output of 4 to 20 mA throughout the calibrated range of operation. The transmitter output is not specified by Rosemount for pressures outside of the calibrated range of operation. It has been observed in a limited number of transmitters that an output between 4 and 20 mA can occur with certain input pressures outside of the calibrated range. These ambiguous outputs can occur in both an over pressure condition and a reverse pressure condition. Both conditions arise when the center diaphragm of the pressure sensor bottoms out against either of the fixed capacitor plates. In each case the normal capacitance signal becomes a very high capacitance signal which affects the operation of the electronic circuit.

For the over pressure condition, the effect of the high capacitance from the sensor is a modulated output on the oscillator circuit which may cause the output current of the transmitter to drop below 20 mA. In a limited sample size, the ambiguous output during this over pressure condition occurred in 5% of the transmitters at ambient conditions. Referring to the attached graph, this does not occur until the over pressure condition is 140% of the upper range limit regardless of span. At that point a discontinuity can occur with the output current instantaneously decreasing to less than 20 mA. As an example of this potential applications problem, the upper range limit of a range 5 1152 differential pressure transmitter (Model 1152DP5A22) is 750"H<sub>2</sub>O. The range of this pressure transmitter can be set from 0 to 150"H<sub>2</sub>O. If the ambiguous output in the over pressure condition is to occur, it will occur at 140% or more of the upper range limit or, in this case, at pressures 1050"H<sub>2</sub>O (750"H<sub>2</sub>O x 1.4). The transmitter then could give an output less than 20 mA at a pressure that is, in this example, seven

times (1050"H<sub>2</sub>O ' 150"H<sub>2</sub>O) the upper range value. Note that the significant figure for use in determining the pressure above which an ambiguous output can occur is the specified upper range limit (750" H<sub>2</sub>O in this example) not the customer selected upper range value (150"H<sub>2</sub>O in this example).

For the reverse pressure condition, the effect of the high capacitance from the sensor is the oscillator circuit drawing more current which may cause the output current of the transmitter to exceed 4 mA. In a limited sample size, the ambiguous output during this reverse pressure condition occurred in 55% of the transmitters at ambient conditions. Referring to the attached graph, this does not occur until the reverse pressure condition exceeds 140% of the upper range limit regardless of the span. At this point the output may exceed 4 mA. As an example of this potential applications problem consider the range 5 differential transmitter in the previous paragraph. If the ambiguous output in the reverse pressure condition is to occur, it will occur at 140% or more of the upper range limit, or in this case at reversed pressures J 1050" H<sub>2</sub>O (750"H<sub>2</sub>O x 1.4). The transmitter then could give an output greater than 4 mA at a pressure that is, in this example, seven times (1050" H<sub>2</sub>O ' 150" H<sub>2</sub>O) the upper range value, but reversed. Also note that with absolute pressure units a reverse pressure is not possible since the low pressure side of the cell is evacuated. With gage units a reverse pressure is possible only if a vacuum is present on the connected part since the low pressure side of the cell is vented to ambient atmosphere. Since the maximum reverse pressure would be one atmosphere, only range 3 and 4 gage units could obtain a reverse pressure exceeding 140% of the upper range limit.

Due to the effects of radiation or elevated temperature, we believe that the frequency of occurrence of the ambiguous output will be greater in a radiated or an elevated temperature environment than was experienced in our limited sample size testing, which was in a non-radiated ambient temperature environment.

After the occurrence of an ambiguous output from an over pressure or a reverse pressure condition, the transmitter will return to specified operation when the input pressure returns to the calibrated range, provided the over pressure or reverse pressure was within the maximum pressure limits specified by Rosemount.

- (v) The date on which the information of the potential applications problem was obtained.

Amended to March 6, 1980.

- (vi) The number and location of all in use at, supplied for, or being supplied for one or more facilities or activities subject to the regulations in this part.


Not applicable.

- (vii) The corrective action recommended to negate this potential application problem.

The safety system should be analyzed in view of this supplementary report to determine if a potential application problem exists and appropriate corrections to the safety system should be implemented.

- (viii) Any related to the defect or failure to comply about the facility, activity, or basic component that has been, is being, or will be given or purchasers or licensees.

Not applicable.



RECENTLY ISSUED  
IE BULLETINS

Bulletin No.	Subject	Date Issued	Issued To
80-15	Possible Loss Of Hotline With Loss Of Off-Site Power	6/18/80	All nuclear facilities holding OLs
80-14	Degradation of Scram Discharge Volume Capability	6/12/80	All BWR's with an OL
80-13	Cracking In Core Spray Spargers	5/12/80	All BWR's with an OL
80-12	Decay Heat Removal System Operability	5/9/80	Each PWR with an OL
80-11	Masonry Wall Design	5/8/80	All power reactor facilities with an OL, except Trojan
80-10	Contamination of Nonradioactive System and Resulting Potential for Unmonitored, Uncontrolled Release to Environment	5/6/80	All power reactor facilities with an OL or CP
80-09	Hydramotor Actuator Deficiencies	4/17/80	All power reactor operating facilities and holders of power reactor construction permits
80-08	Examination of Containment Liner Penetration Welds	4/7/80	All power reactors with a CP and/or OL no later than April 7, 1980
80-07	BWR Jet Pump Assembly Failure	4/4/80	All GE BWR-3 and BWR-4 facilities with an OL
79-03A	Longitudinal Weld Defects In ASME SA-312 Type 304 Stainless Steel Pipe	4/4/80	All power reactor facilities with an OL or CP
80-06	Engineered Safety Feature (ESF) Reset Controls	3/13/80	All power reactor facilities with an OL



SSINS No.: 6830  
Accession No.:  
8005050067

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
WASHINGTON, D.C. 20555

June 27, 1980

IE Circular No. 80-16

OPERATIONAL DEFICIENCIES IN ROSEMOUNT MODEL 510DU TRIP UNITS AND MODEL 1152  
PRESSURE TRANSMITTERS

Description of Circumstances:

The NRC has recently been advised through a 10 CFR 21 report that operational deficiencies exist in Rosemount Inc. Model 510DU trip units and Model 1152 pressure transmitters as follows:

MODEL 510DU TRIP UNITS

The 510DU trip units have common mode failures of two switches; S1 in the trip status output, LED logic circuit and S2 in the trip output logic circuit. The trip units involved are those with serial numbers 3001 to 4203. The 510DU units having serial numbers within this range that are not trip units are not affected. (i.e., Card Files, Readout Assemblies, Calibration Units, etc.) Malfunction of these switches appears as an open circuit in the output logic upon receipt of an actual trip signal. Switch (S2) failure could result in failure to automatically activate a safety function.

MODEL 1152 PRESSURE TRANSMITTERS

The model 1152 pressure transmitters have a common mode failure of a capacitor when the transmitter operating environmental temperature is greater than 175F, and when the damping potentiometer is rotated clockwise. The failure results in a decrease in transmitter output current of up to 10 percent of the correct current. For example, when the transmitter is used in an indication circuit, the parameter indication would be correspondingly lower than the correct value if the capacitor failure occurred. The failure potentially involves all pressure transmitters with the following model designations:

Rosemount Pressure Transmitter Models:

1152 - - - E - - T0280  
1152 - - - E - - T0445  
1152 - - - E - - T0400

Available information indicates that the problems outlined above have been reported to each customer who was furnished the Model 510DU trip units and Model 1152 pressure transmitters.

RECOMMENDED ACTION FOR LICENSEES AND HOLDERS OF CONSTRUCTION PERMITS

All licensees of nuclear power reactors and holders of construction permits should be aware of the potential problems discussed above. It is recommended that the following actions be taken:

1. Determine if your facility has installed or plans to install the Rosemount Model 510DU trip units and/or the pressure transmitters described herein in any safety-related equipment.
2. If it is determined that your facility has installed or plans to install any of the affected units described herein, contact the supplier for performance of the required modifications to the units to resolve the problems.
3. Modifications should be performed on all affected units prior to plant operation. If the affected units are installed in plants that are operating, the following actions are recommended for continued operation until the units are modified.

a. 510DU Trip Units

A functional test verifying proper operation of the trip units should be performed.

b. Model 1152 Pressure Transmitters

On pressure transmitters that are affected and that may be subjected to operating environmental temperatures greater than 175F, the transmitters should be operated with the damping potentiometer (R12) in the fully counterclockwise position.

CAUTION

The circuit output should be monitored to assure that no action detrimental to operation results from placing R12 in the counterclockwise position, such as spurious tripping caused by unstable operation.

No written response to this circular is required. If you require additional information regarding this matter, contact the Director of the appropriate NRC Regional Office.

IE Circular No. 80-16  
June 27, 1980

Enclosure

RECENTLY ISSUED  
IE CIRCULARS

Circular No.	Subject	Date of Issue	Issued to
80-15	Loss of Reactor Coolant Pump Cooling and Natural Circulation Cooldown	6/20/80	All power reactor facilities with an OL or CP
80-14	Radioactive Contamination of Plant Demineralized Water System and Resultant Internal Contamination of Personnel	6/24/80	All holders of Power and Research Reactor licenses (Operating and Construction Permits), and Fuel Cycle licensees
80-13	Grid Strap Damage in Westinghouse Fuel Assemblies	5/18/80	All holders of Reactor OLs and CPs
80-12	Valve-Shaft-To-Actuator Key May Fall Out of Place When Mounted Below Horizontal Axis	5/14/80	All holders of Reactor OLs and CPs
80-11	Emergency Diesel Generator Lube Oil Cooler Failures	5/13/80	All holders of a power reactor OL or CP
80-10	Failure to Maintain Environmental Qualification of Equipment	4/29/80	All holders of Reactor OLs and CPs
80-09	Problems With Plant Internal Communications Systems	4/28/80	All holders of a power reactor OL or CP
80-08	BWR Technical Specification Inconsistency - RPS Response Time	4/18/80	All General Electric BWR's holding a power reactor OL
80-07	Problems with HPCI Turbine Oil System	4/3/80	All holders of a power reactor OL or CP
80-06	Control and Accountability Systems for Implant Therapy Sources	4/14/80	Medical licensees in Categories G and G1
80-05	Emergency Diesel-Generator Lubricating Oil Addition and Onsite Supply	4/1/80	All holders of a power reactor OL or CP