•	REGUINORY	INFORMAT	ION DISTRIBUT	TEM (RIDS)	-
ACCESSID FACIL: 5 AUTH. N MORGAN, RECIP.	N NBR: 8709110271 0-361 San Onofre Nu AME AUTHOR A H.E. Southern NAME RECIPIEN	DOC.DAT clear St FFILIATI Califorr T AFFILI	E: 87/09/04 NOTARIZE ation, Unit 2, Southe ON ia Edison Co. ATION	ED: NO ern Californ	DOCKET # 05000361
SUBJECT	: LER 87-012-00:on sys inadvertently control room isol employee error Em	870808,c actuate ation sy ployee c	ontrol room emergency d during 31-day funct s radiation monitor.( ounseled.W/8870904 1	y air cleanup tional test o Caused by tr.	) )f
DISTRIB TITLE:	UTION CODE: IE22D 50.73 Licensee Even	COPIES R t Report	ECEIVED:LTR <u>)</u> ENCL (LER), Incident Rpt,	SIZE:	¥
NOTES: E	LD Chandler 1cy.		•		05000361
· .	RECIPIENT ID CODE/NAME PD5 LA ROOD,H	COPIES LTTR EN 1 1 1 1	RECIPIENT ICL ID CODE/NAME PD5 PD	COPIES LTTR ENCL 1 1	-
INTERNAL:	ACRS MICHELSON AEOD/DOA AEOD/DSP/ROAB DEDRO	i i 1 1 2 2 1 1	ACRS MOELLER AEOD/DSP/NAS AEOD/DSP/TPAB NRR/DEST/ADS	2 2 1 1 1 1 1 0	
۰ ۲۰ ۲۰ ۲۰	NRR/DEST/CEB NRR/DEST/ICSB NRR/DEST/MTB NRR/DEST/RSB NRR/DLPQ/HFB	1 1 1 1 1 1 1 1 1 1	NRR/DEST/ELB NRR/DEST/MEB NRR/DEST/PSB NRR/DEST/SGB NRR/DLPQ/QAB	1 1 1 1 1 1 1 1 1 1	
C	NRR/DOEA/EAB NRR/DREP/RPB REG FILE 02 RES TELFORD, J RGN5 ELLE 01	1 1 2 2 1 1 1 1	NRR/DREP/RAB NRR/PMAS/ILRB RES DEPY GI RES/DE/EIB	1 1 1 1 1 1 1 1	
EXTERNAL	EG&G GROH, M LPDR NSIC HARRIS, J	5 5 1 1 1 1	H ST LOBBY WARD NRC PDR NSIC MAYS,G	1 1 1 1 1 1	

NOTES:

1 1

.

TOTAL NUMBER OF COPIES REQUIRED: LTTR 44 ENCL

43

<u> </u>																		
NRC Form 366 (9/83)					L	LICENSEE EVENT REPORT (LER)						U.	U.S. NUCLEAR REGULATORY COMMISSION APPROVED OMB NO. 3150-0104 EXPIRES: 8/31/85					
FACILITY NAME (1)				·				<u>·</u> .						DOCKET	NUMBE	ER (2)	PA	GE (3)
SAN ONOFRE NUCLEAR GENERATING STATION, UNIT 2							. (	)  5 (	0   0	0   3   6   3	l 1 0	F 0 2						
CONTROL RO	OM I	[SOL	ATI	ON S'	YSTE	M (C	RIS	) IN/	ADVERT	ENT	ACTU	ATION DUR	ING	FUNC	TION	AL TES	FING	
EVENT DATE (5) LER NUMBER (6) REPORT DATE (7) OTHER FACILITIES INVOLVED (8)																		
MONTH DAY	YEAR	YEA	R ())	NUM	BER	<u></u> NÜ	MBER	MONTH	DAY	YEAR	SON	GS, UNIT	3	· .		0 5 0		, 3 6 2
0 8 0 8	8 7	8	7 –	0 1	l   2	-  c	010	0   9	0 4	8 7		· ·				0  5  0	0   0	
OPERATING MODE (9)	1	THIS	20.4	02(b)	SUBMI	ITED I	PURSL	20 4		QUIREN		OF 10 CFR $\S$ :	(Check	one or	more	of the follo	wing) (	11)
POWER	 		20.4	05(a)(1	)(i)			50.3	6(c)(1)		Ľ	50.73(a)(2	)(v) )(v)	•		73.71(b) 73.71(c)		
<u>(10)</u> U	9 5	8	20.4	05(a)(1	)(#) )(#)			50.3	6(c)(2)			50.73(a)(2	)(vii)			OTHER (Sp below and	ecify in in Text,	Abstract NRC
			20.4	05(a)(1) 05(a)(1)	)(iii) )(iv)			50.7	3(a)(2)(i) 3(a)(2)(ii	)		50.73(a)(2) 50.73(a)(2)	)(viii)(A )(viii)(E	A) 3)		Form 3664	A)	÷
			20.4	05(a)(1	)(v)			50.7	3(a)(2)(ii	i)		50.73(a)(2)	)(x)					
NAME							LICEN	ISEE C	ONTACT	FORT	HISLE	R (12)		1	TEL	EPHONE	UMBE	
	A NI	стл <sup>-</sup>		1. MAX		~					•			AREA	CODE			
H. L. MUKG	AN,	51A												7	1 4	3 <sub> </sub> 6 <sub> </sub> 8 <sub> </sub>	- 6 2	2 <sub> </sub> 4 <sub> </sub> 1
			MAN						MPONEN					DRT (1	3)			
			τu	RER	· •	ONPRE	os ()			CAUSE	YSTEM	COMPONENT	TU	IRER	TO	ORTABLE NPRDS		
		1																
			SUPP			REPO	PT F	PECT								- <u>1</u>		r
YES (If yes, complete EXPECTED V NO							E SU	EXPECTED SUBMISSION DATE (15)		YEAR								
Abstract (Limit to	1400	space:	s, i.e.,	approx	imate	y fifte	en sir	- igle-spa	ce typewi	ritten lir	nes) (16	)	<u> </u>					
On August 8, 1987, at 1957, with Unit 2 at 95% power and Unit 3 at 100% power, the Control Room Emergency Air Cleanup System (CREACUS) was inadvertently actuated while performing the 31-day functional test on Control Room Isolation System (CRIS) Train B Radiation Monitor.																		
The cause of the CRIS actuation was the failure of the technician to place the monitor back in "Alarm Defeat" prior to releasing the "Reset/Bypass" switch. Recognizing this error, the technician immediately reset the CRIS and returned the monitor to "Alarm Defeat".																		
CREACUS components operated according to design with the exception of Control Room Cabinet Area Emergency Cooling Unit E-423, which did not start. E-423 was subsequently started and stopped by using its Control Room handswitch and also by manually initiating CRIS Train B. It was concluded that the fan failure was associated with the immediate resetting of CRIS by the technician.																		
The technic monitor tes during perf LER 84-077. and a sprin required by Safety Feat	cian stin form Ag-lo v the cure:	inv g we ance des oade e su s Ac	volv ere of ign d s irve tua	ed w brie the cha witc illa tion	as c fed san nge h fo nce Sys	oun on tha r tl proo tem	sele the unct t wi he r cedu rad	ed an even iona 11 i reset ire, liati	d all t. A l tes nstal funct is cur on mor	othe simi t occ l a k tion, rrent nitor	r te lar urre eylo the ly b s in	chnicians inadverte d previou ck switch reby simp eing impl both Uni	s inv ent a usly n for olify lemen its 2	volve actua and the ving ited and	d wi tior was byp the on a 3.	ith rad report bass fu manipu all Eng	iatio IS ed in nctio latio ineer	on on ons red
RC Form 366 -83)	 	870 PDF S	911	1027 ADOC		709 500	04 036 PDR	1						<u>1</u>	Ec	22 4	11	
	·																	

ę

## LICENSEE EVENT REPORT (LER) TEXT CONTINUATION

SAN ONOFRE NUCLEAR GENERATION STATION	DOCKET NUMBER	LER NUMBER	PAGE
<u>UNIT 2</u>	05000361	87-012-00	2 OF 2

On August 8, 1987, at 1957, with Unit 2 at 95% power and Unit 3 at 100% power, the Control Room Emergency Air Cleanup System (CREACUS) (EIIS System Code VI) was inadvertently actuated while performing the 31-day functional test on Control Room Isolation System (CRIS) Train B Radiation Monitor 2/3 RE-7825B (EIIS Component Code RIT).

The technician reported to the Control Room that the cause of the CRIS actuation was his failure to place 2/3 RE 7825 B back in "Alarm Defeat" prior to releasing the "Reset/Bypass" switch (EIIS Component Code HS), and recognizing this error, he had immediately reset the CRIS and returned the monitor to "Alarm Defeat".

CREACUS components operated according to design with the exception of Control Room Cabinet Area Emergency Cooling Unit E-423 (EIIS Component Code FAN), which did not start. The proper operation of E-423 was verified by manually starting and stopping the fan using its Control Room handswitch and also verifying that it would start by manually initiating CRIS Train B. It was concluded that the fan failure was associated with the immediate resetting of CRIS by the technician.

CRIS was reset and CREACUS was returned to the stand-by mode at 2007.

A similar inadvertent actuation of CRIS during performance of the same functional test occurred previously and was reported in LER 84-077 (Docket No. 50-361). A design change that will install a keylock switch for the bypass function and a spring-loaded switch for the reset function, thereby simplifying the manipulations required by the surveillance procedure, is currently being implemented on all ESFAS (Engineered Safety Features Actuation System) radiation monitors in both Units 2 and 3.

The technician involved was counseled and all other technicians involved with radiation monitor surveillances were briefed on the event.

There are no reasonable or credible circumstances which could have increased the severity of the event. The health and safety of the public or plant personnel was not affected.



## Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN STATION MANAGER

TELEPHONE (714) 368-6241

September 4, 1987

U. S. Nuclear Regulatory Commission Document Control Desk Washington, D.C. 20555

Subject: Docket No. 50-361 30-Day Report Licensee Event Report No. 87-012 San Onofre Nuclear Generating Station, Units 2 and 3

Pursuant to 10 CFR 50.73(a)(2)(iv), this submittal provides the required 30-day written Licensee Event Report (LER) for an occurrence involving an actuation of the Control Room Isolation System (CRIS). Since this event involved shared systems between Units 2 and 3, a single report is being submitted in accordance with NUREG-1022. Neither the health and safety of plant personnel nor the health and safety of the public was affected by this event.

If you require any additional information, please so advise.

Sincerely, HEmorg

Enclosure: LER No. 87-012

cc: F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

J. B. Martin (Regional Administrator, USNRC Region V)

Institute of Nuclear Power Operations (INPO)

JE21