

[PLEASE PRINT ALL REQUIRED INFORMATION]

LICENSEE NAME					LICENSE NUMBER										LICENSE TYPE					EVENT TYPE		
01	C	A	S	01	0	0	-	0	0	0	0	0	-	0	0	4	1	1	1	1	0	1
7	8	9		14	15										25	26				30	31	32

CATEGORY		REPORT TYPE	REPORT SOURCE	DOCKET NUMBER						EVENT DATE					REPORT DATE										
01	CON'T	P	O	P	L	0	5	0	-	0	2	0	6	0	9	1	9	7	7	1	0	0	3	7	7
7	8	57	58	59	60	61							68	69					74	75					80

EVENT DESCRIPTION

02	Eddy current examinations of steam generator tubes indicate there are 8	80
03	tubes in A steam generator; 7 tubes in B steam generator and 10 tubes	80
04	in C steam generator that have greater than 50% tube wall thinning. (S)	80
05	One tube in A steam generator is leaking.	80
06	No. 77-13	80

SYSTEM CODE		CAUSE CODE	COMPONENT CODE					COMPONENT SUPPLIER	COMPONENT MANUFACTURER				VIOLATION			
0	7	C	C	E	H	T	E	X	C	4	N	W	1	2	0	N
7	8	9	10	11	12					17	43	44			47	48

CAUSE DESCRIPTION

08	Westinghouse Steam Generator, Model 27. Tube thinning at the antivibra-	
7 8 9		80
09	tion bars and above the tube sheet. All tubes with greater than 50%	
7 8 9		80
10	thinning indication and leaking will be plugged.	

FACILITY STATUS		% POWER			OTHER STATUS		METHOD OF DISCOVERY		DISCOVERY DESCRIPTION	
11	G	0	0	0	NA		B	Eddy current of S/G-tubes		
7	8	9	10	12	13	44	45	46	80	

FORM OF ACTIVITY RELEASED CONTENT OF RELEASE AMOUNT OF ACTIVITY LOCATION OF RELEASE

1	2
---	---

2

 NA NA

7 8 9 10 11 44 45 80

PERSONNEL EXPOSURES

NUMBER				TYPE	DESCRIPTION
1	3	0	0	2	NA

PERSONNEL INJURIES

NUMBER				DESCRIPTION	
1	4	0	0	0	NA

OFFSITE CONSEQUENCES

1	5	NA
7	8	9

LOSS OR DAMAGE TO FACILITY

TYPE		DESCRIPTION
16		NA

PUBLICITY

17	NA
----	----

ADDITIONAL FACTORS

1	8	NA
---	---	----

119	NA
-----	----

NAME: J. M. CURRAN

PHONE: (714) 492-7700

8103050931